

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

AXA - 45

TS

VEHICLE NO : SHC 1933R

DATE 23/7/2018

MAKE :

MODEL : HYUNDAI SONATA

1115

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>X Repair</i>			\$ 1,349.50
	Boot Lid Lock Upper <i>X</i>			\$ 132.10
	Boot Lid Lock Lower <i>X</i>			\$ 30.30
	Boot Lid Sonata Plate <i>-</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>-</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>-</i>			\$ 26.10
	Boot Lid CRDI Plate <i>-</i>			\$ 22.70
	Rear Bumper <i>-</i>			\$ 578.40
	Rear Bumper Reinforcement <i>-</i>			\$ 483.30
	Rear Bumper Clip <i>-</i>			\$ 22.00
	Rear Bumper Sponge <i>?</i>			\$ 137.40
	Rear Bumper Under Cover <i>?</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X Repair</i>		\$ 38.00	\$ 76.00
	Rear Panel <i>X Repair</i>			\$ 391.80
	Rear Panel Garnish <i>?</i>			\$ 95.80
	SUB TOTAL			\$ 3,599.00
	LESS 20%			\$ 719.80
	DISCOUNTED TOTAL			\$ 2,879.20
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70
	Rear Bumper Advertisement Logo <i>-</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>-</i>		\$ 100.00	\$ 200.00
				\$ 415.70
	Labour Charge			400
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 5,114.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Kalvin 10/10
23/7/18 1505h
2 Rep
45
After Repair p. 1.

600
X
X
X

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.