



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
Mr YEO CHERN YE Blk 485b Tampines Ave 9 #08-130 Singapore 521485 Contact No Mobile: 98585190	Cust No/Name	/Mr Yeo Chern Ye
	Reg No/Reg Date	SLP2348H / 30/05/2017
	Date In/Mileage	23/07/2018/ 0
	Chassis No	JMYXTGF3WHZ001810
	Engine No	4B12SY4875
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F58)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	23/07/2018/ 17:11	DS	218 / MarsLer	61831
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS		60		80.00
S MIPNT88088	SCANNING / DIAGNOSTIC	900			250.00
S MIPNT88088	TO REPLACE FRT BONNET, FRT BUMPER, REINFORCEMENT, LH FENDER ETC STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS				3000.00
S MIPNT98088	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS	1260			2100.00
M SUNDRY	FRT NUMBER PLATE WITH CASING	11 X			50.00
S MIPNT88088	TOP APPLY SEALANT KIT ON NEW PANEL	11 X			200.00
M JJ5900A739	HOOD	1.00	1094.00	0.00	1094.00
P JJMN175241	LH HINGE, HOOD	1.00	67.00	0.00	67.00
M JJ5220K685	FR LH, FENDER	1.00	621.00	0.00	621.00
P JJ6400H881	FACE, FR BUMPER	1.00	810.00	0.00	810.00
M JJ6400H313	LH SIDE BRACKET, FR B	1.00	18.00	0.00	18.00
M JJ6400H314	RH SIDE BRACKET, FR B	1.00	18.00	0.00	18.00
M JJMR590000HB	CLIP, FR BUMPER	10.00	3.00	0.00	30.00
P JJMU488006	CLIP, FR BUMPER	10.00	2.00	0.00	20.00
M JJ6400J047	COVER, FR BUMPER	1.00	277.00	0.00	277.00
P JJ6407A145	LH GARNISH, FR BUMPER	1.00	218.00	0.00	218.00
P JJ6407A143	LH GARNISH, FR BUMPER	1.00	110.00	0.00	110.00
M JJ6407A141	LH GARNISH, FR BUMPER	1.00	48.00	0.00	48.00
P JJ6407A146	RH GARNISH, FR BUMPER	1.00	218.00	0.00	218.00
P JJ6407A144	RH GARNISH, FR BUMPER	1.00	110.00	0.00	110.00
M JJ6407A142	RH GARNISH, FR BUMPER	1.00	48.00	0.00	48.00
M JJ7450A967	GRILLE ASSY, RADIATOR	1.00	564.00	0.00	564.00
M JJ6400G243	LHF COVER, FOG LAMP	1.00	78.00	0.00	78.00
M JJ8321A669	LHF FOG LAMP ASSY	1.00	220.00	0.00	220.00
M JJ7407A301	LHF WHEEL ARCH MOULD	1.00	197.00	0.00	197.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
Mr YEO CHERN YE Blk 485b Tampines Ave 9 #08-130 Singapore 521485 Contact No Mobile: 98585190	Cust No/Name	/Mr Yeo Chern Ye
	Reg No/Reg Date	SLP2348H / 30/05/2017
	Date In/Mileage	23/07/2018/ 0
	Chassis No	JMYXTGF3WHZ001810
	Engine No	4B12SY4875
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F58)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	23/07/2018/ 17:11	DS	218 / MarsLer	61831

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M JJ7407A315 LH MOULDING, FR BUMP	1.00	114.00	0.00	114.00
M JJ7407A316 RH MOULDING, FR BUMP	1.00	114.00	0.00	114.00
M JJ6400H568 REINFORCEMENT, FR BU	1.00	549.00	0.00	549.00
M JJ6400G576 REINFORCEMENT, FR BUM	1.00	133.00	0.00	133.00
M JJ6400D977 REINFORCEMENT, FR BUM	2.00	21.00	0.00	42.00
M JJ6400D581 LH REINFORCEMENT, FR	1.00	59.00	0.00	59.00
M JJ8301C855 LH HEADLAMP ASSY	1.00	802.00	0.00	802.00

Z NOTES

ACCIDENT ON 22/07/2018 ALONG TMT81 OPEN CARPARK
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP # YP1917T TP INS : EQ

Estimate

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Approved
LKK
tel: 62563581
take photo before party.
25/7/18

Confirm & accepted by

Parts	6,579.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,630.00
Others (Lub, etc)	0.00
Sundry	50.00
Total (w/o GST)	12,259.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.