COMFORTDELGRO ENGINEERING PTE LTD

China

DATE 20/7/2018 11:15

REPAIR ESTIMATE*

VEHICLE NO: SHD 3310U

MAKE :

| Qty | : HYUNDAI i40 | | | |
|--------------|---|---------------------------|---|-------------|
| | Rear Bumper / De | Type | Unit Price | Amount |
| | Rear Bumper Reinforcement | | | 0 |
| | Rear Bumper Reinforcement | _ | | \$ 603.60 |
| | Rear Bumper Reinforcement Bracket (LH/RH) | 2 | \$ 180.00 | \$ 504.35 |
| | Dumpel Sille Brookert | | \$ 180.00 | \$ 360.00 |
| | real Bumper Clips | | | \$ 49.00 |
| 11 | Real Bumper Sponge | | | \$ 22.00 |
| 1 | Rear Bumper Under Cover X NW | | | \$ 143.40 |
| | 1010 | | | |
| | 0.00 | | | \$ 225.00 |
| | SUB TOTA | | - | 6 1 5 |
| | LESS 20 | % | | \$ 1,907.35 |
| | DISCOUNTED TOTA | L | | \$ 381.47 |
| | | | | \$ 1,525.88 |
| | | | | |
| | | | | |
| Re | ear Ruma - D | | | |
| Re | ear Bumper Reverse Sensor X W N | | | |
| ICC | ar Bumper Rubber Mat | | \ s | 135.70 N |
| | 7.00. | | S | |
| | | | 4 | 50.00 No |
| | | | \$ | 105 |
| | | | 5 | 185.70 |
| Lab | our Charge | | | |
| Pane | el Beating | | | |
| Spra | y Painting Charge | | | |
| Wiri | ng Charge | | \$ | 350.00 2 |
| R/Re | fix Reverse Sensor | | \$ | 250.00 2 |
| | SCHSOF | | \$ | 50.00 |
| | | | \$ | |
| | TOTAL LABOUR | | | 120.00 |
| | | | \$ | 770.00 |
| | ESTIMATE TOTAL | | | 770.00 |
| | 2 Days | | \$ 2 | 2,481.58 |
| | | | | 3,401.56 |
| | Past my part. | | | |
| | 2 Mays Part by part. Before part photos. Gua avamp - 8288 0282 20/7/18 4:30pm | the Repair | Consultants hence notify of the following: | |
| | Gue Quano - En et no on | o resurvey o display d | before/after spray painting | 11 |
| | 0000 7 00000 2 | • Parts prices | part(s) during resument | 11 |
| | 20/7/18 16:2 | • No illegal | , and to confilmation | |
| | 4 (20 pm | Supplementa | | |
| | V | is subject to fi | orification(s) is allowed ry item(s) must be resurveyed all nal approval from insurance Cor | nd |
| | | Acknowledged b | Isurance Cor | mpany |
| This is an i | nitial estimate based on a visual inspection of the above | Signature: | y repairer | // |
| an is an i | nitial estimate based on a visual inspection of the above | Dale: | | - |

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. d on a visual inspection of the above vehicle. The final repair quantum will