

ASSIGNMENT (Office)

CS3 / LPC18008151 / Agb-1

From (Person): Ong Li Li To: LPC Date/Time: 17/07/2018

OD (1) / WS / TP / RES / OD / RES / EVA / INV / MY / CG

To inspect Vehicle No: SLV 5142M Insured: SJM 103561

at Work location: Reliable Carz Tel: 8166 9797

Policy No: 3 Kaki Bukit Ave 4 #05-50 Date/Time: 18/13/18 / VP05/020598

Signature: Date: 09/05/2018

CA / REV / REF / REV 24 HRS w/p

Date/Time: 11/05/2018 12:06 pm Person: Jason

Vehicle: (Signature)

Date/Time	Signature
	(Signature)
	(Signature)
	(Signature)

Submit \$13k, 10 days.
17/08/18.
(Red \$5700, 30%)

return the photograph to LPC

RECEIVED 17 AUG 2018

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU942M Yr Regn: 2017 / REC.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius Hybrid cc 1797Colour: Black A/C: Insured / Std / NI / NASp. Reading: 59470 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2VWS06098410Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Newton

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I. 11/05/18 @ 0542pmSurvey held at ReliableDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP LonPac PRS

RECEIVED 29 JUN 2018

Date/Time, File Pass to?

11/6/18 train

Date/Time, File Return to?

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 150

Transportation: _____

S + PS: _____

Photo: _____

Others: _____

TOTAL

150Report Format: PRS

Lump Sum / I.B.I: (\$)



LONPAC INSURANCE

To : LKK

Attention : Catherine / Wirtha .
ask your surveyor to

Please ^ review & return

Colour photograph

From :

Ang Li Li

LONPAC INSURANCE BHD

300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel: (65) 6250 7388 Fax: (65) 6296 3767

With Compliments

- ☐ URGENT
- ☐ For your action
- ☐ For your record
- ☐ For your comments
- ☐ For your information
- ☐ For approval and return
- ☐ Please telephone
- ☐ Please sign and return
- ☐ Please acknowledge receipt

ONG LI LI

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Tuesday, 17 July, 2018 3:54 PM
To: ONG LI LI; assignments@lkkauto.com
Cc: MT_Claim_SG; "SUR"
Subject: RE: Your Ref: Am.jt.Ins.R28.SLU5142M.18 (sj) Our Ref: 18/18/18/VP05/020598

Dear Li Li,

Noted with thanks.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Tuesday, 17 July, 2018 3:05 PM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>; "SUR" <sur@lkkauto.com>
Subject: RE: Your Ref: Am.jt.Ins.R28.SLU5142M.18 (sj) Our Ref: 18/18/18/VP05/020598

Dear Catherine

Attached is the TP survey report for your surveyor to review and comment.

Please arrange for the collection of the stack of TP's survey photographs and return them to us after your surveyor's review.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 11 May, 2018 12:11 PM
To: ONG LI LI; assignments@lkkauto.com
Cc: MT_Claim_SG; "SUR"
Subject: RE: Your Ref: Am.jt.Ins.R28.SLU5142M.18 (sj) Our Ref: 18/18/18/VP05/020598

Dear Li Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 05-18022/DY / 2018
Date of Report : 2 Jul 2018

Reliable Rides Pte Ltd
No.8 Kaki Bukit Ave 4
#05-50 Premier@Kaki Bukit
Singapore 415875

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 9 May 2018

As per your instruction dated 11 May 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLU 5142 M. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLU 5142 M
Model : Toyota Prius
Year / Capacity : 2017/1797
Chassis No : ZVW50-6098410
Engine No : 2ZRS105930
Mileage : 59470
Colour : Black

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	195/65 R15	Neuton	5.00	mm	Sport
REAR	O/S	:	195/65 R15	Neuton	5.00	mm	Sport
FRONT	N/S	:	195/65 R15	Neuton	5.00	mm	Sport
REAR	N/S	:	195/65 R15	Yokohama	5.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Reliable Carz Pte Ltd
No.8 Kaki Bukit Ave 4
#05-50 Premier@Kaki Bukit
Singapore 415875

5. Estimated normal period of repair : 14 working days to complete.

6. Enclosed number of photograph : 258 copies.

7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SLU 5142 M
Report No: TP/ 05-18022/DY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
List Items				
1	Rear windscreen glass <i>Not New</i>	Damage	\$ 1217.85	\$ 1217.85 ✓
1	Rear windscreen moulding	Necessary	\$ 172.45	\$ 172.45 ✓
1	Rear tailgate	Damage	\$ 1712.45	\$ 1712.45 ✓ <i>250</i>
1	Rear tailgate lock	Damage	\$ 374.85	\$ 374.85 ✓
1	Rear tailgate rubber	Necessary	\$ 387.90	\$ 387.90 ✓
1	Rear tailgate outer garnish	Damage	\$ 721.35	\$ 721.35 ✓ <i>458</i>
1	Rear tailgate 'PRIUS' emblem	Necessary	\$ 121.25	\$ 121.25 ✓
1	Rear tailgate logo	Necessary	\$ 131.35	\$ 131.35 ✓
1	Rear tailgate top inner trim <i>Not New</i>	Damage	\$ 591.60	\$ 591.60 X
2	Rear tailgate dampers <i>Not New</i>	Damage	\$ 757.70	\$ 757.70 X
2	Rear tailgate lamps	Damage	\$ 763.80	\$ 763.80 ✓
1	Rear tailgate inner board	Damage	\$ 784.45	\$ 784.45 ✓
1	Rear tailgate centre glass	Damage	\$ 561.60	\$ 561.60 ✓
2	Rear taillamps	Damage	\$ 748.90	\$ 748.90 ✓
2	Rear taillamp panels	Damage	\$ 763.80	\$ 763.80 ✓
1	Rear end panel	Damage	\$ 781.25	\$ 781.25 ✓
1	Rear end panel inner garnish	Damage	\$ 561.60	\$ 561.60 ✓ <i>275</i>
1	Rear smart sensor	Damage	\$ 380.00	\$ 380.00 ✓ <i>125</i>
1	Rear bumper	Damage	\$ 481.75	\$ 481.75 ✓
2	Rear bumper brackets	Damage	\$ 264.50	\$ 264.50 ✓
1	Rear bumper reinforcement	Damage	\$ 372.10	\$ 372.10 ✓
2	Rear bumper side retainers	Damage	\$ 264.20	\$ 264.20 ✓
2	Rear bumper lamps	Damage	\$ 282.90	\$ 282.90 ✓
1	Rear bumper spoiler	Damage	\$ 681.90	\$ 681.90 ✓
1	Rear bumper tow cover	Damage	\$ 43.75	\$ 43.75 ✓
2	Rear bumper lower side under covers	Damage	\$ 246.10	\$ 246.10 ✓
1	Rear lower bumper	Damage	\$ 552.60	\$ 552.60 ✓
2	Rear number plate lamps	Damage	\$ 242.50	\$ 242.50 ✓
1	Rear spare tyre board	Damage	\$ 591.60	\$ 591.60 ✓
1	Rear spare tyre panel <i>Repair</i>	Damage	\$ 581.75	\$ 581.75 X
1	Rear spare tyre tool tray	Damage	\$ 581.35	\$ 581.35 ✓
1	Rear spare tyre top sponge	Damage	\$ 561.60	\$ 561.60 ✓
1	Rear exhaust silencer	Damage	\$ 791.25	\$ 791.25 ✓
2	Rear exhaust silencer mountings <i>Not New</i>	Necessary	\$ 264.20	\$ 264.20 X
1	Rear exhaust silencer heat shield	Damage	\$ 121.45	\$ 121.45 ✓
1	Rear fender <i>Repair</i>	N/S Damage	\$ 1944.20	\$ 997.10 X
1	Rear fender air gate	Damage	\$ 172.45	\$ 172.45 ✓

List Items Sub Total \$ 20576.30 \$ 19629.20

Vehicle No: SLU 5142 M
Report No: TP/ 05-18022/DY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
-----	-------------------	-----------	-----------------------	------------------------

List Items Total c/f \$ 20576.30 \$ 19629.20

List Items

2	Rear fender inner trims	Damage	\$ 1443.80	\$ 1443.80
1	Rear fender quarter glass moulding	Necessary	\$ 172.10	\$ 172.10
1	Roof top panel	Repair	\$ 972.10	\$ 972.10
1	Front passenger seat	Damage	\$ 1627.50	\$ 1627.50
			\$ 24791.80	\$ 22872.60
	Discount 25.0%		\$ 6197.95	\$ 5718.15
			\$ 18593.85	\$ 17154.45

Special Nett Items

1	Rear windscreen sealant	Necessary	\$ 100.00	\$ 60.00
1	Rear windscreen glass solar film	Damage	\$ 380.00	\$ 380.00
1	Rear number plate	Damage	\$ 50.00	\$ 50.00
1	Rear reverse sensor (1 set)	Damage	\$ 320.00	\$ 280.00
1	Rear spare tyre panel insulator	Necessary	\$ 120.00	\$ 120.00
1	Rear reverse camera	Damage	\$ 480.00	\$ 480.00
			\$ 1450.00	\$ 1370.00

Spare Parts Total \$ 20043.85 \$ 18524.45

Vehicle No: SLU 5142 M
Report No: TP/ 05-18022/DY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
Spare Parts Total c/f		\$ 20043.85	\$ 18524.45
1	To provide towing service charge.	\$ 80.00	\$ 80.00 60
2	To remove and refit rear cushion seats, radio speaker board, interior upholstery to facilitate the repairs.	\$ 220.00	\$ 140.00 100
3	To remove and refit fuel tank system.	\$ 120.00	\$ 80.00 X
4	To remove and refit rear bumper sensor.	\$ 110.00	\$ 80.00 60
5	To remove and refit rear windscreen glass.	\$ 200.00	\$ 120.00 ✓
6	To remove and refit quarter glass to facilitate the repairs.	\$ 120.00	\$ 60.00 X
7	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 110.00	\$ 80.00 ✓
8	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 2300.00	\$ 2000.00 1400
9	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 2300.00	\$ 2000.00 1300
10	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 250.00	\$ 150.00 60
Total		\$ 25853.85	\$ 23314.45

3180

Vehicle No: SLU 5142 M
Report No: TP/ 05-18022/DY / 2018


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
Total c/f		\$ 25853.85	\$ 23314.45

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 18700.00

SDLS: EIGHTEEN THOUSAND SEVEN HUNDRED ONLY


Qualified Appraiser

total. 16236.82
L/S 13K
10 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18008651/Aqbe2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 20-08-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 1035G	Veh. Inspected	SLU 5142M	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020598	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	17/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZVW506098410	Colour	BLACK	
Odometer	59470	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEUTON	6 mm	
L/H Front Tyre	195/65 R15	NEUTON	6 mm	
R/H Rear Tyre	195/65 R15	NEUTON	6 mm	
L/H Rear Tyre	195/65 R15	NEUTON	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/05/2018	Inspection Date	11/05/2018	
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5142M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN GLASS	NOT NECESSARY	1,217.85	-
1	REAR WINDSCREEN MOULDING	NECESSARY	172.45	172.45
1	REAR TAILGATE	DAMAGED	1,712.45	1,250.00
1	REAR TAILGATE LOCK	DAMAGED	374.85	374.85
1	REAR TAILGATE RUBBER	NECESSARY	387.90	387.90
1	REAR TAILGATE OUTER GARNISH	DAMAGED	721.35	458.00
1	REAR TAILGATE 'PRIUS' EMBLEM	NECESSARY	121.25	121.25
1	REAR TAILGATE LOGO	NECESSARY	131.35	131.35
1	REAR TAILGATE TOP INNER TRIM	NOT NECESSARY	591.60	-
2	REAR TAILGATE DAMPERS	NOT NECESSARY	757.70	-
2	REAR TAILGATE LAMPS	DAMAGED	763.80	763.80
1	REAR TAILGATE INNER BOARD	DAMAGED	784.45	784.45
1	REAR TAILGATE CENTRE GLASS	DAMAGED	561.60	561.60
2	REAR TAILLAMPS	DAMAGED	748.90	748.90
2	REAR TAILLAMP PANELS	DAMAGED	763.80	763.80
1	REAR END PANEL	DAMAGED	781.25	781.25
1	REAR END PANEL INNER GARNISH	DAMAGED	561.60	275.00
1	REAR SMART SENSOR	DAMAGED	380.00	125.00
1	REAR BUMPER	DAMAGED	481.75	481.75
2	REAR BUMPER BRACKETS	DAMAGED	264.50	264.50
1	REAR BUMPER REINFORCEMENT	DAMAGED	372.10	372.10
2	REAR BUMPER SIDE RETAINERS	DAMAGED	264.20	264.20
2	REAR BUMPER LAMPS	DAMAGED	282.90	282.90
1	REAR BUMPER SPOILER	DAMAGED	681.90	681.90
1	REAR BUMPER TOW COVER	DAMAGED	43.75	43.75
2	REAR BUMPER LOWER SIDE UNDER COVERS	DAMAGED	246.10	246.10
1	REAR LOWER BUMPER	DAMAGED	552.60	552.60
2	REAR NUMBER PLATE LAMPS	DAMAGED	242.50	242.50
1	REAR SPARE TYRE BOARD	DAMAGED	591.60	591.60
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	581.75	-

Report Ref No. CS3/LPC18008651/Aqbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE TOOL TRAY	DAMAGED	581.35	581.35
1	REAR SPARE TYRE TOP SPONGE	DAMAGED	561.60	561.60
1	REAR EXHAUST SILENCER	DAMAGED	791.25	791.25
2	REAR EXHAUST SILENCER MOUNTINGS	NOT NECESSARY	264.20	-
1	REAR EXHAUST SILENCER HEAT SHIELD	DAMAGED	121.45	121.45
1	REAR FENDER	TO REPAIR SEE LABOUR	1,944.20	-
1	REAR FENDER AIR GATE	DAMAGED	172.45	172.45
2	REAR FENDER INNER TRIMS	DAMAGED	1,443.80	750.00
1	REAR FENDER QUARTER GLASS MOUNTING	NOT NECESSARY	172.10	-
1	ROOF TOP PANEL	TO REPAIR SEE LABOUR	972.10	-
1	FRONT PASSENGER SEAT	DAMAGED	1,627.50	1,627.50
	LESS 25% DISCOUNT		-6,197.95	-4,082.28
			18,593.85	12,246.82
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
1	REAR WINDSCREEN GLASS SOLAR FILM (SN)	NOT NECESSARY	380.00	-
1	REAR NUMBER PLATE (SN)	DAMAGED	50.00	50.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	320.00	200.00
1	REAR SPARE TYRE PANEL INSULATOR (SN)	NECESSARY	120.00	120.00
1	REAR REVERSE CAMERA (SN)	DAMAGED	480.00	380.00
			1,450.00	810.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE CHARGE.		80.00	60.00
	TO REMOVE AND REFIT REAR CUSHION SEATS, RADIO SPEAKER BOARD, INTERIOR UPHOLSTERY TTO FACILITATE THE REPAIRS.		220.00	100.00
	TO REMOVE AND REFIT FUEL TANK SYSTEM.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		110.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		200.00	120.00
	TO REMOVE AND REFIT QUARTER GLASS TO FACILITATE THE REPAIRS.	NOT NECESSARY	120.00	-

Report Ref No. CS3/LPC18008651/Aqbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.		110.00	80.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL, REAR FENDER AND ROOF TOP PANEL.		2,300.00	1,400.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		2,300.00	1,300.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		250.00	60.00
			5,810.00	3,180.00
GRAND TOTAL			25,853.85	16,236.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CS3/LPC18008651/Aqbe2-1

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.