

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18013396/AEA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	M495287
Claimant		
Vehicle No : SKJ3705Y	Insured Vehicle No :	GBE6002E
Date of Loss: 20/07/2018	Nature of Claim: TP	Claim No: MC20182644

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ3705Y	
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Engine No: HIDDEN
Reg. Date:	01/03/2013 (Man. Year: 2013)	Chassis No: WDD2040312A823257
Colour:	Silver	Odometer: 131599 km
Engine Capacity:	1595 cc	
Market Value/New Car Price:	N/A	
Sum Insured (\$\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,236.18	16,682.33	12,553.85	42.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,070.00	5,940.00	4,130.00	41.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	39,306.18	22,622.33	16,683.85	42.45
Approved Total (Overridden) (\$\$)		18,100.00		
Nett Amount (\$\$)	39,306.18	18,100.00	21,206.18	53.95
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	20/07/2018	
Date Inspected:	20/07/2018 Inspected At:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	17.0 days	

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2020)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ3705Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,700.00 F	*1,550.00 FL
2	2		*REAR BOOT LID HINGE	Bent	310.00 F	*310.00 FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	49.00 F	*49.00 FL
4	3		*REAR BOOT LID EMBLEM LOGO CLIP	Necessary	12.00 F	*12.00 FL
5	1		*REAR BOOT LID C180 LOGO	Necessary	85.00 F	*85.00 FL
6	1		*REAR BOOT LID CNC LOGO	Necessary	55.00 F	*55.00 FL
7	1		*REAR BOOT LID 7G-TRONIC LOGO	Necessary	82.00 F	*82.00 FL
8	1		*REAR BOOT LID CENTRE CHROME MOULDING	Not Necessary	210.00 F	*- FL
9	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
10	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	56.00 F	*- FL
11	1		*REAR BOOT LID INNER LOCK & COVER	Damaged	301.00 F	*301.00 FL
12	6		*REAR BOOT LID INNER LOCK & COVER CLIP	Not Necessary	39.00 F	*- FL
13	1		*REAR BOOT LID INNER RUBBER	Cut	175.00 F	*175.00 FL
14	1		*REAR BOOT LID INNER TRIM BOARD	Crumpled	232.00 F	*232.00 FL
15	2		*REAR TAIL LAMP	Cracked	1,572.00 F	*1,572.00 FL
16	2		*REAR TAIL LAMP LOWER BRACKET	N/S Smashed / O/S Damaged	136.00 F	*136.00 FL
17	1		*REAR BUMPER	Distorted	1,633.00 F	*1,350.00 FL
18	8		*REAR BUMPER CLIP	Necessary	52.00 F	*52.00 FL
19	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	76.00 F	*38.00 FL
20	1		*REAR BUMPER REINFORCEMENT	Bent	707.00 F	*707.00 FL
21	1		*REAR BUMPER CENTRE INNER TOP BEAM	Cracked	145.00 F	*145.00 FL
22	1		*REAR BUMPER LOWER SPOILER	Cut	506.00 F	*506.00 FL
23	2		*REAR BUMPER LOWER SPOILER INNER BRACKET	Not Necessary	80.00 F	*- FL
24	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	480.00 F	*240.00 FL
25	1		*REAR END PANEL OUTER	Distorted	1,303.00 F	*1,303.00 FL
26	1		*REAR END PANEL INNER MEMBER	Distorted	220.00 F	*220.00 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	125.00 F	*125.00 FL
28	1		*REAR END PANEL LOCK	Not Necessary	85.00 F	*- FL
29	2		*REAR FENDER	Distorted	4,276.00 F	*4,276.00 FL
30	2		*REAR FENDER INNER TRIM BOARD	N/S Crumpled / O/S Deformed	570.00 F	*570.00 FL
31	1		*REAR FENDER INNER COVER	N/S Deformed	136.00 F	*68.00 FL
32	1		*REAR FENDER INNER COVER CLIP (6 PCS)	Necessary	39.00 F	*10.00 FL
33	1		*REAR L/H FENDER INNER PANEL	Repair	492.03 F	*- FL
34	1		*REAR L/H FENDER INNER HOUSING	Repair	5,320.00 F	*- FL
35	1		*REAR L/H FENDER COWLING	Torn	178.00 F	*178.00 FL
36	1		*REAR L/H FENDER AIR DUCT	Damaged	28.00 F	*28.00 FL
37	1		*REAR SPARE TYRE PANEL	Repair	285.00 F	*- FL
38	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	325.00 F	*325.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR WINDSCREEN	Shattered	965.00 F	*965.00 FL
40	1		*REAR WINDSCREEN SEAL	Necessary	165.00 F	*165.00 FL
41	1		*REAR WINDSCREEN INNER SIDE COVER	N/S Cut	80.00 F	*40.00 FL
42	1		*REAR RADIO SPEAKER PANEL	Repair	1,401.00 F	*- FL
43	1		*REAR RADIO SPEAKER PANEL TOP COVER BOX	Cracked	768.15 F	*768.15 FL
44	1		*REAR EXHAUST	Bent	1,957.00 F	*1,245.00 FL
45	1		*REAR EXHAUST CHROME PIPE	Bent	220.00 FS	*120.00 FS
46	2		*REAR EXHAUST MOUNTING	Not Necessary	180.00 F	*- FL
47	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	70.00 F	*- FL
48	1		*REAR L/H EXHAUST SIDE ALUMINIUM COVER	Crumpled	75.00 F	*75.00 FL
49	1		*REAR WINDSCREEN CAMERA	Not Necessary	680.00 FS	*- FS
50	1		*REAR BOOT LID CAMERA	Damaged	550.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 29,236.18 18,478.15
- List Item Discount on L Items 0.00/10.00% (S\$) 0.00 1,795.82

Total Parts (S\$) 29,236.18 16,682.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION	New	380.00	250.00
2	TO REMOVE & REFIT ROOF TOP LINING	New	450.00	0.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
4	GUM	New	50.00	50.00
5	TO REMOVE & REFIT PETROL TANK	New	280.00	120.00
6	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	60.00
7	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	100.00
8	TO REMOVE & REFIT WINDSCREEN CAMERA & BOOT LID CAMERA	New	380.00	100.00
9	TO RESET HEADREST	New	850.00	600.00
10	TO RESET COMPUTER	New	350.00	100.00
11	TO CHECK WIRING	New	100.00	60.00
12	TOWING FEE	New	150.00	120.00
13	TUFF KOTE	New	150.00	160.00
14	PANEL BEATING	New	3,500.00	2,200.00
15	SPRAY PAINTING	New	2,800.00	1,900.00
Gross Labour Cost (\$\$)			10,070.00	5,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >