

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 26 Jul 2018

Preliminary Advice

Vehicle No	: WD158K	Accident Date	: 07/07/2018
Make	: ISUZU CYH52S	Policy No.	: 29088496MKF
Assignment Date	: 23/07/2018	Excess	: S\$1,500.00
Date of Inspection	: 24/07/2018	Est. Duration of Repair	: 20.00
Inspection At	: TRIANGLE AUTO PTE LTD (HQ) 20 TUAS AVE 2 SINGAPORE 639451		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	119,425.60
Revised Amount	:S\$	27,691.60
Check Items (Estimated)	:S\$	83,791.20
Total	:S\$	111,482.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	34,249.00
Salvage Value	:S\$	
Margin for Repair	:S\$	105,751.00

Remarks

() The vehicle is economical/not economical for repair.

(X) Kindly advice on offer repair cost to repairer. Please note the margin repair cost is \$105,751.00