

//11/2018

ASS. REC. BY:

REF:

SLCTI18013406/T1cd30

Est. Inspection

Surveyor
meinen

Taufik

ASSIGNMENT (Office)

From (Person):

Irene Jay

of

CTI

Date/Time:

23/7/18 @ 5.26pm

Estimated Cost:

Bill to:

OD / ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 7064L

Insured:

WC 6387G

at Workshop in/:

Vernogen

Tel:

6368 3031

of

G Beroi & cefer

Policy No:

DMCVSN 1637 531802

Claim No:

SNM18D03595C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/7/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

kup

H.O.D. Endorsement:

Date/Time:

9:14am @ 24/7/18

Person Contacted:

pila

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction

☒ Estimate

SLC 7064L - x

WC 6387G -

38/11/13 wef

ASS. REC. BY:

Tanjia

REF: CTI

ASSIGNMENT

From: Date: 24/7/18

Estimated Cost:

QD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 7064 L

at Workshop m/s Vermogen Ace

of 6 Benel Sector

Insured:

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh:

Moming

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

A72K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS^{1up}

Date: Person Contacted:

Vehicle: IN / OUT

M/notes

Veh No: SLC 7064 L Yr Regn: 2016 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 24/11/6/63

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sanyo

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 24/7/18

Survey held at Vermogen

Des. of Damages (Fr) / Rear / O/S / N/S / U/C / Rooftop or

Fr, O/S, Rear N/S, U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	badly much Rebrate \$43,167
	Repair limit \$28K.
	Inform Minako limit \$26K
28/6/19	Email Minako L/S \$26,000, 28 days (Chad. S3, S26, S1, GF 2)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 28

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

220

Transportation:

S + RS. SI

Photos

Others

TOTAL

220

Report Format: TP

Lump Sum / I.B.I. (\$ 26,000)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CT118013406/T1rd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 24-07-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	WC 6387G	Veh. Inspected	SLC 7064L
Policy No.	DMCVSN1637531802	Coverage (\$)	0.00
Claim No.	SNM18D03595C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	24/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/07/2018	Inspection Date	24/07/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Subm Stg	Adj Auth Stg	Status
Main	23 Jul 2018		23 Jul 2018 17:26 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	YA HUAN TRANSPORT PTE LTD, Co. Reg. No.: 201610485W		
Main Claimant:	KWAN KOK SIONG, ID: S1388797G		
Vehicle Reg. No.:	SLC7064L	Date of Loss:	19/07/2018 19:00 - :59
Claim Type:	TP / SNM18D03595C02	Policy/Cover Note No.:	DMCVSN1637531802 (Comprehensive)
Vehicle Reg. No. (Insured):	WC6387G	Policy No. (Claimant):	
		Excess:	\$50.00
Repairer:	Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/08/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: ezel.t@vermogen-group.com
Sent: Monday, 23 July, 2018 11:44 AM
To: Claims Dept of CTI
Cc: 'Baldoz Juan Paulo Bongon'; 'Edmond Lim'; 'Minoko Chan'; ace@vermogen-group.com; 'Luis Tan'; 'Glorioso Eric Paul Patambang'; 'Yira Rahman'; 'Pila Ng'; 'Vmg admin'; desmond@vermogen-group.com
Subject: Accident involving SLC7064L & WC6387G (Your Insured) on 19/07/2018 - PLEASE ARRANGE TP SURVEY
Attachments: SLC7064L 19JULY2018 TP.PDF

Dear officer in-charge,

Refer to above attachment, kindly arrange our client's vehicle for pre-repair survey at **Vermogen Ace Pte Ltd** here at **6 Benoi Sector** Block B Singapore(629904)

VEHICLE IN WORKSHOP

Beside, we would like to check for the liability on this matter.

Kindly check & revert to us as soon as possible.

Thank you.

Best regards,
Ezel Tejano
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6358 3031
Fax: 6694 4929

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	4597K

Vehicle Details

Vehicle No.:	SLC7064L
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4036167
Chassis No.:	RU11116163
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,054.00
Original Registration Date:	24 May 2016
First Registration Date:	24 May 2016
Transfer Count:	1
Actual ARF Paid:	\$10,076.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 May 2026
PARF Rebate Amount:	\$7,557.00

Intended COE Rebate Details

COE Expiry Date:	23 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$34,629.00
Total Rebate Amount:	\$42,186.00

The information contained herein is correct as at 13 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2018 12:21
Date Of Accident	19/07/2018 19:30
Exact Location Of Accident	PUNGGOL EAST FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC7064L
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995074
Cover Note Number	

Driver

Name of Driver	KWAN KOK SIONG
NRIC No	S1388797G
Date Of Birth	17/08/1958
Occupation	OUTDOOR
Date Of Driving Pass	28/09/1978
Driving Experience	39 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	44 BENOI ROAD BLOCK B
Postcode	629904
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER ATTACHED. THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC6387G
Vehicle Make/Model/Colour	
Details Of Properties	VEH. B
Vehicle Category	TANKER
Name of Driver	HUANG GAOSHEN
NRIC/Passport Number	G5099824Q
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

I. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/IDA No.:

Accident Sketch Plan Pg. 2

SKETCH PLAN

(A) SLCT064L

(B) WC6387G



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along the second lane with cautions. suddenly I felt an impact from my rear right portion and makes my car moved and faced to a stop to the opposite. I realised a cement lorry has collided with me caused my car had damaged.

(Pending Police report).

DECLARATION

✓We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Constable's Signature
Name:
NRIC/ID No.:

Punggol East Flyover - Google Maps

7/20/2018

Google Maps Punggol East Flyover




Image capture: Oct 2017 © 2018 Google

Singapore

Google, Inc.

Street View - Oct 2017

https://www.google.com/maps/@1.3800869,103.9119142,3a,75y,231.19m,87.52t/data=!3m1!1e1!3m4!1annymZ-sdM_v40pAdVAXgl2e07113312186656

NRIC AND LICENSE



240	240	2200
892.3	100	1400
97	100	200
122.3	45	250
35	160	100
87.7	60	200
35.2	240	100
792	945	30
50		150
144		100
96.8		200
35		80
130		1400
96.8		1000
398.3		250
275.2		200
150.6		30
52		100
134.1		60
139.5		120
321		8170
576.2		
85		
35		
568.1		
960		
114		
148.2		
75		
59.6		
2900		
114		
320		
170		
1117.4		
306		
165		
115		
55		
63		
260		
80		
309.2		
196		
337.5		
36.8		
36.7		
26.95		
32		
60		

~~12.5~~
~~175~~
~~374.1~~
~~98.7~~
~~110~~
~~85~~
~~1178.4~~
~~245~~
~~390~~
~~181.4~~
~~795~~
~~600~~
~~490~~
~~650.5~~
~~78~~
~~85~~
~~755~~
~~70~~
~~1185.6~~
~~20~~
~~48~~
~~48~~
~~55~~
~~155~~
~~110~~
~~27.5~~
~~30~~
~~382.5~~ 382.90
~~262.3~~
~~588.5~~
~~40~~
~~95.5~~
~~230~~
~~62~~
~~1861.2~~
~~40~~
~~95.2~~
~~110~~
~~14.9~~
~~29.2~~
~~210~~
~~635~~
~~40~~
~~95.5~~
~~1809.4~~
~~150~~
~~306~~
~~180.8~~
~~80~~
~~508.5~~

50

144

390

428.7

18

330

263.5

1350

600

~~33099.85~~ 33100.25

20% - ~~26477.88~~ 26480.20

945

8170

~~35594.88~~ 35595.20

20% - ~~28475.90~~ 28476.16

2/5 of 26,000



SLC7064L

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 19-07-18

Vehicle Reg. No. : SLC7064L
Vehicle Reg. Date: 24-May-2016
Make / Model : VEZEL 1.5X CVT ABS D/All
Engine No. : L15B4036167
Chassis No. : RU11116163

COST OF CLAIMS

Parts Cost / List Items : \$ 64,992.30
Plus/Less 20% \$ 12,998.46
Total Cost / List : \$ 51,993.84
Special Nett Items : \$ 3,050.00
Total Parts Amount : \$ 55,043.84
Total Labour Amount : \$ 19,280.00
Gross Total : \$ 74,323.84
GST % : 7% \$ 5,202.67
Nett Amount : \$ 79,526.51

Surveyor Name and Company :

Tanpin 9749549

Date of survey : 24/7/18 @ 1345

Part by Part / Lump Sum : _____ days

Resurvey Before Paint / After Paint After

Authorize/Not Authorize/Without Prejudice Without

Email : sure@lkkauto.com

Fax No : _____

HP No : _____

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

*To check repair limit
*28 days

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC7064L**

Vehicle Reg. Date: **24-05-16**

Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**

Engine No. : **L15B4036167**

Chassis No. : **RU11116163**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT WINDSCREEN GLASS MOULDING	Run	\$ 240.00		
2	1	FRONT WIPER PANEL	Rp	\$ 250.20		
3	1	FRONT WIPER PANEL GARNISH	del	\$ 240.00		240
4	1	BONNET	bt	\$ 892.30		892.30
5	2	BONNET HINGES LH/RH	bt	\$ 97.00		97.00
6	1	BONNET INSULATOR	del	\$ 122.30		122.30
7	1SET	BONNET INSULATOR CLIPS	del	\$ 35.00		35.00
8	1set	BONNET LOCK	? bt ✓	\$ 87.70		87.70
9	1	BONNET LOCK CABLE	? run	\$ 42.50		
10	1	BONNET RUBBER FRONT	del	\$ 35.20		35.20
11	2	BONNET SIDE RUBBER LH/RH	Run	\$ 66.80		
12	1	FRONT BUMPER	del	\$ 927.50	792	927.50
13	1SET	FRONT BUMPER CLIPS	del	\$ 50.00		50.00
14	2	FRONT BUMPER RETAINER LH/RH	del	\$ 144.00		144.00
15	1	FRONT BUMPER LOWER SKIRT	del	\$ 96.80		96.80
16	1SET	FRONT BUMPER LOWER SKIRT CLIPS	del	\$ 35.00		35.00
17	1	FRONT BUMPER LIP RUBBER	Run	\$ 87.10		
18	2	FRONT UNDERSHIELD LH/RH	del	\$ 130.00		130.00
19	1	FRONT ENGINE LOWER COVER	? del	\$ 96.80		96.80
20	1	FRONT GRILLE BASE	del	\$ 1,150.00	398.30	1150.00
21	2	FRONT GRILLE GARNISH	del	\$ 510.00	275.20	510.00
22	2	FRONT GRILLE CHROME LH/RH	del	\$ 242.00	150.60	
23	2	FRONT GRILLE LOGO	del	\$ 52.00		
24	2	FRONT GRILLE SIDE BRACKET LH/RH	del	\$ 134.10		
25	1	FRONT GRILLE CENTER BRACKET	del	\$ 139.50		
26	1	FRONT BUMPER REINFORCEMENT	bt	\$ 321.00		
27	2	FRONT REINFORCEMENT GARNISH LH/RH	Run	\$ 48.40		
28	2	FRONT CHASSIS MEMBER LH/RH	Rp	\$ 1,510.00		
29	1	FRONT SUPPORT PANEL	bt	\$ 576.20		
30	1	FRONT SUPPORT TOP GARNISH	del	\$ 85.00		
31	1	FRONT SUPPORT TOP GARNISH CLIPS	del	\$ 35.00		
32	1	CONDENSER	? bt ✓	\$ 568.10		
33	1	CONDENSER FAN MOTOR	? fan	\$ 308.00		
34	1	CONDENSER FAN MOTOR BLADE	? fan	\$ 58.00		
35	1	CONDENSER FAN MOTOR COWLING	? fan	\$ 98.00		
36	1	RADIATOR	? bt ✓	\$ 1,250.60	960	
37	1	RADIATOR FAN MOTOR	? fan	\$ 298.00		
38	1	RADIATOR FAN MOTOR BLADE	? fan	\$ 57.70		
39	1	RADIATOR FAN MOTOR COWLING	? fan	\$ 125.00		
40	2	RADIATOR AIR GUIDE LH/RH	? del	\$ 114.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC7064L**
 Vehicle Reg. Date: **24-05-16**
 Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **L15B4036167**
 Chassis No. : **RU11116163**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	AIRCON DISCHARGE PIPE	?	\$ 210.00		
42	1	AIRCON LIQUID PIPE	?	\$ 195.00		
43	1	AIRCON SUCTION PIPE	?	\$ 121.50		
44	1	RADIATOR TOP HOSE	?	\$ 40.00		
45	1	RADIATOR BOTTOM HOSE	?	\$ 42.00		
46	2	HORN HIGH/LOW	✓ Cover	\$ 148.20		
47	1	WASHER TANK	de	\$ 75.00		
48	1	WASHER TANK NECK	x	\$ 28.00		
49	1	WASHER TANK MOTOR	mis	\$ 59.60		
50	1	AIR RESONATOR	x	\$ 180.00		
51	1	SPARETANK RESERVIOR	x	\$ 186.20		
52	1	SPARETANK RESERVIOR BY PASS HOSE	x	\$ 36.00		
53	2	HEAD LAMP LH/RH	Chr	\$ 3,569.00	2900	
54	2	HEAD LAMP BRACKET LH/RH	chr	\$ 114.00		
55	2	FOG LAMP LH/RH	? chr	\$ 756.40	320	
56	2	FOG LAMP GARNISH LH/RH	de	\$ 170.00		
57	2	FRONT FENDER LH/RH	ht	\$ 1,117.40		
58	2	FRONT FENDER ARC GARNISH LH/RH	de	\$ 306.00		
59	1/2	FRONT WHEEL HOUSE EXTENSION LH/RH	LH-RH-buc	\$ 330.00		165.00
60	1/2	FRONT WHEEL HOUSE UPPER MEMBER LH/RH	LH-RH-bi	\$ 230.00		115.00
61	1/2	FRONT WHEEL HOUSE SIDE GUSSET LH/RH	LH-RH-de	\$ 110.00		55
62	1/2	FRONT WHEEL HOUSE SIDE GUSSET PLATE LH/RH	LH-RH-de	\$ 126.00		63
63	2	FRONT FENDER APRON LH/RH	x	\$ 230.00		
64	2	FRONT FENDER UNDERSHIELD LH/RH	de	\$ 260.00		
65	2SET	FRONT FENDER UNDERSHIELD CLIPS	de	\$ 80.00		
66	2	ENGINE MOUNTING LH/RH	? ht	\$ 309.20		
67	2	ENGINE MOUNTING BRACKET LH/RH	? ht	\$ 196.00		
68	1	ENGINE MOUNTING REAR	x	\$ 135.00		
69	1/2	FRONT SHOCK ABSORBER LH/RH	LH-RH-bi	\$ 675.00		337.50
70	1/2	FRONT SHOCK MOUNTING LH/RH	LH-RH-bi	\$ 73.60		36.80
71	1/2	FRONT SHOCK MOUNTING BEARING LH/RH	LH-RH-bi	\$ 73.40		36.70
72	1/2	FRONT SHOCK STOPPER LH/RH	LH-RH-bi	\$ 53.90		26.95
73	1/2	FRONT SHOCK DUST COVER LH/RH	LH-RH-de	\$ 64.00		32.00
74	1/2	FRONT STABILIZER BUSH LH/RH	LH-RH-bi	\$ 120.00		60
75	1/2	FRONT STABILIZER LINK LH/RH	LH-RH-bi	\$ 25.00		12.50
76	1	FRONT STABILIZER BAR	? ht	\$ 175.00		
77	1/2	FRONT LOWER ARM LH/RH	LH-RH-bi	\$ 748.20		374.10
78	1/2	FRONT LOWER ARM BALL JOINT LH/RH	LH-RH-bi	\$ 197.40		98.70
79	1/2	TIE ROD END LH/RH	LH-RH-bi	\$ 220.00		110.00
80	1/2	RACK END LH/RH	LH-RH-bi	\$ 170.00		85.00

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC7064L**
 Vehicle Reg. Date: **24-05-16**
 Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **L15B4036167**
 Chassis No. : **RU11116163**

PAGE 3

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
81	1	STEERING RACK & PINION ASSY	Bt	\$ 1,750.00	1178.42	/
82	1	FRONT WHEEL HUB LH/RH	RH Bt	\$ 490.00	245	/
83	1	FRONT KNUCKLE ARM LH/RH	RH Bt	\$ 780.00	390	/
84	1	FRONT WHEEL BEARING LH/RH	RH Nec	\$ 362.80	181.42	/
85	2	FRONT ABS SENSOR LH/RH	X n	\$ 360.00	/	X
86	2	FRONT DRIVE SHAFT LH/RH	X n	\$ 2,200.00	/	X
87	1	FRONT ENGINE CROSSMEMBER	? Bt	\$ 795.00	/	/
88	4	FRONT RIM LH/RH	at	\$ 1,900.00	600	/
89	4	FRONT TYRE LH/RH	LH-RH, RH p/wheel	80% 0	\$ 600.00	240
90	1	FRONT WINDSCREEN GLASS SEALANT	X n	\$ 80.00	/	X
91	1	FRONT WINDSCREEN GLASS INNER SEAL	X n	\$ 80.00	/	X
92	1	FRONT WINDSCREEN GLASS PRIME & CLEANER	X n	\$ 80.00	/	X
93	1	RADIATOR COOLANT	? n	\$ 100.00	/	/
94	1	AIRCON GAS	? n	\$ 100.00	/	/
95	1	FRONT NUMBER PLATE WITH FRAME	MB	45	\$ 50.00	/
96	1	FRONT CHASSIS SEALANT	X n	\$ 160.00	/	X
97	1	BATTERY	X n	\$ 300.00	/	X
98	1	FUSE BOX ASSY RH LH	X n	\$ 980.00	490	/
99	1	SIDE MIRROR ASSY RH	RH	\$ 794.50	650.50	/
100	1	SIDE MIRROR GLASS RH	Che	\$ 78.00	/	/
101	1	SIDE MIRROR COVER RH	Che	\$ 85.00	/	/
102	2	SIDE SKIRT	at	\$ 755.00	/	/
103	2SET	SIDE SKIRT CLIPS	at	\$ 70.00	/	/
104	2	ROCKER PANEL	RH	\$ 1,321.20	/	/
105	1	FRONT DOOR PILLAR RH	RH	\$ 933.50	/	/
106	2	FRONT DOOR PILLAR-INNER RH	RH	\$ 222.00	/	/
107	2	FRONT DOOR	Bt	\$ 1,900.00	1185.60	/
108	1	FRONT DOOR STICKER RH	at	\$ 20.00	/	/
109	1	FRONT DOOR HINGE TOP RH	Bt	\$ 48.00	/	/
110	1	FRONT DOOR HINGE BOTTOM RH	Bt	\$ 48.00	/	/
111	1	FRONT DOOR CHECKER RH	Bt	\$ 55.00	/	/
112	1	FRONT DOOR WEATHERSTRIP RH	at	\$ 155.00	/	/
113	1	FRONT DOOR STRIKER RH	X n	\$ 25.10	/	X
114	1	FRONT DOOR RUBBER TOP RH	? de	\$ 110.00	/	/
115	1	FRONT DOOR RUBBER LOWER RH	? de	\$ 27.50	/	/
116	1	FRONT DOOR RUBBER FRT RH	? de	\$ 30.00	/	/
117	1	FRONT DOOR POWER WINDOW MOTOR RH	? n	\$ 382.90	6	/
118	1	FRONT DOOR POWER WINDOW MECHANISM RH	? Bt	\$ 262.30	/	/
119	1	FRONT DOOR TRIM RH	? de	\$ 650.00	588.50	/
120	1SET	FRONT DOOR TRIM CLIPS	? n	\$ 40.00	/	/

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC7064L**
 Vehicle Reg. Date: **24-05-16**
 Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD SDR**
 Engine No. : **L15B4036167**
 Chassis No. : **RU11116163**

PAGE 4

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
121	1	FRONT DOOR SPEAKER RH	? de	\$ 95.50		/
122	1	FRONT DOOR OUTER HANDLE CHROME RH	ant	\$ 385.00	230	/
123	1	FRONT DOOR INNER HANDLE RH	x hn	\$ 65.00		x
124	1	FRONT DOOR WINDOW SWITCH RH	x an	\$ 244.40		x
125	1	FRONT DOOR GLASS RH	x an	\$ 578.30		x
126	1	FRONT OUTER MOULDING RH	? de	\$ 62.00		/
127	1	FRONT DOOR RUN CHANNEL RH	? X hn	\$ 88.00		x
128	1	CENTER PILLAR INNER RH	Ry	\$ 251.20		x
129	1	CENTER PILLAR OUTER RH	X an	\$ 933.50		x
130	1	CENTER PILLAR INNER TRIM RH	X an	\$ 72.50		x
131	2	REAR DOOR	bt	\$ 1,861.20		/
132	2	REAR DOOR STICKER	rec	\$ 40.00		/
133	1	REAR DOOR HINGE TOP	Ry	\$ 48.00		x
134	1	REAR DOOR HINGE BOTTOM	Ry	\$ 48.00		x
135	1	REAR DOOR CHECKER	Ry	\$ 55.00		x
136	1	REAR DOOR WEATHERSTRIP	de	\$ 95.20		/
137	1	REAR DOOR STRIKER	X hn	\$ 25.10		x
138	1	REAR DOOR RUBBER TOP	? de	\$ 110.00		/
139	1	REAR DOOR RUBBER LOWER	? de	\$ 14.90		/
140	1	REAR DOOR RUBBER FRT	? de	\$ 29.20		/
141	1	REAR DOOR POWER WINDOW MOTOR	X hn	\$ 390.00		x
142	1	REAR DOOR POWER WINDOW MECHANISM	? bt	\$ 210.00		/
143	1	REAR DOOR TRIM	? de	\$ 635.00		/
144	1set	REAR DOOR TRIM CLIPS	? de	\$ 40.00		/
145	1	REAR DOOR SPEAKER	? de	\$ 95.50		/
146	1	REAR DOOR OUTER HANDLE	x	\$ 98.00		x
147	1	REAR DOOR INNER HANDLE	x	\$ 65.00		x
148	1	REAR DOOR WINDOW SWITCH	x	\$ 48.00		x
149	1	REAR DOOR GLASS	x an	\$ 428.00		x
150	1	REAR OUTER MOULDING	x	\$ 65.00		x
151	1	REAR DOOR RUN CHANNEL	x	\$ 88.00		x
152	2	REAR FENDER	bt	\$ 1,809.40		/
153	2	REAR FENDER AIR DUCT	? de	\$ 150.00		/
154	1	REAR FENDER QTR GARNISH RH	X hn	\$ 38.00		x
155	2	REAR FENDER ARC GARNISH	mis	\$ 306.00		/
156	2	REAR FENDER INNER TRIM UPPER	x an	\$ 73.00		x
157	2	REAR FENDER INNER TRIM LOWER	x an	\$ 590.00		x
158	2	REAR WHEEL HOUSE	x an	\$ 1,457.20		x
159	2	REAR FENDER UNDERSHIELD	de	\$ 180.80		/
160	2SET	REAR FENDER UNDERSHIELD CLIPS	rec	\$ 80.00		/

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC7064L**
 Vehicle Reg. Date: **24-05-16**
 Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **L15B4036167**
 Chassis No. : **RU11116163**

PAGE 4

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
161	1	FUEL LID COVER	X nn	\$ 65.00		X
162	1	CENTER PILLAR SEALANT	X nn		\$ 100.00	X
163	2	REAR FENDER SEALANT	nn		\$ 160.00	/
164	1	SUNDRIES	/		\$ 60.00	/
165	1	REVERSE SENSOR	X nn		\$ 300.00	X
166	1	TAILGATE	X nn	\$ 1,100.90		X
167	1	TAILGATE LOGO	X nn	\$ 52.00		X
168	1	TAILGATE EMBLEM "VEZEL"	X nn	\$ 56.20		X
169	1	TAILGATE WEATHERSTRIP	X nn	\$ 96.80		X
170	1	REAR BUMPER	nn	\$ 508.50		/
171	1SET	REAR BUMPER CLIPS	nn	\$ 50.00		/
172	2	REAR BUMPER RETAINER	nn	\$ 144.00		/
173	2	REAR BUMPER SIDE COVER	nn	\$ 390.00		/
174	2	REAR BUMPER REFLECTOR	X	\$ 296.60		/
175	1	REAR END PANEL INNER	X	\$ 415.60		/
176	1	REAR END PANEL OUTER	X	\$ 415.60		/
177	1	REAR END PANEL TOP GARNISH	X	\$ 185.00		X nn
178	1SET	REAR END PANEL TOP GARNISH CLIPS	X	\$ 25.00		/
179	1	EXHAUST MUFFLER	X	\$ 528.00		/
180	2	EXHAUST MUFFLER RUBBER MOUNTING	X	\$ 36.00		/
181	1	EXHAUST MUFFLER HEAT SHIELD	X	\$ 165.00		/
182	1-2	TAIL LAMP	LH-X nn, RH-nt	\$ 857.40		428.70
183	1-2	TAIL LAMP CLIPS	LH+Y nn, RH-nt	\$ 36.00		18.00
184	2	TAILLAMP PANEL	Ry	\$ 270.00		X
185	2	REAR CHASSIC MEMBER	Ry	\$ 1,440.00		X
186	1-2	REAR SHOCK ABSORBER	nn-bt	\$ 660.00	330	/
187	2	REAR SHOCK STOPPER	X nn	\$ 52.00		X
188	2	REAR SHOCK DUST COVER	X nn	\$ 58.00		X
189	1-2	REAR WHEEL HUB BEARING ASSY	nn	\$ 527.00	263.50	/
190	1	REAR AXLE BEAM	X nn	\$ 1,513.20	1350	/
191	2	REAR ABS SENSOR	X nn	\$ 256.00		X
192	2	REAR RIM	nn	\$ 1,900.00	600	/
193	2	REAR TYRE	LH-nt, RH-patched	\$ 600.00		240
194	1	REAR END PANEL SEALANT	X nn	\$ 80.00		X
195	1	BRAKE FUILD	X nn	\$ 120.00		X
196	1	ROCKER PANEL SELANT	X nn	\$ 80.00		X
197	0	0				
198	0	0				
199	0	0				
200	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC7064L**
Vehicle Reg. Date: **24-05-16**
Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2'**
Engine No. : **L15B4036167**
Chassis No. : **RU11116163**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To knock jack out damaged parts, panel beating welding, align, refix & to replace accident parts. Front Portion.	\$ 4,000.00	1800 2200
2	To putty, respray painting and polish affected areas. Front Portion.	\$ 3,000.00	1400
3	To remove & refit engine to assist work load.	\$ 400.00	200? photo / 200
4	To conduct front chassis member alignment.	\$ 400.00	250
5	To remove & refix electrical wiring	\$ 250.00	100
6	To remove & rebleed radiator	\$ 180.00	X NH
7	To spray rust proof paint	\$ 600.00	200
8	To remove & refix front windscreen glass	\$ 180.00	120? X NH
9	To remove & refix support panel	\$ 180.00	100
10	To check wiring, focus headlamp	\$ 120.00	30
11	To reset engine management	\$ 480.00	150
12	To remove & refix air con condenser	\$ 180.00	100
13	To conduct water leakage tests to ensure proper air and sealing	\$ 180.00	X NH
14	To remove and replace front undercarriage	\$ 350.00	200?
15	To perform electronic wheel alignment.	\$ 150.00	80

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 2

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jul 2018		23 Jul 2018 17:26 Edit Adj Rpt	\$26,000.00 Edit Estimates	\$26,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	YA HUAN TRANSPORT PTE LTD, Co. Reg. No.: 201610485W								
Main Claimant:	KWAN KOK SIONG, ID: 51388797G								
Vehicle Reg. No.:	SLC7064L	Date of Loss:	19/07/2018 19:00 - :59 [25 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03595C02	Policy/Cover Note No.:	DMCVSN1637531802 (Comprehensive)						
Vehicle Reg. No. (Insured):	WC6387G	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel: 66944919								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 01/08/2018]								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC7064L (SNM18D03595C02)
[WC6387G]
TP
KWAN KOK SIONG
Jul 19 2018 7:00PM
[YA HUAN TRANSPORT PTE LTD]
Vermogen Ace Pte Ltd (benol)

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)						Thumbnail	Print		
1	20/07/18 11:08	Accident Statement						1 Load HTM			
Photos/Images									3 per page		☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)						Thumbnail	Print		
1	20/07/18 11:05	Scene Photo [Linked Accident Report Documents]						1 Load JPG	☒		
2	20/07/18 11:05	Scene Photo [Linked Accident Report Documents]						1 Load JPG	☒		
3	20/07/18 11:05	Scene Photo [Linked Accident Report Documents]						1 Load JPG	☒		
4	20/07/18 11:05	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
5	20/07/18 11:05	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
6	20/07/18 11:06	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
7	20/07/18 11:06	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
8	20/07/18 11:06	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
9	20/07/18 11:06	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
10	20/07/18 11:06	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
11	20/07/18 11:06	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
12	20/07/18 11:06	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
13	20/07/18 11:06	Accident Photo [Linked Accident Report Documents]						1 Load JPG	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	16/07/19 09:27	General View						1 Load PDF			
2	16/07/19 09:27	Photographs of Damaged Parts						1 Load PDF			
3	16/07/19 09:27	Photo After Spray						1 Load PDF			
Documentation									1 per page		☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	23/07/18 17:26	PRS						1 Load PDF			
2	23/07/18 17:26	OI GIA						1 Load PDF			
No	Finalized On	Jin Auto Services Pte Ltd (Defu)						Thumbnail	Print		
1	20/07/18 11:02	Accident Sketch Plan [Linked Accident Report Documents]						1 Load JPG	☒		
2	20/07/18 11:02	Accident Sketch Plan [Linked Accident Report Documents]						1 Load JPG	☒		
3	20/07/18 11:02	Authorization Letter [Linked Accident Report Documents]						1 Load JPG	☒		
4	20/07/18 11:02	Identification Card [Linked Accident Report Documents]						1 Load JPG	☒		
5	20/07/18 11:02	Driving Licence [Linked Accident Report Documents]						1 Load JPG	☒		

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	1 per page	☒
1	20/07/18 11:08	Accident Statement		Load HTML
Photos/Images			3 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	20/07/18 11:05	Scene Photo	Load JPG	☒
2	20/07/18 11:05	Scene Photo	Load JPG	☒
3	20/07/18 11:05	Scene Photo	Load JPG	☒
4	20/07/18 11:05	Accident Photo	Load JPG	☒
5	20/07/18 11:05	Accident Photo	Load JPG	☒
6	20/07/18 11:06	Accident Photo	Load JPG	☒
7	20/07/18 11:06	Accident Photo	Load JPG	☒
8	20/07/18 11:06	Accident Photo	Load JPG	☒
9	20/07/18 11:06	Accident Photo	Load JPG	☒
10	20/07/18 11:06	Accident Photo	Load JPG	☒
11	20/07/18 11:06	Accident Photo	Load JPG	☒
12	20/07/18 11:06	Accident Photo	Load JPG	☒
13	20/07/18 11:06	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	20/07/18 11:02	Accident Sketch Plan	Load JPG	☒
2	20/07/18 11:02	Accident Sketch Plan	Load JPG	☒
3	20/07/18 11:02	Authorization Letter	Load JPG	☒
4	20/07/18 11:02	Identification Card	Load JPG	☒
5	20/07/18 11:02	Driving Licence	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118013406/T1CD3E2

Date: 16/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1637531802

Claimant Vehicle No: SLC7064L Insured Vehicle No: WC6387G

Date of Loss: 19/07/2018 Nature of Claim: TP Claim No: SNM18D03595C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC7064L

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4036167

Reg. Date: 24/05/2016 (Man. Year: 2016) Chassis No: RU11116163

Colour: White Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,043.84	27,425.20	27,618.64	50.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,280.00	8,170.00	11,110.00	57.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	74,323.84	35,595.20	38,728.64	52.11
Approved Total (Overridden) (S\$)		26,000.00		
(S\$)	74,323.84	26,000.00	48,323.84	65.02
+ GST 7.00/7.00% (S\$)	5,202.67	1,820.00	3,382.67	65.02
Nett Amount (S\$)	79,526.51	27,820.00	51,706.51	65.02

INSPECTION

Date of Assignment: 23/07/2018

Date Inspected: 24/07/2018 Inspected At: Vermogen Ace Pte Ltd (benoi) (HQ)
6 Benoi Sector
Singapore 629904

Estimated Period of Repair: 28.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC7064L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	240.00 FL	*- FL
2	1		*FRONT WIPER PANEL	Repair	250.20 FL	*- FL
3	1		*FRONT WIPER PANEL GARNISH	Deformed	240.00 FL	*240.00 FL
4	1		*BONNET	Bent	892.30 FL	*892.30 FL
5	2		*BONNET HINGES LH / RH	Bent	97.00 FL	*97.00 FL
6	1		*BONNET INSULATOR	Deformed	122.30 FL	*122.30 FL
7	1		*SET BONNET INSULATOR CLIPS	Necessary	35.00 FL	*35.00 FL
8	1		*SET BONNET LOCK	Bent	87.70 FL	*87.70 FL
9	1		*BONNET LOCK CABLE	Not Necessary	42.50 FL	*- FL
10	1		*BONNET RUBBER FRONT	Deformed	35.20 FL	*35.20 FL
11	2		*BONNET SIDE RUBBER LH / RH	Not Necessary	66.80 FL	*- FL
12	1		*FRONT BUMPER	Distorted	927.50 FL	*792.00 FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
14	2		*FRONT BUMPER RETAINER LH / RH	Necessary	144.00 FL	*144.00 FL
15	1		*FRONT BUMPER LOWER SKIRT	Deformed	96.80 FL	*96.80 FL
16	1		*SET FRONT BUMPER LOWER SKIRT CLIPS	Necessary	35.00 FL	*35.00 FL
17	1		*FRONT BUMPER LIP RUBBER	Not Necessary	87.10 FL	*- FL
18	2		*FRONT UNDERSHIELD LH / RH	Deformed	130.00 FL	*130.00 FL
19	1		*FRONT ENGINE LOWER COVER	Deformed	96.80 FL	*96.80 FL
20	1		*FRONT GRILLE BASE	Deformed	1,150.00 FL	*398.30 FL
21	2		*FRONT GRILLE GARNISH	Cracked	510.00 FL	*275.20 FL
22	2		*FRONT GRILLE CHROME LH / RH	Cut	242.00 FL	*150.60 FL
23	2		*FRONT GRILLE LOGO	Necessary	52.00 FL	*52.00 FL
24	2		*FRONT GRILLE SIDE BRACKET LH / RH	Distorted	134.10 FL	*134.10 FL
25	1		*FRONT GRILLE CENTER BRACKET	Deformed	139.50 FL	*139.50 FL
26	1		*FRONT BUMPER REINFORCEMENT	Bent	321.00 FL	*321.00 FL
27	2		*FRONT REINFORCEMENT GARNISH LH / RH	Not Necessary	48.40 FL	*- FL
28	2		*FRONT CHASSIS MEMBER LH / RH	Repair	1,510.00 FL	*- FL
29	1		*FRONT SUPPORT PANEL	Bent	576.20 FL	*576.20 FL
30	1		*FRONT SUPPORT TOP GARNISH	Deformed	85.00 FL	*85.00 FL
31	1		*FRONT SUPPORT TOP GARNISH CLIPS	Necessary	35.00 FL	*35.00 FL
32	1		*CONDENSER	Bent	568.10 FL	*568.10 FL
33	1		*CONDENSER FAN MOTOR	Not Necessary	308.00 FL	*- FL
34	1		*CONDENSER FAN MOTOR BLADE	Not Necessary	58.00 FL	*- FL
35	1		*CONDENSER FAN MOTOR COWLING	Not Necessary	98.00 FL	*- FL
36	1		*RADIATOR	Bent	1,250.60 FL	*960.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*RADIATOR FAN MOTOR	Not Necessary	298.00 FL	*- FL
38	1		*RADIATOR FAN MOTOR BLADE	Not Necessary	57.70 FL	*- FL
39	1		*RADIATOR FAN MOTOR COWLING	Not Necessary	125.00 FL	*- FL
40	2		*RADIATOR AIR GUIDE LH / RH	Deformed	114.00 FL	*114.00 FL
41	1		*AIRCON DISCHARGE PIPE	Not Necessary	210.00 FL	*- FL
42	1		*AIRCON LIQUID PIPE	Not Necessary	195.00 FL	*- FL
43	1		*AIRCON SUCTION PIPE	Not Necessary	121.50 FL	*- FL
44	1		*RADIATOR TOP HOSE	Not Necessary	40.00 FL	*- FL
45	1		*RADIATOR BOTTOM HOSE	Not Necessary	42.00 FL	*- FL
46	2		*HORN HIGH / LOW	Cracked	148.20 FL	*148.20 FL
47	1		*WASHER TANK	Deformed	75.00 FL	*75.00 FL
48	1		*WASHER TANK NECK	Not Necessary	28.00 FL	*- FL
49	1		*WASHER TANK MOTOR	Missing	59.60 FL	*59.60 FL
50	1		*AIR RESONATOR	Not Necessary	180.00 FL	*- FL
51	1		*SPARETANK RESERVIOR	Not Necessary	186.20 FL	*- FL
52	1		*SPARETANK RESERVOIR BY PASS HOSE	Not Necessary	36.00 FL	*- FL
53	2		*HEAD LAMP LH / RH	Cracked	3,569.00 FL	*2,900.00 FL
54	2		*HEAD LAMP BRACKET LH / RH	Necessary	114.00 FL	*114.00 FL
55	2		*FOG LAMP LH / RH	Cracked	756.40 FL	*320.00 FL
56	2		*FOG LAMP GARNISH LH / RH	Deformed	170.00 FL	*170.00 FL
57	2		*FRONT FENDER LH / RH	Bent	1,117.40 FL	*1,117.40 FL
58	2		*FRONT FENDER ARC GARNISH LH / RH	Deformed	306.00 FL	*306.00 FL
59	1		*FRONT WHEEL HOUSE EXTENSION LH / RH	N/S Repair / O/S Buckled	330.00 FL	*165.00 FL
60	1		*FRONT WHEEL HOUSE UPPER MEMBER LH / RH	N/S Repair / O/S Bent	230.00 FL	*115.00 FL
61	1		*FRONT WHEEL HOUSE SIDE GUSSET LH / RH	N/S Repair / O/S Deformed	110.00 FL	*55.00 FL
62	1		*FRONT WHEEL HOUSE SIDE GUSSET PLATE LH / RH	N/S Repair / O/S Deformed	126.00 FL	*63.00 FL
63	2		*FRONT FENDER APRON LH / RH	Not Necessary	230.00 FL	*- FL
64	2		*FRONT FENDER UNDERSHIELD LH / RH	Deformed	260.00 FL	*260.00 FL
65	2		*SET FRONT FENDER UNDERSHIELD CLIPS	Necessary	80.00 FL	*80.00 FL
66	2		*ENGINE MOUNTING LH / RH	Bent	309.20 FL	*309.20 FL
67	2		*ENGINE MOUNTING BRACKET LH / RH	Bent	196.00 FL	*196.00 FL
68	1		*ENGINE MOUNTING REAR	Not Necessary	135.00 FL	*- FL
69	1		*FRONT SHOCK ABSORBER LH / RH	N/S Not Necessary / O/S Bent	675.00 FL	*337.50 FL
70	1		*FRONT SHOCK MOUNTING LH / RH	N/S Not Necessary / O/S Bent	73.60 FL	*36.80 FL
71	1		*FRONT SHOCK MOUNTING BEARING LH / RH	N/S Not Necessary / O/S Bent	73.40 FL	*36.70 FL
72	1		*FRONT SHOCK STOPPER LH / RH	N/S Not Necessary / O/S Bent	53.90 FL	*26.95 FL
73	1		*FRONT SHOCK DUST COVER LH / RH	N/S Not Necessary/O/S Deformed	64.00 FL	*32.00 FL
74	1		*FRONT STABILIZER BUSH LH / RH	N/S Not Necessary / O/S Bent	120.00 FL	*60.00 FL
75	1		*FRONT STABILIZER LINK LH / RH	N/S Not Necessary / O/S Bent	25.00 FL	*12.50 FL
76	1		*FRONT STABILIZER BAR	Bent	175.00 FL	*175.00 FL
77	1		*FRONT LOWER ARM LH / RH	N/S Not Necessary / O/S Bent	748.20 FL	*374.10 FL
78	1		*FRONT LOWER ARM BALL JOINT LH / RH	N/S Not Necessary / O/S Bent	197.40 FL	*98.70 FL
79	1		*TIE ROD END LH / RH	N/S Not Necessary / O/S Bent	220.00 FL	*110.00 FL
80	1		*RACK END LH / RH	N/S Not Necessary / O/S Bent	170.00 FL	*85.00 FL
81	1		*STEERING RACK & PINION ASSY	Bent	1,750.00 FL	*1,178.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
82	1		*FRONT WHEEL HUB LH / RH	O/S Bent	490.00 FL	*245.00 FL
83	1		*FRONT KNUCKLE ARM LH / RH	O/S Bent	780.00 FL	*390.00 FL
84	1		*FRONT WHEEL BEARING LH / RH	O/S Necessary	362.80 FL	*181.40 FL
85	2		*FRONT ABS SENSOR LH / RH	Not Necessary	360.00 FL	*- FL
86	2		*FRONT DRIVE SHAFT LH / RH	Not Necessary	2,200.00 FL	*- FL
87	1		*FRONT ENGINE CROSSMEMBER	Bent	795.00 FL	*795.00 FL
88	4		*FRONT RIM LH / RH	Cut	1,900.00 FL	*600.00 FL
89	1		*FUSE BOX ASSY LH	Cracked	980.00 FL	*490.00 FL
90	1		*SIDE MIRROR ASSY RH	Cracked	794.50 FL	*650.50 FL
91	1		*SIDE MIRROR GLASS RH	Cracked	78.00 FL	*78.00 FL
92	1		*SIDE MIRROR COVER RH	Cracked	85.00 FL	*85.00 FL
93	2		*SIDE SKIRT	Cut	755.00 FL	*755.00 FL
94	2		*SET SIDE SKIRT CLIPS	Necessary	70.00 FL	*70.00 FL
95	2		*ROCKER PANEL	Repair	1,321.20 FL	*- FL
96	1		*FRONT DOOR PILLAR RH	Repair	933.50 FL	*- FL
97	2		*FRONT DOOR PILLAR - INNER RH	Repair	222.00 FL	*- FL
98	2		*FRONT DOOR	Bent	1,900.00 FL	*1,185.60 FL
99	1		*FRONT DOOR STICKER RH	Necessary	20.00 FL	*20.00 FL
100	1		*FRONT DOOR HINGE TOP RH	Bent	48.00 FL	*48.00 FL
101	1		*FRONT DOOR HINGE BOTTOM RH	Bent	48.00 FL	*48.00 FL
102	1		*FRONT DOOR CHECKER RH	Bent	55.00 FL	*55.00 FL
103	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	155.00 FL	*155.00 FL
104	1		*FRONT DOOR STRIKER RH	Not Necessary	25.10 FL	*- FL
105	1		*FRONT DOOR RUBBER TOP RH	Deformed	110.00 FL	*110.00 FL
106	1		*FRONT DOOR RUBBER LOWER RH	Deformed	27.50 FL	*27.50 FL
107	1		*FRONT DOOR RUBBER FRT RH	Deformed	30.00 FL	*30.00 FL
108	1		*FRONT DOOR POWER WINDOW MOTOR RH	Jammed	382.90 FL	*382.90 FL
109	1		*FRONT DOOR POWER WINDOW MECHANISM RH	Bent	262.30 FL	*262.30 FL
110	1		*FRONT DOOR TRIM RH	Deformed	650.00 FL	*588.50 FL
111	1		*SET FRONT DOOR TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
112	1		*FRONT DOOR SPEAKER RH	Deformed	95.50 FL	*95.50 FL
113	1		*FRONT DOOR OUTER HANDLE CHROME RH	Cut	385.00 FL	*230.00 FL
114	1		*FRONT DOOR INNER HANDLE RH	Not Necessary	65.00 FL	*- FL
115	1		*FRONT DOOR WINDOW SWITCH RH	Not Necessary	244.40 FL	*- FL
116	1		*FRONT DOOR GLASS RH	Not Necessary	578.30 FL	*- FL
117	1		*FRONT OUTER MOULDING RH	Deformed	62.00 FL	*62.00 FL
118	1		*FRONT DOOR RUN CHANNEL RH	Not Necessary	88.00 FL	*- FL
119	1		*CENTER PILLAR INNER RH	Repair	251.20 FL	*- FL
120	1		*CENTER PILLAR OUTER RH	Not Necessary	933.50 FL	*- FL
121	1		*CENTER PILLAR INNER TRIM RH	Not Necessary	72.50 FL	*- FL
122	2		*REAR DOOR	Bent	1,861.20 FL	*1,861.20 FL
123	2		*REAR DOOR STICKER	Necessary	40.00 FL	*40.00 FL
124	1		*REAR DOOR HINGE TOP	Repair	48.00 FL	*- FL
125	1		*REAR DOOR HINGE BOTTOM	Repair	48.00 FL	*- FL
126	1		*REAR DOOR CHECKER	Repair	55.00 FL	*- FL
127	1		*REAR DOOR WEATHERSTRIP	Necessary	95.20 FL	*95.20 FL
128	1		*REAR DOOR STRIKER	Not Necessary	25.10 FL	*- FL
129	1		*REAR DOOR RUBBER TOP	Deformed	110.00 FL	*110.00 FL
130	1		*REAR DOOR RUBBER LOWER	Deformed	14.90 FL	*14.90 FL
131	1		*REAR DOOR RUBBER FRT	Deformed	29.20 FL	*29.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
132	1		*REAR DOOR POWER WINDOW MOTOR	Not Necessary	390.00 FL	*- FL
133	1		*REAR DOOR POWER WINDOW MECHANISM	Bent	210.00 FL	*210.00 FL
134	1		*REAR DOOR TRIM	Deformed	635.00 FL	*635.00 FL
135	1		*SET REAR DOOR TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
136	1		*REAR DOOR SPEAKER	Deformed	95.50 FL	*95.50 FL
137	1		*REAR DOOR OUTER HANDLE	Not Necessary	98.00 FL	*- FL
138	1		*REAR DOOR INNER HANDLE	Not Necessary	65.00 FL	*- FL
139	1		*REAR DOOR WINDOW SWITCH	Not Necessary	48.00 FL	*- FL
140	1		*REAR DOOR GLASS	Not Necessary	428.00 FL	*- FL
141	1		*REAR OUTER MOULDING	Not Necessary	65.00 FL	*- FL
142	1		*REAR DOOR RUN CHANNEL	Not Necessary	88.00 FL	*- FL
143	2		*REAR FENDER	Bent	1,809.40 FL	*1,809.40 FL
144	2		*REAR FENDER AIR DUCT	Deformed	150.00 FL	*150.00 FL
145	1		*REAR FENDER QTR GARNISH RH	Not Necessary	38.00 FL	*- FL
146	2		*REAR FENDER ARC GARNISH	Missing	306.00 FL	*306.00 FL
147	2		*REAR FENDER INNER TRIM UPPER	Not Necessary	73.00 FL	*- FL
148	2		*REAR FENDER INNER TRIM LOWER	Not Necessary	590.00 FL	*- FL
149	2		*REAR WHEEL HOUSE	Not Necessary	1,457.20 FL	*- FL
150	2		*REAR FENDER UNDERSHIELD	Deformed	180.80 FL	*180.80 FL
151	2		*SET REAR FENDER UNDERSHIELD CLIPS	Necessary	80.00 FL	*80.00 FL
152	1		*FUEL LID COVER	Not Necessary	65.00 FL	*- FL
153	1		*TAILGATE	Not Necessary	1,100.90 FL	*- FL
154	1		*TAILGATE LOGO	Not Necessary	52.00 FL	*- FL
155	1		*TAILGATE EMBLEM VEZEL	Not Necessary	56.20 FL	*- FL
156	1		*TAILGATE WEATHERSTRIP	Not Necessary	96.80 FL	*- FL
157	1		*REAR BUMER	Deformed	508.50 FL	*508.50 FL
158	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
159	2		*REAR BUMPER RETAINER	Necessary	144.00 FL	*144.00 FL
160	2		*REAR BUMPER SIDE COVER	Deformed	390.00 FL	*390.00 FL
161	2		*REAR BUMPER REFLECTOR	Not Necessary	296.60 FL	*- FL
162	1		*REAR END PANEL INNER	Not Necessary	415.60 FL	*- FL
163	1		*REAR END PANEL OUTER	Not Necessary	415.60 FL	*- FL
164	1		*REAR END PANEL TOP GARNISH	Not Necessary	185.00 FL	*- FL
165	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	25.00 FL	*- FL
166	1		*EXHAUST MUFFLER	Not Necessary	528.00 FL	*- FL
167	2		*EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	36.00 FL	*- FL
168	1		*EXHAUST MUFFLER HEAT SHIELD	Not Necessary	165.00 FL	*- FL
169	1		*TAIL LAMP	N/S Not Necessary / O/S Cut	857.40 FL	*428.70 FL
170	1		*TAIL LAMP CLIPS	N/S Not Necessary/O/SNecessary	36.00 FL	*18.00 FL
171	2		*TAILLAMP PANEL	Repair	270.00 FL	*- FL
172	2		*REAR CHASSIC MEMBER	Repair	1,440.00 FL	*- FL
173	1		*REAR SHOCK ABSORBER	O/S Bent	660.00 FL	*330.00 FL
174	2		*REAR SHOCK STOPPER	Not Necessary	52.00 FL	*- FL
175	2		*REAR SHOCK DUST COVER	Not Necessary	58.00 FL	*- FL
176	1		*REAR WHEEL HUB BEARING ASSY	O/S Necessary	527.00 FL	*263.50 FL
177	1		*REAR AXLE BEAM	Bent	1,513.20 FL	*1,350.00 FL
178	2		*REAR ABS SENSOR	Not Necessary	256.00 FL	*- FL
179	2		*REAR RIM	Cut	1,900.00 FL	*600.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
180	1		*FRONT TYRE LH / RH (\$300.00) (80%) (4pcs)	N/SNotNeccessary/O/SPunctured	600.00 FS	*240.00 FS
181	1		*FRONT WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
182	1		*FRONT WINDSCREEN GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
183	1		*FRONT WINDSCREEN GLASS PRIME & CLEANER	Not Necessary	80.00 FS	*- FS
184	1		*RADIATOR COOLANT	Necessary	100.00 FS	*100.00 FS
185	1		*AIRCON GAS	Necessary	100.00 FS	*100.00 FS
186	1		*FRONT NUMBER PLATE WITH FRAME	Missing	50.00 FS	*45.00 FS
187	1		*FRONT CHASSIS SEALANT	Not Necessary	160.00 FS	*- FS
188	1		*BATTERY	Not Necessary	300.00 FS	*- FS
189	1		*CENTER PILLAR SEALANT	Not Necessary	100.00 FS	*- FS
190	2		*REAR FENDER SEALANT	Necessary	160.00 FS	*160.00 FS
191	1		*SUNDRIES	Necessary	60.00 FS	*60.00 FS
192	1		*REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
193	1		*REAR TYRE (\$300.00) (80%)	N/SNotNeccessary/O/SPunctured	600.00 FS	*240.00 FS
194	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
195	1		*BRAKE FLUID	Not Necessary	120.00 FS	*- FS
196	1		*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$) **68,042.30** **34,045.25**
 - List Item Discount on L Items 20.00/20.00% (\$\$) 12,998.46 6,620.05

Total Parts (\$\$) **55,043.84** **27,425.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,JACK OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX & TO REPLACE ACCIDENT PARTS,FRONT PORTION	New	4,000.00	2,200.00
2	TO PUTTY,RESPRAY PAINTING AND POLISH AFFECTED AREAS.FRONT PORTION	New	3,000.00	1,400.00
3	TO REMOVE & REFIT ENGINE TO ASSIST WORK LOAD	New	400.00	200.00
4	TO CONDUCT FRONT CHASSIS MEMBER ALIGNMENT	New	400.00	250.00
5	TO REMOVE & REFIX ELECTRICAL WIRING	New	250.00	100.00
6	TO REMOVE & REBLEED RADIATOR	New	180.00	0.00
7	TO SPRAY RUST PROOF PAINT	New	600.00	200.00
8	TO REMOVE & REFIX FRONT WINDSCREEN GLASS	New	180.00	0.00
9	TO REMOVE & REFIX SUPPORT PANEL	New	180.00	100.00
10	TO CHECK WIRING,FOCUS HEADLAMP	New	120.00	30.00
11	TO RESET ENGINE MANAGEMENT	New	480.00	150.00
12	TO REMOVE & REFIX AIR CON CONDENSER	New	180.00	100.00
13	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	180.00	0.00
14	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE	New	350.00	200.00
15	TO PERFORM ELECTRONIC WHEEL ALIGNMENT	New	150.00	80.00
16	TO KNOCK,JACK OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX & TO REPLACE ACCIDENT PARTS.REAR PORTION	New	3,500.00	1,400.00
17	TO PUTTY,RESPRAY PAINTING AND POLISH AFFECTED AREAS.REAR PORTION	New	2,500.00	1,000.00
18	TO CONDUCT REAR CHASSIS MEMBER ALIGNMENT	New	400.00	250.00
19	TO REMOVE AND REPLACE REAR UNDERCARRIAGE	New	350.00	200.00
20	TO REMOVE AND REPLACE TYRE,TYRE BALANCING	New	150.00	30.00
21	TO REMOVE & REFIT PETROL TANK TO ASSIST WORK LOAD	New	300.00	0.00
22	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD	New	180.00	0.00
23	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD	New	250.00	100.00
24	TO REMOVE & INSTA FRONT BOTH DOOR TRIM,DOOR GLASS,WINDOW REGULATOR,DOORLOCK TO ASSIST WORK LOAD	New	500.00	60.00
25	TO REMOVE & INSTA REAR BOTH DOOR TRIM,DOOR GLASS,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD	New	500.00	120.00
Gross Labour Cost (\$\$)			19,280.00	8,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >