

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: SGY5033H180712

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Address Motor Claims Department

8 Shenton Way #27-01

AXA Tower Singapore 068811

Date: 23-07-18

Vehicle No: SGY5033H

Model/Make: Honda Vezel
1.5X ARepair Sum \$5100
6 day.

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bootlid <i>Bedgood 953</i>	\$ 1,100.90	
2	Bootlid "Vezel" Emblem <i>nu</i>	\$ 56.20	
3	Bootlid Inner Lock <i>twi</i>	\$ 198.50	
4	Bootlid Lock Striker <i>11</i>	\$ 25.50	X
5	Bootlid Inner Trim Board <i>11</i>	\$ 321.70	X
6	Bootlid Inner Trim Board Clips 1 set <i>11</i>	\$ 50.00	X
7	Bootlid Weatherstrip <i>twi</i>	\$ 135.00	
8	Bootlid Keyless Sensor <i>one</i>	\$ 180.00	
9	Bumper Centre <i>no 1/2</i>	\$ 762.70	
10	Bumper Sides 02 pcs (@ \$235.10) <i>11</i>	\$ 470.20	X
11	Bumper Sides Retainers 02 pcs (@ \$35.20) <i>11</i>	\$ 70.40	X
12	Bumper Screw Spacers 02 pcs (@ \$12.00) <i>11</i>	\$ 24.00	X
13	Bumper Reflectors 02 pcs (@ \$151.20) <i>11</i>	\$ 302.00	X
14	Bumper Reverse Sensor 1 set <i>shorted</i>	\$ 280.00	SN 2005.~
15	End Panel <i>3.5500</i>	\$ 514.00	
16	End Panel Top Garnish <i>twi</i>	\$ 125.00	
17	End Panel Sealant <i>nu</i>	\$ 50.00	SN
18	Bumper Lower Diffuser <i>del to in</i>	\$ 348.20	
19	Bumper Lower Diffuser Clips 1 set <i>nu</i>	\$ 50.00	
20	Fender Inner Trims 02 pcs (@ \$295.30) <i>11</i>	\$ 590.60	X
21	Fender Inner Trims Clips 1 set <i>11</i>	\$ 50.00	X
22	Fender Outer Garnish 02 pcs (@ \$195.80) <i>11</i>	\$ 391.60	X
23	Floor Panel <i>2</i>	\$ 912.30	X
24	Floor Panel Tools Sponge <i>to in 585</i>	\$ 685.00	
25	Floor Panel Insulator <i>11</i>	\$ 180.00	SN X
26	Windscreen Glass Moulding <i>nu</i>	\$ 121.30	
27	Windscreen Glass Sealant <i>nu</i>	\$ 50.00	SN 405.~
	To check all wiring & electrical component for proper function	\$ 80.00	30
	Remove and refix rear Bumper distance sensor	\$ 80.00	50
	Remove and refix rear Bootlid components & mechanism	\$ 100.00	60
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 150.00	120
	Remove & refix seat & cushion upholstery to facilitate repair	\$ 100.00	80
	To apply Rust Proofing , reseal tuff-coating treatment on accident a	\$ 150.00	60
	To mount vehicle on car o-Liner <i>11</i>	\$ 380.00	20
	Remove and refix rear tailgate reverse camera & mechanism <i>11</i>	\$ 80.00	X
	Remove and refix Petrol Tank <i>11</i>	\$ 100.00	X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts E	\$ 2,000.00	800
	To putty & spray painting & including touch up paint on accident affected	\$ 2,000.00	800

Total Parts & Labour of estimate for damaged vehicle

\$ 13,265.10

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



M/s Liu's Brother Auto Engrg Wks

P. 422470

20%

3379-76

S.N - 2905.~

1chm - 2020

5688-76