Catherine Chong (LKK Auto)

From:

Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Sent:

Friday, 20 July, 2018 5:13 PM

To:

assignments

Subject:

FW: RE: NEW ASSIGNMENT - VEHICLE YK 3690J - OUR REF: 17.23342

Attachments:

TP GIA.pdf; GIA INSURED.pdf; PF survey report.pdf; YK3690J Report.pdf; 3199_

001.pdf; 1502_001.pdf; RT.pdf

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chee Kiong [mailto:cheekiong@seahong.com.sg]

Sent: Wednesday, 27 June 2018 5:08 PM

To: SUR <sur@lkkauto.com>

Cc: 'Xin Yi' <xinyi@seahong.com.sg>; samson@seahong.com.sg; june tan <june@seahong.com.sg>

Subject: RE: NEW ASSIGNMENT - VEHICLE YK 3690J - OUR REF: 17.23342

Dear Adrian Ling

MC / MC SUIT NO. 17119 of 2017

CLAIM BY MANMADHAN S/O PILLAI T/A SIMITRANS & TRADING (OWNER & DRIVER OF YK

ACCIDENT ALONG PIE TOWARDS CHANGI AFTER STEVEN ROAD EXIT INVOLVING YM 8358B AND YK 3690J ON 13.02.17

- We act for AXA Insurance Singapore Pte Ltd, the insurer of motor vehicle no. YM 8358B at the material 1. time of the abovesaid accident.
- We enclose herewith copies of the following:-2.
 - Singapore Accident statement by the driver of YM 8358B and YK 3690J; a.
 - b. Survey report dated 17 October 2017 issued by RT Appraisal Pte Ltd;
 - Survey report dated 5 February 2018 issued by RT Appraisal Pte Ltd; C.
 - d. Quote from AJK Engineering obtained by Virtual;
 - Survey report by Car Link Consultancy (Plaintiff's surveyor). e.
- Our client appointed RT Appraisal to conduct inspections and prepare their survey report. They reports 5. are enclosed. However, our client's insured's agent, Virtual, obtained a quote from a contractor on the wooden body at only \$3,000 (whereas RT recommended \$8,000 in their report). Virtual also informed that RT Appraisal's recommended amount for the other items are still too high.

- Our client would like to engage you to give your opinion and report on the damage and the repair cost accordingly.
- 7. May we hear from you urgently?

1.1

Thanks v much!

Yours faithfully TAN CHEE KIONG SEAH ONG & PARTNERS LLP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	some to the distinct of the report of the centre and to copies of the report son girade available
AND THE PERSON OF THE PERSON O	ACCIDENT STATEMENT
Date Of Report	14/02/2017 10:14
Date Of Accident	13/02/2017 14:45
Exact Location Of Accident	PIE AFTER STEVEN RD EXIT TWDS CHANGI
Country/State of Loss	Singapore
深格的 的现在分词 1000 1000 1000 1000 1000 1000 1000 10	DETAILS OF OWN VEHICLE
Vehicle Registration Number	YK3690J
'nsured/Policyholder	The second secon
Name Of Registered Owner	SIMITRANS & TRADING
Co Reg No	53011909M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-67649810
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FUSO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Commercial Vehicle
Insurance Company	
Name of Insurance Company	EQ Insurance Company Ltd
Type Of Coverage	Third Party
Fleet Policy	No
Policy Number	DMCPHQ16-001788
Cover Note Number	
Driver	
Name of Driver	MANMADHAN S/O PILLAI
NRIC No	S1108829E
Date Of Birth	11/02/1955
Occupation	Outdoor
Date Of Driving Pass	08/02/2003
Driving Experience	14 Years And 0 Months
Gender	Male
Mobile Number	+65-94878069
Fax Number	
Contact Number	

NOEMAIL

Address

BLK 665 CHOA CHU KANG CRESCENT

#06-277

stcode

680665

Was driver an employee of the Insured's Company Yes

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

Collision- Head to Rear (TP Hit Insured)

Weather Conditions

Road Surface

Dry

Other Information

Was any foreign vehicle involved in this accident?

No

Was any body injured in the Accident?

Yes

Was any other material or property damaged?

Yes

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

No 1

Details of Police Action

Was the accident reported to the police?

No

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

No

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?

Yes

Was there any video captured by Car Camera?

No

Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YM8358B

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

MANMADHAN S/O PILLAI

Approximate Age


Page 2 of 21

Injuries Sustain BODY
Injured person in which vehicle? YK3690J

were seat belts worn? Yes
 Was injured conveyed to hospital by ambulance? No
 No

Address Postcode

SKETCH PLAN



IMPORTANT NOTICE

44 44

- 1 Please report correctly the details of the accident to speed up the claims process
- 2. This Formittee to completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any will ulmsrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy katility on the cart of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee the made available upon application by interested parties.
- 7. By the loagement of this report to the insurers, you hereby consent to the sichwing of this report at the centre and to copies of the report being made available aforesed.
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand acknowledge, agree and consent that

(a) My insurer my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use disclose and or processing personal data personal information set out in this [form] and any other personal information provided by the or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers" into histories law yers/law firms the Monetary Authority of Singapore and any relevant government agency authority (such as the police), for the purpose(s) of

in processing, handling and or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

III) investigating the accident and/or my claims.

(iii) carrying out and or dealing with my instructions or responding to any enquiries by me

IN) administering my disins (including the making of correspondence, statements invoices reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopesimal packages), and/or

iv) complying with applicable law in administering processing handling and/or dealing with my claims.

collectively the Purposes I

(b) all insurer(s) with have insured vehicle(s) involved in this accident and the hisurers, law yes-flaw firms, may are permitted to collect, use disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their taw yers faw firms), which may be sked outside of Singapore, for one or more of the above Purposes.

Pulcyholder's Signature / Date &

Driver's Signature (# driver is not the policyholder): Date 8 Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Pla towards January Africa Staven aum Exit

WENDER A - JK 3690]

Image As per Original --CSU--

Describe Circumstances of the Accide	nt
--------------------------------------	----

Describe circumstances of the Acousem
I was provided many fill turners their present on a
I CHARL I WAY TRAFFIC I WAS ON THE RATHER LIFT LAND WHILE
= was teavilling straight altero supplied I. Felt A GRIAT
IMPSET FROM THE REAR OF MY VEHICLE. SO I TEXENTED FROM MY
venious an manuser a venicus (4m \$3581) Har courses to
THE REAR OF M'S WE MICHE.
AT THE TIME OF ACCURENT, END WESTHER WAS CHEER AND
THE FLOOR WOOD DAYS.
VEHICLE A- SKEDS
NETTICE 13 - MM 53 TYB.
\

Declaration

IMe declare the to egong particulars are true in every respect.

Poic holder's Signature / Date & Time

Driver's Signature (# driver is not the policyholder) / Date \$ Time

Vitnessed by Reporting Centre

. .

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number EMail Address

Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

By the lodgement of this report to the insurers, you hereby con aforesaid.	sent to the archiving of this report at the centre and to copies of the report being made available
Market Michigan Comment of the Comme	ACCIDENT STATEMENT
Date Of Report	14/02/2017 13:06
Date Of Accident	13/02/2017 15:40
Exact Location Of Accident	PIE TOWARDS CHANGI AFTER STEVEN RD EXIT
Country/State of Loss	SINGAPORE
建筑的 交流是是对自己的。	DETAILS OF OWN VEHICLE
Vehicle Registration Number	YM8358B
Insured/Policyholder	
Name Of Registered Owner	DCH FOTON AUTO PTE LTD
Co Reg No	200510021K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-87202673
Vehicle Particulars	
Manufacturer	ISUZU
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	NORMAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	VFX/P1847744
Cover Note Number	
Driver	
Name of Driver	TAN NYAP CHUN
Passport No/FIN	G7452528N
Date Of Birth	01/10/1984
Occupation	OUTDOOR
Date Of Driving Pass	02/10/2008
Driving Experience	8 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Free Nicordina	

NOEMAIL

Postcode Was driver an employee of the Insured's Company YES If No, Relationship of the Driver with the Insured Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident Type Of Accident COLLISION- HEAD TO REAR (INSURED HIT TP) Weather Conditions CLEAR Road Surface DRY Other Information Was any foreign vehicle involved in this accident? NO Was any body injured in the Accident? NO Was any other material or property damaged? YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. Number of Passengers (Including Driver) 2 Details of Police Action Was the accident reported to the police? NO If Yes, Please state which Police Station Was notice of intended Prosecution given? NO If Yes, against whom? Circumstances of Accident REFER TO SKETCH PLAN Attachment(s) Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YK3690J

Vehicle Make/Model/Colour

Details Of Properties

News

Name of Driver

NRIC/Passport Number

Contact Number

94878069

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

. .

-). Pease report correctly the details of the accident to speed up the clams process
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any will utilisepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy fisbility on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may fare permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to at insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yerslaw firms, the Monetary Authority of Singapore and any relevant government agencylauthority (such as the police), for the purposets) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims:
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling ancier dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GR to their third party service providers or agents (including their law yers/lew firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Sibuature / Date & Driver's Signature (If driver a not the policyholder) / Date

Time

Sketch Plan

P. F.E. towneds Changi After Steven Ro

Exft

A - YM 8358B

B - YK 3690J

W	ile dif	vhig alor	ig PI	E toward	S
Che	mgi a	Aten Cle	ven R	d Exit,	
Shd	denty	vehicle	В	jammed	brak
îv	front	ofme.	I	braced i	immodat.
ent	stíl	hit th	e rea	v porti	m of
Vel	ricle !)			

Declaration

I'We declare the foregoing particulars are true in every respect.

Policyhobter's Signature / Data & Tirre Driver's Signature (T driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



FIRE - AUTOMOBILE - LICENSED APPRAISERS

COMPANY REGISTRATION NO 199507108W

ADD BLK 305 #02-167 Ubi Avenue 1, Singapore 400305

6748 6076 FAX 6748 0361

EMAIL rta@rta.com.sg

VEHICLE DAMAGE INSPECTION REPORT

AXA/YK3690J/13022017

Date:

17/10/2017

REFERENCE

Handling Insurer: Claimant Vehicle AXA Insurance Pte Ltd

Policy No:

P1847744

No:

YK3690J

Insured Vehicle No: YM8358B

Date of Loss:

13/02/2017

Nature of Claim:

TP

Claim No:

C0421239

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

YK3690J

Make & Model:

MITSUBISHI FUSO, 3.0 D FE83BE6SRDEA (M) 13/04/2000 (Man. Year: 1999)

Engine No:

4D34H25219

Reg. Date:

Colour:

White

Chassis No: Odometer:

FE639EA40415 849243 km

Engine Capacity:

3907 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Engine Modification:

No

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

7.00-16LT

Rear Tyre Size:

7.00-16LT

Front Left Side: Front Right Side:

TEXXAN 4 mm

Yes

Rear Left Side: Rear Right Side:

TEXXAN 4 mm TEXXAN 4 mm

TEXXAN 4 mm The above values represent the remaining tyre treads depth

	Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	44,839.22	42,476.72 22.000.00	2,362.50	5.27
Towing	_	0.00	0.00	0.00	
Paintwork Labour	Market Control of the	0.00	0.00	0.00	at a
Labour		6,980.00	6,380.00	600.00	8.60
Miscellaneous Items		0.00	0.00	0.00	
Parts		37,859.22	36,096.72	1,762.50	4.66
COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %

Nett Amount (S\$) 44.839.22 22,000.00 22,839.22 50.94

INSPECTION

Date of Assignment:

15/02/2017

Date Inspected:

15/02/2017, 27/02/2017

Inspected At:

N-51 Automotive Pte Ltd (HQ)

BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT

AUTOHUB

Singapore 417921

Estimated Period of Repair:

11.0 days

Adjuster: Michael Cheong

Manager:

Elgene Teng

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

SPECIAL REMARKS

Should our adjustment of \$22,000 lump sum be rejected and not accepted, we suggest a physical re-inspection be carried out.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Oct 2017)

Parts: N/A MITSUBISHI FUSO 3.0 D FE83BE6SRDEA (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)
Print Code: RT Appraisal Pte Ltd/YK3690J/17/10/2017 14:19

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers

with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty N	Particulars	Condition	Repairer's	Amount
1	1	*AIR INTAKE DUCT ASSY		780.80 FL	*780.80 FI
2	1	*CABIN REAR LOCK ASSY		490.10 FL	*490.10 FL
3	1	*CABIN REAR LOCK HANDLE		260.00 FL	*260.00 FL
4	1	*CABIN REAR LOCK LINKAGE		360.10 FL	*360.10 FL
5	1	*FRONT LH DOOR ASSY	To Reject - Waived	2,350.00 FL	See Remarks
6	1	*FRONT LH DOOR LOWER PROTECTOR		391.00 FL	*391.00 FL
7	1	*FRONT LH DOOR WEATHERSTRIP		208.00 FL	*208.00 FL
8	1	*FRONT LH REAR FENDER ARCH GARNISH		910.20 FL	*910.20 FL
9	1	*FRONT LH WHEEL REAR MUDFLAP		140.00 FL	*140.00 FL
10	1	*FRONT LH WHEEL REAR MUDGUARD ASSY		645.10 FL	*645.10 FL
11	1	*REAR LEAF SPRING FRONT SHACKLE BRACKE	T LH	480.00 FL	*480.00 FL
12	1	*SHACKLE BRACKET PIN LH		125.00 FL	*125.00 FL
13	1	*CANVAS HOOK L/R		240.00 F	*240.00 F
14	1	*REAR WHEEL MUDGUARD ASSY LH		450.00 F	*450.00 F
15	1	*REAR WHEEL MUDGUARD BRACKET LH		80.00 F	*80.00 F
16	1	*REAR WOODEN BODY FRONT BOARD ASSY		1,500.00 F	*1,500.00 F
17	1	*REAR WOODEN FLOOR BOARD		2,000.00 F	*2,000.00 F
18	1	*REAR WOODEN STEP MEMBER		180.00 F	*180.00 F
19	1	*SIDE BOARD C/W ANGLE IRON LH		2,100.00 F	*2,100.00 F
20	1	*SIDE BOARD C/W ANGLE IRON RH		2,100.00 F	*2,100.00 F
21	1	*SIDE BOARD HINGE LATCH LOCK C/W CHAIN LI		136.00 F	*136.00 F
22	1	*SIDE BOARD HINGE LATCH LOCK C/W CHAIN R	H	136.00 F	*136.00 F
23	1	*SIDE BOARD HINGES LH		1,050.00 F	*1,050.00 F
	1	*SIDE BOARD HINGES RH		1,050.00 F	*1,050.00 F
25	1	*SIDE BOARD LOWER METAL PANEL LH		1,200.00 F	*1,200.00 F
	1	*SIDE BOARD LOWER METAL PANEL RH		1,200.00 F	*1,200.00 F
27	1	*SIDE BOARD WOODEN PARTITION BRACKET LI		200.00 F	*200.00 F
	1	*SIDE BOARD WOODEN PARTITION BRACKET RE		200.00 F	*200.00 F
	1	*SIDE BOARD WOODEN PARTITION MEMBER (HORIZONTAL) LH		840.00 F	*840.00 F
	1	*SIDE BOARD WOODEN PARTITION MEMBER (HORIZONTAL) RH		840.00 F	*840.00 F
	1	*SIDE BOARD WOODEN PARTITION MEMBER (VERTICAL) LH		720.00 F	*720.00 F
32		*SIDE BOARD WOODEN PARTITION MEMBER (VERTICAL) RH		720.00 F	*720.00 F
	1	*TAILBOARD HINGES		840.00 F	*840.00 F
	1	*TAILBOARD HINGES LATCH LOCK C/W CHAIN		136.00 F	*136.00 F
	1	*TAILBOARD LOWER METAL PANEL		600.00 F	*600.00 F
36		*TAILBOARD LOWER WOODEN MEMBER		280.00 F	*280.00 F
	1	*TAILBOARD WITH ANGLE IRON		1,500.00 F	*1,500.00 F
88		*TAILBOARD WOODEN PARTITION (HORIZONTAL		420.00 F	*420.00 F
	1	*TAILBOARD WOODEN PARTITION (VERTICAL)		360.00 F	*360.00 F
	1	*WOODEN BODY FRONT PARTITION MEMBER (HORIZONTAL LONG)		840.00 F	*840.00 F
11	1	*WOODEN BODY FRONT PARTITION MEMBER (HORIZONTAL SHORT)		180.00 F	*180.00 F

		Total Parts (S\$)	37,859.22	36,096.72
		- List Item Discount on L Items 25.00/25.00% (S\$)	1,785.08	1,197.58
		Sub Total (S\$)		37,294.30
F=Fra	anchise p	part. L=ListItemDisc.	1,440.001	1,440.00 F
57	1	*WOODEN BODY U CLAMP	1,440.00 F	*1,440.00 F
56	1	*TAILLAMP BRACKET RH	98.00 F	*98.00 F
55	1	*TAILLAMP BRACKET LH	98.00 F	*98.00 F
54	1	*TAILLAMP ASSY RH	230.00 F	*230.00 F
53	1	*TAILLAMP ASSY LH	230.00 F	*230.00 F
52	1	*SIDE GUARD RAIL BRACKET LH	240.00 F	*240.00 F
51	1	*SIDE GUARD RAIL ASSY LH	1,500.00 F	*1.500.00 F
50	1	*REAR NUMBER PLATE LAMP	68.00 F	*68.00 F
49	1	*REAR NUMBER PLATE BRACKET	125.00 F	*125.00 F
48	1	*REAR NUMBER PLATE	35.00 F	*35.00 F
47	1	*REAR BUMPER WITH BRACKET	1,800.00 F	*1,800.00 F
46	1	*FRONT LH DOOR COMPANY, TEL, FAX, H/P STICKER	210.00 F	*210.00 F
45	1	*60 KM/H STICKER	12.00 F	*12.00 F
44	1	*WOODEN BODY WOODEN CROSS MEMBER	1,800.00 F	*1,800.00 F
43	1	*WOODEN BODY MAIN WOODEN BEAM L/R	1,600.00 F	*1,600.00 F
42	1	*WOODEN BODY FRONT PARTITION MEMBER (VERTICAL)	920.00 F	*920.00 F

RT Appraisal Pte Ltd/YK3690J/17/10/2017 14:19. Not valid without Reference section.

Recommended Miscellaneous Items There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PROVIDE TOWING CHARGE	New	150.00	150.00
2	TO CHECK ALIGN CHASSIS MAIN FRAME CHASSIS CROSS MEMBER AND ETC TO SYMMETRICAL SPECIFICATION	New	600.00	150.00 600.00
3	TO CHECK WIRING AND LIGHT SYSTEM	New	80.00	80.00
4	TO TRANSFER LH FRONT DOOR MECHANISM	New	80.00	80.00
5	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New		
6	TO REMOVE, DISPOSE DAMAGED WOODEN BODY AND ETC TO REJECT - WAIVED	New	120.00 400.00	120.00
7	TO RECONSTRUCT NEW REAR WOODEN BODY, WOODEN PARTITION AND ETC	New	1,800.00	1,800.00
8	TO REMOVE, REPLACE DAMAGED FRONT DOOR LH, FRONT LH DOOR QUARTER PANEL, CABIN LOCK AND ETC.	New	1,500.00	1,500.00
9	TO SPRAY PAINT AFFECTED AREAS	New	1.050.00	
10	TO VARNISH WOODEN BODY		1,250.00	1,250.00
		New	1,000.00	800.00
	Gross Labour	Cost (S\$)	6,980.00	6,380.00

RT Appraisal Pte Ltd/YK3690J/17/10/2017 14:19. Not valid without Reference section.

< END OF ESTIMATES >

CARLINK CONSULTANCY

60 Hillside Drive Singapore 549009 Tel: 62856178

62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CLM13914TP/N

REFERENCE

Date of request

: 15th February 2017

Requested by : M/S Simitrans & Trading

C/o Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-18

Singapore 417921

Type of claim

Workshop

: M/S N-51 Automotive Pte Ltd

Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-18

Singapore 417921

Date of survey Accident date

: 15th February 2017 13th February 2017

2 DETAILS OF VEHICLE

Registration No.

: YK 3690 J

: Third party

Make & Model

: Mitsubishi FE639E6RDE

Date of registration

: 13th April 2000

Engine No. Chassis No. : 4D34H25219

Transmission

: FE639EA40415

Colour

: Manual : White

Speedometer reading

: 849243 Km

3 STATIC CHECK

Steering

: In order

Paintwork

: Good

Footbrake Handbrake . In order : In order

Modification General condition : Good

: Nil

4 TYRE CONDITION

Nearside/Make

Offside/Make

Size

Front tyre Rear tyre

: 7mm/Texxan : 7mm/Vikrant

7mm/Texxan 7mm/Vikrant

: 7.00-16C : 7.00-16C

5 POINT OF IMPACT

See Annex(es) and Motor Accident Reports

6 REMARK

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.

Vehicle No. YK3690J

Parts and Labour Assesment

PARTS

Description of part	Repairer's	Qty	Condition	Repairer's	Our
AIR INTAKE DUCT ASSY	Qty	1	DENTED/CUT	estimate	adjustment
CABIN REAR LOCK ASSY	;	1	DISTORTED/JAMMED	780.80	780.80
CABIN REAR LOCK HANDLE		1	BENT BENT	490.10	490.10
CABIN REAR LOCK LINKAGE	;	1		260.00	260.00
FRONT LH DOOR ASSY Reput	1	1	BENT/JAMMED	360.10	360.10
FRONT LH DOOR ASST	1	1	DENTED/DISTORTED/JAMMED	2,350.00	2,350.00 /
FRONT LH DOOR LOWER PROTECTOR FRONT LH DOOR REAR QUARTER	MM	1	CUT/SLACK 2 496	391.00	391.00 +
PANEL	1	0	REPAIR	795.10	0.00
FRONT LH DOOR WEATHER STRIP	e Nevi	1	DEFORMED/CUT /872	208.00	208.00 ⊀
al .	al .		1812	200.00	200.00 1
FR T LH FENDER ARCH GARNISH	ec . 1	1	CRACKED	910.20	910.20 ×
FRONT LH WHEEL REAR MUDFLAP	7 NA 1	1	GRAZED/CUT	140.00	140.00×
FRONT LH WHEEL REAR MUDGUARD	(NOC				
ASSY	1	1	BENT/CUT	645.10	645.10
REAR LEAF SPRING FRONT SHACKLE					
BRACKET LH	1	I	CRACKED	480.00	480.00
SHACKLE BRACKET PIN LH	1	1	DISTORTED/SLACK	125.00	125.00/
	Control to the Control of the Contro		Subtotal before discount	S\$ 7,935.40	S\$ 7,140.30
Percen	tage discount	25% and	25%	S\$ 1,983.85	S\$ 1,785.08
			Sub-total	S\$ 5,951.55	S\$ 5,355.23
CANVAS HOOK L/R	8	8	TORN	240.00	240.00 X
REAR WHEEL MUDGUARD ASSY LH	1	1	TORN	450.00	450.00 -
REAR WHEEL MUDGUARD ASSY RH	ì	0	REPAIR	450.00	0.00 X
REAR WHEEL MUDGUARD BRACKET	8		Tua Tille	450.00	0.00 /
LH	4	4	TORN/MISSING	80.00	80.00
REAK WHEEL MUDGUARD BRACKET			Totavitasonia	80.00	80.00
RH	4	0	REPAIR	80.00	0.00 X
REAR WOODEN BODY FRONT BOARD			rus riik	80.00	0.00
ASSY	1	1	CRACKED/DISTORTED	1,500.00	1,500.00
REAR WOODEN FLOOR BOARD	8	8	DISTORTED/CRACKED/TORN	2,000.00	2,000.00
REAR WOODEN STEP MEMBER	1	1	CRACKED	180.00	180.00
SIDE BOARD C/W ANGLE IRON LH	1 1	1	CRACKED/TORN	2,100.00	2,100.00
SIDE BOARD C/W ANGLE IRON RH	\ i	i	SHIFTED/CRACKED	2,100.00	2,100.00
SIDE BOARD HINGE LATCH LOCK C/W		•		2,100.00	2,100.00
CHAIN LH	2	2	TORN/MISSING	136.00	136.00
SIDE BOARD HINGE LATCH LOCK C/W	1 -	-	a deal million to	130.00	130.00
CHAIN RH	2	2	BENT/JAMMED	136.00	136.00
SIDE BOARD HINGES LH	5	5			
	3	3	TORN/MISSING	1.050.00	1 050 00
SIDE BOARD HINGES RH	5	5	TORN/MISSING DISTORTED/SLACK	1,050.00	1,050.00

			Sub-total	S\$ 26,948.00	S\$ 26,418.00	
	Percentage discount	0% and	0%	S\$ 0.00	S\$ 26,418.00 S\$ 0.00	
MEMBER	9	9	CRACKED Subtotal before discount	1,800.00 S\$ 26,948.00	1,800.00	J
WOODEN BODY WOODEN CROS		2	DISTORTED/CRACKED	1,600.00	1,600.00	
WOODEN BODY MAIN WOODEN L/R	BEAM		SHIFTED/SLACK/CRACKED	920.00	920.00	
WOODEN BODY FRONT PARTITI MEMBER (VERICAL)		4			180.00	
WC DEN BODY FRONT PARTITI MENIBER (HORIZONTAL SHORT)		2	SLACK/CRACKED	180.00	190.00	
WOODEN BODY FRONT PARTITI MEMBER (HORIZONTAL LONG)	ION 4	4	DISTORTED/CRACKED	840.00	840.00	
(VERTICAL)	2	2	MISSING	360.00	360.00	
TAIL BOARD WOODEN PARTITION (HORIZONTAL) TAIL BOARD WOODEN PARTITION	2	2	MISSING	420.00	420.00	
TAIL BOARD WITH ANGLE IRON	1	1	TORN/MISSING	280.00 1,500.00	280.00 1,500.00	
TAIL BOARD LOWER METAL PA TAIL BOARD LOWER WOODEN MEMBER	NEL !	1	TORN/MISSING TORN/MISSING	600.00	600.00	
C/W CHAIN	2	2	TORN/MISSING	136.00	136.00	
TAIL BOARD HINGES LATCH LO	OCK	1.77	MANAGORIA	840.00	840.00	
SIF YOARD WOODEN PARTITI MEMBER (VERTICAL) RH TAIL BOARD HINGES	ON 4	4	SHIFTED/CRACKED TRN/MISSING	720.00	720.00	
SIDE BOARD WOODEN PARTITI MEMBER (VERTICAL) LH	4	4	TORN/MISSING	720.00	720.00	
SIDE BOARD WOODEN PARTITI MEMBER (HORIZONTAL) RH	ON 4	4	SLACK/SHIFTED/CRACKED	840.00	840.00	
SIDE BOARD WOODEN PARTITI MEMBER (HORIZONTAL) LH	ON 4	4	TORN/MISSING	840.00	840.00	
SIDE BOARD WOODEN PARTITI BRACKET RH	ION 8	8	DISTORTED/SLACK	200.00	200.00	1
SIDE BOARD WOODEN PARTITI BRACKET LH		8	MISSING	1,200.00	1,200.00 200.00	
SIDE BOARD LOWER METAL PARH	ANEL 1	1	TORN/MISSING BENT/DENTED	1,200.00	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
SIDE BOARD LOWER METAL PA	CONCRETE OF THE PARTY OF THE PA					

60 KM/H STICKER	1	1	NECESSARY	12.00	12.00
FRONT LH DOOR		956			
COMPANY, TEL, FAX, H/P STICKER	1	1	NECESSARY	210.00	210.00
REAR BUMPER WITH BRACKET	1	1	DISTORTED/SLACK	1,800.00	1,800.00
REAR NUMBER PLATE	1	1	BENT 1176	35.00	35.00
REAR NUMBER PLATE BRACKET	1	1		125.00	125.00
REAR NUMBER PLATE LAMP	1	1	SLACK/FAULTY	68.00	68.00
SIDE GUARD RAIL ASSY LH	1	1	SHIFTED/BENT	1,500.00	1,500.00
SIDE GUARD RAIL ASSY RH	1	0	REPAIR	1,500.00	0.00×
SIDE GUARD RAIL BRACKET LH	2	2	SHIFTED/BENT/SLACK	240.00	240.00
SIDE GUARD RAIL BRACKET RH	2	0	REPAIR	240.00	0.00
TAILLAMP ASSY LH	1	Ī	MISSING	230.00	230.00
TAILLAMP ASSY RH	1	1	SHIFTED/CRACKED	230.00	230.00
TAILLAMP BRACKET LH	1	1	MISSING	98.00	98.00
TAILLAMP BRACKET RH	1	1	BENT	98.00	98.00
WOODEN BODY U CLAMP ?	8	8	DISTORTED/SLACK	1,440.00	1,440.00
7.			Subtotal before discount	S\$ 7,826.00	S\$ 6,086.00
together w	HU Froo		Sub-total	S\$ 7,826.00	S\$ 6,086.00
IV	the front.		Parts-total	S\$ 40,725.55	S\$ 37,859.23
LABOUR					
To provide towing charge				250.00	150.00
To check, align chassis main frame chassis	cross member and e	tc to syr	mmetrical specification.	800.00	600.00
To check wiring and light system			-	250.00	80.00
To transfer LH front door mechanism				150.00	80.00 ×
To apply anti-rust chemical on repaired and	i replaced panel.		2400	200.00	120.00
To remove, dispose damaged wooden body				500.00	400:00 360
To reconstruct new rear wooden body, woo				2,100.00	1,800.00
To remove, replace damaged front door LF	i, front Lh door quate	er panel	, cabin lock and etc.	1,800.00	1,500.00 1200
To spray paint affected areas.	(3)	2. 5		1,500.00	1,250.00
To varnish wooden body				1,200.00	1,000.00 800
			Labour Total	S\$ 8,750.00	S\$ 6,980.00
			Parts & Labour Total	S\$ 49,475.55	S\$ 44,839,23
					1,007,100

Results of inspection of the accident vehicle are as shown above,

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is: S\$ 38,100.00 and the recommended number of working days for the repairs is within 12 day(s).

total: 18048

PATRICK SURVEYOR)
Automotive Appraiser



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 17.23342

Date: 07th Sep 2018

Our Ref: CS1/LAW18013424/Atbe2

M/s Seah Ong & Partners LLP

36 Robinson Road #12-03 City House Singapore 068877

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YK 3690J

INSURED VEHICLE: YM 8358B ACCIDENT DATE: 13/02/2017

We thank you for your instruction on 27/06/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YK 3690J from M/s Carlink Consultancy.
- b) Survey report by RT Appraisal Pte Ltd with colour photographs.
- c) Singapore Accident Statement of Vehicles YK 3690J and YM 8358B.
- d) Colour damaged vehicle photographs of YK 3690J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: YK 3690J

Make & Model

: Mitsubishi FE639E6RDE

Year of Registration

: 2000

Chassis Number

: FE639EA40415

Engine Capacity

: 3907 cc

- We recommend that the repairs of the entire damage require about <u>12 (Twelve)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YK 3690J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	AIR INTAKE DUCT ASSY	DENTED / CUT	780.80	780.80
1	CABIN REAR LOCK ASSY	DISTORTED / JAMMED	490.10	490.10
1	CABIN REAR LOCK HANDLE	BENT	260.00	260.00
1	CABIN REAR LOCK LINKAGE	BENT / JAMMED	360.10	360.10
1	FRONT LH DOOR ASSY	TO REPAIR SEE LABOUR	2,350.00	-
1	FRONT LH DOOR LOWER PROTECTOR	NOT NECESSARY	391.00	
1	FRONT LH DOOR REAR QUARTER PANEL	TO REPAIR SEE LABOUR	795.10	-
1	FRONT LH DOOR WEATHER STRIP	NOT NECESSARY	208.00	-
1	FRONT LH FENDER ARCH GARNISH	NOT NECESSARY	910.20	/4
1	FRONT LH WHEEL REAR MUDFLAP	NOT NECESSARY	140.00	Ca.
1	FRONT LH WHEEL REAR MUDGUARD ASSY	NOT NECESSARY	645.10	1=
1	REAR LEAF SPRING FRONT SHACKLE BRACKET LH	CRACKED	480.00	480.00
1	SHACKLE BRACKET PIN LH	DISTORTED / SLACK	125.00	125.00
	LESS 25% DISCOUNT		-1,983.85	-624.00
			5,951.55	1,872.00
	SPECIAL NETT ITEMS			
8	CANVAS HOOK L/R (SN)	NOT NECESSARY	240.00	-
1	REAR WHEEL MUDGUARD ASSY LH (SN)	TORN	450.00	450.00
1	REAR WHEEL MUDGUARD ASSY RH (SN)	TO REPAIR SEE LABOUR	450.00	1-
4	REAR WHEEL MUDGUARD BRACKET LH (SN)	TORN / MISSING	80.00	80.00
4	REAR WHEEL MUDGUARD BRACKET RH (SN)	TO REPAIR SEE LABOUR	80.00	1
1	REAR WOODEN BODY FRONT BOARD ASSY (SN) }	CRACKED / DISTORTED	1,500.00	7,500.00
8	REAR WOODEN FLOOR BOARD (SN) }	DISTORTED / CRACKED / TORN	2,000.00	1-
1	REAR WOODEN STEP MEMBER (SN) }	CRACKED	180.00	
1	SIDE BOARD C/W ANGLE IRON LH (SN) }	CRACKED / TORN	2,100.00	7.4

Report Ref No. CS1/LAW18013424/Atbe2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SIDE BOARD C/W ANGLE IRON RH (SN) }	SHIFTED / CRACKED	2,100.00	-
2	SIDE BOARD HINGE LATCH LOCK C/W CHAIN LH (SN) }	TORN / MISSING	136.00	
2	SIDE BOARD HINGE LATCH LOCK C/W CHAIN RH (SN) }	BENT / JAMMED	136.00	
5	SIDE BOARD HINGES LH (SN) }	TORN / MISSING	1,050.00	-
5	SIDE BOARD HINGES RH (SN) }	DISTORTED / SLACK	1,050.00	
1	SIDE BOARD LOWER METAL PANEL LH (SN) }	TORN / MISSING	1,200.00	
1	SIDE BOARD LOWER METAL PANEL RH (SN) }	BENT / DENTED	1,200.00	
8	SIDE BOARD WOODEN PARTITION BRACKET LH (SN) }	MISSING	200.00	-
8	SIDE BOARD WOODEN PARTITION BRACKET RH (SN) }	DISTORTED / SLACK	200.00	
4	SIDE BOARD WOODEN PARTITION MEMBER (HORIZONTAL) LH (SN) }	TORN / MISSING	840.00	
4	SIDE BOARD WOODEN PARTITION MEMBER (HORIZONTAL) RH (SN) }	SLACK / SHIFTED / CRACKED	840.00	
4	SIDE BOARD WOODEN PARTITION MEMBER (VERTICAL) LH (SN) }	TORN / MISSING	720.00	
4	SIDE BOARD WOODEN PARTITION MEMBER (VERTICAL) RH (SN) }	SHIFTED / CRACKED	720.00	
4	TAIL BOARD HINGES (SN) }	TORN / MISSING	840.00	
2	TAIL BOARD HINGES LATCH LOCK C/W CHAIN (SN) }	TORN / MISSING	136.00	,
1	TAIL BOARD LOWER METAL PANEL (SN) }	TORN / MISSING	600.00	-
1	TAIL BOARD LOWER WOODEN MEMBER (SN) }	TORN / MISSING	280.00	-
1	TAIL BOARD WITH ANGLE IRON (SN) }	TORN / MISSING	1,500.00	
2	TAIL BOARD WOODEN PARTITION (HORIZONTAL) (SN) }	MISSING	420.00	
2	TAIL BOARD WOODEN PARTITION (VERTICAL) (SN) }	MISSING	360.00	
4	WOODEN BODY FRONT PARTITION MEMBER (HORIZONTAL LONG) (SN) }	DISTORTED / CRACKED	840.00	-
2	WOODEN BODY FRONT PARTITION MEMBER (HORIZONTAL SHORT) (SN) }	SLACK / CRACKED	180.00	
4	WOODEN BODY FRONT PARTITION MEMBER (VERTICAL) (SN) }	SHIFTED / SLACK / CRACKED	920.00	,
2	WOODEN BODY MAIN WOODEN BEAM L/R (SN) }	DISTORTED / CRACKED	1,600.00	-
9	WOODEN BODY WOODEN CROSS MEMBER (SN) }	CRACKED	1,800.00	

Report Ref No. CS1/LAW18013424/Atbe2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
8	WOODEN BODY U CLAMP (SN) }	DISTORTED / SLACK	1,440.00	_
1	60KM/H STICKER (SN)	NECESSARY	12.00	12.00
1	FRONT LH DOOR COMPANY, TEL, FAX, H/P STICKER (SN)	NECESSARY	210.00	210.00
1	REAR BUMPER WITH BRACKET (SN)	DISTORTED / SLACK	1,800.00	1,200.00
1	REAR NUMBER PLATE (SN)	BENT	35.00	35.00
1	REAR NUMBER PLATE BRACKET (SN)	BENT	125.00	125.00
1	REAR NUMBER PLATE LAMP (SN)	SLACK / FAULTY	68.00	68.00
1	SIDE GUARD RAIL ASSY LH (SN)	SHIFTED / BENT	1,500.00	1,200.00
1	SIDE GUARD RAIL ASSY RH (SN)	TO REPAIR SEE LABOUR	1,500.00	·-
2	SIDE GUARD RAIL BRACKET LH (SN)	SHIFTED / BENT / SLACK	240.00	240.00
2	SIDE GUARD RAIL BRACKET RH (SN)	TO REPAIR SEE LABOUR	240.00	:-
1	TAILLAMP ASSY LH (SN)	MISSING	230.00	230.00
1	TAILLAMP ASSY RH (SN)	SHIFTED / CRACKED	230.00	230.00
1	TAILLAMP BRACKET LH (SN)	MISSING	98.00	98.00
1	TAILLAMP BRACKET RH (SN)	BENT	98.00	98.00
			34,774.00	11,776.00
	LABOUR			
	TO VARNISH WOODEN BODY.		1,200.00	700.00
	TO PROVIDE TOWING CHARGE.		250.00	150.00
	TO CHECK, ALIGN CHASSIS MAIN FRAME CHASSIS CROSS MEMBER AND ETC TO SYMMETRICAL SPECIFICATION.		800.00	600.00
	TO CHECK WIRING AND LIGHT SYSTEM.		250.00	80.00
	TO TRANSFER LH FRONT DOOR MECHANISM.	NOT NECESSARY	150.00	-
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	A Secretary Secr	200.00	120.00
	TO REMOVE, DISPOSE DAMAGED WOODEN BODY AND ETC.		500.00	300.00

Report Ref No. CS1/LAW18013424/Atbe2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO RECONSTRUCT NEW REAR WOODEN BODY, WOODEN PARTITION AND ETC. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR ASSY, FRONT LH DOOR REAR QUARTER PANEL, REAR WHEEL MUDGUARD BRACKET RH, REAR WHEEL MUDGUARD BRACKET RH, SIDE GUARD RAIL ASSY RH AND SIDE GUARD RAIL BRACKET RH.	NOT NECESSARY	2,100.00). -
	TO REMOVE, REPLACE DAMAGED FRONT DOOR LH, FRONT LH DOOR QUATER PANEL, CABIN LOCK AND ETC.		1,800.00	1,200.00
	TO SPRAY PAINT AFFECTED AREAS.		1,500.00	1,250.00
			8,750.00	4,400.00
	GRAND TOTAL		49,475.55	18,048.00

RECOMMENDED COST OF REPAIRS	18,048.00
-----------------------------	-----------

Report Ref No. CS1/LAW18013424/Atbe2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.