

ASS. REC. BY:

REF: CS/FCI/8013425/ U fd3 n2

Special Instruction:

SURVEYOR:

CWS

ASSIGNMENT (Office)

From (Person):

Lurene Jaw

of

FCI

Date/Time:

24/7/18 @ 9.21am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KX 1551M

Insured:

8HC 7088R

at Workshop m/s

Progressive Automotive

Tel:

67415336

of

81k 3022A Ubi Rd 1 #01-45/46

Policy No:

Claim No:

D18005583 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/07/2018

CA / REV / REP. / REV 24 HRS

DS?

H.O.D. Endorsement:

Date/Time: 10.52am 24/7/18

Person Contacted:

800

Vehicle-IN/OUT

Date/Time

Action/Instruction (✓) Estimate

8KX 1551M-X

8HC 7088 R CS/FCI 15001886/Kvbi2

DOA: 30/1/2015

24/7-

Revert prell advise

(08/11/13) waf

ASS' REC. BY: MORIAS

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX1551Mat Workshop m/s PA 46.

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 44391

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKX1551M Yr Reg: 11 / 15Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA1Make: Toyota A400 C.C. 1496Colour: White A/C: Insured / Std / NI / NASp. Reading: 214020 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NHP10 6461803Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or h.c.fly

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 20/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/18 Contd 1/5 @ 1550 with Ray. (Red 1844-88; 54%)

RECEIVED 02 AUG 2018

Date/Time, File Pass to?

12/8 Typist

Date/Time, File Return to?

2)

Report Format: PLump Sum / I.B.I. (\$) 1550Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

1305036216



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005583MFSH

Date: 27/7/2018

Our Ref: CS/FCI18013425/Utd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKX 1551M

Please be informed that we had conducted the inspection of the abovementioned vehicle 25/7/2018 at the premises of M/s Progressive and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 3,394.88</u>
Revised Estimate Amount	: <u>S\$ 1,966.33</u>
"Check" Items Amount	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Marcus
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-07-2018	Our Ref No. D18005583MFSH
Accident Date	20-07-2018	Claim Type. Third Party
Insured Vehicle	SHC7088R	Third Party Vehicle. SKX1551M
Survey Location	BLK 3022A UBI ROAD 1 #01-45/46	
Contact Person.	LEONG.KEAT. SOO	
Contact No.	67415336/ 0	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242607)



PRI Documents



Close



PRI Header Details

Claim No	D18005583MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PROGRES
Workshop Name	PROGRESSIVE AUTOMOTIVE PTE LTD (Contact Person : LEONG.KEAT. SOO)	Survey Location & Contact Details	BLK 3022A UBI ROAD 1 #01-45/46 Mobile: 0 , Phone: 67415336 , Fax: 0 EmailId: LKSOO@PROG.AUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7088R	TP Vehicle No	SKX1551M
PRI Recieved Date	23-07-2018 05:50:29 PM	Surveyor Appointed Date	24-07-2018 09:20:32 AM	Surveyor Accept Date	24-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	24-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name	Action
-----------	--------

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 27 July 2018 2:37 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005583MFSH/1
Attachments: PRELI ADVISED SKX 1551M.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKX 1551M**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 24 July 2018 10:59 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005583MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 24 July 2018 9:21 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005583MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	9442H

Vehicle Details

Vehicle No.:	SKX1551M
Vehicle to be Exported:	No
Intended De-registration Date:	25 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	AQUA HYBRID 1.5S A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1NZ7697355
Chassis No.:	NHP106461803
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$17,656.00
Original Registration Date:	27 Nov 2015
First Registration Date:	27 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Nov 2025
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	26 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$40,641.00
Total Rebate Amount:	\$44,391.00

The information contained herein is correct as at 25 Jul 2018

OK

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

Not Affected
25/7/18
3dy
The prob. Affected

M/S : LEGEND MOTORS & LEASING PTE LTD
 69 UBI ROAD 1 #10-33 OXLEY BIZHUB 1
 SINGAPORE 408731

Estimate No: EST1503879
Date: 20 Jul 2018
Policy No: P1917604
Veh Reg No: SKX1551M
Make/Model: TOYOTA AQUA
 HYBRID 1.5S A
Chassis No: NHP106461803
Engine No: 1NZ7697355
Reg. Date: 27/11/2015

ATTN:

Your Ref No: TP 0718-5157
Claim Type: Third Party
Accident Date: 20/07/2018
TP Veh Reg No: SHC7088R

Estimate Repair Cost to Vehicle No :SKX1551M

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT AQUA LOGO	98.6000	1 PCS	98.60	✓
2 REAR BOOT TOYOTA LOGO	85.4000	1 PC	85.40	✓
3 REAR BOOT HYBRID SYNERGY DRIVE LOGO	101.4000	1 PCS	101.40	✓
4 REAR PANEL (NO STOCK)	780.6000	1 PC	780.60	X
5 REAR PANEL TOP GARNISH	380.4000	1 PCS	380.40	X
6 REAR BUMPER	360.5000	1 PC	360.50	✓
7 REAR BUMPER CLIPS	9.8000	10 PC	98.00	✓
8 REAR BUMPER SIDE HOLDER - LH	105.6000	1 PCS	105.60	✓
9 REAR BUMPER SIDE HOLDER - RH	105.6000	1 PCS	105.60	✓
10 REAR BUMPER UNDER GARNISH	130.4000	1 PCS	130.40	X
			2,246.50	
		Less 25%	561.63	1,684.88
Special Net				
11 REAR BUMPER SENSOR	220.0000	1 SET	220.00	200
			220.00	220.00
Labour				
12 TO KNOCK OUT DENTS, CUT/ WELD, REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	600.0000	1 JOB	600.00	400
13 TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.0000	1 JOB	600.00	520
14 TO REMOVE, TRANSFER REAR BUMPER SENSOR	50.0000	1 JOB	50.00	✓
15 TO CHECK WIRING	50.0000	1 JOB	50.00	20
16 TO REMOVE, TRANSFER REAR BOOT	80.0000	1 JOB	80.00	X
17 TO REMOVE, REFIX REAR GARNISH AND RELATED PARTS	80.0000	1 JOB	80.00	60
18 TO TUFF-KOTE	30.0000	1 JOB	30.00	X
			1,490.00	1,490.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : LEGEND MOTORS & LEASING PTE LTD
69 UBI ROAD 1 #10-33 OXLEY BIZHUB 1
SINGAPORE 408731

ATTN:

Your Ref No: TP 0718-5157
Claim Type: Third Party
Accident Date: 20/07/2018
TP Veh Reg No: SHC7088R

Estimate No: EST1503879
Date: 20 Jul 2018
Policy No: P1917604
Veh Reg No: SKX1551M
Make/Model: TOYOTA AQUA
HYBRID 1.5S A
Chassis No: NHP106461803
Engine No: 1NZ7697355
Reg. Date: 27/11/2015

Estimate Repair Cost to Vehicle No :SKX1551M

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 3,394.88
			Add GST @ 7%	237.64
			Total Amount Payable	S\$ 3,632.52

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED THIRTY TWO AND CENTS FIFTY TWO ONLY

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

Not Affected
25/7/18
30/7/18
John

M/S : LEGEND MOTORS & LEASING PTE LTD
69 UBI ROAD 1 #10-33 OXLEY BIZHUB 1
SINGAPORE 408731

Estimate No: EST1503879
Date: 20 Jul 2018
Policy No: P1917604
Veh Reg No: SKX1551M
Make/Model: TOYOTA AQUA
HYBRID 1.5S A
Chassis No: NHP106461803
Engine No: 1NZ7697355
Reg. Date: 27/11/2015

ATTN:

Your Ref No: TP 0718-5157
Claim Type: Third Party
Accident Date: 20/07/2018
TP Veh Reg No: SHC7088R

TP 5157

Estimate Repair Cost to Vehicle No :SKX1551M

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 REAR BOOT AQUA LOGO	98.6000	1 PCS	98.60	
2 REAR BOOT TOYOTA LOGO	85.4000	1 PC	85.40	
3 REAR BOOT HYBRID SYNERGY DRIVE LOGO	101.4000	1 PCS	101.40	
4 REAR PANEL (NO STOCK)	780.6000	1 PC	780.60	
5 REAR PANEL TOP GARNISH	380.4000	1 PCS	380.40	
6 REAR BUMPER	360.5000	1 PC	360.50	
7 REAR BUMPER CLIPS	9.8000	10 PC	98.00	
8 REAR BUMPER SIDE HOLDER - LH	105.6000	1 PCS	105.60	
9 REAR BUMPER SIDE HOLDER - RH	105.6000	1 PCS	105.60	
10 REAR BUMPER UNDER GARNISH	130.4000	1 PCS	130.40	
			2,246.50	
		Lcss 25%	561.63	1,684.88
Special Net				
11 REAR BUMPER SENSOR	220.0000	1 SET	220.00	
			220.00	220.00
Labour				
12 TO KNOCK OUT DENTS, CUT/ WELD, REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	600.0000	1 JOB	600.00	
13 TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.0000	1 JOB	600.00	
14 TO REMOVE, TRANSFER REAR BUMPER SENSOR	50.0000	1 JOB	50.00	
15 TO CHECK WIRING	50.0000	1 JOB	50.00	
16 TO REMOVE, TRANSFER REAR BOOT	80.0000	1 JOB	80.00	
17 TO REMOVE, REFIX REAR GARNISH AND RELATED PARTS	80.0000	1 JOB	80.00	
18 TO TUFF-KOTE	30.0000	1 JOB	30.00	
			1,490.00	1,490.00
			PART. 716.33	1050
			SN 200.00	
			LAB. 1050.00	
			1966.33	

1530



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013425/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7088R	Veh. Inspected	SKX 1551M	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005583MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	24/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA AQUA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	NHP106461803	Colour	WHITE	
Odometer	214020	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	HIFLY	6 mm	
L/H Front Tyre	195/55 R15	HIFLY	6 mm	
R/H Rear Tyre	195/55 R15	HIFLY	6 mm	
L/H Rear Tyre	195/55 R15	HIFLY	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/07/2018	Inspection Date	25/07/2018	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 1551M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT AQUA LOGO	NECESSARY	98.60	98.60
1	REAR BOOT TOYOTA LOGO	NECESSARY	85.40	85.40
1	REAR BOOT HYBRID SYNERGY DRIVE LOGO	NECESSARY	101.40	101.40
1	REAR PANEL	TO REPAIR SEE LABOUR	780.60	-
1	REAR PANEL TOP GARNISH	NOT NECESSARY	380.40	-
1	REAR BUMPER	DENTED / DEFORMED	360.50	360.50
10	REAR BUMPER CLIPS @\$9.80	NECESSARY	98.00	98.00
1	REAR BUMPER SIDE HOLDER-LH	BENT	105.60	105.60
1	REAR BUMPER SIDE HOLDER-RH	BENT	105.60	105.60
1	REAR BUMPER UNDER GARNISH	NOT NECESSARY	130.40	-
	LESS 25% DISCOUNT		-561.62	-238.78
			1,684.88	716.32
SPECIAL NETT ITEMS				
1	SET REAR BUMPER SENSOR (SN)	SHORTED	220.00	200.00
			220.00	200.00
LABOUR				
	TO KNOCK OUT DENTS,CUT/WELD,REAR PANEL,REMOVE,REPLACE ACCIDENT PARTS.		600.00	400.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		600.00	520.00
	TO REMOVE,TRANSFER REAR BUMPER SENSOR.		50.00	50.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE,TRANSFER REAR BOOT.	NOT NECESSARY	80.00	-
	TO REMOVE,REFIX REAR GARNISH AND RELATED PARTS.		80.00	60.00
	TO TUFF-KOTE.	NOT NECESSARY	30.00	-
			1,490.00	1,050.00
GRAND TOTAL			3,394.88	1,966.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,550.00

Report Ref No. CS/FC118013425/Utd3n2



Report Ref No. CS/FC118013425/Utd3n2

A handwritten signature in black ink, appearing to be 'Ch' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.