CWS POINTS	ASSIGNMENT (Office)	
Estimated Cost:	of FCL	Date/Time 24/7/188 12.32pm
OD (TP) WS/TP RES/OD RES/E	Bill to: VA/INV/MV7CS	
To Inspect Vehicle No.	SLH 6643X	Insured: 3HB 3612 (
AN AN	Him Motor	Tel 6/92/12/1/
of No 10, AMK Policy No:	ing park 24 #01	-09
Sum Insured:		D18005581 MFSH
Make of Veh: (Client's Record)	Excess:	D.O.A 19/07/2018
CA / REV / REP. / REV 24 HRS Date/Time: 1242pm@241718		H.O.D. Endorsement:  Vehicle IN OUT
Date/Time Action/Instruction (V	) Estimate	
JHB 36/21-00	3/FCT/(GCA 182/K-	h3d1 DOA: 26/12/15
25/07/18 @ 17:42 p.m.	reused PA to Sit	hara via email.
2419 89438.52 6	a fime	
25/09/18 Confirmed \$ 9 (\$ 9.767.92	438_52 @ IT days	with Kennyl
(\$ 9.767.92	Red - 51%)	w Norwin.

From:  Estimated Cost:  OD ITP J WS / TP RES / OD RES / EVA / INV / MV  To Inspect Vehicle No:  at Workshop m/s  Of  Date:  Veh No:  SUIT 6643 X Yr Regn:  Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /  Truck / Trailer or  Make:  I / Ym do: Elante c.c / 5°  Colour-  Lubit AC: Insured / Std / NI / N.	nneth	ASSIGNMENT
Truck   Tailer or As   Truck   Tailer   Tai	From: Date:	P/11/6/12
Truck   Tailer or As   Truck   Tailer   Tai	Estimated Cost:	Type: MCar/ HOULE 1
To inspect Vehicle No: at Workshop m/s insured:	OD ITP/WS/TP RES/ OD RES/ EVA / INV / MV	- Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
colour Sp. Reading 2993 TRAdic: Insured Istd INTIN Eng/No: Claims No. Claims No. Claims Roc. Claims Roc. Claims Roc. Claims Roc. Closer's Record) Make of Veh:  Sternark: Insured: Jammed I Leaked I Burnt or Mod! NII I SIRM I STEARRIM or Tyre Stee: F:  185 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR I SUMI / TOYO / YOK Or  Frool Rear Roc. Roc. Accident Roort Consistent?: Yes or No List. Repairs: days Res.: Yes or No List. Repairs: days Res.: Yes or No No. It. Repairs: days Res.: Yes or No No. It. Repairs: days Res.: Yes or No No. I REV / REP. / 24 HRS  Des. of Damages: Frt / Rear? O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.  REGETIVED TO Days Of Repair:  Resurvey No. of Trip: 2 Survey Fee:  Resurvey No. of Trip: 3 Survey Fee:  Resurvey No. of Trip: 4 S	To Inspect Vehicle No:	
Sp. Reading 2993 Tradic: Insured 15td INTN Sp. Reading 2993 Tradic: Insured 15td INTN INTRODUCTION TRADIC: Insured 15td INTO INTRODUCTION TRADIC: Insured 15td INTO INTRODUCTION TRADIC: Insured 15td INTN INTRODUCTION TRADIC: Insured 15td INTO INTRODUCTION TRADIC: Insured 15td INTN INTRODUCTION TRADIC: Insured 15td INTN INTRODUCTION TRADIC: Insured 15td INTN INTRODUCTION TRADIC INTRODUCTION TO	at Workshop m/s	Make: 19mdo: Elasto c.c 15
EngNo:  Claims No.  Claims No.  Sum insured:  Excess:  (Client's Record)  Make of Veh:  (Policy Condition)  Barmark: The veh had commenced its repair at the time of inspection.  al. or Market Value:  B 5 H.  AC Accident Roort  Consistent?: Yes or No.  It. Repairs:  AS I REV I REP. I 24 HRS  Person Contacted:  Vehicle: IN / OUT  Person Contacted:  Vehicle: IN / OUT  RECEIVED 2 F CON Accident From Its Body Structure affected due to collision.  ACT Repairs:  Add Fee:  Survey No. of Trip:  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  Add Fee:  Site Insp (\$ ) \$ - Result Transporters.  The Interview (\$ ) \$ - Result Transporters.  The Interview (\$ ) \$ - Result Transporters.  The Interview (\$ ) \$ - Result Transporters.  Add Fee:  Summ It.B.I: (\$ 9 1/28 - Result Transporters.  The Interview (\$ ) \$ - Re	01	NGIA NO. Insured / Std / NI / N
Policy No.  Claims No.  Sum insured:  Excess:  Claims Record)  Make of Veh:  Performance of Its performance	Insured:	- Communication State Nick
Sum insured:  Excess:    Client's Record    Make of Veh:	Policy No.	
Sum insured:  Excess:    Client's Record    Make of Veh:	Claims No.	CNO: KMHO841CM.144239.
(Client's Record)  Make of Veh:  (Policy Condition)  (Policy Condi	Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt
Summ   Legal   Leaked   Burnt or   Modi: NII   SIRIm   STO ARIJIM or   Tyre Size: F:   R\$   LIZA   MIC   OHTSU   PIR   SUMI   TOYO   YOKO or   Leaked   Burnt or   Tyre Size: F:   R\$   LIZA   MIC   OHTSU   PIR   SUMI   TOYO   YOKO or   Leaked   Burnt or   Leaked   Burnt or   Tyre Size: F:   R\$   LIZA   MIC   OHTSU   PIR   SUMI   TOYO   YOKO or   Leaked   Burnt or   Leaked   Burnt or   Toyo   Yoko or   Toyo   Yoko		
(Policy Condition)  Permark: The veh had commenced its repair at the time of inspection.  all or Market Value:		
Remark: The veh had commenced its repair at the time of inspection.  al. or Market Value:  BS FM.  AC Accident Rport  Consistent?: Yes or No  Id. / PR Seen:  Consistent?: Yes or No  Id. / PR Seen:  Consistent?: Yes or No  Id. Repairs:  days Res.: Yes or No  Id. Repairs:  days Res.: Yes or No  Id. Repairs:  A. / REP. / 24 HRS  Vehicle: IN / OUT  The U/C / Chassis frame / Body Structure affected due to collision.  A / REP. / Parson Contacted:  The U/C / Chassis frame / Body Structure affected due to collision.  REGETIVED 2 TOTAL 2018  Add Fee:  Site Insp  Sirvey No. of Trip:  Survey Fee:  Transportation:  Add Fee:  Interview (\$ ) Final Report  Tech Invs (\$ ) Others  Tech Invs (\$ ) Others  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  Add Fee:  Interview (\$ ) Final Report  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  Add Fee:  Interview (\$ ) Final Report  Transportation:  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  Add Fee:  Interview (\$ ) Final Report  Transportation:  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / C		Modi: Nil / S/Rim / ST/O A/Rim or
Remark: The veh had commenced its repair at the time of inspection.  al. or Market Value:  BS FM.  AC Accident Rport  Consistent?: Yes or No  Id. / PR Seen:  Consistent?: Yes or No  Id. / PR Seen:  Consistent?: Yes or No  Id. Repairs:  days Res.: Yes or No  Id. Repairs:  days Res.: Yes or No  Id. Repairs:  A. / REP. / 24 HRS  Vehicle: IN / OUT  The U/C / Chassis frame / Body Structure affected due to collision.  A / REP. / Parson Contacted:  The U/C / Chassis frame / Body Structure affected due to collision.  REGETIVED 2 TOTAL 2018  Add Fee:  Site Insp  Sirvey No. of Trip:  Survey Fee:  Transportation:  Add Fee:  Interview (\$ ) Final Report  Tech Invs (\$ ) Others  Tech Invs (\$ ) Others  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  Add Fee:  Interview (\$ ) Final Report  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  Add Fee:  Interview (\$ ) Final Report  Transportation:  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  Add Fee:  Interview (\$ ) Final Report  Transportation:  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / Chassis frame / Body Structure affected for the collision.  The U/C / C	(Policy Condition)	Tyre Size: F: 195/65R15
Trepair at the time of Inspection.  al. or Market Value:  B 5 FL  AC Accident Rport  Consistent?: Yes or No  AL PR Soon:  Consistent?: Yes or No  DOA 19 7 11 DOI 194 11 S  Survey held at  Des. of Darnages: Frt   Rear'   OIS   NIS   UIC   Rooftop or  The UIC   Chassis frame   Body Structure affected due to collision.  DITAL PRESSOR  REGETIVED & FRED 2018  The UIC   Chassis frame   Body Structure affected due to collision.  Add Fee:  Site Insp (\$ Survey Fee: 170 1 1 3 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Remark: The yeh had comment	R:
all or Market Value:  B 5 HL  TOYO / YOKO or    Consistent?: Yes or No   Real		BS / DON / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
ACC Accident Roort: Consistent?: Yes or No IA / PR Seen: Consistent?: Yes or No IA / PR Seen: Consistent?: Yes or No IA / PR Seen: Donald Rear R/Bal. Amm		TOYOTYOKO OF Hankeuk
A / PR Soon: Consistent?: Yes or No  Id. Repairs: days Res.: Yes or No  Survey held at  Des. of Damages: Frt   Rear'   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.  Id. The U/C   Chassis frame   Body Structure affected due to collision.  REGETATED 2 F SCO 2018		Front
Add Fee:    Survey No. of Trip: 2   Survey Fee:   1/20   1/25   1		R/Bal. A mm R/Bal I
M Sum: 1/3, 1 % 3 Val.: Yes or No  A / REV / REP. / 24 HRS  The Person Contacted:  Vehicle: IN / OUT  The U/C / Chassis frame / Body Structure affected due to collision.  REGENTED 25 2518  REG		L/Bal. 7 mm L/Bal 7
Des. of Damages: Frt   Rear'   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.  The U/C   Chassis frame   Body Structure affected due to collision.  The U/C   Chassis frame   Body Structure affected due to collision.  RECEIVED 2 5 200 2018  The U/C   Chassis frame   Body Structure affected due to collision.  RECEIVED 2 5 200 2018  The U/C   Chassis frame   Body Structure affected due to collision.  RECEIVED 2 5 200 2018  The U/C   Chassis frame   Body Structure affected due to collision.  RECEIVED 2 5 200 2018  The U/C   Chassis frame   Body Structure affected due to collision.  RECEIVED 2 5 200 2018  The U/C   Chassis frame   Body Structure affected due to collision.  RECEIVED 2 5 200 2018  The U/C   Chassis frame   Body Structure affected due to collision.  Add Fee: Survey No. of Trip: 2 Survey Fee: 190 + 135  Transportation: 50  Transportati	55/5 765 01 140	1004 /9 /7 /10
Vehicle: IN/OUT  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  REGENTED 2.5 SCD 2318  REGEN		Survey held at
The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  REGELVED 2 F. SED 2018  REGELVED 2 F. SED 2018  Transportation  Add Fee: Site Insp (\$ Survey Fee: 170 + 175 me, File Return to?  Add Fee: Site Insp (\$ Servey Fee: 170 + 175 me, File Return to?  Tech Invs (\$ Servey Fee: 170 + 175 me, File Return to? Survey Fee: 170 + 175 me, File Return to?  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.  The U/C / Chassis frame / Body Structure affected due to collision.	1 / REV / REP. / 24 HRS	Des. of Damages : Frt 1/Rear 1 O/S / N/S / U/C / Rootton or
The U/C / Chassis frame / Body Structure affected due to collision.    15/7 File part	te:Person Contacted: Vehicle: IN /	001
REGEINED 2 F CCD 2019  REGEINED 2 F CCD 2019  Trupist Trupist Trupist Trupist Transportation  Add Fee:  Still Insp (\$ ) Silvey Fee:  Interview (\$ ) Fixos (\$ )  Tech Invs (\$ ) Others (\$ )  Tech Invs (\$ )  Tech Invs (\$ )  Tech Invs (\$ )  The still interview (\$ )  Tech Invs (\$ )	ate / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
REGELVED 2.5 SEP 2018  Topist Sine, Fie Pass 107  Typist Sine, Fie Return 107  Add Fee: Site Insp (\$ ) S+RS_SI 90+50  Interview (\$ ) Fieros (\$ ) Others (\$ ) Other	1 6 1	
Days Of Repair: Survey Fee: 190 + 125  Add Fee: Site Insp (\$ ) _ s.Rs_si		
Days Of Repair: 15  Typist V: Final Report Resurvey No. of Trip: 2 Survey Fee: 170 + 175  Add Fee: : Site Insp (\$ ) _ s.Rs_si		
Days Of Repair: Survey Fee: 170 + 175  Typist V: Final Report Resurvey No. of Trip: Survey Fee: 170 + 175  Add Fee: :Site Insp (\$ ) _ s.Rs_si 50 + 50  Interview (\$ ) Fixos S		
Days Of Repair: Survey Fee: 170 + 175  Typist V: Final Report Resurvey No. of Trip: Survey Fee: 170 + 175  Add Fee: :Site Insp (\$ ) _ s.Rs_si 50 + 50  Interview (\$ ) Fixos S	REGEIVED 2.5 SEP	2018
Days Of Repair: Survey Fee: 170 + 175  Typist V: Final Report Resurvey No. of Trip: Survey Fee: 170 + 175  Add Fee: :Site Insp (\$ ) _ s.Rs_si 50 + 50  Interview (\$ ) Fixos S		V
Days Of Repair: Survey Fee: 190 + 125  Add Fee: Site Insp (\$ ) _ s.Rs_si		
Days Of Repair: Survey Fee: 190 + 125  Add Fee: Site Insp (\$ ) _ s.Rs_si		
Typist Sime, File Return to?  Resurvey No. of Trip: Survey Fee: 130 + 135  Transportation: 50  Add Fee: Site Insp (\$ )s.rssi	Prell. Report	Days Of Repair:
Add Fee: : Site Insp (\$ ) _ s + Rs _ si	Typist V: Final Report	Postupion No. 4715
Add Fee: : Site Insp (\$ )s - Rssi	ino, File Return to?	170 1 197
rt Format : Interview (\$ ) Fixos (\$ 100 )  Sum / I.B.I: (\$ 9 1120 = 5 ) Others	Add Fe	ee!   Site lear /s
Sum / I.B.I: (S 9 1/20		
Sum / I.B.I: (\$ 9 1/20/	rt Format :	
17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		lech invs (s



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

# MOTOR SURVEY ASSIGNMENT

Date

23-07-2018

Our Ref No. D18005581MFSH

Accident Date

19-07-2018

Claim Type. Third Party

Insured Vehicle

SHB3612J

Third Party Vehicle. SLH6643X

Survey Location

NO. 10 ANG MO KIO IND. PARK 2A #01-09 AMK AUTOPOINT

Contact Person.

EILEEN CHUA

Contact No.

64831244/0

Fax No. 64836170

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

# FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

AH LIM MOTOR

COMPANY

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SITHARA

# IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/	ClaimWS/Surveyor/JobSheet,	/242604) 🛴 P	RI Documents 🚇 Close 🗶		
1	1	3	PRI Header Details		
Claim No	D18005581MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & AH LIM N
Workshop Name	AH LIM MOTOR COMPANY (Contact Person : EILEEN CHUA)	Survey Location & Contact Details	NO. 10 ANG MO KIO IND. I Mobile: 0 , Phone: 64831 EmailId: AHLIMMC@SING	244 , Fax: 64	-09 AMK AUTOF 836170
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE	ADMIT LIABIL	ITY QUANTUM
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3612J	TP Vehicle No	SLH6643X
PRI Recieved Date	23-07-2018 04:03:19 PM	Surveyor Appointed Date	24-07-2018 12:31:17 PM	Surveyor Accept Date	24-07-2018
			Survey Report Upload	-	
Surveyor Inspection Date *:		Surveyor Report Date	24-07-2018	Upload Survey Report *:	Choose File
,			Vehicle Particulars		
Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple Do	cuments Upload				
		Upload Multiple	Documents		
File Name	e			Action	
Surveyor Jo	b Remarks				
Remarks				Save	

# > Back to OneMotoring

# **Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7363F

Vehicle Details

Vehicle No.: SLH6643X

Vehicle to be Exported: Yes

Intended De-registration Date: 20 Jul 2018
Vehicle Make: HYUNDAI

Vehicle Model: ELANTRA AD 1.6 GLS AT

Primary Colour: White Manufacturing Year: 2016

Engine No.: G4FGGU219252

Chassis No.: KMHD841CMHU239588

Maximum Power Output: 93.8 kW (125 bhp)

Open Market Value: \$12,352.00
Original Registration Date: 15 Nov 2016
First Registration Date: 15 Nov 2016

Transfer Count: 0

Actual ARF Paid: \$12,352.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Nov 2026 PARF Rebate Amount: \$9,264.00

Intended COE Rebate Details

COE Expiry Date: 14 Nov 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

 QP Paid:
 \$52,668.00

 COE Rebate Amount:
 \$42,134.00

 Total Rebate Amount:
 \$51,398.00

The information contained herein is correct as at 20 Jul 2018

OK

### Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Wednesday, 25 July 2018 5:42 PM

To:

SITHARA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'

Cc:

ASSIGNMENTS@LKKAUTO.COM; sur@lkkauto.com; 'Nivitha (LKK Auto)'

Subject:

RE: SURVEY ASSESSMENT - D18005581MFSH/1

Attachments:

SLH 6643X - Preli Advise.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLH 6643X.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Tuesday, 24 July 2018 12:51 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM

Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com Subject: RE: SURVEY ASSESSMENT - D18005581MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 24 July 2018 12:31 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18005581MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey. Kindly submit your report via CWS within the next 14 days.

Best Regards, Admin Team Claim Workflow System

Motor Claims Department MS·First Capital Insurance Limited Tel: 6507 3848 Fax: 6507 3849		
PS: This is a system generated mail. Please do not reply to this mail.		
This email has been checked for viruses by AVG antivirus software.  www.avg.com		



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18005581MFSH

Date: 25 July 2018

Our Ref: CS/FCI18013427/Ksd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


# INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 6643X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on <u>24/07/2018</u> at the premises of M/s <u>Ah Lim Motor Company</u> and have the following to report:-

Workshop Estimate Amount	: <u>SS</u>	19,197.80	-
Revised Estimate Amount	: S\$	9,437.88	
"Check" Items Amount	: S\$	1,319.76	
Market Value	: S\$		
LTA Reimbursement Value	: <u>S</u> \$		
Nett Value	: <u>S\$</u>		

### **Description of Damage:**

The vehicle sustained damages at the rear portion.



### Comments/ Present Status:

Damages Consistent. Repair days: 15 Days

Remarks: Pending some parts prices

Yours faithfully, Kenneth Kong Automotive Assessor

#### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

Fax Number Contact Number

**EMail Address** 

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	20/07/2018 10:41	
Date Of Accident	19/07/2018 16:45	
Exact Location Of Accident	TPE (PIE) PUNGGOL ROAD ENTRANCE	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLH6643X	
Insured/Policyholder		
Name Of Registered Owner	CHOON GUOBIN, EUGENE	
NRIC No	S8727363F	
Email Address	EUGENECHOON@GMAIL.COM	
Mobile Phone No	(LOCAL) +65-81231758	
Alternative Phone No	OTHERS-81231758	
Vehicle Particulars		
Manufacturer	HYUNDAI	
Model	ELANTRA AD 1.6 GLS AT	
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE	
Are you claiming under your own insurance policy for repair to your vehicle?	NO	
If No, Please state action to be taken	THIRD PARTY	
Vehicle Category	PRIVATE CAR	
Insurance Company		
Name of Insurance Company	FWD SINGAPORE PTE. LTD.	
Type Of Coverage	COMPREHENSIVE	
Fleet Policy	NO	
Policy Number	PNPV2017-00007381	
Cover Note Number	15/11/2017 - 14/11/2018	
Driver		
Name of Driver	CHOON GUOBIN, EUGENE	
NRIC No	S8727363F	
Date Of Birth	12/09/1987	
Occupation	INDOOR	
Date Of Driving Pass	27/02/2012	
Driving Experience	6 YEARS AND 4 MONTHS	
Gender	MALE	
Mobile Number	(LOCAL) +65-81231758	

OTHERS-81231758

EUGENECHOON@GMAIL.COM

- Approximate Age Injuries Sustain Injured person in which vehicle? Were seat belts worn?

**BACK PAIN** SLH6643X

Was this injured conveyed to hospital by ambulance?

Address

Postcode

#### Sketch Plan Pg. 2

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 20/7/18

930.46

Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/7/18 , 930cm

Reporting Centre Personnel's Signature

NRIC/FIN No.:

### Sketch Plan Pg. 4





2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20180719/7045

I am making this report on behalf of the Taxi uncle who rear ended me. I hope that some kind of assistance can be rendered to him if it is a genuine scam case. I

If you need video evidence of the accident but i cant upload due to the file size. I have it with me if it helps.

Victim	01100110110011100111	AND THE PARTY OF T	HORE-RUNEYS AND THE REAL PROPERTY OF
Person Name	CHOON GUOBIN, EUGENE		
ID Type	NRIC NO	ID No	S8727363F
Gender	Male	Age	30
Race	Chinese	Language	English
Occupation	TEACHER	Address Type	
Address	APT BLK 278B COMPASSVALE BOW #11-561 SINGAPORE 542278	Mobile No	81231758
ls Informant A Victim?	Yes		

Signature Of Officer Recording The Report:	Signature Of Informant: The identity of the person making this
Not applicable	report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 19/07/2018 21:14
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

Addition to damp







CHOON GUOBIN, EUGENE (GONG GUOBIN)





国斌 CHINESE

SINGAPORE

Date of birth 12-09-1987

88727363"

5955865

8123 1758

Hp: 8123 1758

Ement. eygene chain Ogmail. com

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Motor Cars=<3000kg with =<7 passengers, exclusive 27 Feb 2012 of the driver; and other motor vehicles =< 2500kg

Licence No: S8727363F

NP 428A

09-06-2018

APT BLK 278B COMPASSVALE BOW #11-561 SINGAPORE 542278



#### CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2017-00007381 (Comprehensive - Classic Plan)

Car plate number: SLH6643X

Your name (As the policyholder): Choon Guobin Eugene

Coverage start date: 15/11/2017

Coverage end date: 14/11/2018

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

#### Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Maybank

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 19/09/2017

Abhishek Bhatia Chief Executive Officer FWD Singapore Pte Ltd

Shitie

Please immediately inform us at +65-6820-8888 or email us at contact.sg@fwd.com if any details in this Certificate of Insurance need to be changed.



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 GST:M9-0009639-E RCB NO:06470300B

M/S: CHOON GUOBIN, EUGENE

SINGAPORE 542278

BLK 278B COMPASSVALE BOW #11-561

Estimate No:

MC0913284

Date:

20 Jul 2018

Policy No:

PNPV2017-00007381

Veh Reg No:

**SLH6643X** 

Make/Model:

15 days

HYUNDAI ELANTRA

AD 1.6 GLS AT

ATTN:

Not Notherske Resurry BEpeing

Third Party

Accident Date:

Your Ref No: Claim Type:

19/07/2018

TP Veh Reg No:

SHB3612J

Estimate Repair Cost to Vehicle No :SLH6643X

	Description	Qua	ntity	List Pric	e Amount
	CD-DE D-DEC			<u>S\$</u>	<u>S\$</u>
-	SPARE PARTS		0.000	na -	. ~
1	REAR WINDSCREEN MOULDING		1 PC	By 1620.4	
2	REAR BOOT		1 PC	1,020.1	
3	REAR BOOT HINGE LH & RH		2 PC	0	60 ×
4	REAR BOOT INSULATOR		1 PC		
5	REAR BOOT INSULATOR CLIPS X 14		14 PC	1 42.0	
6	REAR BOOT INNER (PULL) HOLDER RH		1 PC	-	00 X
7	REAR BOOT INNER LOCK		1 PC	ne 216.2	
8	REAR BOOT INNER LOCK COVER - CHECK PRICE		1 PC		00 7
9	REAR BOOT INNER LOCK CABLE - CHECK PRICE		1 PC		00 7
10	REAR BOOT LOCK CATCH		1 PC		00 <b>X</b>
11	REAR BOOT SIDE STOPPER RUBBER BIG X 2		2 PC	20.0	00 ×
12	REAR BOOT CLIPS BLACK SMALL X 4 3		4 PC	Ma 40.0	00 —
13	REAR BOOT EMBLEM		1 PC	ne 28.0	00 —
14	REAR BOOT LOGO (ELANTRA) LH		1 PC	Ma 48.8	30 <u> </u>
15	REAR BOOT RUBBER (AT BODY)		1 PC	Dis 100 92.5	
16	REAR BOOT NUMBER PLATE LAMP X 2		2 PC	Su 50.0	00 ×
17	REAR BOOT BUZZER SENSOR - CHECK PRICE		1 PC	NSP 0.0	00 X
18	REAR BOOT LAMP NOT LED LH & RH		2 PC	CM 769.8	30
19	TAILAMP NOT LED X 2		2 PC	CM 925.2	20
20	TAILAMP CLIPS LH & RH		6 PC	Ma 54.0	00 —
21	TAILAMP PANEL LH & RH	NISA	2 PC	386.2	20 4
22	REAR FENDER LH & RH		2 PC	N 3,736.6	0 X
23	REAR FENDER COWLING X 2		2 PC	0	00 🗶
24	REAR FENDER COWLING CLIPS X 16		16 PC	an 48.0	
25	REAR FENDER INNER TRIM X 2		2 PC	SVC × 435.8	80 7
26	REAR FENDER INNER TRIM CLIPS LH & RH		20 PC	nn × 60.0	
27	REAR FENDER AIR VENT LH & RH		2 PC	SVE X 117.8	
28	REAR FENDER LOWER SEAL RUBBER LH & RH - CHECK PRICE		4 PC	SVCX 0.0	
29	REAR FENDER LOWER MUDFLAT X 2	nls dus	2 PC	200	00 4
30	REAR BUMPER		1 PC	By 559.4	55 *
31	REAR BUMPER SIDE RETAINER X 2		2 PC	•	0
32	REAR BUMPER CLIPS X 12		12 PC	4	00
33	REAR BOOT LOWER LIP BLACK		1 PC	1	0 —
34	REAR BUMPER LOWER REFLECTOR X 2	NISIM	2 PC		80 Lt
35	REAR BUMPER REINFORCEMENT	18	1 PC	n	30
36	REAR BUMPER REINFORCEMENT BRACKET X 2		2 PC		00 3
	REAR BUMPER REINFORCEMENT CENTRE BRACKET		3 PC	R×18.0	
31	REAL DOME EN REIN ONCEMENT CENTRE BRACKET		210	10.0	1



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 GST:M9-0009639-E RCB NO:06470300B

M/S: CHOON GUOBIN, EUGENE

SINGAPORE 542278

BLK 278B COMPASSVALE BOW #11-561

MC0913284

Date:

20 Jul 2018

Policy No:

Estimate No:

PNPV2017-00007381

Veh Reg No:

**SLH6643X** 

Make/Model:

HYUNDAI ELANTRA

AD 1.6 GLS AT

ATTN:

Your Ref No:

Claim Type:

Third Party

Accident Date:

19/07/2018

TP Veh Reg No:

SHB3612J

# Estimate Repair Cost to Vehicle No :SLH6643X

	Description	Quantity	List Price	Amount
			S\$	<u>S\$</u>
8	REAR BUMPER LOWER SIDE COVER	1 PC	CM 57.20	
9	REAR BUMPER LOWER SIDE COVER CLIPS LH	8.PC	Mc 24.00	
10	REAR BUMPER LOWER SIDE COVER	1 PC	ÇV € X 25.00	7
11	REAR BUMPER LOWER SIDE COVER CLIPS RH	8 PC	↑↑ ×24.00	7
12	END PANEL	1 PC	479.60	
13	END PANEL TOP GARNISH	1 PC	79.80	
14	END PANEL TOP GARNISH CLIPS X 14	14 PC	Ma 42.00	_
15	END PANEL OUTER SIDE SEAL RUBBER X 2	2 PC	2 SVCX 0.00	7
16	SPARE TYRE PANEL	1 PC	97/Bu 775.20	
17	SPARE TYRE PANEL TOP TRIM BOARD	1 PC	رم 219.10	×
18	SPARE TYRE PANEL TOP GARNISH - CHECK PRICE	1 PC	NSP 0.00	X
19	SPARE TYRE PANEL TOP GARNISH CLIPS X 12	12 PC	NSP 0.00	
50	SPARE TYRE PANEL HOOK - CHECK PRICE	1 PC	CM 0.00	
51	SPARE TYRE PANEL HOOK BRACKET - CHECK PRICE	1 PC	R×0.00	1
52	REAR CHASSIS CENTRE PANEL LH & RH	2 PC	F-X500.60	7
53	REAR CHASSIS FRAME LH & RH	2 PC	R 2,021.80	X
54	REAR EXHAUST BOX	1 PC	n 688.40	×
55	REAR EXHAUST BOX TOP HEAT PLATE	1 PC	FX 118.50	
56	REAR EXHAUST BOX MOUNTING X 4	4 PC	119.20	
		10.00	16,016.00	^
		Less 20%	3,203.20	12,812.80
	Special Nett			
57	REAR REVERSE CAMERA - CHECK PRICE	1 PC	A 3/ 0.0000	X
58	REAR REVERSE RECORDER CAMERA - CHECK PRICE	1 PC	~~ 0.0000	X
9	REAR REVERSE SENSOR X 2	2 PC	Ret 200.00	
0	REAR NUMBER PLATE BLACK	1 PC	R 35.00	_
1	REAR WINDSCREEN SEALANT	1 PC	~~ 50.00	×
2	REAR WINDSCREEN INNER SEAL	1 PC	40.00	X
53	SPRAY TYRE PANEL PROTECTION ANTI-RUST	1 PC	Nec 150.00	80sa
			475.00	475.00
	LABOUR			
4	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL	1 PC		201
	UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.			
5	UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	601
		1 PC 1 EA	80.00 Vn 150.00	100 m



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S: CHOON GUOBIN, EUGENE

SINGAPORE 542278

BLK 278B COMPASSVALE BOW #11-561

Estimate No:

MC0913284

Date:

20 Jul 2018

Policy No:

PNPV2017-00007381

Veh Reg No:

**SLH6643X** 

Make/Model:

HYUNDAI ELANTRA

AD 1.6 GLS AT

ATTN:

Your Ref No:

Claim Type:

Third Party

Accident Date: TP Veh Reg No: 19/07/2018 SHB3612J

Estimate Repair Cost to Vehicle No :SLH6643X

	Description	Quantity	List Price	Amount
68	TO REMOVE & REINSTALL/REPLACE REAR REVERSE CAMERA	1 PC	~~ \frac{\finte}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\fint}}}}}{\frac{\fin}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\fin}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\fin}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\fin}}}}}{\firac{\frac{\frac{\frac{\fin}}}}{\firac{\frac{\frac{\fin}}}}}{\firac{\frac{\fir}{\firighta}}}}}{\frac{\firac{\frac	× <u>ss</u>
69	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. REAR UNDERCARRIAGE	1 PC	380.00	2201
70	TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS. REAR LH	1 PC	120.00	601
71	TO RESET REAR BOOT LOCK BUZZER SENSOR, ENGINE LIGHT	1 PC	<b>N</b> ≈ 280.00	*
72	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	80.00	501
73	TO SPRAY ANTI-RUST COATING ON TAILLAMP PANEL X 2, REAR CHASSIS FRAME, CHASSIS SIDE PANEL X 2, END PANEL, SPARE TYRE PANEL	1 PC	200.00	901
74	TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE. EXHAUST BOX, MOUNTING	1 PC	180.00	1600
75	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL X 2, REAR CHASSIS SIDE PANEL X 2, REAR FENDER X 2(RH/LH), REAR BUMPER REINFORCEMENT BRACKET. TO KNOCK & REPAIR REAR FENDER INNER LH & RH, REAR CHASSIS FRAME LH & RH	1 PC	2,400.00	,
76	TO SPRAY REAR BOOT, REAR BUMPER, REAR BUMPER REINFORCEMENT & BRACKET, TAILLAMP PANEL X 2, END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, REAR FENDER INNER LH & RH, REAR CHASSIS FRAME LH & RH, REAR CHASSIS CENTRE PANEL	1 PC	1,800.00	14001
			5,910.00	5,910.00
			Total	S\$ 19,197.80
		Add G	ST @ 7%	1,343.85
		Total Amou	nt Payable	S\$ 20,541.65

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FIVE HUNDRED FORTY ONE AND CENTS SIXTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ature:

For AH LIM MOTOR COMPANY

AUTHORISED SIGN



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S:

CHOON GUOBIN, EUGENE

SINGAPORE 542278

BLK 278B COMPASSVALE BOW #11-561

Estimate No:

MC0913284

SURVEYOR COP

Date:

20 Jul 2018

Policy No:

PNPV2017-00007381

Veh Reg No:

SLH6643X

Make/Model:

HYUNDAI ELANTRA

AD 1.6 GLS AT

ATTN:

Not Nothern Resourcy BEperry

Claim Type: Accident Date:

Your Ref No:

Third Party 19/07/2018

SHB3612J

TP Veh Reg No:

Estimate Repair Cost to Vehicle No :SLH6643X

	Description Description	cie No :SLF	16643X				
	Description	Q	uantity	I	ist Price	Aı	mount
	SPARE PARTS				<u>S\$</u>		<u>S\$</u>
-1-	REAR-WINDSCREEN-MOULDING-				SI		
2			I-PC		~ 74.20	7	
3	REAR-BOOT-HINGE-LH-&-RH-		1 PC		1,620.40		
4-	REAR-BOOT-INSULATOR-		2.PC	N	1-88-60-	-x-	
5				12	146:80	-X-	
- 6-	REAR-BOOT-INNER-(PULL-)-HOLDER-RH		14 PC	14	72.00		
7	REAR BOOT INNER LOCK		I-PG		15:00	-X-	
	REAR-BOOT-INNER-LOCK-COVER-CHECK-PRICE		1 PC	1101	216.20		
9-	REAR BOOT-INNER-LOCK-CABLE—CHECK-PRICE-		I-PC-	5,	0.00	7	
10-	REAR-BOOT-LOCK-CATCH		I-PC-		0:00		
	-REAR-BOOT-SIDE-STOPPER-RUBBER-BIG-X-2		I-PE-		25.00	X-	
12	REAR BOOT CLIPS BLACK SMALL X * 3		2-PC-		20:00-	-×	
13	REAR BOOT EMBLEM		3 APC	THE .	40.00		
14	REAR BOOT LOGO (ELANTRA) LH		1 PC	- CE	28.00	_	
15	REAR BOOT RUBBER (AT BODY)		1 PC	ne	48.80	_	
1-6-	REAR-BOOT-NUMBER-PLATE-LAMP-X-2			Dis 111	92.50		
-1-7-	-REAR-BOOT-BUZZER-SENSORCHECK-PRICE-		2 PC	54	50.00	X	
18	REAR BOOT LAMP NOT LED LH & RH		I-PC-		0:00-	-X	
19	TAILAMP NOT LED X 2		2 PC	cm	769.80		
	TAILAMP CLIPS LH & RH		2 PC	CM	925.20		
21	TAILAMP PANEL LH & RH	NISA	6 PC	na	54.00		
_22_	REAR FENDER LH & RH	7	2 PC	100	386.20	4	
23	REAR-FENDER-COWLING-X-2		2-PC-		3,736.60		
24	-REAR-FENDER-COWLING-CLIPS-X-16-		—-2-PC-		-1-32.00		
25	REAR FENDER INNER TRIM X 2		-16-PC-	P	-48:00		
26-	-REAR-FENDER-INNER-TRIM-CLIPS-LH-&-RH-		2 PC	Sn	435.80_		
27	REAR FENDER AIR VENT LH & RH		-20-PC-		-60:00-		
-28-	-REAR-FENDER-LOWER-SEAL-RUBBER-LH-&-RHCHECK-PRICE-		2-P.G	Sh	-1-1-7-80		
29	REAR FENDER LOWER MUDFLAT X 2	nls du	-4-PC-	350		7	
30	REAR BUMPER	.5 .007		n	66.00	F ()	
31	REAR BUMPER SIDE RETAINER X 2		1 PC	By	559.40		
32	REAR BUMPER CLIPS X 12		2 PC	Dry	108.60		
33	REAR BOOT LOWER LIP BLACK		12 PC	My	36.00		
34	REAR BUMPER LOWER REFLECTOR X 2	NISTM	I PC	MI	270.10		
35	REAR BUMPER REINFORCEMENT		1 2 PC	By	103.80	4	
36	REAR BUMPER REINFORCEMENT BRACKET X 2		1 PC		394.80		
37	REAR-BUMPER-REINFORGEMENT-GENTRE-BRACKET		2 PC	cm		7	
			-3-PC-	R	<del>-18:00-</del>	7	



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S:

CHOON GUOBIN, EUGENE

SINGAPORE 542278

BLK 278B COMPASSVALE BOW #11-561

Estimate No:

MC0913284

Date:

20 Jul 2018

Policy No:

PNPV2017-00007381

Veh Reg No:

SLH6643X

Make/Model:

HYUNDAI ELANTRA

AD 1.6 GLS AT

ATTN:

Your Ref No:

Claim Type:

Third Party

Accident Date:

19/07/2018

TP Veh Reg No: SHB3612J

Estimate Repair Cost to Vehicle No :SLH6643X

38	Description	Quantity	7 2752 77
38		Quantity	List Price Amount
	REAR BUMPER LOWER SIDE COVER		SS SS
	REAR BUMPER LOWER SIDE COVER CLIPS LH	1 PC	cm = 57.20 -
-40	-REAR-BUMPER-LOWER-SIDE-GOVER	8 PC	Mc 24.00
	-REAR-BUMPER LOWER-SIDE-COVER-CLIPS-RH-	I-PC	25,00 Z
	END PANEL	8-PC-	24.00
	END PANEL TOP GARNISH	1 PC	Br 479.60
	END PANEL TOP GARNISH CLIPS X 14	I PC	79.80
	END-PANEL-OUTER-SIDE-SEAL-RUBBER-X-2-	14 PC	Ma 42.00 _
	SPARE TYRE PANEL	2-PC-	P 0:00 - X
		1 PC	BTIBLE 775.20
	SPARE-TYRE PANEL-TOP-TRIM-BOARD	I-PG-	219.10 ×
48	SPARE-TYRE-PANEL-TOP-GARNISHCHECK-PRICE-	I-PC-	0.00 X
49-	SPARE-TYRE-PANEL-TOP GARNISH CLIPS X-12	12 PC	10.00 X
	SPARE TYRE PANEL HOOK - CHECK PRICE	1 PC	CM 0.00 -
-5	SPARE-TYRE-PANEL-HOOK-BRACKETCHECK-PRICE		R 0.00-1
52	REAR-CHASSIS CENTRE PANEL LH & RH	2 PC	N 500.60 ★
53	REAR-CHASSIS-FRAME-LH-&-RH	2-PC	N 2,021-80→X
	REAR-EXHAUST-BOX-	I-PC	n 688.40 X
	REAR EXHAUST BOX TOP HEAT PLATE		1.18.50-
-56-	REAR-EXHAUST-BOX-MOUNTING-X-4	4-PC-	^
		470	1-19:20-X
		Less 20%	16,016.00
0	Special Nett	LCSS 2076	3,203.20 12,812.80
	A Marine Statement Co.		
-5/	REAR-REVERSE-GAMERACHECK-PRICE-	I-PC	13/ 0.0000 X
-58	REAR-REVERSE-RECORDER-CAMERA - CHECK-PRICE	1-PC	~~ 0.0000_X
	REAR REVERSE SENSOR X 2	2 PC	Res 200.00
	REAR NUMBER PLATE BLACK	1 PC	Ry 35.00
	REAR-WINDSGREEN-SEALANT		1. ~50:00-X
	REAR-WINDSCREEN-INNER-SEAL-		<u> </u>
63	SPRAY TYRE PANEL PROTECTION ANTI-RUST	1 PC	ne 150.00 80sa
ī	LABOUR		475.00 475.00
64	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS	1 PC	40.00 201
1	AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL	(A. F. 27)	10.00
65	UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		.3
66	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00 601
67 7	FO-REMOVE-&-REFIT-REAR-WINDSCREEN-	I-EA-	-na-150:00-X
	FO-REMOVE-&-INSTALL/REPLAGE-REAR-REGORDER-GAMERA	I-PG-	100:00 X



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S:

CHOON GUOBIN, EUGENE

SINGAPORE 542278

BLK 278B COMPASSVALE BOW #11-561

Estimate No:

MC0913284

Date:

20 Jul 2018

Policy No:

PNPV2017-00007381

Veh Reg No:

SLH6643X

Make/Model:

HYUNDAI ELANTRA

AD 1.6 GLS AT

ATTN:

Your Ref No:

Claim Type:

Third Party

Accident Date:

19/07/2018

TP Veh Reg No:

SHB3612J

Estimate Repair Cost to Vehicle No :SLH6643X

	Description	Quantity	List Price	Amount
68-	TO REMOVE-&-REINSTALL/REPLACE-REAR-REVERSE-CAMERA	1.00	na SS	× <u>S\$</u>
69	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. REAR UNDERCARRIAGE	I PC	100.00	2201
	TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS. REAR LH	1 PC	120.00	601
-71-	TO-RESET-REAR-BOOT-LOCK-BUZZER-SENSOR-ENGINE-LIGHT-		~~	*
72	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS	I PC	280:00-	7
73	TO SPRAY ANTI-RUST COATING ON TALL LAMP BANEL V. 2 PEAR	- 1177	80.00	201
	CHASSIS FRAME, CHASSIS SIDE PANEL X 2, END PANEL, SPARE TYRE PANEL	1 PC	200.00	401
74	TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE. EXHAUST BOX, MOUNTING	I PC	180.00	601
75	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL X 2, REAR CHASSIS SIDE PANEL X 2, REAR FENDER X 2(RH/LH), REAR BUMPER	I PC	2,400.00	1600
76	REINFORCEMENT BRACKET. TO KNOCK & REPAIR REAR FENDER INNER LH & RH, REAR CHASSIS FRAME LH & RH TO SPRAY REAR BOOT, REAR BUMPER, REAR BUMPER REINFORCEMENT & BRACKET, TAILLAMP PANEL X 2, END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, REAR FENDER INNER LH & RH, REAR CHASSIS FRAME LH & RH, REAR CHASSIS CENTRE PANEL	1 PC	1,800.00	14001
		**	5.910.00	5 910 00

5,910.00 5,910.00

Total

S\$ 19,197.80 1,343.85

Total Amount Payable

Add GST @ 7%

19206.44

S\$ 20,541.65

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FIVE HUNDRED FORTY ONE AND CENTS SIXTY FIVE ONLY Please arrange this vehicle to be surveyed soonest possible.

Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display demaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Admouledged by Repairor

Signature:

Date:

For AH LIM MOTOR COMPANY

AUTHOR TURE



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S:

CHOON GUOBIN, EUGENE

BLK 278B COMPASSVALE BOW #11-561

SINGAPORE 542278

Estimate No:

MC0913284

Date:

27 Jul 2018

Policy No:

PNPV2017-00007381

Veh Reg No:

SLH6643X

Make/Model:

HYUNDAI ELANTRA

AD 1.6 GLS AT

ATTN:

Your Ref No: Claim Type:

Accident Date:

Third Party 19/07/2018 TP Veh Reg No:

SHB3612J

Estimate Repair Cost to Vehicle No :SLH6643X

Description

Quantity

List Price

Amount

<u>SS</u>

Supplementary Parts to Repair

SPARE PARTS

I SPARE TYRE CENTRE LOCK CLAMP

1 PC

10.80

10.80

Less 20%

2.16

Total

GNATURE

S\$ 8.64

8.64

GST Amount

S\$ 0.60

Total Amount Payable

S\$ 9.24

The above vehicle was surveyed by LKK - KENNETH on 24/07/2018

For AH LIM MO/TOR COMPANY

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



M/S:

CHOON GUOBIN, EUGENE

BLK 278B COMPASSVALE BOW #11-561

SINGAPORE 542278

Claim No:

MC0913284

No:

MF0911282

Date:

05 Sep 2018

Policy No:

PNPV2017-00007381

Veh Reg No:

**SLH6643X** 

Make/Model:

HYUNDAI ELANTRA

AD 1.6 GLS AT

ATTN:

Your Ref No:

Claim Type:

Third Party

Accident Date:

19/07/2018

TP Veh Reg No:

Decembelow

SHB3612J

Repair Cost to Vehicle No (For Finalization):SLH6643X

	Description	Quantity	List Price	Amount
	SPARE PARTS		<u>S\$</u>	<u>S\$</u>
1	REAR BOOT	1.00	G0000120024 50 00V	
2	REAR BOOT INSULATOR CLIPS X 14	I PC	1,620.40	
3	REAR BOOT INNER LOCK	14 PC	42.00	
4	REAR BOOT CLIPS BLACK SMALL	I PC	216.20	
5	REAR BOOT EMBLEM	3 PC	30.00	
6	REAR BOOT LOGO (ELANTRA) LH	I PC	28.00	
7	REAR BOOT RUBBER (AT BODY)	1 PC	48.80	
8	REAR BOOT LAMP NOT LED LH & RH	1 PC	92.50	
9	TAILAMP NOT LED X 2	2 PC	769.80	
10	TAILAMP CLIPS LH & RH	2 PC	925.20	
11	TAILAMP PANEL LH	6 PC	54.00	
12	REAR FENDER LOWER MUDFLAT LH	1 PC	193.10	
13	REAR BUMPER	1 PC	33.00	
14	REAR BUMPER SIDE RETAINER X 2	1 PC	559.40	
15	REAR BUMPER CLIPS X 12	2 PC	108.60	
16	REAR BOOT LOWER LIP BLACK	12 PC	36.00	
17	REAR BUMPER LOWER REFLECTOR LH	I PC	270.10	
18	REAR BUMPER REINFORCEMENT	1 PC	51.90	
19		1 PC	394.80	
20	REAR BUMPER REINFORCEMENT BRACKET	2 PC	12.00	
21	REAR BUMPER LOWER SIDE COVER	1 PC	57.20	
22	REAR BUMPER LOWER SIDE COVER CLIPS LH END PANEL	8 PC	24.00	
23		1 PC	479.60	
24	END PANEL TOP GARNISH	1 PC	79.80	
25	END PANEL TOP GARNISH CLIPS X 14 SPARE TYRE PANEL	14 PC	42.00	
26		1 PC	775.20	
20	SPARE TYRE CENTRE LOCK CLAMP	1 PC	10.800	)
		1,00	6,954.40	
		Less 20% 600	1,390.88	5,563.52
	Special Nett			
27	REAR REVERSE SENSOR X 2	LIV 2PC	200.00	
28	REAR NUMBER PLATE BLACK	No. 10 Appeter Fig. 11	200.00	
29	SPRAY TYRE PANEL PROTECTION ANTI-RUST,	1 PC	35.00	
		Test 60/	80.00	Secret Additional
	LABOUR		315.00	315.00



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S:

CHOON GUOBIN, EUGENE

BLK 278B COMPASSVALE BOW #11-561

SINGAPORE 542278

Claim No:

MC0913284

No:

MF0911282

Date:

05 Sep 2018

Policy No:

PNPV2017-00007381

DRAFT CHIMINGST. OC

Veh Reg No: - SLH6643X

Make/Model HYUNDAI ELANTRA

AD 1.6 GLS AT

ATTN:

Your Ref No: Claim Type:

Third Party

Accident Date: TP Veh Reg No:

19/07/2018

SHB3612J

Repair Cost to Vehicle No (For Finalization):SLH6643X

	Description	Quantity	List Price	Amount
			SS	THE RESERVE ASSESSMENT
30	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	I PC	20.00	<u>SS</u>
31	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	60.00	
32	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. REAR UNDERCARRIAGE	I PC	220.00	
33	TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS. REAR LH	1 PC	60.00	
34	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	50.00	
35	TO SPRAY ANTI-RUST COATING ON TAILLAMP PANEL Y 2 PEAR	100000	50.00	
	CHASSIS FRAME, CHASSIS SIDE PANEL X 2, END PANEL, SPARE TYRE PANEL	I PC	90.00	
36	TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE. EXHAUST BOX, MOUNTING	1 PC	60.00	
37	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL X 2, REAR CHASSIS SIDE PANEL X 2, REAR FENDER X 2(RH/LH), REAR BUMPER REINFORCEMENT BRACKET. TO KNOCK & REPAIR REAR FENDER INNER LH & RH, REAR CHASSIS FRAME LH & RH	I PC	1,600.00	
38	TO SPRAY REAR BOOT, REAR BUMPER, REAR BUMPER REINFORCEMENT & BRACKET, TAILLAMP PANEL X 2, END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, REAR FENDER INNER LH & RH, REAR CHASSIS FRAME LH & RH, REAR CHASSIS CENTRE PANEL	1 PC	1,400.00	
			3,560.00	3,560.00
		0	Γotal	S\$ 9,438.52

\$ 9,438.52 Less Excess S\$ 0.00 Amount Before GST \$\$ 9,438.52 Add GST @ 7% 660.70

Total Amount Payable

\$\$ 10,099.22

TOTAL: SINGAPORE DOLLAR TEN THOUSAND NINETY NINE AND CENTS TWENTY TWO ONLY

The above vehicle was surveyed by LKK - KENNETH on 24/07/2018

For AHLIMMOTOR COMPAN No. 10 Ang Mo Kie Industri #01-09 AMK Autopoint Tel: 6483 (244)

AUTHORISED SIGNATURE



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	ationale Des Experts En Auton	nobile
FIRST CAPITAL INSU	RANCE LTD	Ref : CS/FCI180134	27/Ksd3e2
36 ROBINSON ROAD #16-01 CITY HOUSES		Date: 25-10-2018 Code: FCI2	
	Policy Particula	rs :- THIRD PARTY CLAI	M
Insured Veh.	SHB 3612J	Veh. Inspected	SLH 6643X
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18005581MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	24/07/2018
	Vehicle Pa	rticulars & Condition	
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHD841CMHU239588	Colour	WHITE
Odometer	24430	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	195/65 R15	HANKOOK	7 mm
L/H Front Tyre	195/65 R15	HANKOOK	7 mm
R/H Rear Tyre	195/65 R15	HANKOOK	7 mm
L/H Rear Tyre	195/65 R15	HANKOOK	7 mm
	Descri	ption of Damages	
	ISTAINED DAMAGES AT THE	REAR PORTION.	
DAMAGES SEE I		eral Information	
Accident Date	19/07/2018	Inspection Date	24/07/2018
200		inspection Date	24/01/2010
Survey held at	NO 10 ANG MO KIO IND PK #01-09 AMK AUTOPOINT SINGAPORE 568047	2A	
ia.		Remarks	
B)THE INSPECTI	NSISTENT TO ACCIDENT REF ON WAS CONDUCTED ON A''\ ICE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	

Estimate Days of Repair

15 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 6643X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	74.20	-
1	REAR BOOT	BENT	1,620.40	1,620.40
2	REAR BOOT HINGE LH & RH	TO REPAIR SEE LABOUR	188.60	-
1	REAR BOOT INSULATOR	SERVICEABLE	146.80	=
14	REAR BOOT INSULATOR CLIPS	NECESSARY	42.00	42.00
1	REAR BOOT INNER (PULL) HOLDER RH	SERVICEABLE	15.00	5
1	REAR BOOT INNER LOCK	DENTED	216.20	216.20
1	REAR BOOT INNER LOCK COVER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOT INNER LOCK CABLE (NPA)	SERVICEABLE	-	-
1	REAR BOOT LOCK CATCH	TO REPAIR SEE LABOUR	25.00	-
2	REAR BOOT SIDE STOPPER RUBBER BIG	SERVICEABLE	20.00	-
4	REAR BOOT CLIPS BLACK SMALL	NECESSARY-3PCS ONLY	40.00	30.00
1	REAR BOOT EMBLEM	NECESSARY	28.00	28.00
1	REAR BOOT LOGO (ELANTRA) LH	NECESSARY	48.80	48.80
1	REAR BOOT RUBBER (AT BODY)	DISTORTED / DENTED	92.50	92.50
2	REAR BOOT NUMBER PLATE LAMP	SERVICEABLE	50.00	-
1	REAR BOOT BUZZER SENSOR (NPA)	NO SUCH PARTS	-	
2	REAR BOOT LAMP NOT LED LH & RH	CRACKED	769.80	769.80
2	TAILLAMP NOT LED	CRACKED	925.20	925.20
6	TAILLAMP CLIPS LH & RH	NECESSARY	54.00	54.00
2	TAILLAMP PANEL LH & RH	N/S BENT	386.20	193.10
2	REAR FENDER LH & RH	TO REPAIR SEE LABOUR	3,736.60	-
2	REAR FENDER COWLING	SERVICEABLE	132.00	
16	REAR FENDER COWLING CLIPS	NOT NECESSARY	48.00	-
2	REAR FENDER INNER TRIM	SERVICEABLE	435.80	-
20	REAR FENDER INNER TRIM CLIPS LH & RH	NOT NECESSARY	60.00	-
2	REAR FENDER AIR VENT LH & RH	SERVICEABLE	117.80	

Report Ref No. CS/FCI18013427/Ksd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
4	REAR FENDER LOWER SEAL RUBBER LH & RH (NPA)	SERVICEABLE	-	-
2	REAR FENDER LOWER MUDFLAT	N/S CUT	66.00	33.00
1	REAR BUMPER	BENT	559.40	559.40
2	REAR BUMPER SIDE RETAINER	DISTORTED	108.60	108.60
12	REAR BUMPER CLIPS	NECESSARY	36.00	36.00
1	REAR BOOT LOWER LIP BLACK	MISSING	270.10	270.10
2	REAR BUMPER LOWER REFLECTOR	N/S CRACKED	103.80	51.90
1	REAR BUMPER REINFORCEMENT	BENT	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET	CRACKED	12.00	12.00
3	REAR BUMPER REINFORCEMENT CENTRE BRACKET	TO REPAIR SEE LABOUR	18.00	
1	REAR BUMPER LOWER SIDE COVER	CRACKED	57.20	57.20
8	REAR BUMPER LOWER SIDE COVER CLIPS LH	NECESSARY	24.00	24.00
1	REAR BUMPER LOWER SIDE COVER	SERVICEABLE	25.00	
8	REAR BUMPER LOWER SIDE COVER CLIPS RH	NOT NECESSARY	24.00	
1	END PANEL	BENT	479.60	479.60
1	END PANEL TOP GARNISH	MTG DISTORTED	79.80	79.80
14	END PANEL TOP GARNISH CLIPS	NECESSARY	42.00	42.00
2	END PANEL OUTER SIDE SEAL RUBBER (NPA)	SERVICEABLE	-	
1	SPARE TYRE PANEL	BENT / BUCKLED	775.20	775.20
1	SPARE TYRE PANEL TOP TRIM BOARD	SERVICEABLE	219.10	
1	SPARE TYRE PANEL TOP GARNISH (NPA)	NO SUCH PARTS	-	
12	SPARE TYRE PANEL TOP GARNISH CLIPS (NPA)	NO SUCH PARTS	-	
1	SPARE TYRE PANEL HOOK (NPA)	CRACKED	-	
1	SPARE TYRE PANEL HOOK BRACKET (NPA)	TO REPAIR SEE LABOUR		,
2	REAR CHASSIS CENTRE PANEL LH & RH	TO REPAIR SEE LABOUR	500.60	,
2	REAR CHASSIS FRAME LH & RH	TO REPAIR SEE LABOUR	2,021.80	
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	688.40	
1	REAR EXHAUST BOX TOP HEAT PLATE	TO REPAIR SEE LABOUR	118.50	,
4	REAR EXHAUST BOX MOUNTING	SERVICEABLE	119.20	

Report Ref No. CS/FCI18013427/Ksd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SPARE TYRE CENTRE LOCK CLAMP (ADDITIONAL)	CRACKED	10.80	10.80
	LESS 20% DISCOUNT		-3,205.36	-1,390.88
			12,821.44	5,563.52
	SPECIAL NETT ITEMS			
1	REAR REVERSE CAMERA (SN) (NPA)	NO SUCH PARTS		2
1	REAR REVERSE RECORDER CAMERA (SN) (NPA)	NOT NECESSARY	-	-
2	REAR REVERSE SENSOR (SN)	DENTED	200.00	200.00
1	REAR NUMBER PLATE BLACK (SN)	BENT	35.00	35.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	=
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	40.00	-
1	SPARE TYRE PANEL PROTECTION ANTI-RUST (SN)	NECESSARY	150.00	80.00
			475.00	315.00
	LABOUR			
	TO REMOVE & REINSTALL / REPLACE REAR REVERSE CAMERA.	NOT NECESSARY	100.00	=
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	150.00	
	TO REMOVE & INSTALL / REPLACE REAR RECORDER CAMERA.	NOT NECESSARY	100.00	
	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. REAR UNDERCARRIAGE.		380.00	220.00
	TO REMOVE AND REINSTALL / REPLACE FUEL TANK, FIXTURE AND ATTACMENTS. REAR LH		120.00	60.00
	TO RESET REAR BOOT LOCK BUZZER SENSOR, ENGINE LIGHT.	NOT NECESSARY	280.00	-
	TO REMOVE AND REINSTALL / REPLACE REAR BUMPER SENSORS.		80.00	50.00
	TO SPRAY ANTI-RUST COATING ON TAILLAMP PANEL X2, REAR CHASSIS FRAME, CHASSIS SIDE PANELX2, END PANEL, SPARE TYRE PANEL.		200.00	90.00
	TO REALIGN, DISMANTLE AND REINSTALL / REPLACE EXHAUST PIPE, EXHAUST BOX, MOUNTING.		180.00	60.00

Report Ref No. CS/FCI18013427/Ksd3e2



RECOMMENDED COST OF REPAIRS

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

9,438.52

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL X2, REAR CHASSIS SIDE PANEL X2, REAR FENDER X2 (RH/LH), REAR BUMPER REINFORCEMENT BRACKET. TO KNOCK & REPAIR REAR FENDER INNER LH & RH, REAR CHASSIS FRAME LH & RH. INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE LH & RH, REAR BOOT INNER LOCK COVER, REAR BOOT LOCK CATCH, REAR FENDER LH & RH, REAR BUMPER REINFORCEMENT CENTRE BRACKET, SPARE TYRE PANEL HOOK BRACKET, REAR CHASSIS CENTRE PANEL LH & RH, }		2,400.00	1,600.00
	REAR CHASSIS FRAME LH & RH, REAR EXHAUST BOX AND REAR EXHAUST BOX TOP HEAT PLATE. }		-	-
	TO SPRAY REAR BOOT, REAR BUMPER, REAR BUMPER REINFORCEMENT & BRACKET, TAILLAMP PANEL X2, END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, REAR FENDER INNER LH & RH, REAR CHASSIS FRAME LH & RH, REAR CHASSIS CENTRE PANEL.		1,800.00	1,400.00
			5,910.00	3,560.00
	GRAND TOTAL		19,206.44	9,438.52

Report Ref No. CS/FCI18013427/Ksd3e2

KONG SENG CHEONG

**Licensed Appraiser**