

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18013440/DEA3Q2

Date: 31/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994844

Claimant
Vehicle No : SHA8236J **Insured Vehicle No :** SLT8974P

Date of Loss: 21/07/2018 Nature of Claim: TP Claim No: 0905189693SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA8236J	Engine No:	D4DFDU539885
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU077289
Reg. Date:	17/09/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	60,739.52	34,852.28	25,887.24	42.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,960.00	3,020.00	2,940.00	49.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	66,699.52	37,872.28	28,827.24	43.22
Approved Total (Overridden) (S\$)		26,215.00		
Nett Amount (S\$)	66,699.52	26,215.00	40,484.52	60.70
+ Loss of Use (20.0 x S\$50.00/day) (S\$)		1,000.00		
+ Car Rental (20.0 x S\$115.00/day) (S\$)		2,300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		29,522.45		
Global Sum Settlement (S\$)		29,500.00		

INSPECTION

Date of Assignment: 23/07/2018

Date Inspected: 27/07/2018 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A,
#03-19 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 20.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	1,526.00 FL	*1,526.00 FL
2	1		*BONNET RUBBER (LH)	Serviceable	19.80 FL	*- FL
3	1		*BONNET RUBBER (RH)	Serviceable	19.80 FL	*- FL
4	2		*BONNET HINGE (LH/RH)	Bent	182.60 FL	*182.60 FL
5	1		*BONNET LOCK	Bent	50.90 FL	*50.90 FL
6	1		*BONNET INSULATOR	Bent	243.00 FL	*243.00 FL
7	1		*BONNET INSULATOR CLIPS	Necessary	8.40 FL	*8.40 FL
8	1		*RADIATOR GRILLE	Broken	1,480.00 FL	*1,480.00 FL
9	1		*RADIATOR GRILLE H EMBLEM	Necessary	290.80 FL	*290.80 FL
10	1		*RADIATOR GRILLE CHROME MOULDING	Broken	395.50 FL	*395.50 FL
11	1		*FRONT BUMPER COVER	Broken	1,052.20 FL	*1,052.20 FL
12	1		*FRONT BUMPER SPONGE	Torn	142.20 FL	*142.20 FL
13	1		*FRONT BUMPER REINFORCEMENT	Buckled	526.10 FL	*526.10 FL
14	1		*FRONT BUMPER GRILLE (LH/RH)	O/S Deformed /N/S Serviceable	571.00 FL	*285.50 FL
15	2		*FRONT BUMPER GRILLE AIRDUCT (LH/RH)	Mtg Cracked	310.00 FL	*310.00 FL
16	1		*FRONT BUMPER LIP	Torn	62.50 FL	*62.50 FL
17	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Serviceable	44.80 FL	*- FL
18	1		*FRONT BUMPER RETAINER MOUNTING	O/S Broken / N/S Serviceable	18.40 FL	*9.20 FL
19	1		*HEADLAMP SUPPORT TOP COVER	Broken	398.00 FL	*398.00 FL
20	1		*HEADLAMP SUPPORT PANEL ASSY	Dented	1,067.50 FL	*1,067.50 FL
21	2		*HEADLAMP (LH/RH)	Broken	2,776.00 FL	*2,776.00 FL
22	1		*RADIATOR	Punctured	850.20 FL	*850.20 FL
23	1		*RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY	Broken	792.95 FL	*792.95 FL
24	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
25	1		*RADIATOR HOSE UPPER	Deformed	47.40 FL	*47.40 FL
26	1		*RADIATOR HOSE LOWER	Not Necessary	47.40 FL	*- FL
27	1		*RADIATOR EXPANSION TANK	Broken	48.00 FL	*48.00 FL
28	2		*RADIATOR GUARD	Broken	70.00 FL	*70.00 FL
29	2		*HORN UNIT (LH/RH)	Broken	173.50 FL	*173.50 FL
30	1		*HORN WIRE	Torn	156.50 FL	*156.50 FL
31	2		*FRONT FENDER (LH/RH)	Dented	1,238.00 FL	*1,238.00 FL
32	1		*FRONT FENDER APRON PANEL (LH/RH)	O/S Dented / N/S Repair	3,151.00 FL	*1,575.50 FL
33	2		*FRONT FENDER SHIELD (LH/RH)	O/S Dislodged / N/S Torn	339.60 FL	*339.60 FL
34	2		*FRONT FENDER RETAINER	Not Necessary	18.40 FL	*- FL
35	1		*AIR CLEANER ASSY	Broken	188.00 FL	*188.00 FL
36	1		*AIR DUCT	Broken	206.05 FL	*206.05 FL
37	1		*AIR FLOW SENSOR	Broken	633.35 FL	*633.35 FL
38	1		*RESONATOR TANK HOSE	Not Necessary	261.95 FL	*- FL
39	1		*AIRCON BLOWER MOTOR UNIT	Not Necessary	1,115.50 FL	*- FL
40	1		*AIRCON SENSOR PRESSURE-SUC/LIQ	Not Necessary	244.10 FL	*- FL
41	1		*AIRCON CONDENSER	Bent	1,137.35 FL	*1,137.35 FL
42	1		*AIRCON RECEIVER	Not Necessary	71.50 FL	*- FL
43	1		*AIRCON SUCTION & LIQUID HOSE	Bent	658.90 FL	*658.90 FL
44	1		*AIRCON BLOWER MOTOR	Not Necessary	619.00 FL	*- FL
45	1		*AIRCON COMPRESSOR	Distorted	2,857.55 FL	*2,857.55 FL
46	1		*AIRCON EVAPORATION COIL & HEATER UNIT	Not Necessary	2,492.40 FL	*- FL
47	1		*FRONT WINDSCREEN GLASS	Cracked	1,059.25 FL	*1,059.25 FL
48	1		*FRONT WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*WIPER CONTAINER	Broken	61.90 FL	*61.90 FL
50	1		*WIPER CONTAINER MOTOR	Damaged	65.90 FL	*65.90 FL
51	1		*FRONT WHEEL RIM (RH)	Not Necessary	351.90 FL	*- FL
52	1		*FRONT WHEEL HUB CAP (RH)	Not Necessary	150.70 FL	*- FL
53	1		*FRONT WHEEL BEARING	Damaged	258.50 FL	*258.50 FL
54	1		*FRONT WHEEL ABSORBER (ASSY) (RH)	Distorted	342.20 FL	*342.20 FL
55	1		*FRONT WHEEL ABSORBER MOUNTING (RH)	Not Necessary	75.10 FL	*- FL
56	1		*FRONT DRIVE SHAFT (RH)	Damaged	1,069.55 FL	*1,069.55 FL
57	1		*RACK & PINION ASSY	Damaged	2,184.00 FL	*2,184.00 FL
58	1		*STG & TIE END	Distorted	69.50 FL	*69.50 FL
59	1		*STABILIZER BAR	Distorted	252.30 FL	*252.30 FL
60	1		*STABILIZER BAR BUSH (RH)	Not Necessary	16.10 FL	*- FL
61	1		*STABILIZER BAR LINK	Distorted	81.70 FL	*81.70 FL
62	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	*- FL
63	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	715.10 FL	*715.10 FL
64	1		*FRONT CHASSIS MEMBER	Bent	1,575.85 FL	*1,575.85 FL
65	1		*KNUCKLE ARM (RH)	Distorted	582.95 FL	*582.95 FL
66	1		*ENGINE UNDER COVER	Broken	343.10 FL	*343.10 FL
67	1		*ENGINE CROSSMEMBER	Distorted	2,236.90 FL	*2,236.90 FL
68	1		*GEARBOX	Not Necessary	14,808.00 FL	*- FL
69	1		*GEARBOX MOUNTING	Not Necessary	342.50 FL	*- FL
70	1		*INTER COOLER	Punctured	921.90 FL	*921.90 FL
71	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	*- FL
72	1		*ABS SENSOR ,RH	Not Necessary	261.50 FL	*- FL
73	1		*AUTO GEAR OIL	Not Necessary	110.40 FL	*- FL
74	1		*AIRBAG COMPLETE	Activated	2,948.50 FL	*2,948.50 FL
75	1		*AIRBAG CONTROL MODULE	Activated	1,894.00 FL	*1,894.00 FL
76	1		*STEERING ANGLE ASSY	Not Necessary	1,150.60 FL	*- FL
77	1		*SENSOR ASSY IMPACT -FRT INPACT	Activated	1,180.50 FL	*1,180.50 FL
78	2		*AIRBAG SENSOR	Not Necessary	1,160.00 FL	*- FL
79	1		*ELECTRIC POWER STEERING	Not Necessary	4,880.50 FL	*- FL
80	1		*FRONT NUMBER PLATE	Broken	25.00 FS	*25.00 FS
81	1		*FRONT NO PLATE TRIM COVER	Bent	30.00 FS	*30.00 FS
82	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
83	1		*FRONT ERP STICKER	Necessary	26.00 FS	*26.00 FS
84	1		*FRONT TYRE (RH)	Not Necessary	216.00 FS	*- FS
85	1		*BATTERY TRAY	Broken	55.45 FL	*55.45 FL
86	1		*ACTUATOR -SWIRL CONTROL	Broken	835.10 FL	*835.10 FL
87	1		*FAN BELT IDLE PULLEY	Broken	189.50 FL	*189.50 FL
88	1		*FAN BELT	Torn	155.00 FL	*155.00 FL
89	1		*SOLENOID VALVE	Broken	443.40 FL	*443.40 FL
90	2		*FRT SAFETY BELT (ASSY) (LH/RH)	Activated	1,145.30 FL	*1,145.30 FL
91	2		*FRONT SEAT ADJUSTER (OUTER) (LH/RH)	Activated	900.00 FL	*900.00 FL
92	1		*AIRBAG CONTROL MODULE	Repeated	1,894.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 75,838.65 43,533.60
- List Item Discount on L Items 20.00/20.00% (\$\$) 15,099.13 8,681.32

Total Parts (\$\$) 60,739.52 34,852.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	2,000.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,200.00	800.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	60.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
9	REMOVE/REFIX ENGINE/GEARBOX	New	650.00	80.00
10	REMOVE/REFIX DASHBOARD	New	450.00	180.00
11	REMOVE/REFIX FUSE BOX	New	180.00	50.00
12	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
13	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	0.00
14	RE-PROGRAMME AIR BAG & SAFETY BELT SYSTEM	New	550.00	250.00
Gross Labour Cost (\$\$)			5,960.00	3,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >