

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

AIG

VEHICLE NO : SHA 8236J

DATE : 23.07.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>Bnc</i>			\$ 1,526.00	✓
	Bonnet Rubber (LH) <i>SLC</i>			\$ 19.80	X
	Bonnet Rubber (RH) <i>SLC</i>			\$ 19.80	X
	Bonnet Hinge (LH/RH) <i>Bt</i>		\$ 91.30	\$ 182.60	✓
	Bonnet Lock <i>Bt</i>			\$ 50.90	✓
	Bonnet Insulator <i>Bt</i>			\$ 243.00	✓
	Bonnet Insulator Clips <i>Hke</i>			\$ 8.40	✓
	Radiator Grille <i>broken</i>			\$ 1,480.00	✓
	Radiator Grille H Emblem <i>Nuc</i>			\$ 290.80	✓
	Radiator Grille Chrome Moulding <i>broken</i>			\$ 395.50	✓
	Front Bumper Cover <i>broken</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>torn</i>			\$ 142.20	✓
	Front Bumper Reinforcement <i>Bnc</i>			\$ 526.10	✓
	Front Bumper Grille (LH/RH) <i>o/s deformed N/S SLC</i>	\$	285.50	\$ 571.00	✓
	Front Bumper Grille Airduct (LH/RH) <i>st mounting crack</i>	\$	155.00	\$ 310.00	X ✓
	Front Bumper Lip <i>torn</i>			\$ 62.50	✓
	Front Bumper Bracket Top (LH/RH) <i>SLC</i>	\$	22.40	\$ 44.80	X
	Front Bumper Retainer Mounting <i>o/s broken N/S SLC</i>	\$	9.20	\$ 18.40	✓
	Headlamp Support Top Cover <i>broken</i>			\$ 398.00	✓
	Headlamp Support Panel Assy <i>Dented</i>			\$ 1,067.50	✓
	Headlamp (LH/RH) <i>broken</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>& punctured</i>			\$ 850.20	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>& broken</i>			\$ 792.95	✓
	Radiator Bracket (RH/LH) <i>NH</i>	\$	6.50	\$ 13.00	X
	Radiator Hose Upper <i>& deformed</i>			\$ 47.40	✓
	Radiator Hose Lower <i>NH</i>			\$ 47.40	X
	Radiator Expansion Tank <i>broken</i>			\$ 48.00	✓
	Radiator Guard <i>broken</i>	\$	35.00	\$ 70.00	✓
	Horn Unit (LH/RH) <i>broken</i>	\$	86.75	\$ 173.50	✓
	Horn Wire <i>& torn</i>			\$ 156.50	✓
	Front Fender (LH/RH) <i>Dented</i>	\$	619.00	\$ 1,238.00	✓
	Front Fender Apron Panel (LH/RH) <i>o/s Dented N/S R/V</i>	\$	1,575.50	\$ 3,151.00	✓
	Front Fender Shield (LH/RH) <i>o/s deformed N/S torn</i>	\$	169.80	\$ 339.60	✓
	Front Fender Retainer <i>NH</i>	\$	9.20	\$ 18.40	X
	Air Cleaner Assy <i>& broken</i>			\$ 188.00	✓
	Air Duct <i>broken</i>			\$ 206.05	✓
	Air Flow Sensor <i>& broken</i>			\$ 633.35	✓
	Resonator Tank Hose <i>NH</i>			\$ 261.95	X
	Aircon Blower Motor Unit <i>NH</i>			\$ 1,115.50	X
	Aircon Sensor Pressure - Suc/Liq <i>NH</i>			\$ 244.10	X
	Aircon Condenser <i>Bt</i>			\$ 1,137.35	✓
	Aircon Receiver <i>NH</i>			\$ 71.50	X
	Aircon Suction & Liquid Hose <i>& Bt</i>			\$ 658.90	✓
	Aircon Blower Motor <i>NH</i>			\$ 619.00	X
	Aircon Compressor <i>NH dist. 4.5A</i>			\$ 2,857.55	✓
	Aircon Evaporation Coil & Heater Unit <i>NH</i>			\$ 2,492.40	X

SHA 8236J

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 1200/-
	Spray Painting Charge			\$ 1,200.00 800/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 100.00 60/-
	Towing Charge			\$ 50.00 114
	Remove/Refix Undercarriage (FRT)			\$ 200.00 2150/-
	FRT Wheel Alignment			\$ 120.00 760/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80/-
	Remove/Refix Engine/Gearbox			\$ 650.00 200/-
	Remove/Refix Dashboard			\$ 450.00 114
	Remove/Refix Fuse Box			\$ 180.00 114
	Remove/Refix Front Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 114
	Re-programme Air Bag & Safety Belt System			\$ 550.00 250/-
	TOTAL LABOUR			\$ 5,960.00
	ESTIMATE TOTAL			\$ 62,205.32
	27/07/2018 @ 1320h Not done 2/3rd 18 days <u>rya</u> LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

REPAIR ESTIMATE*

VEHICLE NO : SHA 8236J (Supplementary)

DATE : 3.08.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Battery Tray broken			\$ 55.45
	Actuator - Swirl Control broken			\$ 835.10
	Fan Belt Idle Pulley broken			\$ 189.50
	Fan Belt torn			\$ 155.00
	Solenoid Valve broken			\$ 443.40
	Frt Safety Belt (Assy) (LH/RH) actuated		\$ 572.65	\$ 1,145.30
	Front Seat Adjuster (Outer) (LH/RH) actuated		\$ 450.00	\$ 900.00
	Airbag Control Module activated			\$ 1,894.00
	SUB TOTAL			\$ 5,617.75
	LESS 20%			\$ 1,123.55
	DISCOUNTED TOTAL			\$ 4,494.20
	 Ryan			
	 LKK Auto			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.