

59061

ASSIGNMENT

23/07/2018

Registered in Merimen:

Pre-assign / CCU / FTE



"VIRTUAL"

940000000

Name of Insured :

VOLATILITY TRADING

Claim No. :

Policy No. :

Insured Tel No. _____

HP:

Make / Model :

Excess Sec II :SS

D.O.A: 28/8/18

Place of Accident

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

UPHANA MORTUARY IN MADRAS AND

OI GLA REPORT

YES / NO ; TP GLA REPORT: YES / NO

Driver Tel No. :

911688203 (V/L: YES)


Insured Liability :

%	Final? Yes / No
100	Yes
90	Yes
80	Yes
70	Yes
60	Yes
50	Yes
40	Yes
30	Yes
20	Yes
10	Yes
0	Yes

COL 5906J



Autopsy
Report
Confidential



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS;
WSP;
Tel :
Liability ;
RMKS:

Date/ Time		STAGE		DATE / PIC	
22/12		Non-Reporting ltr (1st):			
17/12		Non-Reporting ltr (2nd):			
SALES J- 14/01/16 12525/r3 100A 2/1/16		Non-Reporting ltr (Final):			
Ym 834111 - x		Notification ltr (if non-pickup):			
		Call OI:			
		After call ltr to OI:			
		Documentation Check List:		Handler	Typist
		Notification ltr (if non-pickup)		☐	☐
		After call ltr to OI:		☐	☐
		Authorisation To Act:		☐	☐
		Release Voucher:		☐	☐
		Final Repair Bill:		☐	☐
		Car Rental Invoice:		☐	☐
		Towing Invoice		☐	☐
		LTA / GIA :		☐	☐
		Medical Bill:		☐	☐
		PIR:		☐	☐
		Mandate/Reject Instruction:		☐	☐
		LOD		☐	☐
		Payment Breakdown Form:		☐	☐
		Post-Repair Photos:		☐	☐
		Others:		☐	☐
Instruction From AXA to reject TP claim based on damage.					
TP have provided the first vehicle reported. However, AXA to maintain our rejection.					
RECEIVED 10 OCT 2018					
PRELIMINARY ADVICE	Date/Time: 22/12/18	Sent By: John Cullen			
FINALIZATION	Date/Time:	Confirm with:	Confirm by:		
Repair Cost:	SS () days	Reduction: %	Email	☐	Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email	☐	Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :		
Repair Cost:	SS				
Loss of Rental (LOR):	SS () days				
Loss of Use (LOU):	SS (\$ x days)				
Loss of Income (LOI):	SS (\$ x days)				
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)					
GIA/LTA Search	SS				
Medical:	SS		1) Claim status: Normal/Reject/Private Settle		
Disbursement:	SS (e.g. Tow/ Independent)		2) Report Format:		
Legal Cost	SS		3) Survey fee: 9350.00		
Total:	SS	Global Sum SS:			
FINAL PAYMENT	Date/Time:	Confirm with:	Email	☐	Call ☐
Payee 1:	SS	Name 1:			
Payee 2: (Strike if N.A.)	SS	Name 2:			
Payee 3: (Strike if N.A.)	SS	Name 3:			

89593

Lump Sum / I.B.I: (\$)

☐ Weekend (\$)

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1807-066

DATE : 20-Jul-2018

POLICY NO. : DIRECTASIA MT/00483001

VEHICLE REG. NO. : SDL5900J

VEHICLE MAKE : MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

TO Motor Claim Department

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Tel: 1800-880-4741

Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Bumper	1	\$ 880.00	\$ DE ✓ 880.00
2	Front Bumper Clips	10	\$ 5.00	\$ m ✓ 50.00
3	Front Reinforcement	1	\$ X 480.00	\$ X SE 480.00
4	Front Bumper Retainer RH	1	\$ X 30.00	\$ SM X 30.00
5	Front Bumper Retainer LH	1	\$ X 30.00	\$ SM X 30.00
6	Front Radiator Upper Panel	1	\$ X X AM 180.00	\$ DE X 180.00
7	Front Grille	1	\$ 150.00	\$ CRA ✓ 150.00
8	Front Grille Bracket RH	1	\$ 30.00	\$ m ✓ 30.00
9	Front Grille Bracket LH	1	\$ 30.00	\$ m ✓ 30.00
10	Front Grille Chrome Moulding LH	1	\$ 200.00	\$ CRA ✓ 200.00
11	Front Grille Black Moulding LH	3	\$ X 40.00	\$ X AM ✓ 120.00
12	Front Grille Black Long Moulding	3	\$ X 70.00	\$ X AM ✓ 210.00
13	Front Emblem	1	\$ 60.00	\$ m ✓ 60.00
14	Front Emblem Base	1	\$ 30.00	\$ m ✓ 30.00
15	Front License Plate Garnish	1	\$ 80.00	\$ DE ✓ 80.00
16	Head Lamp LH	1	\$ CRA / 3,600.00	\$? 3,600.00
17	Head Lamp Upper Bracket LH	1	\$ X 20.00	\$ X AM ✓ 20.00
18	Head Lamp Lower Bracket LH	1	\$ X 20.00	\$ X AM ✓ 20.00
19	Front Center Brace	1	\$ X 40.00	\$ X AM ✓ 40.00
20	Front Support Panel	1	\$ X 480.00	\$ X AM ✓ 480.00
21	Rear Bumper	1	\$ 1,080.00	\$ DE ✓ 1,080.00
22	Rear Bumper Clips	10	\$ 5.00	\$ m ✓ 50.00
23	Rear Reinforcement	1	\$ 580.00	\$ X AM ✓ 580.00
24	Rear Bumper Retainer RH	1	\$ 40.00	\$ m ✓ 40.00
25	Rear Bumper Retainer LH	1	\$ X 40.00	\$ X AM 40.00
26	Rear Bumper Bracket	1	\$ 50.00	\$ m ✓ 50.00
27	Rear Bumper Reflector RH	1	\$ 60.00	\$ CRA ✓ 60.00
28	Rear Bumper Tow Eye Cover RH	1	\$ 20.00	\$ m ✓ 20.00
29	Rear Fender RH	1	\$ 1,200.00	\$ X AM ✓ 1,200.00
30	Rear Fender Shield RH	1	\$ X 150.00	\$ X AM 150.00
31	Rear Fender Clip	10	\$ 5.00	\$ m ✓ 50.00
32	End Panel	1	\$ X 380.00	\$ X AM ✓ 380.00



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1807-066
DATE : 20-Jul-2018
POLICY NO. : DIRECTASIA MT/00483001
VEHICLE REG. NO. : SDL5900J
VEHICLE MAKE : MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

RASUL - HP 90010068
9 days - Lumpsum
24/07/18 @ 1230
Repay after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
33	End Panel Garnish 9085	1	\$ X 100.00	\$ X 100.00
34	Tail lamp RH 2090	1	\$ 900.00	\$ 900.00
35	Boot lamp RH 7268	1	\$ X 450.00	\$ X 450.00
36	Rear Windscreen Molding	1	\$ 80.00	\$ 80.00
Total Spare Parts				\$ 11,950.00
SPECIAL NETT				
37	Front License Plate	1	\$ 40.00	\$ CPA 40.00 35
38	Rear Windscreen Sealant	1	\$ 40.00	\$ me 40.00
39	Front Grille Moulding 653	1	\$ 60.00	\$ CPA 60.00 40
40	Front Center Chrome Moulding	1	\$ 60.00	\$ CPA 60.00 40
41	Rear Reflector Chrome Moulding RH	1	\$ 60.00	\$ MTS 60.00 40
42	Rear Bootlamp Chrome Moulding RH	1	\$ 60.00	\$ SCR 60.00 30
43	Rear Reverse Sensor *	1	\$ (supp) 200.00	\$ X 200.00
44	Nano Ceramic Coating	1	\$ 428 600.00	\$? 600.00
Total Special Nett				\$ 1,120.00
LABOUR 1950				
45	Spray painting Whole Front and Rear	1	\$ 1,200.00	\$ 800 1,200.00
46	Repair, Replace and Refill Affected Accident Area	1	\$ 1,200.00	\$ 800 1,200.00
47	Remove and Refit A/C Condenser, Radiator including A/C Gas	1	\$ 100.00	\$ M X 100.00
48	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 60 100.00
49	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
50	Reset, Check Fault and Resyncing	1	\$ 180.00	\$ 80 180.00
51	Remove and Replace Rear Reverse Sensor	1	\$ 80.00	\$ 60 80.00
52	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

Total Labour	\$ 3,010.00
Amount Before Excess	\$ 16,080.00
Add GST @ 7%	1,125.60
Total Amount Payable	\$ 17,205.60

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

- To display damaged parts before repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-7268
Supp - 720
S/N - 653
L - 1950
T - 10,591
20%
8472.80
43-8450
9 days

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

**Supplementary
Estimate**

ESTIMATE NO. : EST1807-066 (SUP)

DATE : 25-Jul-2018

POLICY NO. : DIRECTASIA MT/00483001

VEHICLE REG. NO. : SDL5900J

VEHICLE MAKE : MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

TO Motor Claim Department

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Tel: 1800-880-4741

Fax: 6880 4740

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Radiator Grille Panel	1	\$ 350.00	\$ 350.00
2	Radiator Grille Top Bracket	1	\$ 70.00	\$ 70.00
3	Front Support Seal Plate Center	1	\$ 80.00	\$ 80.00
4	Reverse Sensor (Original)	2	\$ 200.00	\$ 400.00
Total Spare Parts				\$ 900.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ -
Amount Before Excess	\$ 900.00
Add GST @ 7%	63.00
Total Amount Payable	\$ 963.00

900
20%
720

raymond@automotiverepaircentre.com.sg

From: raymond@automotiverepaircentre.com.sg
Sent: Friday, 20 July 2018 3:26 PM
To: 'motor.survey@axa.com.sg'
Cc: 'Lin Shu Juan'
Subject: SDL5900J - TP Claim against YM8541M
Attachments: SAS2441933.PDF; EST1807-066 SDL5900J.pdf

Dear Person in-charge,

My client's vehicle **SDL5900J** wants to make a third party claim against **YM8541M** which is insured by **AXA Insurance Pte. Ltd**

Let us know the Claim officer in-charge for **liability / settlement** of my client's claim.

E.g. your principle's advice on the validity of the policy holder.

***Please send us your top 10 surveyor companies for survey.**

Thank you.

Best Regards,
Raymond Tan
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: +65 64688834
Fax: +65 64622278

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 23 July 2018 4:06 PM
To: assignments
Subject: FW: SDL5900J - TP Claim against YM8541M
Attachments: SAS2441933.PDF; EST1807-066 SDL5900J.pdf

Hi,

TP PRI. – claiming against AXA. Please inform TP repairer that no direct settlement for this case.

Instruction given by AXA - to conduct PRI only.

6:07pm @ 23/07/2018
vehicle in
person @ Raymond

FYNA please.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: raymond@automotiverepaircentre.com.sg <raymond@automotiverepaircentre.com.sg>
Sent: Saturday, 21 July, 2018 1:29 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: 'Lin Shu Juan' <shujuan@automotiverepaircentre.com.sg>
Subject: FW: SDL5900J - TP Claim against YM8541M

Dear Person in-charge,

Upon our email sent on 20 July 2018. We have yet to received any response from you.

Kindly help to arrange your assigned surveyor to contact us soonest as possible.

Thank you.

Best Regards,

Raymond Tan

Automotive Repair Centre Pte Ltd

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: +65 64688834

Fax: +65 64622278

From: raymond@automotiverepaircentre.com.sg
Sent: Friday, 20 July 2018 3:26 PM
To: 'motor.survey@axa.com.sg'
Cc: 'Lin Shu Juan'
Subject: SDL5900J - TP Claim against YM8541M

*Dear Person in-charge,

My client's vehicle SDL5900J wants to make a third party claim against YM8541M which is insured by **AXA Insurance Pte. Ltd**

Let us know the Claim officer in-charge for liability / settlement of my client's claim.

E.g. your principle's advice on the validity of the policy holder.

*Please send us your top 10 surveyor companies for survey.

Thank you.

Best Regards,
Raymond Tan
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: +65 64688834
Fax: +65 64622278



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18013458/R1ua3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: JAS TAN

Date : 11-10-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 8541M	Veh. Inspected	SDL 5900J
Policy No.	VFX/P1814731	Coverage (\$)	0.00
Claim No.	S8M00PB6	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	23/07/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 1.5L	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0148501	Colour	BLUE
Odometer	28502	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/60R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/60R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/60R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/07/2018	Inspection Date	24/07/2018
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDL 5900J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	880.00	880.00
10	FRONT BUMPER CLIPS @ \$5.00 (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT REINFORCEMENT (CONSISTENT)	SERVICEABLE	480.00	-
1	FRONT BUMPER RETAINER RH (CONSISTENT)	SERVICEABLE	30.00	-
1	FRONT BUMPER RETAINER LH (CONSISTENT)	SERVICEABLE	30.00	-
1	FRONT RADIATOR UPPER PANEL (CONSISTENT)	NOT NECESSARY	180.00	-
1	FRONT GRILLE (CONSISTENT)	CRACKED	150.00	150.00
1	FRONT GRILLE BRACKET RH (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT GRILLE BRACKET LH (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT GRILLE CHROME MOULDING LH (CONSISTENT)	CRACKED	200.00	200.00
3	FRONT GRILLE BLACK MOULDING LH @ \$40.00 (CONSISTENT)	SCRATCHED	120.00	120.00
3	FRONT GRILLE BLACK LONG MOULDING (CONSISTENT)	SCRATCHED	210.00	210.00
1	FRONT EMBLEM (CONSISTENT)	MISSING	60.00	60.00
1	FRONT EMBLEM BASE (CONSISTENT)	MISSING	30.00	30.00
1	FRONT LICENCE PLATE GARNISH (CONSISTENT)	DEFORMED	80.00	80.00
1	HEAD LAMP LH (CONSISTENT)	CRACKED	3,600.00	3,600.00
1	HEAD LAMP UPPER BRACKET LH (CONSISTENT)	SERVICEABLE	20.00	-
1	HEAD LAMP LOWER BRACKET LH (CONSISTENT)	SERVICEABLE	20.00	-
1	FRONT CENTER BRACE (CONSISTENT)	SERVICEABLE	40.00	-
1	FRONT SUPPORT PANEL (CONSISTENT)	SERVICEABLE	480.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,080.00	1,080.00
10	REAR BUMPER CLIPS @ \$5.00 (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR REINFORCEMENT (CONSISTENT)	BENT	580.00	580.00
1	REAR BUMPER RETAINER RH (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR BUMPER RETAINER LH (CONSISTENT)	SERVICEABLE	40.00	-
1	REAR BUMPER BRACKET (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	CRACKED	60.00	60.00
1	REAR BUMPER TOW EYE COVER RH (CONSISTENT)	MISSING	20.00	20.00
1	REAR FENDER RH (CONSISTENT)	BUCKLED	1,200.00	1,200.00
1	REAR FENDER SHIELD RH (CONSISTENT)	SERVICEABLE	150.00	-

Report Ref No. CC4/ASM18013458/R1ua3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	REAR FENDER CLIP @ \$5.00 (CONSISTENT)	NECESSARY	50.00	50.00
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	380.00	-
1	END PANEL GARNISH (CONSISTENT)	SERVICEABLE	100.00	-
1	TAIL LAMP RH (CONSISTENT)	BROKEN	900.00	900.00
1	BOOT LAMP RH (CONSISTENT)	SERVICEABLE	450.00	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	80.00	80.00
1	RADIATOR GRILLE PANEL (CONSISTENT) (ADDITIONAL)	DEFORMED	350.00	350.00
1	RADIATOR GRILLE TOP BRACKET (CONSISTENT) (ADDITIONAL)	CUT	70.00	70.00
1	FRONT SUPPORT SEAL PLATE CENTER (CONSISTENT) (ADDITIONAL)	CRACKED	80.00	80.00
2	REVERSE SENSOR (ORIGINAL) (CONSISTENT) (ADDITIONAL)	NECESSARY	400.00	400.00
	LESS 20% DISCOUNT		-	-2,090.00
			12,850.00	8,360.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENCE PLATE (SN) (CONSISTENT)	CRACKED	40.00	35.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT GRILLE MOULDING (SN) (CONSISTENT)	CRACKED	60.00	40.00
1	FRONT CENTER CHROME MOULDING (SN) (CONSISTENT)	CRACKED	60.00	40.00
1	REAR REFLECTOR CHROME MOULDING RH (SN) (CONSISTENT)	MISSING	60.00	40.00
1	REAR BOOTLAMP CHROME MOULDING RH (SN) (CONSISTENT)	SCRATCHED	60.00	30.00
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	200.00	-
			520.00	225.00
	<u>LABOUR</u>			
	NANO CERAMIC COATING.		600.00	428.00
	SPRAY PAINTING WHOLE FRONT AND REAR.		1,200.00	800.00
	REPAIR, REPLACE AND REFILL AFFECTED ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF END PANEL.		1,200.00	800.00
	REMOVE AND REFIT A/C CONDENSER, RADIATOR INCLUDING A/C GAS.	NOT NECESSARY	100.00	-

Report Ref No. CC4/ASM18013458/R1ua3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY RUST PROOFING ON REPLACED / REPAIRED PANEL.		100.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN.		120.00	120.00
	RESET, CHECK FAULT AND RESYNCING.		180.00	80.00
	REMOVE AND REPLACE REAR REVERSE SENSOR.		80.00	60.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			3,610.00	2,378.00
	GRAND TOTAL		16,980.00	10,963.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				750.00

Report Ref No. CC4/ASM18013458/R1ua3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.