

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One
Singapore 038987

Our File No: CS/ICS18013463/KRD3E2

Date: 04/10/2018

REFERENCE

Insured/Claimant: TRIPLE K SERVICES LLP Policy No: MPC17A00614900
Date of Loss: 21/07/2018 Nature of Claim: OD Claim No: DMPC1800295H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA2767Y**
Make & Model: AUDI A4, 2.0 (A) Engine No: CDN089688
Reg. Date: 10/02/2011 (Man. Year: 2009) Chassis No: WAUZZZ8K2AA094060
Colour: Metallic Black Odometer: 150139 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$45,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35ZR19 Rear Tyre Size: 245/35ZR19
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 7 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,691.13	4,034.80	656.33	13.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,260.00	370.00	22.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,321.13	5,294.80	1,026.33	16.24
- Excess (S\$)	750.00	750.00	0.00	0.00
Nett Amount (S\$)	5,571.13	4,544.80	1,026.33	18.42

INSPECTION

Date of Assignment: 24/07/2018
Date Inspected: 25/07/2018 Inspected At: Chuan Ho Auto Service (Sin Ming)
Blk 160 #07-09, Sin Ming Autocity
Singapore 575722
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2018)
Parts: 143	AUDI A4 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKA2767Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Bent	936.00 F	*935.00 F
2	1		*FROTN BONNET (WCP)	Bent	800.00 F	*800.00 F
3	1		*RHF FENDER (WCP)	Bent	410.00 F	*410.00 F
4	1		*RH HEADLAMP (WCP)	Cracked	880.00 F	*880.00 F
5	1		*RH WASHER COVER (WCP)	Missing	23.40 F	*23.00 F
6	1		*RH WASHER (WCP)	Cracked	100.00 F	*100.00 F
7	1		*RH FOG LAMP (WCP)	Serviceable	105.30 F	*- F
8	1		*RH FOG LAMP COVER (WCP)	Dented	70.20 F	*70.00 F
9	1		*TOP GARNISH (WCP)	Cracked	52.65 F	*52.00 F
10	4		*TOP GARNISH CLIPS (WCP)	Necessary	8.56 F	*8.00 F
11	1		*RH BUMPER BRACKET (WCP)	Distorted	46.80 F	*46.00 F
12	1		*RH HEADLAMP RETAINER (WCP)	Distorted	16.05 F	*16.00 F
13	1		*RHF WHEEL ARCH PROTECTOR (WCP)	Serviceable	93.60 F	*- F
14	1		*FRONT REINFORCEMENT BAR (WCP)	Repair	333.45 F	*- F
15	1		*FRONT REINFORCEMENT SPONGE (WCP)	Serviceable	58.50 F	*- F
16	1		*FRONT LOWER ENGINE COVER (WCP)	Cracked	257.40 F	*257.00 F
17	10		*FRONT LOWER ENGINE COVER CLIPS (WCP)	Necessary	26.75 F	*25.00 F
18	1		*RHF FENDER BRACKET (WCP)	Distorted	46.00 F	*46.00 F

F=Franchise part.

Sub Total (S\$)	4,264.66	3,668.00
+ Margin on L,N Items 10.00/10.00% (S\$)	426.47	366.80
Total Parts (S\$)	4,691.13	4,034.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REPLACE REMOVE ALL PARTS AND REPLACE,RE-ALIGN FRONT HEAD AND WIRING CHECKS	New	550.00	480.00
2	SPRAY PAINTING BONNET INNER,BONNET OUTER,FRONT BUMPER AND RHF FENDER	New	800.00	660.00
3	RH HEADLAMP COMPUTERIZED PROGRAMMING	New	280.00	120.00
Gross Labour Cost (S\$)			1,630.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >