

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI18013529/KRBS2**Date:** 11/10/2018REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3072901702		
Claimant Vehicle No :	SLZ9317Z	Insured Vehicle No :	SKV8696T		
Date of Loss:	18/07/2018	Nature of Claim:	TP	Claim No:	SNM18D03555C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ9317Z		Engine No:	2ZR0A22859
Make & Model:	TOYOTA PRIUS ALPHA, 1.8 (A)		Chassis No:	ZVW400027131
Reg. Date:	23/05/2018 (Man. Year: 2017)		Odometer:	7898 km
Colour:	Metallic Black			
Engine Capacity:	1797 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,308.80	1,750.57	1,558.23	47.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	740.00	610.00	45.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,658.80	2,490.57	2,168.23	46.54
Approved Total (Overridden) (\$\$)		1,950.00		
(\$\$)	4,658.80	1,950.00	2,708.80	58.14
+ GST 7.00/7.00% (\$\$)	326.12	136.50	189.62	58.14
Nett Amount (\$\$)	4,984.92	2,086.50	2,898.42	58.14

INSPECTION

Date of Assignment:	24/07/2018	
Date Inspected:	14/08/2018	Inspected At: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Janice Lee Si Hua*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)
Parts:	M1-MPV	TOYOTA PRIUS ALPHA 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ9317Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Cut	912.50 FL	*912.50 FL
2	1		*FRONT BUMPER	Buckled / Cut	1,002.73 FL	*1,002.73 FL
3	10		*FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	375.60 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	87.90 FL	*- FL
6	1		*FRONT BUMPER BRACKET RH	Repair	211.67 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Serviceable	97.80 FL	*- FL
8	1		*FOG LAMP RH	Not Necessary	256.70 FL	*- FL
9	1		*FOG LAMP GARNISH RH	Scratched	147.80 FL	*147.80 FL
10	1		*RH FRONT FENDER	Repair	811.67 FL	*- FL
11	1		*RH FRONT FENDER UNDERSHIELD	Serviceable	196.30 FL	*- FL
12	10		*RH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	40.00 FL	*- FL
13	1		*RHF FENDER WORDING HYBRID	Necessary	44.17 FL	*44.17 FL
14	1		*RH FRONT HUB CAB	Dented	186.90 FL	*186.90 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,411.74	2,334.10
- List Item Discount on L Items 25.00/25.00% (S\$)	1,102.94	583.53
Total Parts (S\$)	3,308.80	1,750.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (RHF FENDER, FRONT BUMPER)	New	600.00	320.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (RHF FENDER, FRONT BUMPER)	New	600.00	400.00
3	TO CHECK WIRING & FOCUS HEADLAMP.	New	50.00	20.00
4	TO TUFF COAT.	New	100.00	0.00
Gross Labour Cost (\$)			1,350.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >