



Your Ref : D18/5600M/CT/EE/OD

Date: 17th September 2018

Our Ref : CS/FCI18013589/Nvbs2

M/s First Capital Insurance Ltd

36 Robinson Road
#16-01 City House
Singapore 068877
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHD 4218Y
ACCIDENT ON 19/07/2018**

Instruction was received to inspect the vehicle Reg. No. SHD 4218Y. The inspection was conducted on 25/07/2018 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SHD 4218Y
Make/Model	: Hyundai Sonata
Year of Registration	: 2012
Body Colour	: Blue
Chassis Number	: KMHET41VMCA825050
Engine Capacity	: 1991 cc
Speedometer Reading	: Burnt

The whole vehicle burnt. (Details see photographs enclosed)

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**Total Loss**".

Book Value	S\$	25,921.33
Less: LTA Reimbursement Value (RV)	(S\$	18,802.00)
Nett Liability	S\$	<u>7,119.33</u>

Vehicle Inspected By:

MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London

K.K.LAU

*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), Minst.AEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.