

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG18013600/AES3Q2  
**Date:** 25/03/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800064062
<b>Claimant Vehicle No :</b>	SLV3483L	<b>Insured Vehicle No :</b>	SFW49T
Date of Loss:	24/07/2018	Nature of Claim:	TP
		Claim No:	8417137318SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLV3483L</b>	Engine No:	2ARH994290
Make & Model:	TOYOTA VELLFIRE, 2.5 CVT (A)	Chassis No:	AGH300154151
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	16121 km
Colour:	Black		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	26/07/2018		
Date Inspected:	26/07/2018	Inspected At:	United SG Automobile Pte Ltd (HQ) 1 Sunview Road #08-44, Ecotech@Sunview Singapore 627615
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	0.00 F	*- F	
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
3	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F	
4	2		*REVERSE SENSOR	Damaged	0.00 F	*- F	
5	1		*REAR END PANEL	Dented	0.00 F	*- F	
6	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F	
7	1		*TAILGATE	Dented	0.00 F	*- F	
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F	
9	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F	
10	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F	
11	1		*TAILGATE LOCK	Damaged	0.00 F	*- F	
12	1		*TAILGATE RUBBER	Cut	0.00 F	*- F	
13	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F	
					<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >