

12/02/2011

ASS. REC. BY: W. Wilson REF: CS3 / MSE / 8004311 / Btb-1 Special Instruction: Range

Surveyor: Menmen ASSIGNMENT (Office)

From (Person): Christina Wong of MSIG Date/Time: 26/7/2018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKF 2511S Insured: WC 2867P

at Workshop m/s: Lian Heng Painter Tel: 9863 2371

of: 160 Sin Ming Drive #06-10

Policy No: B28744750 MKC Claim No: 551317

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS lwp' H.O.D. Endorsement: _____

Date/Time: 10:22am @ 6/3/18 Person Contacted: Mr. Henry Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKF 2511S - X</u>
	<u>WC 2867P - X</u>
	<u>After repair: 15/03/2018</u>

URGENT

L/S 6700/-
 Repair days 6
 (Red 2400, 26%)

[Signature]
 27/7/2018

317 - File pass to typist

RECEIVED 31 JUL 2018

TG Lim [Signature]

26/7/18

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: SKF 2511 S

at Workshop No: Liang Hong

of 168 Sunning Drive

Insured

Policy No:

Claims No:

Sum Insured:

Excess:

Client's Record:

Make of Ver:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	OS

Bail or Market Value

ADAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Result: Yes or No

Lump Sum: \$ 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date Time Action / Instruction:

Veh No: SKF 2511 S Regn: 12/12/2011

Type: AL Car / PM Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 730i cc: 2996

Colour: Silver Insured / Std / Nil / NA

Sp Reading: 491232 T Ratio: Insured / Std / Nil / NA

Eng No:

C No: WBAK32204XC951387

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size F: 245/50 R15

R: 245/50 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal: 4 mm R/Bal: 3 mm

L/Bal: 4 mm L/Bal: 3 mm

D.O.A: 1/3/2018 DO: 6/3/2018

Survey held at: As Above

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

both Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Range - \$7900 - \$8900

5 Days

Repairs

4/4/2018

RECEIVED 2018

Date Time Rep Pass to:

06042018

Date Time Rep Return to:

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transport

U/C - FE \$

Add Fee: ☐ Site Insp \$

☐ Inter. Br \$

☐ Tech. Insp \$

☐ Weekend \$

Report Format: PR

Lump Sum / I.B.H.E

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Mar 2018		05 Mar 2018 17:26 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	SAMWOH READY MIX PTE LTD, Co. Reg. No.: NA			[Created by insurer]
Main Claimant:	SONNY BENSI, ID: S2511636D			
Vehicle Reg. No.:	SKF2511S	Date of Loss:	01/03/2018 16:00 - :59 [74 Months and 17 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 551317	Policy/Cover Note No.:	B28744750MKC (Comprehensive) Coverage: 05/06/2017 - 04/06/2018	
Vehicle Reg. No. (Insured):	WC2867P	Policy No. (Claimant):		
		Excess:		
Repairer:	Lian Heng Painter Company () 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 30/07/2018]			
Driver/Custodian (Insured):	GUO LEI (), NRIC: G3197054M, Tel: +6591247224			

ASSOCIATED MAIL RECEIVED

- MSIG_SG (26/07/2018): Report Send Back Alerts - SKF2511S (TP)

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0418 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Sonny Bensily
C/o: 160 Sin Ming Drive #06-10
Sing Ming AutoCity (S) 575722

Date of report: 30.03.2018
Date of request: 02.03.2018
Date of inspection: 02.03.2018
Date of accident: 01.03.2018
Claim type: Third Party Claim

Report No: AAS/2018/084

Particulars of affected vehicle:

Registration no: SKF2511S
Make/Model: BMW 730Li (A)
Year of registration: 2011
Colour: Metallic Silver

Odometer: 49229 km
Engine Capacity: 2996 cc
Engine no: 09417955N52B30AF
Chassis no: WBAKB22040C951387

Condition of tires:

Front Left: 6mm
Make: Continental
Rear Left: 6mm
Make: Continental

Front Right: 6mm
Make: Continental
Rear Right: 6mm
Make: Continental

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : In order
Footbrake : In order
Steering : In order
Apparent engine modification : Nil

The Assignment

The inspection was conducted at M/s. Lian Heng Painter Company
160 Sin Ming Drive #06-10
Sing Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate: \$ 18,582.50

Revised estimate: \$ 11,364.85

Recommended reserve: \$ 9,100.00 (Lump sum)

Estimated normal duration of repairs : 9 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0418 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SKF2511S

Report No: AAS/2018/084

W/O PREJUDICE

Point of impact

At the rear LH portion.

General description of damages

The truck lid, truck lid lamp LH, tail lamp LH, rear bumper, LHR fender, tail end panel, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Lian Heng Painter Company as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$11,364.85

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$9,100.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 9 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 60 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0418 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SKF2511S

Report No: AAS/2018/084

Appraisement Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Rear bumper	1	Dented		\$ 1,569.70	\$ 1,569.70 DD ✓
2	Rear bumper trim cover	1	Dented/Cut		\$ 467.50 246.20	\$ 467.50 CUT ✓
3	Rear bumper reflector LH	1	Grazed		\$ 59.90	\$ 59.90 SVC ✓
4	Rear bumper adaptor	1	Cracked		\$ 111.85 88.00	\$ 111.85 CRA ✓
5	Rear bumper carrier	1	Dented		\$ 691.25	\$ 691.25 R X
6	Rear bumper centre guide	1	Cracked		\$ 128.95 44.90	\$ 128.95 CRA ✓
7	Rear bumper mount LH	1	Cracked		\$ 91.10	\$ 91.10 CRA ✓
8	Rear bumper ultrasonic sensor	1	Malfunctioned		\$ 189.85	\$ 189.85 DM ✓
9	Rear bumper ultrasonic sensor decoupling	4	Necessary	\$ 8.30	\$ 33.20	\$ 33.20 NECV ✓
10	Tail light LH	1	Broken		\$ 659.60	\$ 659.60 BRV ✓
11	LHR fender	1	Dented/Repair		\$ 1,950.50	-
12	Rear glass top moulding	1	Not Necessary		\$ 65.70	\$ -65.70 NN X
13	Rear glass lower moulding	1	Not Necessary		\$ 58.75	\$ -58.75 NN X
14	Truck lid	1	Dented		\$ 1,778.10	\$ 1,778.10 DD ✓
15	Truck lid emblem	1	Necessary		\$ 64.00	\$ 64.00 NECV ✓
16	Truck lid chrome strip	1	Grazed		\$ 279.30 180.30	\$ 279.30 SCLR ✓
17	Truck lid cover	1	Cracked		\$ 432.10	\$ 432.10 CRA ✓
18	Truck lid lamp LH	1	Grazed		\$ 401.35	\$ 401.35 CRA ✓
19	Truck lid lamp chrome LH	1	Grazed		\$ 47.25	\$ 47.25 CUT ✓
20	Truck lid inner trim	1	Serviceable		\$ 133.25	-
21	Truck lid lock	1	Distorted/Jammed		\$ 461.65	\$ 461.65 JM ✓
22	Truck lid lock power drive	1	Malfunctioned		\$ 610.60	\$ 610.60 DD ✓
23	Truck lid striker	1	Serviceable		\$ 170.10	-
24	Truck lid spindle drive LH/RH	2	Serviceable	\$ 474.40	\$ 948.80	-
25	Truck lid weather-strip	1	Serviceable		\$ 97.65	-
26	Tail end panel	1	Dented/Repair		\$ 1,575.90	-
27	Loading sill cover	1	Serviceable		\$ 141.45	-
28	Exhaust tail pipe chrome	1	Missing		\$ 233.15 85.00	\$ 233.15 M19 ✓
List total:					\$ 13,452.50	\$ 8,434.85 6982.90
1	Rear glass sealant	1	Not Necessary		\$ 60.00	-
2	Joint sealant	2	Not Necessary	\$60.00	\$ 120.00	-
3	Truck lid inner trim clips	1set	Necessary		\$ 50.00	\$ 50.00 NN X
Special nett total:					\$ 230.00	\$ 50.00
Parts Total:					\$ 13,682.50	\$ 8,484.85 6982.90 349.15 6633.76

@ 5%



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0418 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SKF2511S

Report No: AAS/2018/084

S/N Labour Description

Repairer's Est

Revised Est

1	Rust proofing.	\$ 100.00	\$ 80.00 60.00
2	To remove & refit rear trimmings, rear seats, etc	\$ 200.00	\$ 100.00 60.00
3	To transfer truck lid fittings.	\$ 200.00	\$ 150.00 100.00
4	To remove & refit glass.	\$ 200.00	-
5	To renew/transfer reverse sensor.	\$ 100.00	\$ 100.00 60.00
6	To conduct electrical diagnosis, reset fault code, calibrate rear distance sensor, reprogrammed all related, check all lightings & wiring.	\$ 300.00	\$ 250.00 150.00
7	To remove and renew damaged parts.	\$ 2,000.00	\$ 1,000.00 600.00
8	To putty and respray all damaged parts.	\$ 1,800.00	\$ 1,200.00 800.00
Labour Total:		\$ 4,900.00	\$ 2,880.00 1830.00

Grand Total: \$ 18,582.50 \$ ~~11,364.85~~ 8463.76

The final adjusted lump sum amount is \$9,100.00

Under normal circumstances, the repair should be completed within a reasonable period of 9 working days.

60 Photographs were taken at the time of inspection.

L/S 6,700/-

Repair days 6

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Mar 2018		05 Mar 2018 17:26 Edit Adj Rpt	S\$6,700.00 Edit Estimates	S\$6,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SAMWOH READY MIX PTE LTD , Co. Reg. No.: NA									
Main Claimant: SONNY BENSILY , ID: S2511636D									
Vehicle Reg. No.: SKF2511S		Date of Loss: 01/03/2018 16:00 - :59 [74 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 551317		Policy/Cover Note No.: B28744750MKC (Comprehensive) Coverage: 05/06/2017 - 04/06/2018							
Vehicle Reg. No. (Insured): WC2867P		Policy No. (Claimant):							
		Excess:							
Repairer: Lian Heng Painter Company () 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 30/07/2018]									
Driver/Custodian (Insured): GUO LEI (), NRIC: G3197054M, Tel: +6591247224									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (26/07/2018): Report Send Back Alerts - SKF2511S (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKF2511S (551317)**
[WC2867P]
TP
SONNY BENSIY
Mar 1 2018 4:00PM
[SAMWOH READY MIX PTE LTD]
Lian Heng Painter Company

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports

1 per page
☐

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/03/18 17:21	Accident Statement From: SC - Reg. No: WC2867P, Claimant: SAMWOH READY MIX PTE LTD	Load HTM	

Photos/Images

3 per page
☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 11:18	General View	Load JPG	☒
2	06/04/18 11:18	General View	Load JPG	☒
3	06/04/18 11:18	General View	Load JPG	☒
4	06/04/18 11:18	General View	Load JPG	☒
5	06/04/18 11:18	General View	Load JPG	☒
6	06/04/18 11:18	General View	Load JPG	☒
7	06/04/18 11:18	General View	Load JPG	☒
8	06/04/18 11:18	General View	Load JPG	☒
9	06/04/18 11:18	General View	Load JPG	☒
10	06/04/18 11:18	General View	Load JPG	☒
11	06/04/18 11:18	General View	Load JPG	☒
12	06/04/18 11:18	General View	Load JPG	☒
13	06/04/18 11:18	General View	Load JPG	☒
14	06/04/18 11:18	General View	Load JPG	☒
15	06/04/18 11:18	General View	Load JPG	☒
16	06/04/18 16:29	Photo After Spray	Load JPG	☒
17	06/04/18 16:29	Photo After Spray	Load JPG	☒
18	06/04/18 16:29	Photo After Spray	Load JPG	☒
19	06/04/18 16:29	Photo After Spray	Load JPG	☒
20	06/04/18 16:29	Photo After Spray	Load JPG	☒
21	06/04/18 16:29	Photo After Spray	Load JPG	☒

Documentation

1 per page
☐

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/03/18 17:21	SKF2511S GIA Rpt From: SC - Reg. No: WC2867P, Claimant: SAMWOH READY MIX PTE LTD	Load PDF	
2	05/03/18 17:22	PRI	Load PDF	
3	12/05/18 14:17	Surveyor report & some photos	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/07/18 15:23	PRS Invoice	Load PDF	
2	31/07/18 15:23	PHOTO	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004311/BTBE2-1

Date: 31/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28744750MKC

Claimant Vehicle No : SKF2511S

Insured Vehicle No : WC2867P

Date of Loss: 01/03/2018

Nature of Claim: TP

Claim No: 551317

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKF2511S**

Make & Model: BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A)

Engine No: 09417955N52B30AF

Reg. Date: 12/12/2011 (Man. Year: 2011)

Chassis No: WBAKB22040C951387

Colour: Silver

Odometer: 49232 km

Engine Capacity: 2996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18

Rear Tyre Size: 245/50 R18

Front Left Side: Continental 4 mm

Rear Left Side: Continental 3 mm

Front Right Side: Continental 4 mm

Rear Right Side: Continental 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,682.50	6,633.75	7,048.75	51.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	1,830.00	3,070.00	62.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,582.50	8,463.75	10,118.75	54.45
Approved Total (Overridden) (S\$)		6,700.00		
Nett Amount (S\$)	18,582.50	6,700.00	11,882.50	63.94

INSPECTION

Date of Assignment: 05/03/2018

Date Inspected: 06/03/2018 Inspected At:

Lian Heng Painter Company
160 SIN MING DRIVE, #06-10 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2018)
Parts:	143	BMW 730LI 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF2511S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Dented	1,569.70 F	*1,569.70 FL
2	1	*REAR BUMPER TRIM COVER	Cut	467.50 F	*246.20 FL
3	1	*REAR BUMPER REFLECTOR LH	Serviceable	59.90 F	*- FL
4	1	*REAR BUMPER ADAPTOR	Cracked	111.85 F	*88.00 FL
5	1	*REAR BUMPER CARRIER	Repair	691.25 F	*- FL
6	1	*REAR BUMPER MOUNT LH	Cracked	91.10 F	*91.10 FL
7	1	*REAR BUMPER ULTRASONIC SENSOR	Damaged	189.85 F	*189.85 FL
8	4	*REAR BUMPER ULTRASONIC SENSOR DECOUPLING	Necessary	33.20 F	*33.20 FL
9	1	*TAIL LIGHT LH	Broken	659.60 F	*659.60 FL
10	1	*LHR FENDER	Repair	1,950.50 F	*- FL
11	1	*REAR GLASS TOP MOULDING	Not Necessary	65.70 F	*- FL
12	1	*REAR GLASS LOWER MOULDING	Not Necessary	58.75 F	*- FL
13	1	*TRUCK LID	Dented	1,778.10 F	*1,778.10 FL
14	1	*TRUCK LID EMBLEM	Necessary	64.00 F	*64.00 FL
15	1	*TRUCK LID CHROME STRIP	Scratched	279.30 F	*180.30 FL
16	1	*TRUCK LID COVER	Cracked	432.10 F	*432.10 FL
17	1	*TRUCK LID LAMP LH	Cracked	401.35 F	*401.35 FL
18	1	*TRUCK LID LAMP CHROME LH	Cut	47.25 F	*47.25 FL
19	1	*TRUCK LID INNER TRIM	Serviceable	133.25 F	*- FL
20	1	*TRUCK LID LOCK	Jammed	461.65 F	*461.65 FL
21	1	*TRUCK LID LOCK POWER DRIVE	Dented	610.60 F	*610.60 FL
22	1	*TRUCK LID STRIKER	Serviceable	170.10 F	*- FL
23	2	*TRUCK LID SPINDLE DRIVE LH / RH	Serviceable	948.80 F	*- FL
24	1	*TRUCK LID WEATHER-STRIP	Serviceable	97.65 F	*- FL
25	1	*TAIL END PANEL	Repair	1,575.90 F	*- FL
26	1	*LOADING SILL COVER	Serviceable	141.45 F	*- FL
27	1	*EXHAUST TAIL PIPE CHROME	Missing	233.15 F	*85.00 FL
28	1	*REAR GLASS SEALANT	Not Necessary	60.00 FS	*- FS
29	2	*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
30	1	*SET TRUCK LID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
31	1	*REAR BUMPER CENTRE GUIDE	Cracked	128.95 F	*44.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,682.50	6,982.90
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	349.15
Total Parts (\$\$)	13,682.50	6,633.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	100.00	60.00
2	TO REMOVE & REFIT REAR TRIMMINGS, REAR SEATS, ETC	New	200.00	60.00
3	TO TRANSFER TRUCK LID FITTINGS	New	200.00	100.00
4	TO REMOVE & REFIT GLASS	New	200.00	0.00
5	TO RENEW / TRANSFER REVERSE SENSOR	New	100.00	60.00
6	TO CONDUCT ELECTRICAL DIAGNOSIS, RESET FAULT CODE, CALIBRATE REAR DISTANCE SENSOR, REPROGRAMMED ALL RELATED, CHECK ALL LIGHTINGS & WIRING	New	300.00	150.00
7	TO REMOVE AND RENEW DAMAGED PARTS	New	2,000.00	600.00
8	TO PUTTY AND RESPRAY ALL DAMAGED PARTS	New	1,800.00	800.00
Gross Labour Cost (\$\$)			4,900.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >