

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Registration No

Chassis No

Owner's Name

Ins Policy No.

Date of Accident

Model

Website: www.honda.com.sg

068877

: MS FIRST CAPITAL INSURANCE

36 ROBINSON ROAD

#16-01 CITY HOUSE

: MRHFC5650GT000960

: CIVIC 1.6 VTI YM2016

: KWEK CHU YEONG

SINGAPORE

: SJL3593D

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

Document No.

: SQT18003235

Page

Date Customer No.

Qtv

: 2. Aug 2018

: WZF002

Svc Advisor

Engine No.

: R16B21601232

Date | Time

: 2. Aug 2018 8:15:53 PM

Surveyor Name

Survey Date

**Authorisation Date** 

Item

Description

Unit Price Disc %

Amount

Amount incld GST

Amount

0% GST

TP DIRECT SETTLEMENT (J/NO:

OWNER:

OWNER INSURER:

ACC DATE:

SURVEYED BY:

DATE:

REF NO:

TP INSURER:

TP VEH:

SUPPLEMENTARY

91555-TBA-K01

CLIPAMBIENT SENSOR

5.30 (RK/

3.97 3.97 0.28 0.28

4 25 4.25

Survey By

Date & Time

Excess

Status

Signature

**Total Amount** 

Sum Item

3.97

0.28

4.25

Total (Inclusive of GST)

4.25

## LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" besis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/8/2018 8:16:52 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)