



Your Ref : S8M00PU9

Date: 03rd August 2018

Our Ref : CS/ASM18013652/Drd3s2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

(The Motor Claims Department)

Attn: Kitty Teo

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGU 8854G
ACCIDENT ON 24/07/2018**

Instruction was received to inspect the vehicle Reg. No. SGU 8854G. The inspection was conducted on 26/07/2018 at the premises of M/s Ah Lim Motor Company, No 10 Ang Mo Kio Industrial Park 2A #01-09 AMK Autopoint Singapore 568047.

The following vehicle information was recorded:

Registration Number	: SGU 8854G
Make/Model	: Nissan Sunny
Year of Registration	: 2007
Body Colour	: Beige
Chassis Number	: JN1CFAN16Z0107712
Engine Capacity	: 1597 cc

The vehicle caught fire at the engine compartment. Cause of fire due to electrical nature to the wiring. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	22,000.00
Less: LTA Reimbursement Value (RV)	(S\$	19,435.00)
Nett Liability	S\$	2,565.00
		=====

Vehicle Inspected By:



ANG BRYAN TANI

Automotive Assessor / Investigator



K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.