

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7815C

DATE 24/7/2018 10:52

MAKE :

MODEL : HYUNDAI i40

LKK/Quang pbyP
Lke EQINS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) <i>Mc</i>			\$ 2,020.10
	Rear Fender Inner Lining (RH) <i>X NN</i>			\$ 164.40
	Rear Windscreen Moulding <i>Mc</i>			\$ 60.00
	Rear Wheel Hup-Cap (RH) <i>Cost</i>			\$ 150.70
R	Rear Bumper Cover - #603,60 <i>cut</i>			
	SUB TOTAL			\$ 2,395.20
R	Rear Bumper Bracket Rh #49 <i>Mc</i>			\$ 479.04
	LESS 20% DISCOUNTED TOTAL			\$ 1,916.16
	Rear Bumper Rubber Mat <i>Mc</i>			\$ 50.00
	Rear Windscreen Sealant <i>Mc</i>			\$ 46.00
				\$ 96.00
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Rear Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 1,960.00
	ESTIMATE TOTAL			\$ 3,972.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*600
400
30
60
100
40
60*

*5 Days.
part by part.
before part photos.
Gino Quip
24/7/18 4pm*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.