

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD18013665/UEA3Q2

**Date:** 07/04/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00000573-01

**Claimant**  
**Vehicle No :** YM6737D **Insured Vehicle No :** SJB5069R

**Date of Loss:** 08/07/2018 **Nature of Claim:** TP **Claim No:** 1201800008706

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YM6737D		
Make & Model:	MITSUBISHI FE83BE6SRDEA, 3.0 D (A)	Engine No:	4M42A43081
Reg. Date:	03/08/2007 (Man. Year: 2007)	Chassis No:	FE83BEA10160
Colour:	Black	Odometer:	396668 km
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	185 R14 (D)
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6/6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,465.50	4,609.57	2,855.93	38.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,210.00	830.00	40.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,505.50</b>	<b>5,819.57</b>	<b>3,685.93</b>	<b>38.78</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,505.50</b>	<b>4,650.00</b>	<b>4,855.50</b>	<b>51.08</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 25/07/2018

Date Inspected: 26/07/2018 Inspected At:

Liu's Brother Auto Engineering  
Workshop (kaki Bukit) (HQ)  
Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay  
@ Kaki Bt Singapore 417883, Kaki  
Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 27 Sep 2018)	
<b>Parts:</b>	N/A	mitsubishi FE83BE6SRDEA 3.0 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YM6737D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Dented / Bent	2,129.30 F	*2,129.30 FL
2	1		*FRONT LH BUMPER	Distorted	1,092.40 F	*1,092.40 FL
3	1		*FRONT LH BUMPER BRACKET	Repair	227.10 F	*- FL
4	1		*FRONT LH STEP PANEL GARNISH N/S	Grazed	590.00 F	*345.10 FL
5	1		*FRONT LH GRILLE	Cracked	1,027.20 F	*1,027.20 FL
6	1		*SET FRONT LH GRILLE CLIP	Not Necessary	65.00 FS	*- FS
7	1		*FRONT LH MITSUBISHI LOGO MOTIF	Necessary	82.30 F	*82.30 FL
8	1		*FRONT LH FUSO EMBLEM	Necessary	163.80 F	*163.80 FL
9	1		*FRONT LH HEAD LAMP N/S	Cracked	768.50 F	*768.50 FL
10	1		*FRONT LH HEAD BRACKETS	Not Necessary	99.20 F	*- FL
11	1		*FRONT LH SIDE LAMP	Cracked	292.60 F	*292.60 FL
12	1		*FRONT LH SIGNAL LAMP	Broken	244.90 F	*244.90 FL
13	1		*FRONT LH SIDE MIRROR ARM	Not Necessary	513.80 F	*- FL
14	1		*FRONT LH SIDE MIRROR ARM COVER (Missing)	Not Consistent With The Impact	141.40 F	*- FL
15	1		*FRONT LH NUMBER PLATE METAL	Not Necessary	28.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,465.50</b>	<b>6,146.10</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>1,536.53</b>
<b>Total Parts (\$\$)</b>	<b>7,465.50</b>	<b>4,609.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	20.00
2	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,000.00	500.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	800.00	600.00
4	TO APPLY & RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	30.00
5	TO REMOVE,REPLACE AND TRANSFER DOOR PANEL,FITTING AND MECHANISMS	New	80.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,040.00</b>	<b>1,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >