

## 205 Braddell Road S(579701)

	ACCIDENT R	EPAIR ESTIMATE	
Our Ref:			
Type of Claim :	TP	Vehicle No.	SKZ9544X
***************************************		Make & Model	: HYUNDAI ELANTRA 1.6 A
		Year of Manufacture	: <b>2015</b>
		Chassis No.	KMHDH41CMGU65663
Ins Company : AIC	S VS LONPAC	Engine No.	: G4FGFU068069
Excess :	-	Policy No.	<u>:</u>
Date of Accident :	21.07.2018	Time of Accident	10:50
Suggested Days of Repair :		In-house Vehicle Asset	ssor
Repair Estimate		Case Owner	WILLIAM
Parts (a) Cost / List Price Items Plus/Less 20% Total of Cost / List (b) Nett Price Items Less Total of Nett Item (c) Special Nett Items Total Parts Cost (Appendix A) Labour (Appendix B) Total Repair Cost	\$ 1,169.68 \$ 4,678.72 \$ -	Signature  Contact No Frt Counter Operatio 63837103 – Patrick Tia 63837730 - Brenda Ng 63837466 – Rohani braddell cr@sparkcarcal  Workshop Operation 63837656 - Ngo Toh We 63837362 - 63838115 - William Wan 63838115 - Andrew Go braddell operation@spar	re.com se g oh
The above total will be subjecte	d to 7% G.S.T.		
Name of Co.			

# Spark Car Care

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

#### **Spare Parts**

√ehicle No	:	SKZ9544X	Case Owner	:	WILLIAM
Make & Model	:	HYUNDAI ELANTRA 1.6 A	Year Manufacture	:	2015
Chassis No	:	KMHDH41CMGU656631	Engine No	:	G4FGFU068069
Sales Order	:		Supplier	:	
Order Bv	:		Type of Claim		TP

S/No	Doub Douguistics	QTY	Cost	List	Nett	1	Disposition By
S/NO	Part Description		Price	 Price	Price	S/N	Surveyor
1	Front bumper	1		\$ 448.30			
2	Front bumper lower lip	1		\$ 48.60			
3	Front bumper lower lip clips	1		\$ 52.50			
4	Front bumper fog lamp RH	1		\$ 233.50			
5	Front bumper center grille	1		\$ 255.70			
6	Front bumper sponge	1		\$ 110.70			
7	Front bumper reinforcement	1		\$ 515.10			
8	Front bumper lower stiffener	1		\$ 138.40			
9	Front bumper upper side bracket RH	1		\$ 28.00			
10	Front bumper side bracket RH	1		\$ 28.00			
11	Front bumper side support LH	1		\$ 28.00			
12	Front bumper side support RH	1		\$ 28.00			
13	Front bumper side support rivets	6		\$ 20.40			
14	Front grille assy	1		\$ 126.00			
15	RH headlamp	1		\$ 1,756.00			:
16	RH headlamp lower bracket	1		\$ 65.00			
17	RH front fender	1		\$ 460.60			
18	RH front fender inner shield	1		\$ 56.50			
19	RH front fender inner shield clips	8		\$ 28.00			
20	Washer tank	1		\$ 43.00			
21	Bonnet	1		\$ 1,184.30			
22	Bonnet seal front	1		\$ 18.00			
23	Bonnet insulator clips	8		\$ 28.00			
24	Bonnet hinge LH	1		\$ 52.00			
25	Bonnet hinge RH	1		\$ 52.00			
26	Bonnet lock	1		\$ 43.80			
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

25/07/2018 3:13 PM

## **Spark Car Care**

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

#### <u>Labour</u>

Vehicle No.	:	SKZ9544X	Case Owner	•	WILLIAM
Make & Model	:	HYUNDAI ELANTRA 1.6 A	Year of Manufacture	:	2015

	a model i manufacturo				
S/No	Labour Description	Esimated Price	Adjusted Price		
1	To remove/refit aircond parts, vacuum & recharge gas.	\$120.00			
2	Labour charges to repair and panel beat the frt support panel,	\$720.00			
	RH front pillar panel, LH front fender and replace damaged				
	parts. (per day \$240.00)				
3	To check wiring functions and focus headlamps.	\$60.00			
<u> </u>	To check withing functions and locus fleadiamps.	Ψ00.00			
4	To putty, apply primer & spray-paint the front bumper, bonnet,	\$1,500.00			
	LH front fender, RH front fender, RH front pillar panel, front				
	support panel and affected areas.				
		0.470.00			
5	To apply rust-proofing on repaired/replaced panels.	\$150.00			
6	To check/re-set steering geometry and wheel alignment.	\$120.00			
		-			
			·		
	J.				

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.