

REF: CS3 / MS618007598 / Bsb-^{ex}
 ASSIGNMENT (Office)
 From (Person): Christina Wang of M217 Date/Time: 27/07/2018
 Estimated Cost: Bill to:
 OD (1) / WS / TP RES / OD RES / EVA / INV / MV / C
 To Inspect Vehicle No: SJR 3175X Insured: SLT 7817S
 at Workshop no: Blumel Tel:
 of: Blk 1 Kaki Bukit Ave 6 #01-28
 Policy No: 290500470001 Claim No: M556340
 Name Insured: Excess:
 Make of Vch: D.O.A. 23042018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS wpi
 Date/Time: 25/07/2018 1400pm Person Contacted: Sally HOD Endorsement: Vehicle: B / LOT

Date/Time	Action/Instruction (x) Estimate	Do not Finalize
	SJR 3175X	
	SLT 7817S	
	(\$4,000.00 Red - 41%)	

4/3 5,800/2
 Repair days 9 days


 31/7/2018
URGENT

RECEIVED 01 AUG 2018

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res:

Lump Sum:

%

3 Val:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Veh No: STR 3175X Yr Regn: 18 Jun 2009
 Type: C / M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make:

Colour:

Sp Reading:

Eng/No:

G/No:

Gen. Cond: C / Fair / Poor / BurntSteering: C / Jammed / Leaked / Burnt orBrake: C / Jammed / Leaked / Burnt orModi: Nil / SiRim / STD / Rim or

Tyre Size

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

R/Bal:

L/Bal:

L/Bal:

D.O.A:

D.O.I:

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

27/6/18

Submit PRS Report

Date/Time: File Pass to:

☐

Prelt. Report

R:

☐

Final Report

Date/Time: File Return to:

S:

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Weekend: \$

Report Format:

Lump Sum / I.B.B: \$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

I. S. + R.T. \$

I. Photos:

I. Other:

TOTAL

120

10

130

Catherine Chong (LKK Auto)

From: Christina Wong <Christina_Wong@sg.msig-asia.com>
Sent: Friday, 27 July, 2018 10:26 AM
To: Catherine Chong (LKK Auto)
Subject: Our Ref:M556340 - Paper survey needed

Hi Catherine

Please arrange for the paper survey to do done Urgently

Best Regards





Christina Wong

Senior Executive, Claims Services (Motor)

Direct line +65 6643 1311 | Direct fax +65 6225 7402 | christina_wong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of  INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		25 Apr 2018 12:46 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
<div> <div>CLAIM SUBFOLDER DETAILS</div> <div> <div>Insured:</div> <div>AU YUEN KENG, ID: S1599172J</div> </div> <div> <div>Main Claimant:</div> <div>LOY ZHI JUN DERRICK, ID: S8202698C</div> </div> <div> <div>Vehicle Reg. No.:</div> <div>SJR3175X</div> </div> <div> <div>Date of Loss:</div> <div>23/04/2018 00:00 - :59 [106 Months and 5 Days From LTA Reg Date (Man Yr)]</div> </div> <div> <div>Claim Type:</div> <div>TP / 556340</div> </div> <div> <div>Policy/Cover Note No.:</div> <div>29050447QMY Coverage: 10/11/2017 - 09/11/2018</div> </div> <div> <div>Vehicle Reg. No. (Insured):</div> <div>SLT7817S</div> </div> <div> <div>Policy No. (Claimant):</div> <div>Excess:</div> </div> <div> <div>Repairer:</div> <div>Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088</div> </div> <div> <div>Handling Insurer:</div> <div>MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]</div> </div> <div> <div>Adjuster:</div> <div>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/07/2018]</div> </div> </div> <div> <div>[Created by insurer]</div> </div>				
<div> <div>ASSOCIATED MAIL RECEIVED</div> <div> View All Compose Case Mail </div> <div> <ul style="list-style-type: none"> MSIG_SG (27/07/2018): Report Send Back Alerts - SJR3175X (TP) </div> </div>				
<div> <div>ALL ASSOCIATED TASKS</div> <div> <div> View All Search Tasks Create New Task Complete </div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div> </div>				
No results.				

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Invoice No 18025-04/MY

Date 10 May 2018

Billing Name & Address

Loh Zhi Jun Derrick
Blk 28B Dover Crescent
#35-33
Singapore 132028

Vehicle No : SJR 3175 X

Model : Honda Civic Type-R

Item	Descriptions	Amount S\$
1	Date of inspection : <u>25 Apr 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>122</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 847.00</u>
	SDLS : EIGHT HUNDRED AND FORTY-SEVEN ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 18025-04/MY / 2018
Date of Report : 10 May 2018

Loh Zhi Jun Derrick
Blk 28B Dover Crescent
#35-33
Singapore 132028

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 23 Apr 2018

Workshop Address : Bluwel Automotive Service Pte Ltd
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

As per your instruction dated **25 Apr 2018** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SJR 3175 X**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SJR 3175 X	Engine No	: K20A5822937
Model	: Honda Civic Type-R	Mileage	: 155629
Year / Capacity	: 2009/1998	Colour	: Silver
Chassis No	: FD21402851		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 225/40 ZR18	Pirelli	5.00	mm	Sport
REAR O/S	: 225/40 ZR18	Pirelli	5.00	mm	Sport
FRONT N/S	: 225/40 ZR18	Pirelli	5.00	mm	Sport
REAR N/S	: 225/40 ZR18	Pirelli	5.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6633 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 12 working days to complete.
5. Enclosed number of photograph : 122 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SJR 3175 X**
 Report No: **TP/ 18025-04/MY / 2018**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear windscreen moulding	Necessary	\$ 55.10	\$ 55.10 NN X
1	Boot lid	Damage	\$ 750.30	\$ 750.30 DD ✓
1	Boot lid lock	Damage	\$ 205.50	\$ ✓205.50 BT ✓
1	Boot lid lock catch	Damage	\$ 30.70	\$ ✓30.70 BT ✓
1	Boot lid logo	Necessary	\$ 86.70	\$ ✓86.70 NEC ✓
1	Boot lid rubber	Damage	\$ 97.60	\$ ✓97.60 CUT ✓
1	Boot lid 'TYRE-R' emblem	Necessary	\$ 65.80	\$ ✓65.80 NEC ✓
2	Boot lid reflectors	Damage	\$ 561.40	\$ ✓561.40 CRA ✓
1	Boot lid outer garnish	Damage	\$ 71.80	\$ 71.80 NN X
2	Rear taillamps	Damage	\$ 631.20	\$ ✓631.20 BR ✓
2	Rear taillamp brackets	Damage	\$ 33.40	\$ ✓33.40 BR ✓
1	Rear taillamp panel	Damage	\$ 83.60	\$ ✓83.60 BT ✓
1	Rear end panel	Damage	\$ 330.40	\$ ✓330.40 DD ✓
1	Rear end panel inner garnish	Damage	\$ 64.00	\$ ✓64.00 BR ✓
1	Rear bumper	Damage	\$ 920.70	\$ ✓920.70 DD ✓
2	Rear bumper side retainers	Damage	\$ 37.00	\$ ✓37.00 NEC ✓
1	Rear bumper lower cover	Damage	\$ 217.50	\$ ✓217.50 BT ✓
1	Rear spare tyre board	Damage	\$ 316.40	\$ 316.40 NN X
1	Rear spare tyre panel	Damage	\$ 984.50	\$ ✓984.50 DD ✓
1	Rear spare tyre tool tray	Damage	\$ 205.30	\$ 205.30 NN X
1	Rear exhaust silencer	Damage	\$ 1150.60	\$ 1150.60 RX
1	Rear exhaust silencer mountings	Necessary	\$ 45.00	\$ ✓45.00 NEC ✓
1	Rear exhaust silencer heat shield	Damage	\$ 89.10	\$ 89.10 RX
2	Rear fenders	O/S Damage	\$ 1560.20	\$ 780.10 RX
1	Rear fender air gate	Damage	\$ 35.10	\$ ✓35.10 BT ✓
2	Rear fender inner trims	Damage	\$ 450.60	\$ 450.60 NN X
1	Rear fender side garnish	Damage	\$ 50.30	\$ ✓50.30 CUT ✓
1	Rear mudflap	Damage	\$ 42.10	\$ 42.10 NN X
			\$ 9171.90	\$ 8391.80
	Discount	20.0%	\$ 1834.38	\$ 1678.36
			\$ 7337.52	\$ 6713.44
<u>Special Nett Items</u>				
1	Rear windscreen sealant	Damage	\$ 80.00	\$ 60.00 NN X
1	Boot lid spoiler	Intact	\$ 900.00	\$
1	Rear bumper lower spoiler	Damage	\$ 750.00	\$ 567.80 750.00 DD ✓
1	Rear reverse sensor (1 set)	Damage	\$ 360.00	\$ 280.00 280.00 CRA ✓
1	Rear reverse camera	Damage	\$ 450.00	\$ 450.00 UB X
			\$ 2540.00	\$ 1540.00
Spare Parts Total			\$ 9877.52	\$ 8253.44

Vehicle No: **SJR 3175 X**
 Report No: **TP/ 18025-04/MY / 2018**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 9877.52	\$ 8253.44 4965.48
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 60.00	\$ 40.00 ✓
2	To remove and refit rear cushion seats, radio speaker board, interior upholstery to facilitate the repairs.	\$ 250.00	\$ 140.00 80.00
3	To remove and refit rear bumper sensor.	\$ 130.00	\$ 80.00 60.00 ○
4	To remove and refit rear camera	\$ 160.00	\$ 80.00 60.00
5	To remove and refit rear windscreen glass.	\$ 210.00	\$ 150.00 NNX
6	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 120.00	\$ 80.00
7	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 2000.00	\$ 1750.00 1200.00
8	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1800.00	\$ 1500.00 800.00 + 300 ○
9	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 250.00	\$ 150.00 50.00
Total		\$ <u>14857.52</u>	\$ <u>12223.44</u>

Vehicle No: SJR 3175 X
Report No: TP/ 18025-04/MY / 2018

LABOUR COST


S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
Total c/f		\$ 14857.52	\$ 12223.44 7335.48

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 9800.00

5800/2

SDLS: NINE THOUSAND EIGHT HUNDRED ONLY


Qualified Appraiser




































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2018		25 Apr 2018 12:46 Edit Adj Rpt	S\$5,800.00 Edit Estimates	S\$5,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AU YUEN KENG , ID: S1599172J								
Main Claimant:	LOY ZHI JUN DERRICK , ID: S8202698C								
Vehicle Reg. No.:	SJR3175X	Date of Loss:	23/04/2018 00:00 - :59 [106 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556340	Policy/Cover Note No.:	29050447QMY Coverage: 10/11/2017 - 09/11/2018						
Vehicle Reg. No. (Insured):	SLT7817S	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (27/07/2018): Report Send Back Alerts - SJR3175X (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJR3175X (556340)**
[SLT7817S]
TP
LOY ZHI JUN DERRICK
Apr 23 2018 12:00AM
[AU YUEN KENG]
Bluwel Automotive Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
2	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
3	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
4	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
5	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
6	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
16	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
17	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
18	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
19	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
22	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
28	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/04/18 17:31	TP PRI & Sketch Plan	 Load PDF	
2	24/04/18 10:49	OI accident report	 Load PDF	
3	25/04/18 12:20	SJR3175X GIA Rpt	 Load PDF	
4	30/05/18 10:50	TP Survey Report	 Load PDF	
5	30/05/18 10:59	Survey Report Pictures Part 1	 Load PDF	
6	30/05/18 10:59	Survey Report Pictures Part 2	 Load PDF	
7	30/05/18 10:59	Survey Report Pictures Part 3	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	01/08/18 10:28	PRS Invoice		Load PDF
2	01/08/18 10:30	PHOTO		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18007598/BSBE2-1

Date: 01/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29050447QMY

Claimant Vehicle No : SJR3175X

Insured Vehicle No : SLT7817S

Date of Loss: 23/04/2018

Nature of Claim: TP

Claim No: 556340

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR3175X

Make & Model: HONDA CIVIC, 2.0 TYPE-R (M)

Engine No: K20A5822937

Reg. Date: 18/06/2009 (Man. Year: 2008)

Chassis No: FD21402851

Colour: Silver

Odometer: 155629 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,877.52	4,952.36	4,925.16	49.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	2,670.00	2,310.00	46.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,857.52	7,622.36	7,235.16	48.70
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	14,857.52	5,800.00	9,057.52	60.96
+ GST 7.00/7.00% (S\$)	1,040.03	406.00	634.03	60.96
Nett Amount (S\$)	15,897.55	6,206.00	9,691.55	60.96

INSPECTION

Date of Assignment: 25/04/2018

Date Inspected: 25/04/2018 Inspected At:

Bluwel Automotive Service Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: XING GUO QIANG**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2018)
Parts: 144	HONDA CIVIC 2.0 TYPE-R (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJR3175X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	55.10 FL	*- FL
2	1		*BOOT LID	Dented	750.30 FL	*750.30 FL
3	1		*BOOT LID LOCK	Bent	205.50 FL	*205.50 FL
4	1		*BOOT LID LOCK CATCH	Bent	30.70 FL	*30.70 FL
5	1		*BOOT LID LOGO	Necessary	86.70 FL	*86.70 FL
6	1		*BOOT LID RUBBER	Cut	97.60 FL	*97.60 FL
7	1		*BOOT LID TYRE-R EMBLEM	Necessary	65.80 FL	*65.80 FL
8	2		*BOOT LID REFLECTORS	Cracked	561.40 FL	*561.40 FL
9	1		*BOOT LID OUTER GARNISH	Not Necessary	71.80 FL	*- FL
10	2		*REAR TAILLAMPS	Broken	631.20 FL	*631.20 FL
11	2		*REAR TAILLAMP BRACKETS	Broken	33.40 FL	*33.40 FL
12	1		*REAR TAILLAMP PANEL	Bent	83.60 FL	*83.60 FL
13	1		*REAR END PANEL	Dented	330.40 FL	*330.40 FL
14	1		*REAR END PANEL INNER GARNISH	Broken	64.00 FL	*64.00 FL
15	1		*REAR BUMPER	Dented	920.70 FL	*920.70 FL
16	2		*REAR BUMPER SIDE RETAINERS	Necessary	37.00 FL	*37.00 FL
17	1		*REAR BUMPER LOWER COVER	Bent	217.50 FL	*217.50 FL
18	1		*REAR SPARE TYRE BOARD	Not Necessary	316.40 FL	*- FL
19	1		*REAR SPARE TYRE PANEL	Dented	984.50 FL	*984.50 FL
20	1		*REAR SPARE TYRE TOOL TRAY	Not Necessary	205.30 FL	*- FL
21	1		*REAR EXHAUST SILENCER	Repair	1,150.60 FL	*- FL
22	1		*REAR EXHAUST SILENCER MOUNTINGS	Necessary	45.00 FL	*45.00 FL
23	1		*REAR EXHAUST SILENCER HEAT SHIELD	Repair	89.10 FL	*- FL
24	2		*REAR FENDERS	Repair	1,560.20 FL	*- FL
25	1		*REAR FENDER AIR GATE	Bent	35.10 FL	*35.10 FL
26	2		*REAR FENDER INNER TRIMS	Not Necessary	450.60 FL	*- FL
27	1		*REAR FENDER SIDE GARNISH	Cut	50.30 FL	*50.30 FL
28	1		*REAR MUDFLAP	Not Necessary	42.10 FL	*- FL
29	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
30	1		*BOOT LID SPOILER	Intact	900.00 FS	*- FS
31	1		*REAR BUMPER LOWER SPOILER	Dented	750.00 FS	*567.80 FS
32	1		*SET REAR REVERSE SENSOR	Cracked	360.00 FS	*200.00 FS
33	1		*REAR REVERSE CAMERA	Used Back	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,711.90	5,998.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,834.38	1,046.14
Total Parts (\$\$)	9,877.52	4,952.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS	New	60.00	40.00
2	TO REMOVE AND REFIT REAR CUSHION SEATS, RADIO SPEAKER BOARD, INTERIOR UPHOLSTERY TO FACILITATE THE REPAIRS	New	250.00	80.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	130.00	60.00
4	TO REMOVE AND REFIT REAR CAMERA	New	160.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	210.00	0.00
6	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS	New	120.00	80.00
7	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	2,000.00	1,200.00
8	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,800.00	1,100.00
9	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	250.00	50.00
Gross Labour Cost (S\$)			4,980.00	2,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >