

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18013684/GGA3Q2

Date: 06/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SFS131J	Insured Vehicle No :	SHD3035P
Date of Loss: 21/07/2018	Nature of Claim:	TP Claim No: MCT18070620

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFS131J	Engine No:	2GR8887117
Make & Model:	TOYOTA LEXUS, 3.5 RX350 STD (A)	Chassis No:	JTHHE5BC705002354
Reg. Date:	04/02/2015 (Man. Year: 2015)	Odometer:	36652 km
Colour:	Blue		
Engine Capacity:	3456 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R19	Rear Tyre Size:	235/40Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,273.39	25,756.87	22,516.52	46.64
Miscellaneous Items	10.00	11.00	-1.00	-10.00
Labour	4,130.00	1,730.00	2,400.00	58.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,413.39	27,497.87	24,915.52	47.54
Approved Total (Overridden) (S\$)		27,496.87		
(S\$)	52,413.39	27,496.87	24,916.52	47.54
+ GST 7.00/7.00% (S\$)	3,668.94	1,924.78	1,744.16	47.54
Nett Amount (S\$)	56,082.33	29,421.65	26,660.68	47.54
+ Car Rental (8.0 x S\$128.40/day) (S\$)		1,027.20		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		30,456.34		

INSPECTION

Date of Assignment:	27/07/2018 Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	27/07/2018 Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2020)
Parts: 143	TOYOTA LEXUS 3.5 RX350 STD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFS131J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR BOOT LAMP L+R	N/S Scratched / O/S Cracked	2,217.20 FL	*1,247.80 FL
2	1		*REAR BOOT	Dented	2,158.70 FL	*1,081.20 FL
3	1		*REAR BOOT WEATHERSTRIP	Cut	451.30 FL	*295.60 FL
4	1		*REAR END PANEL TOP GARNISH	Deformed	641.30 FL	*454.80 FL
5	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
6	1		*REAR BOOT LOGO (RC350)	Necessary	82.50 FL	*62.50 FL
7	1		*REAR BOOT LOGO (LEXUS)	Necessary	89.10 FL	*69.10 FL
8	1		*REAR END PANEL	Buckled	956.10 FL	*836.50 FL
9	2		*REAR FENDER LAMP L+R	N/S Cut / O/S Cracked	1,797.80 FL	*1,572.80 FL
10	2		*REAR FENDER LAMP LOWER BRACKET L+R	Cracked	250.40 FL	*173.00 FL
11	2		*REAR BUMPER RETAINER L+R	Necessary	484.62 FL	*132.60 FL
12	2		*REAR BUMPER SCREW COVER L+R	N/S Necessary /O/S Deformed	185.20 FL	*53.00 FL
13	3		*REAR PARKING SENSOR	Damaged (1 PCS ONLY)	2,067.30 FL	*490.80 FL
14	1		*REAR BUMPER LOWER GARNISH	Deformed	590.30 FL	*395.60 FL
15	1		*REAR BUMPER REFLECTOR LH	Cracked	78.20 FL	*58.20 FL
16	1		*REAR EXHAUST CHROME LH	Cut	778.20 FL	*532.80 FL
17	1		*REAR EXHAUST LH	Not Necessary	1,250.20 FL	*- FL
18	1		*REAR BUMPER TOW COVER	Not Necessary	25.80 FL	*- FL
19	1		*REAR REINFORCEMENT	Bent	1,190.70 FL	*894.70 FL
20	1		*REAR REINFORCEMENT SPONGE	Cracked	195.60 FL	*156.80 FL
21	1		*REAR KEYLESS SENSOR	Damaged	364.60 FL	*265.20 FL
22	1		*REAR BOOT LOCK	Bent	705.83 FL	*498.80 FL
23	1		*FRONT BUMPER	Cracked	1,250.40 FL	*732.30 FL
24	1		*FRONT GRILLE	Cracked	2,972.20 FL	*2,749.30 FL
25	1		*FRONT GRILLE LOWER	Not Necessary	770.60 FL	*- FL
26	1		*FRONT EMBLEM	Necessary	789.40 FL	*588.30 FL
27	1		*FRONT NUMBER PLATE GARNISH	Cracked	185.90 FL	*146.80 FL
28	1		*NUMBER PLATE	Cracked	45.00 FS	*40.00 FS
29	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	698.00 FL	*- FL
30	2		*FRONT BUMPER RETAINER L+R	Necessary	282.60 FL	*168.70 FL
31	2		*FRONT HEADLAMP LOWER BRACKET L+R	Not Necessary	157.20 FL	*- FL
32	2		*FRONT HEADLAMP L+R	Cracked	15,082.40 FL	*11,745.40 FL
33	2		*FRONT PARKING SENSOR CENTRE	Not Necessary	10,982.20 FL	*- FL
34	2		*FRONT PARKING SENSOR COVER	Not Necessary	51.60 FL	*- FL
35	1		*FRONT REINFORCEMENT	Bent	935.10 FL	*738.10 FL
36	1		*FRONT REINFORCEMENT SPONGE	Cracked	157.20 FL	*125.00 FL
37	1		*FRONT REINFORCEMENT TOP GARNISH	Not Necessary	168.50 FL	*- FL
38	1		*FRONT RADIATOR TOP GARNISH	Not Necessary	385.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
39	10		*FRONT RADIATOR TOP GARNISH CLIPS	Not Necessary	50.00 FL	*- FL	
40	1		*FRONT BONNET LOCK - CHECK (NPA)	Not Necessary	-	*- FL	
41	1		*FRONT BONNET CATCH	Not Necessary	275.90 FL	*- FL	
42	1		*REAR BUMPER	Deformed	1,781.25 FL	*1,208.60 FL	
43	2		*FOG LAMP	Cracked	-	*1,100.00 FL	
					Sub Total (S\$)	53,632.10	28,614.30
					- List Item Discount on L Items 10.00/10.00% (S\$)	5,358.71	2,857.43
					Total Parts (S\$)	48,273.39	25,756.87

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	11.00
Sub Total (\$\$)			10.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR FRONT SUPPORT PANEL, FRONT FENDER L+R, REAR FENDER LH, REAR SPARE TYRE HOUSE, REAR FENDER LH AND REALIGN AFFECTED AREAS	New	1,400.00	800.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	1,550.00	800.00
3	TO RUST PROOF AFFECTED AREAS	New	80.00	0.00
4	TO REMOVE & REFIX REAR CUSHION, REAR BACK REST, SIDE GARNISH AND OTHER ATTACHMENT PARTS	New	100.00	60.00
5	TO APPLY SEAL ON WELDING JOINT & NEW PARTS	New	80.00	0.00
6	TO CHECK CHASSIS ALIGNMENT	New	350.00	0.00
7	TO REMOVE & REFIX AIRCON CONDENSER & TOP UP GAS	New	120.00	0.00
8	TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST	New	80.00	30.00
9	TO REMOVE FRONT & REAR PARKING SENSOR AND CHECK WIRING	New	120.00	40.00
10	TO RE-CONFIGURE FRONT HEADLAMP COMPUTER BOX	New	250.00	0.00
Gross Labour Cost (\$\$)			4,130.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >