

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4302L

DATE 26/7/2018 16:51

MAKE :

MODEL : HYUNDAI SONATA

L/Sum

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Refurb</i>			\$ 578.40
	Rear Bumper Reinforcement <i>Refurb</i>			\$ 483.30
	Rear Bumper Clip <i>Refurb</i>			\$ 22.00
	Rear Bumper Sponge <i>Refurb</i>			\$ 137.40
	Rear Bumper Under Cover <i>Refurb</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>Refurb</i>		\$ 38.00	\$ 76.00
	SUB TOTAL			\$ 1,482.90
	LESS 20%			\$ 296.58
	DISCOUNTED TOTAL			\$ 1,186.32
	Rear Bumper Reverse Sensor <i>Refurb</i>			\$ 135.70
	Rear Bumper Rubber Mat <i>Refurb</i>			\$ 50.00
	Rear Bumper Advertisement Logo <i>Refurb</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>Refurb</i>		\$ 100.00	\$ 200.00
				\$ 435.70
	Labour Charge			
	Panel Beating			\$ 350.00 ²⁰⁰
	Spray Painting Charge			\$ 250.00 ²⁰⁰
	Wiring Charge			\$ 50.00 ^{X 2}
	Remove/Refix Reverse Sensor			\$ 120.00 ³⁰
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 2,392.02
<i>Ka lwin 10/10/18</i> <i>27/7/18 1100hr</i> <i>2 Days</i> <i>L/S</i> <i>After Repair & L/S</i> LKK Auto Consultants hereby certify the Report to be a true and correct one. • To resolve any dispute arising from the survey • To display the survey results in writing • Parts prices are based on the latest information • Third party surveys are conducted on a "No Prejudice" basis • No illegal or improper practices are involved • Suppliers of parts and materials are surveyed and is subject to the satisfaction of the insurance company Acknowledged by Reparer Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				