



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 9706C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BOOTLID	TO REPAIR SEE LABOUR	958.00	-
1	BOOTLID MAZDA 3 BADGE	NECESSARY	54.00	54.00
1	BOOTLID SKYACTIV BADGE	NECESSARY	64.00	64.00
1	BOOTLID CENTRE EMBLEM BADGE	NECESSARY	75.00	74.00
2	BOOTLID REFLECTORS @ \$265.00	SERVICEABLE	530.00	-
1	BOOTLID INNER TRIM	SERVICEABLE	121.00	-
4	BOOTLID INNER TRIM CLIPS @ \$5.00	SERVICEABLE	20.00	-
2	BOOTLID RUBBER STOPPERS @ \$13.00	SERVICEABLE	26.00	-
1	BOOTLID LOCK	SERVICEABLE	153.00	-
1	BOOTLID STRIKER BOTTOM	SERVICEABLE	35.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	130.00	-
2	BOOTLID HINGES @ \$146.00	SERVICEABLE	292.00	-
1	BOOTLID KEYLESS SENSOR	SERVICEABLE	78.00	-
1	REAR END PANEL	SERVICEABLE	506.00	-
1	REAR END PANEL INNER TRIM	SERVICEABLE	86.00	-
4	REAR END PANEL INNER TRIM CLIPS @ \$5.00	SERVICEABLE	20.00	-
2	REAR LAMPS @ \$504.00	SERVICEABLE	1,008.00	-
2	REAR LAMP PANEL @ \$358.00	SERVICEABLE	716.00	-
8	REAR LAMP HOLDER CLIPS @ \$26.70	SERVICEABLE	213.60	-
1	REAR BUMPER	DEFORMED	1,075.00	1,075.00
2	REAR BUMPER REFLECTORS @ \$51.00	SERVICEABLE	102.00	-
1	REAR BUMPER END SPLASHSHIELD COVER	SERVICEABLE	80.00	-
10	REAR BUMPER CLIPS @ \$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	538.00	-
2	REAR BUMPER SIDE RETAINERS @ \$37.00	SERVICEABLE	74.00	-
2	REAR BUMPER SIDE HOLDERS @ \$46.00	SERVICEABLE	92.00	-
4	REAR BUMPER SIDE HOLDER RIVETS @ \$9.00	SERVICEABLE	36.00	-
2	REAR BUMPER TOW COVER @ \$18.00	O/S SERVICEABLE / N/S MISSING	36.00	18.00
4	REAR BUMPER SCREW SPACER @ \$8.00	SERVICEABLE	32.00	-

Report Ref No. CC4/EQI18013708/T1pa3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR LICENCE PLATE LAMP @ \$72.00	SERVICEABLE	144.00	-
1	REAR LICENCE PLATE GARNISH	SERVICEABLE	50.00	-
	LESS 20% DISCOUNT		-1,478.92	-267.00
			5,915.68	1,068.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	450.00	-
1	REAR LICENCE PLATE (SN)	SERVICEABLE	80.00	-
			530.00	-
	<b><u>LABOUR</u></b>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	30.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		120.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		150.00	40.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	30.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BOOTLID.		600.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		600.00	400.00
			1,710.00	930.00
<b>GRAND TOTAL</b>			<b>8,155.68</b>	<b>1,998.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,998.00</b>

Report Ref No. CC4/EQI18013708/T1pa3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.