

15/5/2010

INS. CASE OWNER:

CC 4/LPC1801

LKK:
IDAC:

Surveyor:

DOI:

Date / Time

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$S

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

7/7/18

TH

08/07/19

14-1-19

29-1-19

SLC 1A11A -x SGN 3086B -x

OI rear-ended to TP.
- OUIA, TP LOD IN
- LAC APPROVED MANDATE

- SEND 1st OFFER TO TP.
- TP ACCEPTED OFFER.
- ALL DOCS IN ORDER.
- TO CLOSE.

LOD IN. FOR MANDATE

FOR MANDATE

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):
After call ltr to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:
Post-Repair Photos:
Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 181 \$S 8,063.07 10 days) Reduction: 37 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability: 100 % (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: 655 \$S 8,628.02

Loss of Rental (LOR): \$S 1,800 (12 days) 40

Loss of Use (LOU): \$S (S x days)

Loss of Income (LOI): \$S (S x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]

GIA/LTA Search \$S 2.44

Medical: \$S 180

Disbursement: \$S (e.g. Tow/ Independent)

Legal Cost \$S

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$450.00

Total: \$S 10,610.02 Global Sum \$S: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: \$S 10,610.02 Name 1: ACCORD

Payee 2: (Strike if N.A.) \$S - Name 2: AUTO SERVICES PTE LTD

Payee 3: (Strike if N.A.) \$S - Name 3: -

(08/11/13) wef

REF:

LPC

ASS. REC. BY:

ASSIGNMENT

From: Date: 27/07/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLC 1911G

at Workshop m/s

Accord-Auto

of

10 AMK Ind. Park 2A #03-11

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7x10 days Res.: Yes or No

Lum Sum: 1.13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLC 1911G Yr Regn: 04.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey c.c. 2356

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

92371

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTMAC 1890GC 203028

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/ 55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

27/7/18

D.O.I.

27/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/7 Fine post to Catherine

181. \$ 8,063.57
(Net: \$ 4,875.30 (37%))

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18013714/Kub3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 27-07-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGN 3086B		Veh. Inspected	SLC 1911G
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	27/07/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size		Make	Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
4. Description of Damages				
5. General Information				
Accident Date	25/07/2018		Inspection Date	27/07/2018
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SLC1911G
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	ODYSSEY 2.4 EXV-S CVT SR
Chassis No. :	JHMRC1890GC203028
Propellant :	Petrol
Engine No. :	K24W72011362
Engine Capacity :	2356 cc
Maximum Power Output :	129.0 kW (172 bhp)
Maximum Laden Weight :	2450 kg
Unladen Weight :	1855 kg
Year Of Manufacture :	2016
Original Registration Date :	12 Apr 2016
Lifespan Expiry Date :	-
COE Category :	B - Car above 1600cc or 97kW (130bhp)
Quota Premium :	\$46,502.00
COE Expiry Date :	11 Apr 2026
Road Tax Expiry Date :	11 Apr 2019
PARF Eligibility Expiry Date :	11 Apr 2026
Inspection Due Date :	11 Apr 2019
Intended Transfer Date :	26 Jul 2018
CO2 Emission :	184.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised ESTIMATE

Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Attn: Accident Claims Department

*1. B1
Mehway B4 pain*

7-10 days

Date : 27/07/2018
Vehicle No : SLC1911G
Veh Make/Model : Honda Odyssey 2.4 EXV-S
YOM : 2016
Chassis No : JHMRC1890GC203028
Date of Accident : 25/07/2018

No	Qty	Description	Amount \$
		<u>List Items:-</u>	
1	1	Tail gate	\$ <i>Bt</i> 1,193.00
2	1	Tail gate reflector (LH)	\$ <i>cm</i> 378.60
3	1	Tail gate reflector (RH)	\$ <i>cm</i> 378.60
4	1	Tail gate "ODYSSEY" chrome	\$. 225.90
5	1	Tail gate logo	\$ <i>ru</i> 25.80
6	1	Tail gate chrome	\$ <i>wap</i> 195.00
7	2	Tail gate number plate lamp	\$ 110.00
8	1	Tail gate windscreen glass	\$ <i>su</i> 1,211.00
9	1	Tail gate windscreen glass moulding	\$ <i>ru</i> 220.00
10	1	Tail gate wiper motor	\$ 247.40
11	2	Tail gate hinge	\$ <i>n</i> 100.00
12	1	Tail gate weatherstrip	\$ 115.00
13	1	Tail gate lock	\$ <i>Tu</i> 189.00
14	1	Tail gate inner trim board	\$ 202.20
15	10	Tail gate inner trim board clip	\$ 60.00
16	1	LH tail lamp	\$ <i>ru</i> 821.80
17	1	RH tail lamp	\$ 821.80
18	1	Rear LH corner bumper	\$ 75.30
19	1	Rear RH corner bumper	\$ 75.30
20	1	Rear bumper	\$ <i>Bt</i> 552.70
21	1	Rear LH bumper reflector	\$ <i>ru</i> 43.80
22	1	Rear RH bumper reflector	\$ <i>cm</i> 43.80
23	1	Rear LH bumper spoiler	\$ 111.80
24	1	Rear RH bumper spoiler	\$ <i>Bu</i> 111.80
25	2	Rear bumper side retainer	\$ <i>su</i> 80.00
26	10	Rear bumper clips	\$ <i>ru</i> 38.00
27	1	Antenna assy	\$ 85.00
28	1	Keyless smart entry buzze	\$ 85.00
29	1	End panel	\$ <i>Bt</i> 551.80
30	1	End panel top garnish	\$ 135.00
Balance b/f			\$ 8,484.40

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Attn: Accident Claims Department

Date : 27/07/2018

Vehicle No : SLC1911G

Veh Make/Model : Honda Odyssey 2.4 EXV-S

YOM : 2016

Chassis No : JHMRC1890GC203028

Date of Accident : 25/07/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 8,484.40
31	6	End panel top garnish clip	\$ 18.00
32	1	Floor panel	\$ 397.56
33	1	Floor panel board	\$ 465.72
34	1	Exhaust silencer	\$ 636.80
35	2	Exhaust silencer rubber	\$ 50.00
36	1	Exhaust silencer heat shield	\$ 90.36
		Total - List Item	\$ 10,142.84
		Less 20%	\$ 2,028.57
		Total	\$ 8,114.27
		Special Nett Items:-	
1	1	Rear number plate with holder	\$ 55.00
2	1 Set	Rear reverse sensor (original)	\$ 400.00
3	1	Tail gate windscreen glass sealant/gum and clip	\$ 80.00
4	1	Tail gate windscreen glass v-cool	\$ 300.00
		Total - SN Item	\$ 835.00
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 1,200.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,100.00
3		To apply anti rust treatment.	\$ 120.00
4		To check wiring system & light.	\$ 80.00
5		To remove and replace reverse sensor.	\$ 120.00
6		To remove and reinstall tail gate winscreen glass.	\$ 150.00
7		To remove and reinstall rear passenger seats to assist on repair.	\$ 150.00
8		To remove and replace tailgate attachments and test water leaking.	\$ 100.00
9		To remove and reinstall interior upholstery.	\$ 80.00
10		To remove and replace/adjust exhaust silencer, rubber and heat shield.	\$ 150.00
		Total - L/C	\$ 3,250.00
		Sub-Total	\$ 12,199.27
		7% GST	\$ 853.95
		Total	\$ 13,053.22

Acknowledged by Repairer

Signature:

Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Withheld ESTIMATE

Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Attn: Accident Claims Department

Date : 27/07/2018

Vehicle No : SLC1911G

Veh Make/Model : Honda Odyssey 2.4 EXV-S

YOM : 2016

Chassis No : JHMRC1890GC203028

Date of Accident : 25/07/2018

*1. B1
Mewny B4 pain
-10 days
88063.57*

No	Qty	Description	Amount \$
List Items:-			
1	1	Tail gate	\$ <i>Ref</i> 1,193.00
2	1	Tail gate reflector (LH)	\$ <i>CM</i> 378.60
3	1	Tail gate reflector (RH)	\$ <i>CM</i> 378.60
4	1	Tail gate "ODYSSEY" chrome	\$ <i>Sn</i> 225.90
5	1	Tail gate logo	\$ <i>Re</i> 25.80
6	1	Tail gate chrome	\$ <i>Wap</i> 195.00
7	2	Tail gate number plate lamp	\$ <i>Sn</i> 110.00
8	1	Tail gate windscreen glass	\$ <i>Sn</i> 1,211.00
9	1	Tail gate windscreen glass moulding	\$ <i>Re</i> 220.00
10	1	Tail gate wiper motor	\$ <i>Sn</i> 247.40
11	2	Tail gate hinge	\$ <i>Re</i> 100.00
12	1	Tail gate weatherstrip	\$ <i>Sn</i> 115.00
13	1	Tail gate lock	\$ <i>Sn</i> 189.00
14	1	Tail gate inner trim board	\$ <i>Sn Ref</i> 202.20
15	10	Tail gate inner trim board clip	\$ <i>N/A</i> 60.00
16	1	LH tail lamp	\$ <i>Sn</i> <i>Cost Ref</i> 821.80
17	1	RH tail lamp	\$ <i>Sn</i> <i>Cost Ref</i> 821.80
18	1	Rear LH corner bumper	\$ <i>mg 017</i> 75.30
19	1	Rear RH corner bumper	\$ <i>u</i> 75.30
20	1	Rear bumper	\$ <i>Ref</i> 552.70
21	1	Rear LH bumper reflector	\$ <i>Re</i> 43.80
22	1	Rear RH bumper reflector	\$ <i>CM</i> 43.80
23	1	Rear LH bumper spoiler	\$ <i>Sn</i> 111.80
24	1	Rear RH bumper spoiler	\$ <i>Bu</i> 111.80
25	2	Rear bumper side retainer	\$ <i>Sn</i> 80.00
26	10	Rear bumper clips	\$ <i>Re</i> 38.00
27	1	Antenna assy	\$ <i>Sn</i> 85.00
28	1	Keyless smart entry buzze	\$ <i>CM</i> 85.00
29	1	End panel	\$ <i>Ref</i> 551.80
30	1	End panel top garnish	\$ <i>Ref</i> 135.00
Balance b/f			\$ 8,484.40

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Attn: Accident Claims Department

Date : 27/07/2018

Vehicle No : SLC1911G

Veh Make/Model : Honda Odyssey 2.4 EXV-S

YOM : 2016

Chassis No : JHMRC1890GC203028

Date of Accident : 25/07/2018

No	Qty	Description	Amount S
		Balance c/f	\$ 8,484.40
31	6	End panel top garnish clip	\$ 18.00
32	1	Floor panel	\$ 397.56
33	1	Floor panel board	\$ 465.72
34	1	Exhaust silencer	\$ 636.80
35	2	Exhaust silencer rubber	\$ 50.00
36	1	Exhaust silencer heat shield	\$ 90.36
		Total - List Item	\$ 10,142.84
		Less 20%	\$ 2,028.57
		Total	\$ 8,114.27
		Special Nett Items:-	
1	1	Rear number plate with holder	\$ 55.00
2	1 Set	Rear reverse sensor (original)	\$ 400.00
3	1	Tail gate windscreen glass sealant/gum and clip	\$ 80.00
4	1	Tail gate windscreen glass v-cool	\$ 300.00
		Total - SN Item	\$ 835.00
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 1,200.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,100.00
3		To apply anti rust treatment.	\$ 120.00
4		To check wiring system & light.	\$ 80.00
5		To remove and replace reverse sensor.	\$ 120.00
6		To remove and reinstall tail gate winscreen glass.	\$ 150.00
7		To remove and reinstall rear passenger seats to assist on repair.	\$ 150.00
8		To remove and replace tailgate attachments and test water leaking.	\$ 100.00
9		To remove and reinstall interior upholstery.	\$ 80.00
10		To remove and replace/adjust exhaust silencer, rubber and heat shield.	\$ 150.00
		Total - L/C	\$ 3,250.00
		Sub-Total	\$ 12,199.27
		7% GST	\$ 853.95
		Total	\$ 13,053.22

Acknowledged by Repairer

Signature:

Date:

Page 2/2

12,938.95

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

SUPPLEMENTARY

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
Attn: Accident Claims Department

Date : 30/07/2018
Vehicle No : SLC1911G
Veh Make/Model : Honda Odyssey 2.4 EXV-S
YOM : 2016
Chassis No : JHMRC1890GC203028
Date of Accident : 25/07/2018

[illegible]

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 26 July 2018 3:57 PM
To: admin-d@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: Accident Involving SLC1911G & SGN3086B on 25/07/2018 Along Boundary Rd

4.13pm @ 26/7/2018
vehicle in
person @ Jessy
arrange on 27/07/18

Our Ref : 17/18/18/VP05/020787

Dear Nivitha,

Kindly proceed to arrange to the pre-repair survey.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Accord Auto(Claims) [mailto:claims@mycarworkshop.com.sg]

Sent: Thursday, 26 July, 2018 3:53 PM

To: ONG LI LI

Cc: MT_Claim_SG; assignments@lkkauto.com; Nivitha (LKK Auto)

Subject: Re: Accident Involving SLC1911G & SGN3086B on 25/07/2018 Along Boundary Rd

Dear Li Li,

We would be appointing Kenneth Kong to conduct PRS.

No.	Name	Please tick √
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	√
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On 26 July 2018 at 15:33, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick
		√
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	

6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Accord Auto(Claims) [mailto:claims@mycarworkshop.com.sg]

Sent: Thursday, 26 July, 2018 3:27 PM

To: MT_Claim_SG

Cc: Gilbert Ng

Subject: Accident Involving SLC1911G & SGN3086B on 25/07/2018 Along Boundary Rd

Dear Sir/Mdm,

Kindly assist arrange Pre-Repair Survey for SLC1911G, vehicle in workshop.

Please provide us 10 surveyor name list.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile**LONPAC INSURANCE BHD**

Ref : CC4/LPC18013714/Khb3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 24-07-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGN 3086B	Veh. Inspected	SLC 1911G
Policy No.	Z17VP05015900	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020787	Excess (\$)	0.00
Assign From	GERALD	Assign Date	26/07/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY (A)	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMRC1890GC203028	Colour	METALLIC GREY
Odometer	92371	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	7 mm
L/H Front Tyre	215/55 R17	MICHELIN	7 mm
R/H Rear Tyre	215/55 R17	MICHELIN	7 mm
L/H Rear Tyre	215/55 R17	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/07/2018	Inspection Date	27/07/2018
Survey held at	10 ANG MO KIO INDUSTRIAL PARK		
Repairer	ACCORD AUTO SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
 B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
--	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 1911G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE	BENT	1,193.00	1,193.00
1	TAIL GATE REFLECTOR (LH)	CRACKED	378.60	378.60
1	TAIL GATE REFLECTOR (RH)	CRACKED	378.60	378.60
1	TAIL GATE 'ODYSSEY' CHROME	SERVICEABLE	225.90	-
1	TAIL GATE LOGO	NECESSARY	25.80	25.80
1	TAIL GATE CHROME	WARPED	195.00	195.00
2	TAIL GATE NUMBER PLATE LAMP	SERVICEABLE	110.00	-
1	TAIL GATE WINDSCREEN GLASS	SERVICEABLE	1,211.00	-
1	TAIL GATE WINDSCREEN GLASS MOULDING	NECESSARY	220.00	220.00
1	TAIL GATE WIPER MOTOR	SERVICEABLE	247.40	-
2	TAIL GATE HINGE	TO REPAIR SEE LABOUR	100.00	-
1	TAIL GATE WEATHERSTRIP	SERVICEABLE	115.00	-
1	TAIL GATE LOCK	JAMMED	189.00	189.00
1	TAIL GATE INNER TRIM BOARD	SERVICEABLE	202.20	-
10	TAIL GATE INNER TRIM BOARD CLIP	NOT NECESSARY	60.00	-
1	LH TAIL LAMP	SERVICEABLE	821.80	-
1	RH TAIL LAMP	CUT	821.80	821.80
1	REAR LH CORNER BUMPER	MTG DISTORTED	75.30	75.30
1	REAR RH CORNER BUMPER	MTG DISTORTED	75.30	75.30
1	REAR BUMPER	BENT	552.70	552.70
1	REAR LH BUMPER REFLECTOR	DENTED	43.80	43.80
1	REAR RH BUMPER REFLECTOR	CRACKED	43.80	43.80
1	REAR LH BUMPER SPOILER	SERVICEABLE	111.80	-
1	REAR RH BUMPER SPOILER	BUCKLED	111.80	111.80
2	REAR BUMPER SIDE RETAINER	SERVICEABLE	80.00	-
10	REAR BUMPER CLIPS	NECESSARY	38.00	38.00
1	ANTENNA ASSY	SERVICEABLE	85.00	-
1	KEYLESS SMART ASSY BUZZE	CRACKED	85.00	85.00
1	END PANEL	BENT	551.80	551.80
1	END PANEL TOP GARNISH	DENTED	135.00	135.00

Report Ref No. CC4/LPC18013714/Khb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL GATE PULL POCKET (ADDITIONAL)	DENTED	15.50	15.50
1	REAR RH FENDER INNER TRIM (ADDITIONAL)	DEFORMED	849.10	849.10
10	REAR RH FENDER INNER TRIM CLIPS (ADDITIONAL)	NECESSARY	60.00	60.00
6	END PANEL TOP GARNISH CLIP	NECESSARY	18.00	18.00
1	FLOOR PANEL	BENT	397.56	397.56
1	FLOOR PANEL BOARD	SERVICEABLE	465.72	-
1	EXHAUST SILENCER	TO REPAIR SEE LABOUR	636.80	-
2	EXHAUST SILENCER RUBBER	SERVICEABLE	50.00	-
1	EXHAUST SILENCER HEAT SHIELD	TO REPAIR SEE LABOUR	90.36	-
	LESS 20% DISCOUNT		-2,213.49	-1,290.89
			8,853.95	5,163.57
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	55.00	-
1	SET REAR REVERSE SENSOR (ORIGINAL) (SN)	DENTED	400.00	400.00
1	TAIL GATE WINDSCREEN GLASS SEALANT /GUM AND CLIP (SN)	NECESSARY	80.00	60.00
1	TAIL GATE WINDSCREEN GLASS V-COOL (SN)	NOT NECESSARY	300.00	-
			835.00	460.00
	LABOUR			
	SPRAY PAINTING ON ALL AFFECTED AREA.		1,200.00	900.00
	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF TAIL GATE HINGE,EXHAUST SILENCER AND EXHAUST SILENCER HEAT SHIELD.		1,100.00	1,000.00
	TO APPLY ANTI RUST TREATMENT.		120.00	90.00
	TO CHECK WIRING SYSTEM & LIGHT.		80.00	20.00
	TO REMOVE AND REPLACE REVERSE SENSOR.		120.00	50.00
	TO REMOVE AND REINSTALL TAIL GATE WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE AND REINSTALL REAR PASSENGER SEATS TO ASSIST ON REPAIR.		150.00	120.00
	TO REMOVE AND REPLACE TAILGATE ATTACHMENTS AND TEST WATER LEAKING.		100.00	60.00

Report Ref No. CC4/LPC18013714/Khb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REINSTALL INTERIOR UPHOLSTERY .	NOT NECESSARY	80.00	80.00
	TO REMOVE AD REPLACE /ADJUST EXHAUST SILENCER RUBBER AND HEAT SHIELD .		150.00	-
			3,250.00	2,440.00
GRAND TOTAL			12,938.95	8,063.57
RECOMMENDED COST OF REPAIRS				8,063.57

Report Ref No. CC4/LPC18013714/Khb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.