

REC. BY: Kenneth REF: CS/CT#18013747/K9d3 72
 Special Instruction: _____
 Surveyor: Manmen ASSIGNMENT (Office)
 From (Person): Huong Shiong Yi of CTI Date/Time: 27/7/18 @ 2.51pm
 Estimated Cost: _____ Bill to: _____
 OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SFJ 2812L Insured: GX 1979K
 at Workshop n/s: Kew Motor Tel: 6458 2283
 of Blk 9 Sin Ming Ind. Est #01-46
 Policy No: DMCVSN1617591802 Claim No: SNM18D03677C02
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 26/07/2018
 (Client's Record) 30/07/2018
 CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement: _____
 Date/Time: 3:42pm @ 27/7/18 Person Contacted: Ceresa Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SFJ 2812L - CS3 / MSG17023174 / R19/22 -1 DOA: 2/12/2017
	GX 1979K - NA / CTI 18008355 / 24 DOA: 15/05/2018
15/10	84731.43 encil & confirm (Red @ 3296.39, 41%)

(08/11/12) wsf

REF: CTI

ASS. REC. BY:

ASSIGNMENT

From: Date: 30/7/18

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFJ 2812L

at Workshop m/s

of 31x9, Sir Ming Ind. Est #01-46

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.84 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFJ 2812L Yr Regn: 04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Harrier Wagon c.c. 1998

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 5879 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTEBB 3G11 20J 001834

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 26/7/18

D.O.I. 30/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/7 File pass to Customer

RECEIVED 10 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 15/10 12:30 PM

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

120

Report Format :

Lump Sum / I.B.I. (\$) 4731.43

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18013747/Kqd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 27-07-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 1979K	Veh. Inspected	SFJ 2812L	
Policy No.	DMCVSN1617591802	Coverage (\$)	0.00	
Claim No.	SNM18D03677C02	Excess (\$)	0.00	
Assign From	MERIMEN (HWANG SHIANG YI)	Assign Date	27/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/07/2018	Inspection Date	30/07/2018	
Survey held at	KAY MOTOR BLK 9 SIN MING INDUSTRIAL ESTATE #01-46 SINGAPORE 575644			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jul 2018		27 Jul 2018 14:51 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SG LEASING PTE LTD, Co. Reg. No.: 201317520E		
Main Claimant:	NG XI QI, ID: S8539512B		
Vehicle Reg. No.:	SFJ2812L	Date of Loss:	26/07/2018 11:00 - :59
Claim Type:	TP / SNM18D03677C02	Policy/Cover Note No.:	DMCVSN1617591802 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	GX1979K	Policy No. (Claimant):	P2115944
		Excess:	S\$0.00
Repairer:	Kay Motor (HQ) BLK 9 SIN MING INDUSTRIAL ESTATE #01-46, 565744 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/08/2018]		
Driver/Custodian (Insured):	WONG CHIN YUNG (44 / Male), NRIC: S7460855H, Tel: +6596926098		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Ng Xi Qi
c/o Block 9 #01-46
Sin Ming Ind Est
Singapore 575644

27 July. 18

WITHOUT PREJUDICE
Your Ref: GX1979K

via fax: 6224 7478

Attention : The Motor Claims Department

China Taiping Insurance Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Dear Sir,


**ACCIDENT INVOLVING GX 1979K & SFJ 2812L
AT EUNOS LINK SLIP ROAD TO UBI AVE 2 ON 26-07-2018**

I am the registered owner of vehicle – SFJ 2812L which was involved in the above accident.

As the result of your insured driver's (GX 1979K) negligence, thereby causing the said accident, my vehicle sustained damages on the rear portions and it's available for your assessor to inspect at M/S KAY MOTOR of Blk 9 Sin Ming Ind Estate, #01-46
Singapore 575644 Tel: 6458 2283 Fax: 64549 8863
Email : kayautosg@yahoo.com

Kindly arrange for your assessor to inspect my car soonest possible.

Enclosed the Accident Report & LTA search for your attention.

Yours faithfully


KAY MOTOR
BLOCK 9 SIN MING INDUSTRIAL ESTATE
#01-46
SINGAPORE 575644
TEL: 6458 2283 FAX: 6459 8863
EMAIL: kayautosg@yahoo.com

Ms Ng Xi Qi

27 July 2018

Estimate To Repair Toyota Harrier – SFJ 2812L

1pc rear boot lid
 1pc rear boot lid 'Harrier' emblem
 1pc rear boot lid 'Turbo' emblem
 1pc rear boot 'Toyota' badge
 1pc rear boot rubber
 1pc rear boot centre protector
 1pc rear boot n/s lamp
 1pc rear boot lock
 1pc rear bumper
 1pc rear bumper lower
 1pc rear bumper sensor n/s
 1pc rear bumper n/s reflector
 1pc rear bumper reinforcement
 1pc rear bumper sponge
 1pc n/s rear tail lamp
 1pc rear end panel
 1pc rear windscreen moulding

less 20% 25%

1set rear bumper clips
 1 rear windscreen sealant

To remove & refit rear windscreen
 To remove & refit rear wiper motor & wiring
 To repair & panelbeat rear boot inner panel,
 cut/weld & renew rear end panel, dismantle & fit the above parts.
 To putty & spray painting

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

By \$ 1712.29 ✓
 m 121.25 ✓
 m 131.35 ✓
 m 81.10 X
 h 374.45 X
 h 327.70 X
 h 121.28 X
 m 294.70 ✓
 m 1217.45 ✓
 cm 471.60 ✓
 m 380.00 ✓
 h 171.85 X
 h 531.10 X
 h 172.45 X
 m 581.40 X
 h 781.10 X
 m 126.60 ✓

 7597.27
 1519.45

 6077.82
 m 50.00 sn ✓
 m 40.00 sn ✓
 180.00 1201
 80.00 201
 750.00 5001
 850.00 6601

Total: \$ 8027.82

8028.14

Not attached
 Repairing B&P
 1.B.1 @ 4731.43
 4-5 days
 KennethKang@lkkauto.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013747/KQD3N2

Date: 16/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1617591802
Claimant Vehicle No :	SFJ2812L	Insured Vehicle No :	GX1979K
Date of Loss:	26/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03677C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFJ2812L	Engine No:	8ARZ117025
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	JTEZB3GH20J001834
Reg. Date:	24/04/2018 (Man. Year: 2018)	Odometer:	5879 km
Colour:	Metallic Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,168.14	3,431.43	2,736.71	44.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	1,300.00	560.00	30.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	8,028.14	4,731.43	3,296.71	41.06

INSPECTION

Date of Assignment:	27/07/2018	
Date Inspected:	30/07/2018	Inspected At:
		Kay Motor (HQ) BLK 9 SIN MING INDUSTRIAL ESTATE #01-46 Singapore 565744

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2018)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFJ2812L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,712.29 FL	*1,712.29 FL
2	1		*REAR BOOT LID HARRIER EMBLEM	Necessary	121.25 FL	*121.25 FL
3	1		*REAR BOOT LID TURBO EMBLEM	Necessary	131.35 FL	*131.35 FL
4	1		*REAR BOOT TOYOTA BADGE	Not Necessary	81.10 FL	*- FL
5	1		*REAR BOOT RUBBER	Serviceable	374.45 FL	*- FL
6	1		*REAR BOOT CENTRE PROTECTOR	Serviceable	327.70 FL	*- FL
7	1		*REAR BOOT N/S LAMP	Serviceable	121.28 FL	*- FL
8	1		*REAR BOOT LOCK	Dented	294.70 FL	*294.70 FL
9	1		*REAR BUMPER	Buckled	1,217.45 FL	*1,217.45 FL
10	1		*REAR BUMPER LOWER	Cracked	471.60 FL	*471.60 FL
11	1		*REAR BUMPER SENSOR N/S	Dented	380.00 FL	*380.00 FL
12	1		*REAR BUMPER N/S REFLECTOR	Serviceable	171.85 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Serviceable	531.10 FL	*- FL
14	1		*REAR BUMPER SPONGE	Serviceable	172.45 FL	*- FL
15	1		*N/S REAR TAIL LAMP	Serviceable	581.40 FL	*- FL
16	1		*REAR END PANEL	Repair	781.10 FL	*- FL
17	1		*REAR WINDSCREEN MOULDING	Necessary	126.60 FL	*126.60 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,687.67	4,545.24
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,519.53	1,113.81
Total Parts (\$\$)	6,168.14	3,431.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REAR WINDSCREEN	New	180.00	120.00
2	TO REMOVE & REFIT REAR WIPER MOTOR & WIRING	New	80.00	20.00
3	TO REPAIR & PANELBEAT REAR BOOT INNER PANEL,CUT/WELD & RENEW REAR END PANEL,DISMANTLE & FIT THE ABOVE PARTS	New	750.00	500.00
4	TO PUTTY & SPRAY PAINTING	New	850.00	660.00
Gross Labour Cost (S\$)			1,860.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >