

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/TMI18013756/K1RBS2**Date:** 31/08/2018REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MV012010
<b>Claimant Vehicle No :</b>	SH7174T	<b>Insured Vehicle No :</b>	SKZ8080Z
Date of Loss:	25/07/2018	Nature of Claim:	TP
		Claim No:	M1803727

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SH7174T</b>		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU702275
Reg. Date:	11/01/2017 (Man. Year: 2017)	Chassis No:	KMHLB41UMHU098172
Colour:	Blue	Odometer:	257021 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,033.76	1,192.16	1,841.60	60.70
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,790.00	900.00	890.00	49.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,833.76</b>	<b>2,102.16</b>	<b>2,731.60</b>	<b>56.51</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>338.36</b>	<b>147.15</b>	<b>191.21</b>	<b>56.51</b>
<b>Nett Amount (S\$)</b>	<b>5,172.12</b>	<b>2,249.31</b>	<b>2,922.81</b>	<b>56.51</b>

INSPECTION

Date of Assignment:	06/08/2018	
Date Inspected:	27/07/2018	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

**Adjuster:** KALVIN ANG WEI KUN**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 31 Aug 2018)

**Parts:** 143    HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SH7174T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	603.60 FL	*603.60 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*TAIL LAMP RH	Cracked	565.60 FL	*565.60 FL
4	1		*REAR FENDER RH	Repair	2,020.10 FL	*- FL
5	1		*REAR FENDER LINING RH	Serviceable	164.40 FL	*- FL
6	1		*REAR WINDSCREEN MOULDING	Not Necessary	60.00 FL	*- FL
7	1		*REAR BUMPER ADVERTISEMENT	Necessary	50.00 FS	*50.00 FS
8	1		*REAR FENDER ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
9	1		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS
10	1		*REAR BUMPR BRACKET RH	Cracked	49.00 FL	*49.00 FL
11	1		*BUMPER MAT RUBBER	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,730.70</b>	<b>1,440.20</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	696.94	248.04
<b>Total Parts (\$)</b>	<b>3,033.76</b>	<b>1,192.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	10.00
<b>Sub Total (\$\$)</b>			<b>10.00</b>	<b>10.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	500.00	400.00
3	WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	0.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY	New	150.00	50.00
6	REMOVE/REFIX WINDSCREEN	New	120.00	0.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,790.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >