

ASS. REC. BY:

REP: CS/FCI 18013784/Ksd3

n2

Special Instruction:

Surveyor of

Cus

Kenneth

ASSIGNMENT (Office)

From (Person):

May chuan

of

FCI

Date/Time:

30/7/18 @ 8.22am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8LX 7713L

Insured:

SHC 2840T

at Workshop m/s

Esteem Performance

Tel:

64841221

of

81K 5033, Amk Ind. Park 2 #01-251/259

Policy No:

Claim No:

D18005708 MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/07/2018

CA / REV / REP. / REV 24 HRS

CDS

Insp: Sin Ming

H.O.D. Endorsement:

Date/Time:

30/7/18 @ 9.42am

Person Contacted:

Common

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

8LX 7713L-X

SHC 2840T-NA/INC/7005419/K4

DOA: 18/3/2017

31/07/18

@ 15:24 p.m. revised RA to May chuan via email.

31/8

84674.56 Confirm

(08/11/13) wef

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From: Date: 30/07/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 7713L
at Workshop m/s Esteem Performance
of 385 Sin Ming Drive

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$82k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLX 7713L Yr Regn: 04.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle c.c. 1496 Wagon

Colour: n.p. white A/C: Insured / Std / NI / NA

Sp. Reading: 13868 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GP7 1121431

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50R16

R: ————

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 26/7/18

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 30/7/18

Survey held at

Des. of Damages: Frt Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/7 File pass to Catherine

05/09/18 Confirmed P/P \$4,674.56 @ 6 days with Kenneth.
(P\$3,656.20 Red - 44%.)

RECEIVED 06 SEP 2018

Date/Time, File Pass to?

1) 05/09/18 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ 4,674.56 P/P)

160
50
50+50
17
327



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118013784/Ksd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2840T	Veh. Inspected	SLX 7713L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005708MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	30/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/07/2018	Inspection Date	30/07/2018	
Survey held at	385 SIN MING RIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005708MFSH

Date: 31 July 2018

Our Ref: CS/FCI18013784/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 7713L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/07/2018 at the premises of M/s Esteem Performance Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 8,330.76 .
Revised Estimate Amount	: S\$ 4,674.56 .
"Check" Items Amount	: S\$ 795.44 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-07-2018	Our Ref No. D18005708MFSH
Accident Date	26-07-2018	Claim Type. Third Party
Insured Vehicle	SHC2840T	Third Party Vehicle. SLX7713L
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	CARMEN LIM	
Contact No.	64841221/ 87990066	Fax No. 64510394
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242751)



PRI Documents



Close



PRI Header Details

Claim No	D18005708MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & ESTEEM P
Workshop Name	ESTEEM PERFORMANCE PTE LTD (Contact Person : CARMEN LIM)	Survey Location & Contact Details	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259 Mobile: 87990066 , Phone: 64841221 , Fax: 6451039 EmailId: CARMEN@ESTEEMPERF.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2840T	TP Vehicle No	SLX7713L
PRI Recieved Date	27-07-2018 05:43:53 PM	Surveyor Appointed Date	30-07-2018 08:21:04 AM	Surveyor Accept Date	30-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-07-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 31 July 2018 3:24 PM
To: MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'Nivitha (LKK Auto)'; 'SUR'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18005708MFSH/1
Attachments: SLX 7713L - Preli Advise.pdf

Dear May Chua,

Enclosed herewith preliminary advice of SLX 7713L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 30 July 2018 9:41 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005708MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 30 July 2018 8:21 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005708MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLX 7713 L

Parts	(a) Cost / List Price Items	\$	6,007.20
	Plus/Less 20%	\$	1,201.44
	Total of Cost / List	\$	4,805.76
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	295.00
Total Parts Cost		\$	5,100.76
Labour		\$	3,230.00
Total		\$	8,330.76

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Pe

Date: 30/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLX 7713 L**
Make & Model : **HONDA SHUTTLE**
Chassis No. : **GP71121431**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen <i>Sn</i>	1	\$1,011.10		X
2	Rear windscreen moulding <i>Sn</i>	1	\$120.00		✓
3	Rear windscreen sealant <i>Sn</i>	1	\$50.00	S.N	<i>Posn</i>
4	Reverse sensor <i>Short</i>	2	\$200.00	S.N	✓
5	Rear number plate <i>Sn</i>	1	\$45.00	S.N	X
6	Rear bumper <i>Bt</i>	1	\$1,150.60		✓
7	Rear bumper clip <i>Sn</i>	10	\$35.00		✓
8	Rear bumper side retainer LH <i>Sn</i>	1	\$26.50		X
9	Rear bumper side retainer RH <i>Sn</i>	1	\$26.50		X
10	Rear bumper bracket LH <i>R</i>	1	\$48.70		X
11	Rear bumper bracket RH <i>R</i>	1	\$48.70		X
12	Rear bumper sponge <i>Sn</i>	2	\$179.00		X
13	Rear bumper reflector LH <i>Sn</i>	1	\$45.00		X
14	Rear bumper reflector RH <i>Sn</i>	1	\$45.00		X
15	Rear bumper reflector garnish LH <i>Sn</i>	1	\$45.00		X
16	Rear bumper reflector garnish RH <i>Sn</i>	1	\$45.00		X
17	Tail door <i>Bt</i>	1	\$1,193.00		✓
18	Tail door lock <i>R</i>	1	\$157.10		X
19	Tail door emblem <i>Sn</i>	1	\$38.00		✓
20	Wording "SHUTTLE" <i>Sn</i>	1	\$55.00		✓
21	Wording "HYBRID" <i>Sn</i>	1	\$80.10		✓
22	Tail door chrome <i>Sn</i>	1	\$383.10		X
23	Tail door trim <i>Sn</i>	1	\$320.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLX 7713 L
Make & Model : HONDA SHUTTLE
Chassis No : GP71121431

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door trim clip <i>nn</i>	10	\$35.00		<i>X</i>
25	Tail end panel <i>R</i>	1	\$560.80		<i>X</i>
26	Tail end panel garnish <i>nd</i>	1	\$155.50		<i>✓</i>
27	Tail end panel garnish clip <i>nn</i>	10	\$35.00		<i>✓</i>
28	Boot weatherstrip <i>kt</i>	1	\$168.50		<i>✓</i>
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLX 7713 L** Submit By : **Carmen Lim**
Make & Model : **HONDA SHUTTLE** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	800
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To tuff coat	\$150.00	60
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	80
7	To remove & refit rear windscreen.	\$120.00	✓
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013784/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2840T	Veh. Inspected	SLX 7713L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005708MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	30/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71121431	Colour	METALLIC PEARL WHITE	
Odometer	13868	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	FALKEN	9 mm	
L/H Front Tyre	205/50 R16	FALKEN	9 mm	
R/H Rear Tyre	205/50 R16	FALKEN	9 mm	
L/H Rear Tyre	205/50 R16	FALKEN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/07/2018	Inspection Date	30/07/2018	
Survey held at	385 SIN MING DRIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 7713L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN	SERVICEABLE	1,011.10	-
1	REAR WINDSCREEN MOULDING	NECESSARY	120.00	120.00
1	REAR BUMPER	BENT	1,150.60	1,150.60
10	REAR BUMPER CLIP	NECESSARY	35.00	35.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	26.50	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	26.50	-
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	48.70	-
1	REAR BUMPER BRACKET RH	TO REPAIR SEE LABOUR	48.70	-
2	REAR BUMPER SPONGE	SERVICEABLE	179.00	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	45.00	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	45.00	-
1	REAR BUMPER REFLECTOR GARNISH LH	SERVICEABLE	45.00	-
1	REAR BUMPER REFLECTOR GARNISH RH	SERVICEABLE	45.00	-
1	TAIL DOOR	BENT	1,193.00	1,193.00
1	TAIL DOOR LOCK	TO REPAIR SEE LABOUR	157.10	-
1	TAIL DOOR EMBLEM	NECESSARY	38.00	38.00
1	WORDING "SHUTTLE"	NECESSARY	55.00	55.00
1	WORDING "HYBRID"	NECESSARY	80.10	80.10
1	TAIL DOOR CHROME	SERVICEABLE	383.10	-
1	TAIL DOOR TRIM	SERVICEABLE	320.00	-
10	TAIL DOOR TRIM CLIP	NOT NECESSARY	35.00	-
1	TAIL END PANEL	TO REPAIR SEE LABOUR	560.80	-
1	TAIL END PANEL GARNISH	DENTED	155.50	155.50
10	TAIL END PANEL GARNISH CLIP	NECESSARY	35.00	35.00
1	BOOT WEATHERSTRIP	CUT	168.50	168.50
	LESS 20% DISCOUNT		-1,201.44	-606.14
			4,805.76	2,424.56

Report Ref No. CS/FCI18013784/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
2	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	45.00	-
			295.00	240.00
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,TAILDOOR,END PANEL,SPARE TYRE WELL PANEL).INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET LH,REAR BUMPER BRACKET RH,TAIL DOOR LOCK AND TAIL END PANEL.		1,200.00	800.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,TAILDOOR,END PANEL,SPARE TYRE WELL PANEL).		1,200.00	800.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	50.00
	TO TUFF COAT.		150.00	60.00
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD.		150.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
			3,230.00	2,010.00
	GRAND TOTAL		8,330.76	4,674.56
	RECOMMENDED COST OF REPAIRS			4,674.56

Report Ref No. CS/FCI18013784/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.