

ASS. REC. BY:

REF:

CS/FCI18013787/Ktd3/n2

Special Instruction:

Surveyor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

30/7/18 @ 8.18am

Estimated Cost:

Bill to:

OD

TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8HC 51804

Insured:

SHD 7127G

at Workshop m/s

Trung Cab

Tel:

6287 6666

of

No. 2 Amk 8f. 63

Policy No:

Claim No:

D18005601 MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/07/2018

CA / REV / REP. / REV 24 HRS

QDS

Date/Time:

8.40am @ 30/7/18

Person Contacted:

Deshen

H.O.D. Endorsement:

Vehicle

IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	8HC 51804-CC3/AXA 17016497/Kwa3 DOA: 19/8/2017
	SHD 7127G-X

ASSIGNMENT

From: Date: 30/7/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 8HC 51804

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1DS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 51804 Yr Regn: 01, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c. 1995

Colour

M. White / Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

558776

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 276656

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

2

mm

R/Bal.

6

mm

L/Bal.

2

mm

L/Bal.

6

mm

D.O.A.

20/7/18

D.O.I.

30/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

cls body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/7 File pass to Catherine

11pm @ 4150p (Red: 34437.81: 89%)

RECEIVED 16 AUG 2018

Date/Time, File Pass to?



Preli. Report

11/6/18 Typist



Final Report

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I. (\$) 4150p

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

28x15=420

170+420

50

16

656



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18013787/Ktd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 7127G	Veh. Inspected	SHC 5180U
Policy No.		Coverage (\$)	0.00
Claim No.	D18005601MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	30/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/07/2018	Inspection Date	30/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005601MFSH

Date: 15/8/2018

Our Ref: CS/FCI18013787/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5180U

Please be informed that we had conducted the inspection of the abovementioned vehicle 30/7/2018 at the premises of M/s Trans Cab and have the following to report: -

Workshop Estimate Amount	: S\$ <u>38,587.81</u>
Revised Estimate Amount	: S\$ <u>4,150.00</u>
"Check" Items Amount	: S\$ <u>0.00</u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the o/s body portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-07-2018	Our Ref No. D18005601MFSH
Accident Date	20-07-2018	Claim Type. Third Party
Insured Vehicle	SHD7127G	Third Party Vehicle. SHC5180U
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	DESHUAN TAN	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242627)



PRI Documents



Close



PRI Header Details

Claim No	D18005601MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : DESHUAN TAN)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: DESHUAN.TAN@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD7127G	TP Vehicle No	SHC5180U
PRI Recieved Date	25-07-2018 01:47:56 PM	Surveyor Appointed Date	30-07-2018 08:17:37 AM	Surveyor Accept Date	30-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 15 August 2018 4:21 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005601MFSH/1
Attachments: PRELI ADVISED SHC 5180U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 5180U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 30 July 2018 8:25 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005601MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 30 July 2018 8:18 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005601MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHC5180U

Vehicle to be Exported: Yes

Intended De-registration Date: 23 Jul 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2013

Engine No.: M9R8839C001073

Chassis No.: VF1ABL15AUC276656

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 14 Jan 2014

First Registration Date: 14 Jan 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Jan 2022

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 13 Jan 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$60,888.00

COE Rebate Amount: \$26,433.00

Total Rebate Amount: \$35,806.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Jul 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5180U**AAD1807-203***Not Notified
11 Days @ 4150/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5180U

VF1ABL15AUC276656

RENAULT

LATITUDE

20.7.2018

FCIL**PART****LIST**

1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66	<i>X</i>
1	DOOR HINGE UPPER RH	\$	<i>R</i> 261.28	
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55	
1	DOOR CHECK FRT RH	\$	<i>SL</i> 194.77	
1	DOOR LOCK FRT RH	\$	<i>R</i> 908.75	
1	DOOR CATCH FRT RH	\$	<i>R</i> 131.23	
1	DOOR HANDLE OUTER FRT RH	\$	<i>SL</i> 477.76	
1	DOOR HANDLE COVER FRT RH	\$	<i>SL</i> 13.22	
1	DOOR HANDLE MODULE FRT RH	\$	<i>SL</i> 133.60	
1	DOOR REGULATOR FRT RH	\$	<i>SL</i> 505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>SL</i> 796.46	<i>X</i>
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>SL</i> 120.97	
1	DOOR PANEL REAR RH	\$	<i>SL/warp</i> 2,844.66	
1	DOOR GUIDE REAR RH	\$	<i>SL</i> 176.82	
1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50	
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55	
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>SL</i> 203.06	
1	DOOR LOCK REAR RH	\$	<i>R</i> 908.75	
1	DOOR HANDLE OUTER REAR RH	\$	<i>SL</i> 126.49	
1	DOOR HANDLE CAP REAR RH	\$	<i>SL</i> 35.52	
1	DOOR HANDLE SEAL REAR RH	\$	<i>SL</i> 7.89	<i>X</i>
1	DOOR HANDLE COVER REAR RH	\$	<i>SL</i> 13.22	
1	DOOR HANDLE MODULE REAR RH	\$	<i>SL</i> 133.60	
1	DOOR REGULATOR REAR RH	\$	<i>SL</i> 1,135.10	
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>R</i> 893.75	
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>SL</i> 12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>SL</i> 6.31	
1	DOOR FINISHER REAR RH	\$	<i>SL</i> 423.10	
1	DOOR MOULDING REAR RH	\$	<i>SL</i> 176.82	

Trans-cab Auto Services Pte Ltd**AAD1807-203**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5180U

1	DOOR MOULDING CLIP L70Y	\$	na	5.92	
1	DOOR MOULDING SCREW L70Y	\$	nn	6.91	
1	DOOR CASING REAR RH	\$	sn	1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	sn	30.39	
1	DOOR CASING CLIP	\$	nn	12.63	
1	DOOR CASING LIGHT L70Y	\$	sla	48.74	
1	DOOR FINISHER INNER REAR RH	\$	sn	323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	sn	46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	sn	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	sn	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	sn	20.33	
1	DOOR GRAB HANDLE REAR RH	\$	sn	210.96	
1	DOOR BLIND REAR RH	\$	sn	741.80	
1	DOOR WHEATHESTRIP REAR RH	\$	sn	410.66	
1	DOOR SEAL REAR RH	\$	sn	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	sn	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	sn	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	sn	115.64	
1	FENDER PANEL REAR RH	\$	n	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	sn	671.45	
1	WHEELARCH REAR RH	\$	sn	543.47	
1	DOOR MIRROR ASSY RH	\$	sn	1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	sn	466.51	
1	ROCKER PANEL INNER RH	\$	n	1,024.79	
1	ROCKER PANEL CENTER RH	\$	n	990.25	
1	BUMPER COVER REAR	\$	Bu	1,108.46	
1	BUMPER LOWER REAR	\$	sn	768.84	X
1	BUMPER BRACKET CTR REAR	\$	sn	113.47	X
1	BUMEPR BRACKET SIDE RH REAR	\$	sn	135.97	X
1	BUMEPR RETAINER RH REAR	\$	sn	44.99	X

\$ 29,261.8710% **\$ 2,926.19****\$ 26,335.68****Special Nett**

1SET FRAME FULL SUPPORT PANEL CLIP

\$

na 70.00 X

Trans-cab Auto Services Pte Ltd**AAD1807-203**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5180U

2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	nn 30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn 80.00	60%
1	FRONT DOOR STICKER 'Chassis'	\$	nn 300.00	15%
1	DOOR CHECK BOLT	\$	nn 22.69	X
1	DOOR GUIDE SCREW	\$	nn 10.85	
1	DOOR HINGE BOLT	\$	nn 10.85	
1	DOOR HINGE NUT RH	\$	nn 14.60	
1	DOOR CHECK BOLT	\$	nn 22.69	
1	DOOR CHECK NUT	\$	nn 3.75	
1	DOOR LOCK SCREW L70Y	\$	nn 6.12	
1	DOOR CATCH SCREW L70Y	\$	nn 10.06	

TOTAL	\$	632.13
--------------	-----------	---------------

TOTAL PARTS	\$	26,967.81
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	50%
Putty and spray painting of the affected portion.	\$	4,200.00	80%
To rust-proofing of the affected areas.	\$	170.00	30%
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	60%
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20%

Trans-cab Auto Services Pte Ltd

AAD1807-203

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5180U

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	<i>X</i>
To transfer of front ^{<i>Rear</i>} door fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	<i>* 601</i>
To dismantle advertisement sticker	\$	<i>nn</i>	170.00	<i>X</i>
Towing Fees.	\$	<i>nn</i>	120.00	<i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i>	380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	<i>X</i>
TOTAL	\$		11,620.00	
Over All Total	\$		38,587.81	

LUMP SUM (REPAIR DAY)*15 DAYS**4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013787/KId3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7127G	Veh. Inspected	SHC 5180U	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005601MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	30/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC276656	Colour	METALLIC WHITE / RED	
Odometer	558776	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	6 mm	
L/H Rear Tyre	215/60 R16	GITI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/07/2018	Inspection Date	30/07/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5180U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	SERVICEABLE	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH	BENT / WARPED	2,844.66	2,844.66
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH/RH L70Y	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR RH	SERVICEABLE	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	893.75	-

Report Ref No. CS/FCI18013787/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR REGULATOR NUT REAR L70Y	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	NOT NECESSARY	6.91	-
1	DOOR CASING REAR RH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR RH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR RH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	20.33	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH	SERVICEABLE	115.64	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR	990.25	-
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-

Report Ref No. CS/FCI18013787/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
	LESS 10% DISCOUNT		-2,926.19	-395.31
			26,335.68	3,557.81
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CLASSIS" (SN)	NECESSARY	300.00	15.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH 9SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	SERVICEABLE	10.06	-
			632.11	75.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR LOCK FRT RH,DOOR CATCH FRT RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR LOCK REAR RH,FENDER PANEL REAR RH,ROCKER PANEL INNER RH AND ROCKER PANEL CENTER RH.		4,500.00	500.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	880.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00

Report Ref No. CS/FCI18013787/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO DISMANTLE ADVERTISEMENT STICKER.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			11,620.00	1,550.00
	GRAND TOTAL		38,587.79	5,182.81
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,150.00

Report Ref No. CS/FCI18013787/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.