



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SKQ8099TMake & Model : MAZDA 3 4-DOOR SEDANYear of Manufacture : 2014Chassis No. : JM6BM42A8F0155588Ins Company : III / LONPAC

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 21/07/2018

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimate**Case Owner : Andrew

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ 45.00

Total Parts Cost (Appendix A) \$ 45.00

Labour (Appendix B) \$ 2,080.00

Total Repair Cost \$ 2,125.00

Contact No

**Frt Counter Operation**

6383 7466 – Patrick Tia

6383 7730 – Brenda Ng

6383 7890 – Rohani

[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 - Andrew Goh

63838115 - William Wang

[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SKQ8099TMake & Model : MAZDA 3 4-DOOR SEDANYear of Manufacture : 2014Chassis No. : JM6BM42A8F0155588Ins Company : III / LONPAC

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 21/07/2018

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimate**Case Owner : Andrew

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 2,080.00

Total Repair Cost \$ 2,080.00

Contact No

**Frt Counter Operation**

6383 7466 – Patrick Tia

6383 7730 - Brenda Ng

6383 7890 – Rohani

[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 - Andrew Goh

63838115 - William Wang

[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

## Spare Parts

Vehicle No : SKQ8099T Case Owner : Andrew

Make & Model : MAZDA 3 4-DOOR SEDAN Year Manufacture : 2014

Chassis No : JM6BM42A8F0155588 Engine No : 0

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1					
2	Rear bumper side retainer LH	1					
3	Rear bumper side retainer RH	1					
4	Rear bumper clips	10					
5	Rear bumper reinforcement	1					
6	Rear bumper sponge	1					
7	Rear bumper lower garnish	1					
8	Rear bumper tow cover RH	1					
9	Rear bumper reflector LH	1					
10	Rear bumper reflector RH	1					
11	Rear end panel	1					
12	Rear end panel top garnish	1					
13	Reverse sensor	1					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*