

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: CLS.2018.216217

Date: 16th August 2018

Our Ref: CS3/AXA16004935/Bsbs2-1

M/s AXA Insurance Pte Ltd

C/o; ComLaw LLC 64 Cecil Street #06-01 IOB Building Singapore 049711

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: EW 323M INSURED VEHICLE: SJR 9495H ACCIDENT DATE: 15/03/2016

We thank you for your instruction on 30/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of EW 323M from M/s PAR Automotive Consultancy.
- b) Final Repair Bill of EW 323M from M/s N-51 Automotive Pte Ltd.
- Singapore Accident Statement of Vehicles EW 323M and SJR 9495H.
- d) Colour damaged vehicle photographs of EW 323M.

Pre-Repair Inspection Date: 16/03/2016 at M/s N-51 Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

Information Recorded: -

Registration Number

: EW 323M

Make & Model

: Mazda RX8 1.3A

Year of Registration

: 2007

Chassis Number

: SE3P142243

Engine Capacity

: 1308 cc

- We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.