

Surveys

NA 2

REF:

NTUC NS/INC18013871/Ntbez

1

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: FBK 414H

Policy No. 5070087674-03 11.02.18 - 10.02.19

Claims No. MT/1004034-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHB 5361U Yr Regn: 16 OCT 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIMO c.c. 1798

Colour: BROWN MAROON A/C: Insured / Std / NI / NA

Sp. Reading: 279, 282 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKN36U305766247

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 24/7/18 D.O.I. 26/7/18

Survey held at SMART WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHB 5361U - (03/AUG/2021/632/R163/2W2

DOA: 04/11/18

4/5

FBK 414H - X

16/8/2018 FINALIZED LUMP SUM REPAIR \$1,950 / 3 DAY

Cred: 4625.84 : 70%

RECEIVED 10 SEP 2018

Date/Time, File Pass to?

11/09/2018 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 1950

160
160



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013877/Ntb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 31-07-2018

189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBK 414H	Veh. Inspected	SHB 5361U
Policy No.	5070087674-03	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/07/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	24/07/2018	Inspection Date	26/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="24/07/2018 13:16"/>
Vehicle No.(For Motor)	<input type="text" value="FBK414H"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5070087674-03		KYAW LIN OO	S7766416E	GMC	Third Party, Fire & Theft	FBK414H	FBK414H	11/02/2018	10/02/2019

## Denise Tay (LKKAUTO)

**From:** mtreg <mtreg@income.com.sg>  
**Sent:** Monday, 10 September 2018 10:31 AM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** FW: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

**Samsia**  
Senior Admin Assistant,  
Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)**

**in** with you

*'With effect from 1 Oct 2018, we will be discontinuing our fax number 6338 1504.*

*Please forward all motor claims related correspondences to [mtcl@income.com.sg](mailto:mtcl@income.com.sg) so that we can attend to it accordingly.'*

**From:** Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]  
**Sent:** Monday, September 10, 2018 10:17 AM  
**To:** mtreg <mtreg@income.com.sg>  
**Subject:** REQUEST CLAIM NUMBER

2	MT/1004634-002	SMRT TAXIS	SHB
---	----------------	------------	-----

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/07/2018 10:49
Date Of Accident	24/07/2018 17:50
Exact Location Of Accident	SLIP FROM YUAN CHING ROAD TOWARDS BOON LAY WAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5361U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	TEO HOCK SWEE
NRIC No	S1162189I
Date Of Birth	27/01/1956
Occupation	OUTDOOR
Date Of Driving Pass	04/03/1977
Driving Experience	41 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : RONESON NG
	GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	RONESON NG
Phone Number	
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBK414H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	KYAW LIN OO
NRIC/Passport Number	S7766416E
Contact Number	
Address	


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24 Jul 2018, at about 1750 hrs. I was at the slip road from Yuan chin Rd toward Boonlay Way, as my passenger Mr Roneson Ng (+6018 7944487) was heading to Lakeside MRT stn. As there was tree pruning along Boonlay Way. One lane was blocked off with cones, there was a stationary truck on my right which prevent any vehicle coming into the blocked lane. Cones were used to block the slip/exit road 'is' towards Boonlay way, leaving only one vehicle to pass at a time. Due to the blind spot caused by the truck, on the right, I stopped about fifteen seconds to wait for vehicles coming from my right, I checked my left for any vehicle which was none as cones were placed there, then I checked again on the right, slowly I drove off when cleared. Suddenly there was an impact on my front left. Vehicle No FBK 414H hit me and fell next to the cones. My passenger quickly alighted and assist him by shifting the cones, later helped him to lift up the motorcycle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Signature]* 25 Jul 2018  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]* 25/7/2018  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

A SHB 53614  
13 FRK 414 H

~~25/07/18~~  
25/07/18

STS  
Jurong West



Boonlay Way



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





30.7.18 / 12:43.  
30.7.18 / 16:43.

## SMRT Accident Vehicle Repair Estimates

26.7.18 / 16:43.

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre


Reg. No : SHB5361U  
Ref. No : TAX/07/18/2115  
Reg. Date : 16/10/2015  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : TEO HOCK SWEE  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 24/07/2018 05:50:00 PM  
Accident Reported Date / Time : 25/07/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : NAZ  
Vehicle is Towed Back? : ~~No~~ Yes  
Towed Back Date/Time : 24/07/2018  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024097216  
Special Instruction to ARC, if any :  
TOWED \$40 / FBK414H NTW 45  
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL  
SURVEYOR Muhd Nazril (LKK) & Email naz@lkkauto.com HP:98804220 TEL:62563561  
Prepared Date : 25/07/2018 11:39:35 AM



QC 30/7/18 14.51 Pass

279345

279282 km



Recording Camera ☒ ☐

Radio Antenna ☒ ☐

1<sup>st</sup> witness ef Date 26.7.18

2<sup>nd</sup> witness \_\_\_\_\_ Date \_\_\_\_\_

LEE CHENG AUTO PTE LTD

Vehicle Return Date: 30/7/18

Vehicle Return Time: 1200

SMRT Staff Sign: [Signature]



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U305766247

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	500.00
Total Spray Painting Charges	: 1,116.00	600.00
Total Material Charges	: 808.43	1,263.17
Other Charges	: 700.00	-413.17
<b>TOTAL</b>	<b>: 3,300.43</b>	<b>1,950.00</b>
<b>Lump Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 5.00	3.00
Prepared / Adjusted By	:	NAZ ( LKK )
Arc / Surveyor Sign Off Date	: 25/07/2018 07:05:11 PM	26/07/2018 04:43:31 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 25/07/2018 07:05:11 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1808-0048

Invoice No :

Quotation Date : 3/8

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 7/25/2018 7:06:00 PM

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	676.00	500.00
<b>Total Labour</b>	<b>676.00</b>	<b>500.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO RESPRAY FRONT FENDER LH	378.00	200.00
TO RESPRAY RIM	180.00	100.00
TO RESPRAY FRONT WHEEL HOUSE LH	180.00	100.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>600.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 <i>x nn</i>
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 <i>x nn</i>
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	50.00
TO REMOVE AND REFIT TYRE	120.00	20.00
TO REPLACE SUNDRY PARTS	100.00	0.00 <i>x nn</i>
TO WASH AND VACUUM	60.00	0.00 <i>x nn</i>
Lump Sum Adjustment by Surveyor	0.00	-503.17
<b>Total Other Costs</b>	<b>700.00</b>	<b>-413.17</b>

7827.84

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No <i>BT</i>
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No <i>nee</i>
52116-47040		6505516	BUMPER SUPPORT F/LH	0	76.40	25.00	0.00	Replace	Not given	No <i>X SCL</i>
81521-47050			LENS & BODY, FR TURN LH	0	511.80	10.00	0.00	Replace	Not given	No <i>X SCL</i>
81529-47040			BRACKET, FR TURN UPPER LH	0	24.40	25.00	0.00	Replace	Not given	No <i>X SCL</i>
81529-47050			BRACKET, FR TURN LOWER LH	0	26.00	25.00	0.00	Replace	Not given	No <i>X SCL</i>
81529-47060			BRACKET, FR TURN CENTER LH	0	58.20	25.00	0.00	Replace	Not given	No <i>X SCL</i>
53802-47050		6505558	FENDER FRT/LH	1	723.40	100.00	0.00	Replace	Repair	No <i>R</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>nee</i>
53876-47030		6505554	FENDER LINER FRT/LH	0	171.70	25.00	0.00	Replace	Not given	No <i>X SCL</i>
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	0	1,484.20	25.00	0.00	Replace	Not given	No <i>X SCL</i>
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No <i>X SCL</i>
53702-47050			FENDER APRON SUB FRT/LH	0	637.80	25.00	0.00	Replace	Not given	No <i>X SCL</i>
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No <i>SCL</i>
TOTAL MATERIALS							1,263.18	1,263.17		
TOTAL MATERIALS(Discounted)							808.43	1,263.17		

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 1263.17 \\
 500 \\
 + 690 \\
 \hline
 2453.17 \\
 - 20\% \\
 \hline
 1962.54
 \end{array}$$

45-01950

CONFIRMED LUMP SUM REPAIR \$1950 / 3 Days

5/9/18

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5361U  
Ref. No : TAX/07/18/2115  
Reg. Date : 16/10/2015  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : TEO HOCK SWEE  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 24/07/2018 05:50:00 PM  
Accident Reported Date / Time : 25/07/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time : 24/07/2018  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024097216  
Special Instruction to ARC,if any :  
TOWED \$40 / FBK414H  
Prepared Date : 25/07/2018 11:39:35 AM



Chassis No : JTDKN36U305766247

Mileage : 0

Work Shop :

Repair Completed Date / Time :

### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 3,401.68	3,401.68
Other Charges	: 756.00	0.00
<b>TOTAL</b>	<b>: 5,949.68</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 5,950.00</b>	<b>0.00</b>
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 25/07/2018 07:05:11 PM	01/01/1900 12:00:00 AM



6575-84

Prepared / Adjusted Date :

Remarks :

Prepared Date : 25/07/2018 07:05:11 PM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 7/25/2018 7:06:00 PM

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	676.00	0.00 <del>500</del> 500
<b>Total Labour</b>	<b>676.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 100
TO RESPRAY FRONT WHEEL HOUSE LH	180.00	0.00 100
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56.00	0.00 50
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 20
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X 11
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X 11
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 50
TO REMOVE AND REFIT TYRE	120.00	0.00 20
TO REPLACE SUNDRY PARTS	100.00	0.00 X 11
TO WASH AND VACUUM	60.00	0.00 X 11
<b>Total Other Costs</b>	<b>756.00</b>	<b>0.00</b>

**Added Spare Parts / Material Usage After Surveyor Signed off**

- LKK Auto Insurance Inc. will not be liable for the Repairs and/or Parts
- To result in a claim being made against the policy
- To display on the vehicle part(s) during the survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- To be held in confidence with the Insured
- Complementary survey may be resurveyed **and** is subject to final approval from insurance **Company**

Acknowledged by Repairer

Signature \_\_\_\_\_

Date: \_\_\_\_\_

LK

3 DAY-5

AFTER REPAIR PHOTO

Naz@1kkauto.com



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013877/Ntbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 02-10-2018	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	FBK 414H	Veh. Inspected	SHB 5361U	
Policy No.	5070087674-03	Coverage (\$)	0.00	
Claim No.	MT/1004634-002	Excess (\$)	0.00	
Assign From		Assign Date	26/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTDKN36U305766247	Colour	MAROON	
Odometer	279282	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	5 mm	
L/H Front Tyre	195/65 R15	FALKEN	5 mm	
R/H Rear Tyre	195/65 R15	FALKEN	5 mm	
L/H Rear Tyre	195/65 R15	FALKEN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/07/2018	Inspection Date	26/07/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5361U**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BUMPER FRT (DISC 25%)	BENT	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	HEAD LAMP LH (DISC 10%)	SCRATCHED	945.20	850.68
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	LENS & BODY, FR TURN LH	SERVICEABLE	511.80	-
1	BRACKET, FR TURN UPPER LH	SERVICEABLE	24.40	-
1	BRACKET, FR TURN LOWER LH	SERVICEABLE	26.00	-
1	BRACKET, FR TURN CENTER LH	SERVICEABLE	58.20	-
1	FENDER LINER FRT / LH	SERVICEABLE	171.70	-
1	WHEEL DISC. FRONT	SERVICEABLE	1,484.20	-
1	TYRE	SERVICEABLE	126.74	-
1	FENDER APRON SUB FRT / LH	SERVICEABLE	637.80	-
1	FENDER FRT / LH	TO REPAIR SEE LABOUR	723.40	-
			5,335.84	1,263.17
<b><u>LABOUR</u></b>				
	PANEL BEATING & BODY WORK.		676.00	500.00
	SPRAY PAINT.		1,116.00	600.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	50.00
	TO REMOVE AND REFIT TYRE.		120.00	20.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,492.00	1,190.00
<b>GRAND TOTAL</b>			<b>7,827.84</b>	<b>2,453.17</b>

Report Ref No. NS/INC18013877/Ntbe2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,950.00
---	--	--	----------

Report Ref No. NS/INC18013877/Ntbe2

**MUHAMMAD NAZRIL BIN ABDULLAH**

Automotive Assessor



**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**