# Ah Lim Motor Company 10 Ang Mo Kio Industrial Park 2A

#01-09 AMK Autopoint Singapore 568047

Claim Reference:

Assessment Number: AH000889

Version: AHLIM001/1

Date Calculated: 30/07/2018 03:16

SURVEYOR COPY

Full Report - V1

Registration: SJG8288D Printed: 30/07/2018 10:16

**Summary Information** 

Claim

Location: Printed by:

Authorisation Status:

Work Provider:

Claim Reference: Policy Number: Other Reference: Third Party: Insured Amount:

Under Warranty: Warranty Expired:

Singapore (SG) Ahlim ahlim

Interim

AXA Insurance S'pore Pte

Hire Car End: Vehicle Collected

LKK Aut Calesultants hence notify Currency:

the Repairer of the following: Able to Authorise Repairs Authorised:

Appears Authorised:

Parts prices are subject to confirmation

 Third party survey is on a "Without Prejudice" basis Estimated Repair Time illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and Quote Due Date: Actual Repair Days: is subject to final approval from Insurance Company

Parts Ordered Date:
Acknowledged by Repairer

Signature: Date:

#### **Vehicle Details**

Vehicle

Manufacturer: Model: Sub Model:

Model Sheet Number:

Registration: Registration Month:

Registration Year:

VIN Number: Manufacture Year:

Odometer: Colour:

Engine Number: Fuel Level:

**MERCEDES** S Class S 300 LONG 349 96

SJG8288D July

2012

WDD2211542A481697

2012 Not Known

27294632049991

0/0

Model Specs

FROM VIN A 464425 REMOTE LOCKING DAYTIME RUNNING LIGH **DVD CHANGER** LED LIGHT PACK HEADLAMP WASHERS FRT SEAT ADJ MEMORY

**ELECT REAR S/CUSHION** DOUBLE CUP HOLDER CENTRAL LOCKING

KEYLESS GO REARVIEW CAMERA ASHTRAY PACKAGE

ALU WHEELS 8.5J X 18 SPARE WHEEL **ENGINE PROTECTION** 

PARKTRONIC SYSTEM RIGHT HAND DRIVE CLEAR COAT HARD

WOOD TRIM ASH DIPPING MIRROR CONTROL SYST COMAND SMART LIGHT SYSTEM

HIGH BEAM ASSISTANT LEATHER UPHOLSTERY CHILD SEAT DETECTION CHILD SEAT MOUNTING REAR SCREEN BIND PEDESTRIAN PROTECT H/DUTY ALTERNATOR INTER LIGHT AMBIENCE 7 SPEED AUTOMATIC TYRE 255/45 YR 18 ATTENTION ASSIST **ELCTRIC SUNROOF** 

**MODEL 2012** TWO COAT METALLIC

### Vehicle Condition

**Vehicle Status** 

Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF:

Severity of Impact: Vehicle Status on

Inspection:

Date of Inspection:

30/07/2018

Tread Depth RHF:

# **Ah Lim Motor Company**

Claim Reference:

Assessment Number: AH000889


Version: AHLIM001/1

Date Calculated: 30/07/2018 03:16


Full Report - V1

Registration: SJG8288D Printed: 30/07/2018 10:16

Tread Depth LHR: Damage Areas:



Tread Depth RHR: Direction of Impact:



**Addresses** 

**Cost Summary** 

Total Labour	\$832.50
Total Paint/Material	\$136.15
Excess:	TBA
Grand Total Exc GST:	\$968.65
7 % GST:	\$67.81
Grand Total Inc GST:	\$1,036.46

Time Basis 10 WU = 1 HR, Price/CL 1 = \$45.00/HR

The Assessment Contains Unpriced Parts

Repair Information

LABOUR	Price/Dent = \$45.00/HR			
Repair /				
<b>Guide Numb</b>	er Repair Details	WU	Cost Price (\$)	
88-6976 02)	R + R L/R LOWER WING PARTITION	1.0	4.50	
	(WHEEL REMOVED)			
88-8802 02	R + R REAR BUMPER	10.0	45.00	
88-9244 01	R + R LEFT REAR AIR VENT GRILLE	1.0	4.50	
68-3040 02	R + R L/BOOT TRIM	4.0	18.00	
88-8220 02	R + R L/R COVER	2.0	9.00	
60-1592 02	R + R L/TAILLAMP UNIT	3.0	13.50	
	(BOOT TRIM REMOVED)			
68-1112 02)	R + R L/LOWER REAR PILLAR TRIM	3.0	13.50	
68-1111 02	R + R L/UPPER REAR PILLAR TRIM	3.0	13.50	
68-1100 02	ADDITION TO R + R L/UPPER REAR PILLAR	1.0	4.50	
	TRIM (VEHICLE WITH ROLLER BLIND)			
40-1580 01	R + R REAR WHEEL	_ 3.0	13.50	
2583	REPAIR REAR BUMPER COVER	15 30.0*	135.00	
3481	REPAIR L/R WING	30 .50.0*	225.00	
LA	BOUR COST			
	Total Work Units	111.0		
	<b>Corrosion Protection External Labour</b>	0.0HRS	0.00	
	Corrosion Protection Internal Labour	0.0HRS	0.00	
	Sub Total	11.1HRS	\$499.50	
	Paint Labour	7.4HRS	\$333.00	
	Total Labour	18.5HRS	\$832.50	

PAINT WORK Guide Number Description Time Basis 10 WU = 1 HR. Price = \$45.00/HR
WU Cost Price (\$)

- TWO COAT METALLIC

# Ah Lim Motor Company

Claim Reference:

**Assessment Number: AH000889** 

Version: AHLIM001/1

Date Calculated: 30/07/2018 03:16

Full Report - V1

Registration: SJG8288D

Printed: 30/07/2018 10:16

REAR BUMPER COVER REPAIR PAINT PLASTIC				17.0		
81 L/R WING REPAIR PAINTING >50%			.0			
WITH ROOF SIDE PANEL	LING LESS DOOR SHUT					
L/R DOOR SURFACE PAIN	TV	8	.0			
OUR COST - PAINT						
TIME(PAINT)		45	.0			
Preparation Main Work Metal Preparation Comp. Work Plastic Preparation Work Multi Layer Paint			.0			
			.0			
			.0			
			.0			
•				\$333.00		
				Cost Price		
			\$22.91			
				\$23.31		
				\$59.13		
			\$18.10			
			\$12.70			
				\$136.15		
Postlescent Unlift @ 0	0%			\$0.00		
				\$136.15		
Total Family Material Co	731			φ130.13		
			Price Va	alid: 01/06/2015		
Description	Part Number	Supplier	Bet.			
2000	Sub Total			\$0.00		
	Mark Up Fr	om Cost (1	5 %)	\$0.00		
			- ,-,	\$0.00		
NB - COLOUR COD	ED ITEMS/TRIM - PART	NUMBERS MAY	DIFFER			
				\$0.00		
The As	ssessment Contains Unp	riced Parts				
lation						
				\$0.00		
Total Panel/Mechanical			•			
Total Paintwork			\$333.00			
				\$832.50		
Total Labour Total Paint/Material Costs				\$136.15		
				\$968.65		
				\$67.81		
Γ@ 7 %				40,101		
	L/R WING REPAIR PAINT WITH ROOF SIDE PANEL L/R DOOR SURFACE PAIN BOUR COST - PAINT TIME(PAINT) Preparation Main Work Preparation Comp. Wo Preparation Work Mult Total Work Units (10W Total Paintwork Labou TERIAL COST - PAINT Surface-/Blend Paint Repair Painting Repair Painting Plastic Material-Const Main W Material-Const Comp. Total Excluding Pearle Pearlescent Uplift @ 0 Total Paint Material Co Description  NB - COLOUR COD  The As lation  al Panel/Mechanical al Paintwork	WITH ROOF SIDE PANELLING LESS DOOR SHUT L/R DOOR SURFACE PAINT GOUR COST - PAINT TIME(PAINT) Preparation Main Work Metal Preparation Comp. Work Plastic Preparation Work Multi Layer Paint Total Work Units (10WU/HR) Total Paintwork Labour TERIAL COST - PAINT Surface-/Blend Paint Repair Painting Repair Painting Repair Painting Plastic Material-Const Main Work Metal Material-Const Comp. Work Plastic Total Excluding Pearlescent Uplift Pearlescent Uplift @ 0.0% Total Paint Material Cost  NB - COLOUR CODED ITEMS/TRIM - PART Total The Assessment Contains Unp lation  All Panel/Mechanical Paintwork Material Costs	L/R WING REPAIR PAINTING >50% WITH ROOF SIDE PANELLING LESS DOOR SHUT L/R DOOR SURFACE PAINT  80UR COST - PAINT TIME(PAINT) Preparation Main Work Metal Preparation Comp. Work Plastic Preparation Work Multi Layer Paint Total Work Units (10WU/HR) Total Paintwork Labour FERIAL COST - PAINT Surface-/Blend Paint Repair Painting Repair Painting Plastic Material-Const Main Work Metal Material-Const Main Work Plastic Total Excluding Pearlescent Uplift Pearlescent Uplift @ 0.0% Total Paint Material Cost  NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY Total Extras The Assessment Contains Unpriced Parts  In Panel/Mechanical Paintwork  Material Costs	L/R WING REPAIR PAINTING > 50% WITH ROOF SIDE PANELLING LESS DOOR SHUT L/R DOOR SURFACE PAINT BOUR COST - PAINT TIME(PAINT)		

**Assessment Notes**