

Ah Lim Motor Company
10 Ang Mo Kio Industrial
Park 2A
#01-09 AMK Autopoint
Singapore 568047

SURVEYOR COPY

Claim Reference:
Assessment Number: AH000889
Version: AHLIM001/1
Date Calculated: 30/07/2018 03:16

Full Report - V1
Registration: SJG8288D
Printed: 30/07/2018 10:16

Not Withheld
Resurvey After Rain
3 days

Summary Information

Claim

Location: Singapore (SG)
 Printed by: Ahlim ahlim
 Authorisation Status: Interim
 Work Provider: AXA Insurance S'pore Pte Ltd

Currency:
 Date of Incident:
 Able to Authorise Repairs:
 Repairs Authorised:

Claim Reference:
 Policy Number:
 Other Reference:
 Third Party:
 Insured Amount:
 Under Warranty:
 Warranty Expired:

Estimated Repair Time:
 Quote Due Date:
 Actual Repair Days:
 Parts Ordered Date:
 Hire Car Start:
 Hire Car End:
 Vehicle Collected:

LKK AutoCAD Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Vehicle Details

Vehicle

Manufacturer: MERCEDES
 Model: S Class
 Sub Model: S 300 LONG
 Model Sheet Number: 349 96
 Registration: ✓ SJG8288D
 Registration Month: July
 Registration Year: 2012
 VIN Number: WDD2211542A481697
 Manufacture Year: 2012
 Odometer: Not Known
 Colour:
 Engine Number: 27294632049991
 Fuel Level: %

Model Specs

FROM VIN A 464425
 REMOTE LOCKING
 DAYTIME RUNNING LIGHT
 DVD CHANGER
 LED LIGHT PACK
 HEADLAMP WASHERS
 FRT SEAT ADJ MEMORY
 ELECT REAR S/CUSHION
 DOUBLE CUP HOLDER
 CENTRAL LOCKING
 KEYLESS GO
 REARVIEW CAMERA
 ASHTRAY PACKAGE
 ALU WHEELS 8.5J X 18
 SPARE WHEEL
 ENGINE PROTECTION
 PARKTRONIC SYSTEM
 RIGHT HAND DRIVE
 CLEAR COAT HARD

WOOD TRIM ASH
 DIPPING MIRROR
 CONTROL SYST COMAND
 SMART LIGHT SYSTEM
 HIGH BEAM ASSISTANT
 LEATHER UPHOLSTERY
 CHILD SEAT DETECTION
 CHILD SEAT MOUNTING
 REAR SCREEN BIND
 PEDESTRIAN PROTECT
 H/DUTY ALTERNATOR
 INTER LIGHT AMBIENCE
 7 SPEED AUTOMATIC
 TYRE 255/45 YR 18
 ATTENTION ASSIST
 ELCTRIC SUNROOF
 MODEL 2012
 TWO COAT METALLIC

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
 Steering:
 Brakes Pedal Travel:
 Place of Inspection:
 Pre-Accident Damage:

Severity of Impact:
 Vehicle Status on
 Inspection:
 Date of Inspection: 30/07/2018

Tyres Condition:
 Tread Depth LHF:

Tread Depth RHF:

Ah Lim Motor Company

Claim Reference:

Assessment Number: AH000889

Version: AHLIM001/1


Date Calculated: 30/07/2018 03:16

Full Report - V1


Registration: SJG8288D

Printed: 30/07/2018 10:16

Tread Depth LHR:
Damage Areas:



Tread Depth RHR:
Direction of Impact:



Addresses

Cost Summary

Total Labour	\$832.50
Total Paint/Material	\$136.15
Excess:	TBA
Grand Total Exc GST:	\$968.65
7 % GST:	\$67.81
Grand Total Inc GST:	\$1,036.46

The Assessment Contains Unpriced Parts

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
88-6976 02)	R + R L/R LOWER WING PARTITION (WHEEL REMOVED)	1.0	4.50
88-8802 02	R + R REAR BUMPER	10.0	45.00
88-9244 01	R + R LEFT REAR AIR VENT GRILLE	1.0	4.50
68-3040 02	R + R L/BOOT TRIM	4.0	18.00
88-8220 02	R + R L/R COVER	2.0	9.00
60-1592 02	R + R L/TAILLAMP UNIT (BOOT TRIM REMOVED)	3.0	13.50
68-1112 02)	R + R L/LOWER REAR PILLAR TRIM	3.0	13.50
68-1111 02	R + R L/UPPER REAR PILLAR TRIM	3.0	13.50
68-1100 02	ADDITION TO R + R L/UPPER REAR PILLAR TRIM (VEHICLE WITH ROLLER BLIND)	1.0	4.50
40-1580 01	R + R REAR WHEEL	3.0	13.50
2583	REPAIR REAR BUMPER COVER	15 30.0*	135.00
3481	REPAIR L/R WING	30 50.0*	225.00
LABOUR COST			
Total Work Units		111.0	76
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		11.1HRS	\$499.50
Paint Labour		7.4HRS	\$333.00
Total Labour		18.5HRS	\$832.50

PAINT WORK

Guide Number Description

- TWO COAT METALLIC

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

WU Cost Price (\$)

Ah Lim Motor Company

Claim Reference:

Assessment Number: AH000889

Version: AHLIM001/1

Date Calculated: 30/07/2018 03:16

Full Report - V1

Registration: SJG8288D

Printed: 30/07/2018 10:16

2583	REAR BUMPER COVER REPAIR PAINT PLASTIC	17.0	
3481	L/R WING REPAIR PAINTING >50%	20.0	
	WITH ROOF SIDE PANELLING LESS DOOR SHUT		
1781	L/R DOOR SURFACE PAINT	8.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	45.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	8.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	74.0	
	Total Paintwork Labour	7.4HRS	\$333.00
	MATERIAL COST - PAINT		
	Surface-/Blend Paint		\$22.91
	Repair Painting		\$23.31
	Repair Painting Plastic		\$59.13
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$136.15
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$136.15

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
f:		OEM Parts				
g:		Original				
h:		Secondhand				
p:		Parallel				
x:		Exchange				
			Sub Total			\$0.00
			Mark Up From Cost	(15 %)		\$0.00
			Total Parts			\$0.00

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

\$0.00

The Assessment Contains Unpriced Parts

Final Calculation

Total Parts		\$0.00
Labour		
Total Panel/Mechanical	\$499.50	
Total Paintwork	\$333.00	
Total Labour		\$832.50
Total Paint/Material Costs		\$136.15
Grand Total Excludes GST		\$968.65
GST @ 7 %		\$67.81
Grand Total Includes GST		\$1,036.46

\$ 811.15

Assessment Notes