

ASS. REC. BY:

REF:

CS3/MSG18013911/1240302

Special Instruction:

Surveyor:

Marug

ASSIGNMENT (Office)

From (Person):

Monice Chung

of

MSG

Date/Time:

31/7/18 @ 3:51pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCE 3638D

Insured:

8JT 7818M

at Workshop m/s

Motor Intel

Tel:

6281 0087

of

13 Kaki Blct Rd 4 # 01-20

Policy No:

D27816701QMX

Claim No:

565906

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/07/2018

CA / REV / REP. / REV 24 HRS

Cup

01/08/2018

H.O.D. Endorsement:

Date/Time:

1:06pm @ 31/7/18

Person Contacted:

Tinnie

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SCE 3638D - NA / AIG 18013810 / r3

D.O.A: 27/7/2018

8JT 7818M - NA / AIG 18013810 / r3

D.O.A: 27/7/2018

1/8/18

Disassembled.

3/8/18

After Repair

(08/11/13) wef

REF: MSIG

ASS. REC. BY:

ASSIGNMENT

From: Date: 1/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCE 3638 D

at Workshop m/s Motor Intel
of 13 Keki Bkt Rd 4 #01-20

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Wilson G 8388 3318

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Cup)

6469)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SCE 3638 D Yr Regn: 11, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Mercedes C160 c.c. 1595-

Colour: S/ner A/C: Insured / Std / NI / NA

Sp. Reading: 85-484 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R17 R/R

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/7/18 D.O.I. 1/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No sethup.
	S-6/c.
8/7/18	submit JRS Report

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		31 Jul 2018 15:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Loh Boon Tan , ID: S0340184G									
Main Claimant: YEO KIM ENG , ID: S0116469D									
Vehicle Reg. No.: SCE3638D		Date of Loss: 27/07/2018 18:00 - :59 [44 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 565906		Policy/Cover Note No.: D27816701QMX (Comprehensive) Coverage: 01/02/2018 - 31/01/2019							
Vehicle Reg. No. (Insured): SJT7818M		Policy No. (Claimant):							
		Excess:							
Repairer: Motor Intel Automo Pte Ltd (HQ) Bartley Biz Centre, 13 Kakai Bukit Road 4, #01-20, 417807 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/08/2018]									
Driver/Custodian (Insured): Loh Boon Tan (77 / Male), NRIC: S0340184G									
Adj Asg. Remarks: SJE Disagree Please appoint LKK and contact Wilson (HP: 8838 3318); Tinie (Tel: 6281 0087). Liability not clear									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18013911/Uz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-07-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJT 7818M	Veh. Inspected	SCE 3638D
Policy No.	D27816701QMX	Coverage (\$)	0.00
Claim No.	565906	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	31/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	27/07/2018	Inspection Date	01/08/2018
Survey held at	MOTOR INTEL- 13 KAKI BUKIT RD 4 # 01-20		
Repairer	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6469D
Vehicle Details	
Vehicle No.:	SCE3638D
Vehicle to be Exported:	No
Intended De-registration Date:	02 Aug 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 AVANTGARDE (R17 LED)
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	27491030218630
Chassis No.:	WDD2050402R008506
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$32,861.00
Original Registration Date:	13 Nov 2014
First Registration Date:	13 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$28,006.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Nov 2024
PARF Rebate Amount:	\$21,004.00
Intended COE Rebate Details	
COE Expiry Date:	12 Nov 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$73,010.00
COE Rebate Amount:	\$45,834.00
Total Rebate Amount:	\$66,838.00

The information contained herein is correct as at 02 Aug 2018

OK






































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2018		31 Jul 2018 15:51 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case





























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Loh Boon Tan , ID: S0340184G								
Main Claimant:	YEO KIM ENG , ID: S0116469D								
Vehicle Reg. No.:	SCE3638D	Date of Loss:	27/07/2018 18:00 - :59 [44 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 565906	Policy/Cover Note No.:	D27816701QMX (Comprehensive) Coverage: 01/02/2018 - 31/01/2019						
Vehicle Reg. No. (Insured):	SJT7818M	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Intel Automo Pte Ltd (HQ) Bartley Biz Centre, 13 Kakai Bukit Road 4, #01-20, 417807 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 01/08/2018]								
Driver/Custodian (Insured):	Loh Boon Tan (77 / Male), NRIC: S0340184G								
Adj Asg. Remarks:	SJE Disagree Please appoint LKK and contact Wilson (HP: 8838 3318); Tinie (Tel: 6281 0087). Liability not clear								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SCE3638D (565906)**
[SJT7818M]
TP
YEO KIM ENG
Jul 27 2018 6:00PM
[Loh Boon Tan]
Motor Intel Automo Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
2	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
3	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
4	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
5	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
6	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
7	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
8	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
9	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
10	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
11	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
12	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
13	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
14	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
15	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
16	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
17	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
18	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
19	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
43	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
44	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
48	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
49	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
50	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
51	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
52	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
53	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
54	02/08/18 13:48	General View	 Load JPG	<input checked="" type="checkbox"/>
55	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	02/08/18 13:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	02/08/18 13:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	02/08/18 13:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	07/08/18 11:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/07/18 09:21	SJE DISAGREE LKK	 Load PDF	
2	31/07/18 09:21	Third Party Accident Report	 Load PDF	
3	31/07/18 09:21	PRI	 Load PDF	
4	31/07/18 09:22	OI ACCIDENT REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18013911/UZ4D3E2

Date: 08/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: D27816701QMX

Claimant Vehicle No : SCE3638D

Insured Vehicle No : SJT7818M

Date of Loss: 27/07/2018

Nature of Claim: TP

Claim No: 565906

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCE3638D

Make & Model: MERCEDES-BENZ C180, 1.6 (A)

Engine No: 27491030218630

Reg. Date: 13/11/2014 (Man. Year: 2014)

Chassis No: WDD2050402R008506

Colour: Silver

Odometer: 85484 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/07/2018

Date Inspected: 01/08/2018 Inspected At:

Motor Intel Automo Pte Ltd (HQ)
Bartley Biz Centre, 13 Kakai Bukit Road
4, #01-20
Singapore 417807

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 08 Aug 2018)

Parts: 143 MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCE3638D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >