100	
ASS. REC. BY:	7M1/ CC3/TML18013950/Kmbnz
Kenneth	ASSIGNMENT
From: Date:	
Estimated Cost:	Veh No: S/+0 36+B Yr Regn: 05, 16
OD TP IWS I TP RES ! OD RES ! EVA ! INV ! MV	Prime Mover
To Inspect Vehicle No:	Truck / Traller or
	Cab Cale Resour Lontude co 1885
of Vorkshop m/s	COLOUR M. White Red AIC: Insured / Std / NI / NA
Insured: SLE 698M	Sp.Reading 26/678 T/Radio: Insured / Std / NI / NA
Policy No. MW611516	Eng/No:
Claims No. V PX/P1680520	CNO: VI= 1ABL 15 AUC 282736
Court to the second sec	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder I Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: MILI S/Rim I STD A/Rim or
(Policy Condition)	Tyre Size: F: GiTi 215/60R16
Remark: The veh had commenced its	X:61/4m
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /
Bal. or Market Value:	TOYO/YOKO or
IDAC Accident Rport: Consistent? : Yes or N	Front Rear O
GIA / PR Seen: Consistent?: Yes or N	mm R/8a!, of mm
Est. Repairs: 03 days Res.: Yes or	mm L/Bal.
Lum Sum: 1-B-/% 3 Val.: Yes or 1	3/1/18
	Solvey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / ReaC / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehic	Kie. IN / OUT
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
18 File pass to Carten	ne
8 97 73. 03 (Red). 1	857,154.50,861.)
SHO 31-18 MO /SMS10 - O	. 7
SHD 3618 - NA /INC12021161	OCA: 09-11-13
The state of the s	FCFIVED 0 2 AUG 2013
118918 Sent du to Tokio	LOCIVED (2 Not 200
Onte/Time, File Pass to? : Prell. Report	
W7	Days Of Repair: 5
Cote/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
2)	Add Food 250
F	Add Fee: : Site Insp (\$)_s-Rs_s/ 10
Report Format :	: Interview (\$) Foxos
Lump Sum / I.B.I: (S	Tech Invs (\$) Others
a supposite a series of	Weekend (\$
	TOTAL DAG

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Company
3878K
SHD367B
Yes
30 Jul 2018
RENAULT
LATITUDE 2.0L DCI AUTO D/AB 4DR
Red
2015
M9R8839C003032
VF1ABL15AUC282736
127.0 kW (170 bhp)
\$19,998.00
17 May 2016
17 May 2016
0
\$19,998.00
Yes
16 May 2024
\$14,998.00
16 May 2024
A - Car up to 1600cc & 97kW (130bhp)
8
\$36,463.00
\$26,403.00
\$41,401.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Jul 2018

OK

MTCS18098335 / Trans-Cab Services Pte Ltd - HQ ENTRY DATE 6 TIME: 30/05/2018 10:24 SUBMITTED BY: Er We: Chang Calvin

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	ent to the archiving or this report at the centre and to copies or the report detrig made divisions
	ACCIDENT STATEMENT
Date Of Report	30/07/2018 16:24
Date Of Accident	29/07/2018 23:20
Exact Location Of Accident	SENGKANG EAST ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SHD367B
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	WONG HENG SOON
NRIC No	S1777703C

S1777703C 20/06/1966 Date Of Birth

OUTDOOR Occupation 23/10/1989 Date Of Driving Pass

28 YEARS AND 9 MONTHS Driving Experience

MALE

(LOCAL) +65-97877409 Mobile Number

Fax Number Contact Number

EMail Address NOEMAIL BLK 560 PASIR RIS ST 51

Address #05-233

Postcode 510560

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own

ahicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passangers (Including Driver)

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes,against whom?

Circumstances of Accident

On 29.7.2018 at about 2320 hours,I was stationary on the extreme right lane along Sengkang East Road when the traffic light turns green I was about to move forward.Suddenly,I felt an impact.Vehicle B (SLE6998M) had hit onto my taxi rear portion.

Attachment(s)

Are accident photos available for attachment?

YES

NO

NO

NO

NO

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLE6998M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

ANG WEI LUN

NRIC/Passport Number

S8685120B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name WONG HENG SOON

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address Postcode SHD367B

YES

NO

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of .
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature

(If criver is not the policyholder)

Date & Time:

Long

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2

	0		4 CUD367B
		70	A June on
		A	A- SHD367B B- SUE 6998M
			Sengkang East Road
	9 7 7 1 1 1		Rood
SCRIBE CIRCUMSTANCES	OF THE ACCIDENT		
	provide soft to	SOA FRANT	
ECLARATION			
	iculant are true in every respect.		
			- D****
	front		
			Principal of Calebra Bally Canadia Company
Policyhalder's Signature Nafe & Time:	Opygen's Signature Lif driver is not the policyhold		Reporting Centre Personnel's Signature Name

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666

Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 367B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

AAD1807-278

Not Nothante 8 9, 93.03 Permy B4 paint

SHD 367B

VF1ABL15AUC282736

RENAULT

LATITUDE

29.7.2018

TOKIO MARINE

	PART	LIST
1	1 BUMPER COVER REAR	\$ Bu 1,108.46 —
2	1 BUMPER LOWER REAR	\$ nd 768.84 -
3	1 BUMPER BRACKET CTR REAR	\$
4	1 BUMEPR BRACKET SIDE RH REAR	\$ 5 135.97 X
5	1 BUMEPR RETAINER RH REAR	\$ \(\sigma_{\sigma} \) 44.99 \(\times \)
6	1 BUMPER REFLECTOR RH	\$ 5m 43.61 X
7	1 BUMEPR BRACKET SIDE LH REAR	s ∫ 135.97 ≺
8	1 BUMEPR RETAINER LH REAR	\$
9	1 BUMPER REFLECTOR LH	\$ 43.61
10	1 BUMPER BEAM REAR	\$ 777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$ 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$ 1 225.95 X
13	1 BOOT REAR	\$ 2,872.68
14	1 BOOT FINISHER	\$ 470.06 K
15	1 BOOT WHEATERSTRIP	\$ Gr 323.05 _
16	1 BOOT REFLECTOR LAMP LH	\$
17	1 BOOT REFLECTOR LAMP RH	\$ \$\int_{\scale} 493.35 \times
18	1 BOOT BADGE 'RENAULT'	\$ 225.36
19	1 BOOT BADGE	\$ Ma 225.36 —
20	1 BOOT STRUT LH	\$ \$ 276.08
21	1 BOOT STRUT RH	\$ 5- 276.08
22	1 BOOT HINGE LH	\$ 1 367.84
23	1 BOOT HINGE RH	\$ 7 367.84 X
24	1 BOOT INNER TRIM	\$ \$ 586.45 \ ^
25	1 BOOT SWITCH	\$ 54 168.13
26	1 BOOT LOCK	\$ 202.67
27	1 BOOT LOCK CATCH	\$ 74.40
28	2 LICENCE PLATE LAMP	\$ 50.52
29	2 BOOT RUBBER PLUG	\$ Sh 221.81

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 367B

20	4 FENDED DANIEL DEAD LU		\$ R 3,299.13 X
30	1 FENDER PANEL REAR LH		\$ 543.47 X
31	1 WHEELARCH REAR LH		671.45 X
32	1 FENDER PANEL INNER TRIM REAR RH		\$
33	1 FENDER PANEL REAR RH		\$ 7 3,299.13 X
34	1 WHEELARCH REAR RH		543.47 X
35	1 TAILLAMP RH		\$ 「ハ 552.55 X 1 986.70 X
36	1 TAILLAMP PANEL RH		\$ M31M 552.55
37	1 TAILLAMP LH		
38	1 TAILLAMP PANEL LH		\$
39	1 OUTER PANEL REAR (End Panel)		\$ 1,471.77
40	1 OUTER PANEL REAR (End Panel)TRIM		\$ 404.56
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)		\$ 2,189.88 54 612.21
42	1 SPARE WHEEL PANEL TRIM		\$ 012.21
43	1 EXHAUST REAR		\$ 7,489.05
44	1 EXHAUST CAP REAR		\$ 230.49
45	1 CHASSIS PANEL REAR RH		\$ 7 3,766.43
46	1 KUCKLE ARM REAR RH L70Y		\$ 5m 736.67 X
47	1 BRAKE DISC REAR L70Y		\$ √S 525.91
48	1 WHEEL HUB NUT L70Y		\$ 51.11
49	1 WHEEL HUB CAP L70Y		\$ 57.82
50	1 ABS SENSOR REAR RH L70Y		\$ رار _{255.75}
51	1 REAR AXLE L70Y		\$ Sh 4,167.03
52	1 AXLE ARM RH L70Y		\$ Su 117.22
53	1 LOWER ARM REAR RH L70Y		\$ 905.99
54	1 ABSORBER REAR		\$ 389.75
55	1 STABILIZER BAR REAR RH		\$ fn 604.65
56	1 BRAKE CALIPER REAR RH		\$ Ju 1,300.67
57	1 WHEEL HOUSING PANEL REAR RH		\$ N 4,682.09
58	1 CHASSIS PANEL REAR RH		\$ N 3,766.43
		TOTAL	\$ 56,525.01
		10%	\$ 5,652.50
			\$ 50,872.51 49
	Specical Nett		0
1 .	ISET PARKING AID		\$ Ja 700.00 X
2 '	ISET REAR BUMPER CLIP		\$ Ne, 66.00 -
3 '	ISET BUMPER BRACKET CTR CLIP		\$ Ma 33.00 _
4	ISET BUMPER BRACKET SIDE CLIP RH RR		\$ ~~ 10.00 X

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 367B

5 1SET	BUMEPR RETAINER RH CLIP RR	\$	~ 20.00 x	
6 1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00 X	
7 1SET	BUMEPR RETAINER CLIP LH RR	\$	~~ 20.00 X	
8 1SET	BUMPER LOWER REAR RIVET	\$	~~ 22.00 X	
	BUMPER LOWER REAR CLIP	\$	Na 66.00 -	
	EXHAUST MOUNTING REAR	\$	~~ 17.82 ×	
11 1SET	BOOT FINISHER CLIP	\$	ルへ 24.20 X	
	BOOT STICKER "Trans-cab"	\$	Ma 30.00 -	-
1075	BOOT STICKER "6555-3333"	\$	Mc 30.00 €	_
	BOOT INNER TRIM CLIP	\$	~~ 45.00 X	
	FENDER WHEELARCH REAR RH CLIP	\$	~~ 35.00 X	
1070	FENDER WHEELARCH REAR LH CLIP	\$	~~ 35.00 ×	
	FENDER INNER TRIM CLIP LH	\$	マル 28.00 く	
	FENDER INNER TRIM CLIP LH	\$	nn 28.00 人	
- 10 Table 10	TAILLAMP CLIP RH	\$	nn 5.00 X	
100	TAILLAMP CLIP LH	\$	Me 5.00 W	
	REAR WINDSCREEN SELANT	\$	na 80.00 7	
, mar. 1.	WINDSCREEN MOULDING	\$	~~ 100.00	
	REAR WINDSCREEN INNER SPONGE SEAL	\$	12 100 00	~
(TES)	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	~~ 385.00 }	X
	SPARE TYRE	\$	Ja 330.00	
100	RIGHT REAR TYRE	\$	Sn 330.00	
	RIGHT REAR TYRE RIM	\$	Sm 380.00J	
	TOTAL	\$	2,935.02	
		_	F2 007 F2	
	TOTAL PARTS	\$	53,807.53	
	LABOUR			
	Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	dal
	Panel Beating, Knocking And Straightening The			
	Necessary Portion, Remove And Renewal Of Parts,		8194	=
	Adjust And Realign The Same	\$	4,200.00	00%
	To Rust-Proofing Of The Affected Areas.	\$	4,200.00 6	2

No. 2 Ang Mo Kio Street 63 Singapore 569111

Date:

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 367B

Third party survey is on a "Without Prejudice" to PART-BY-PAR No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature:		3day,
To display damaged part(s) during resurvey Parts prices are subject to confirmation		66727.51
LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting Over All Tot	al \$	66,347.53
TOTA	AL \$	12,540.00
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~~ _{380.00} X
To check steering geometry and computer wheel alignment	\$	n~ 220.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~~ 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~~ 380.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	№ 380.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~~ _{170.00} X
To repair and realign rear exhaust pipe.	\$	NR 170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 601
To reinstall rear bumper parking sensor.	\$	170.00 602
3		

AAD1807-278

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI18013950/KRBN2

Date:

14/08/2018

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MW011516

Claimant

Vehicle No :

SHD367B

Insured Vehicle No:

SLE6998M

Date of Loss:

29/07/2018

Nature of Claim:

TP

Claim No: M1803801

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD367B

Make & Model:

RENAULT LATITUDE, 2.0 L (A) 17/05/2016 (Man. Year: 2015) Engine No: Chassis No: M9R8839C003032 VF1ABL15AUC282736

Reg. Date: Colour:

Metallic White/Red

Odometer:

261678 km

Engine Capacity:

Market Value/New Car Price: 1995 cc

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 215/60R16

Rear Tyre Size: Rear Left Side: 215/60R16 Falken 8 mm

Giti 7 mm Giti 7 mm Rear Left Side: Rear Right Side:

Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,807.51	7,723.03	46,084.48	85.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,920.00	1,470.00	11,450.00	88.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	66,727.51	9,193.03	57,534.48	86.22
+ GST 7.00/7.00% (S\$)	4,670.93	643.51	4,027.42	86.22
Nett Amount (S\$)	71,398.44	9,836.54	61,561.90	86.22

INSPECTION

Date of Assignment:

02/08/2018

Date Inspected:

31/07/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair:

5.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 14 Aug 2018) Part Source: MRM-SG

RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

Repairer's (Price-denominated Standard List) Labour:

Print Code: (Unsubmitted, no print-code for SHD367B)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Re	com	men	de	ed	Part	S
A1-	04.	Don't b	1-	Dan	tioular	_

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*-FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*-FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*-FL
6	1	*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*-FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*-FL
9	1	*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*-FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*-FL
12	1	*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*-FL
13	1	*BOOT REAR	Bent		*2,872.68 FL
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*-FL
15	1	*BOOT WEATHERSTRIP	Cut	323.05 FL	*323.05 FL
16	1	*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*-FL
17	1	*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*-FL
18	1	*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1	*BOOT BADGE	Necessary	225.36 FL	
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	
22	1	*BOOT HINGE LH	Repair	367.84 FL	
23	1	*BOOT HINGE RH	Repair	367.84 FL	
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	
25	1	*BOOT SWITCH	Serviceable	168.13 FL	
26	1	*BOOT LOCK	Repair	202.67 FL	
27	1	*BOOT LOCK CATCH	Repair	74.40 FL	*-FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	
30	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	
31	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	
32	1	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	
33	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	
34	1	*WHEELARCH REAR RH	Serviceable	543.47 FL	
35	1	*TAILLAMP RH	Serviceable	552.55 FL	
36	1	*TAILLAMP PANEL RH	Repair	986.70 FL	
37	1	*TAILLAMP LH	Mtg Cracked	552.55 FL	
38	1	*TAILLAMP PANEL LH	Repair	986.70 FL	
	1	*OUTER PANEL REAR (END PANEL)	Bent		*1,471.77 FL
39 40	1	*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	
	4	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)		2,189.88 FL	
41 42	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Serviceable	612.21 FL	
	1				
43	1	*EXHAUST REAR *EXHAUST CAP REAR	Repair Repair	7,489.05 FL 230.49 FL	
44	1	EXHAUST CAP REAR	Kepaii	230.48 FL	- AFL

No.	Qty	Part No. Particulars	Condition I	Repairer's	Amount
45	1	*CHASSIS PANEL REAR RH	Repair	3,766.43 FL	*-FL
46	1	*KNUCKLE ARM REAR RH L70Y	Serviceable	736.67 FL	*-FL
47	1	*BRAKE DISC REAR L70Y	Serviceable	525.91 FL	*-FL
48	1	*WHEEL HUB NUT L70Y	Serviceable	51.11 FL	*-FL
49	1	*WHEEL HUB CAP L70Y	Serviceable	57.82 FL	*-FL
50	1	*ABS SENSOR REAR RH L70Y	Serviceable	255.75 FL	*-FL
51	1	*REAR AXLE L70Y	Serviceable	4,167.03 FL	*-FL
52	1	*AXLE ARM RH L70Y	Serviceable	117.22 FL	*-FL
53	1	*LOWER ARM REAR RH L70Y	Serviceable	905.99 FL	*-FL
54	1	*ABSORBER REAR	Serviceable	389.75 FL	*-FL
55	1	*STABILIZER BAR REAR RH	Serviceable	604.65 FL	*-FL
56	1	*BRAKE CALIPER REAR RH	Serviceable	1,300.67 FL	*-FL
57	1	*WHEEL HOUSING PANEL REAR RH	Repair	4,682.09 FL	*-FL
58	1	*CHASSIS PANEL REAR RH	Repair	3.766.43 FL	*-FL
	1	*SET PARKING AID	Serviceable	700.00 FS	*-FS
59 60	1	*SET PARKING AID	Necessary	66.00 FS	*66.00 FS
		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
61	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
62 63	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
64	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
65	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
66	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
67	1	SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
68	1	*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*-FS
	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
69 70	1	*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
			Necessary	30.00 FS	*30.00 FS
71	1	*BOOT STICKER 6555-3333 *BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
72 73	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*-FS
74	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*-FS
75	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*-FS
	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*-FS
76	1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
77 78	1	*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
79	2	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
80		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
81 82	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Not Necessary	385.00 FS	*- FS
83	1	*SPARE TYRE	Serviceable	330.00 FS	
84	4	*RIGHT REAR TYRE	Serviceable	330.00 FS	
85	4	*RIGHT REAR TYRE RIM	Serviceable	380.00 FS	
2000	anchise	part. S=SpcNett. L=ListItemDisc.	CCIVIOCUDIC	000.001.0	1,500
0.98%			Sub Total (S\$)	59.460.01	8,555.59
		- List Item Discount on L Items			832.56
			Total Parts (S\$)	53,807.51	7,723.03

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Pecom	mended	I aho	nir
Recom	menaea	Labo	Jui

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	660.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,200.00	600.00
3	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
4	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
5	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
6	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
7	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	60.00
8	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	92
9	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	. New	380.00	4
10	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	
11	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	19-
12	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
13	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	
14	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
	Gross Labou	r Cost (S\$)	12,920.00	1,470.00
	Report was unsubmitted durin	a this print-out		

< END OF ESTIMATES >