

REPAIR ESTIMATE*

VEHICLE NO : SH 9639G

DATE 31/7/2018 14:26

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover <i>x repair</i>			\$ 562.30	
	Front Bumper Bracket Top (LH) ?			\$ 22.40	
	Front Bumper Bracket (LH) ?			\$ 24.60	
	Front Door Mirror (LH) x			\$ 980.50	
	Front Wheel Hub Cap (LH) ✓			\$ 150.70	
	<i>Front Fender (LH) x repair</i>				
	SUB TOTAL			\$ 1,740.50	
	LESS 20%			\$ 348.10	
	DISCOUNTED TOTAL			\$ 1,392.40	
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Labour Charge				
	Panel Beating			\$ 350.00 ²⁰⁰	
	Spray Painting Charge			\$ 650.00 ⁴⁰⁰	
	Wiring Charge			\$ 50.00 x	
	Tuff Kote			\$ 50.00 x	
	FRT Wheel Alignment			\$ 120.00 x	
	TOTAL LABOUR			\$ 1,220.00	
	ESTIMATE TOTAL			\$ 2,712.40	
<p><i>Kah (LKK)</i></p> <p><i>31/7/18 1505 L.</i></p> <p><i>2 Dy</i></p> <p><i>PIP</i></p> <p><i>Ath Repair p Lh</i></p> <div style="border: 1px solid black; padding: 5px; transform: rotate(-5deg);"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div> <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					