
22/03/2002 ASS_REC, BY:		REF:	09/FCI	80 1402	5/A6	027 Specia	1 Instruction		
Surveyor			ASSIGNA	MENT (O					
From (Person):	(We haven	Jul of		FUL		Da	ite/Time:	01082018	534pm
Estimated Cost				Bill to:					
OD/FF/WS	TP RES / OD R	ES/EVA/	INV / MV	CS					
To Inspect Vel	nicle No:	SLR	4003 D					1C 7375L	
	Vs			olution			9189	2613	
of		23 Kala	Bukit	AVE 4	#04-	01			
Policy No:				Clair	n No:	DI	800579	14 MFSH	
Sum Insured:_				Ex	cess:				
Make of Veh: (Client's Record)						D.	O.A	37072018	0
CA / REV / Date/Time;	REP. / REV 24 01082018 5.514		n Contacted	5	luhaimi	Veh	H.O.D. End	orsement:	
Date/Time	Action/Instruction	(/) Estima	to					
	CENOTI SIG) County	W.					
	SHC 7375L	- MA/IN	C1601715	4/13				DCA - 110	1916
02/08/18		P.M. re	vet p	rudy	estina	ete from	n rep		
18/09/18	Via email Confirmed		\$ 24.9	399.30	Q 1	3 days	wit	h Adri	21
	(\$ 13.678	00'	Red -	35%)	J			

·. <u>A</u>	SSIGNMENT
From: Dale:	Veh No: SLR 4003 D. Yr Regn: 2017 August
Estimated Cost:	Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Opel Mokkg. c.c 1598
at Workshop m/s	Colour Red . A/C: Insured / Std / NI / NA
of	Sp.Reading 65935. T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WOLJOTE C2H 8180519.
Claims No.	Gen. Cond: Good Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Iporder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inoder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SIRim / STD A/Rim or
	Tyre Size: F: 215/55 R16
(Policy Condition)	R: 215/55R16
Remark: The veh had commenced its N/S 0	DIS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YORO or
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 06 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. Q6 mm L/Bal. Q6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. DO.I. 01 03/18
Lum Sum: % 3 Val.: Yes or No	Survey held at Ace Auto Solution.
CA / REV / REP. / 24 HRS	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftch or
Vehicle: IN /	OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
MV: 881C PV: 51.61C Nett: RECEIVED 2	7 SEP 2018
Date/Time, File Pass 10? 21/09/13 Typist Date/Time, File Return 10? : Preli. Report : Final Report	Days Of Repair: /3
2) Add	
	: Interview (\$) Photos & 160
Report Format:	: Tech Invs (\$) Others
Lump Sum / LB.I: (\$ 24,999.30 P/P)	:Weekend (\$) 0\S
	1000



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Hotor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

31-07-2018

Our Ref No. D18005794MFSH

Accident Date

27-07-2018

Claim Type. Third Party

Insured Vehicle

SHC7375L

Third Party Vehicle. SLR4003D

Survey Location

23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING)

Contact Person.

SUHAIMI

Contact No.

0/91892617

Fax No. 68445185

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

ACE AUTO SOLUTION

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

SGEARMART.COM THE ONLY PLACE FOR SMART CAR BUYERS

Opel Mokka 1.6A X

Price	\$89,800
Reg date	22-May-2017
Manufactured	2017
Mileage	9,000 km
Transmission	Auto
Engine Capacity	1,598 cc
Road Tax	\$1,282 per year
Power	100.0 kW (134 bhp)
Curb Weight	1,501 kg
Fuel Type	Diesel (Euro 5 Engine and Above)
Features	136 BHP 4-cylinder 16-valve DOHC Turbocharged Diesel Engine. Full Tank \$70 CAN Do Nearly 1000KM! 6 Speed Auto! 4 Disc Brakes! LED Day Running Lights
Accessories	Climatic Aircons, Multi Function Steering, Parking Camera, Cruise Control, 18" Sports Rims, Rain Sensing Wiper, Auto Headlights, Traction Control,
Description	\$0 Driveaway Available! Premium EURO 6 Turbo Diesel Continental SUV! Agent Sell Till No Stock! Last Recorded RRP As Per Agent Price List \$135888! 5 Years Unlimited Mileage Warranty, 3 Years Free Servicing As Per Agent Package! In-House Loan Or Bank Loan Available! No Need Guarantor Or Minimum Income! Fast And Easy Loan Approval! Powerful! Luxury! Super Low Fuel Consumption! Grab Fast Before Gone!
COE	\$54,616
ому	\$20,376
ARF	\$15,527
Depreciation	\$9,310 / year
No. of owners	1
Type of Vehicle	Mid-Sized Sedan
Availability	Available



Company	88 Motor Tra	ding
	» dealer's price » 186 vehs sol	elist d 123 vehs available
Address	200 Jalan Sulta	n #02-38/Level 7 Carpark
Location	Textile Centre	
Office No	62911187	
Contact Person(s)	Jeremy	97625070
	Alan	96900054
	Mr Ho	96811390
	Ron	82981859










Posted on: 27-Jul-2018

Last Updated: 27-Jul-2018



All Prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

© 2004-2018 sgCarMart. All rights reserved.



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID:	3483E	
Vehicle Details		
Vehicle No.:	SLR4003D	
Vehicle to be Exported:	Yes	
Intended De-registration Date:	31 Jul 2018	
Vehicle Make:	OPEL	
Vehicle Model:	MOKKA X 1.6 CDTI 6AT	
Primary Colour:	Red	
Manufacturing Year:	2017	
Engine No.:	A1170105GU7X0087	
Chassis No.:	W0LJD7EC2HB180519	
Maximum Power Output:	100.0 kW (134 bhp)	
Open Market Value:	\$20,376.00	
Original Registration Date:	15 Aug 2017	
First Registration Date:	15 Aug 2017	
Transfer Count:	0	
Actual ARF Paid:	\$15,527.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	14 Aug 2027	
PARF Rebate Amount:	\$11,645.00	
Intended COE Rebate Details		
COE Expiry Date:	14 Aug 2027	
COE Category:	E - Open - all except motorcycle	
COE Period(Years):	10	
QP Paid:	\$50,101.00	
COE Rebate Amount:	\$40,000.00	
Total Rebate Amount:	\$51,645.00	

The information contained herein is correct as at 30 Jul 2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3483E
Vehicle Details	
Vehicle No.:	SLR4003D
Vehicle to be Exported:	Yes
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	OPEL
Vehicle Model:	MOKKA X 1.6 CDTI 6AT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	A1170105GU7X0087
Chassis No.:	W0LJD7EC2HB180519
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,376.00
Original Registration Date:	15 Aug 2017
First Registration Date:	15 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$15,527.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2027
PARF Rebate Amount:	\$11,645.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$40,000.00
Total Rebate Amount:	\$51,645.00

The information contained herein is correct as at 01 Aug 2018

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Thursday, 2 August 2018 3:14 PM

To: Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System' ASSIGNMENTS@LKKAUTO.COM; 'SUR'; 'Catherine Chong (LKK Auto)'

Subject:

RE: SURVEY ASSESSMENT - D18005794MFSH/1

Dear Lurene.

Please be informed that we have inspected the vehicle SLR 4003D on 01/08/2018.

We are pending for estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Wednesday, 1 August 2018 5:56 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM

Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18005794MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Wednesday, 1 August, 2018 5:34 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18005794MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCI	דואםח	STAT		MENI	
ACCI	DEN	SIA	-11		ш

 Date Of Report
 28/07/2018 11:20

 Date Of Accident
 27/07/2018 17:15

Exact Location Of Accident ECP TOWARDS CITY LP326 LANE 1

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR4003D

Insured/Policyholder

Name Of Registered Owner ALPINE CAR RENTAL PTE LTD

Co Reg No 199003483E Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-65113023

Vehicle Particulars

Manufacturer OPEL

Model Mokka-1.6 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy YES

Policy Number 5093613878

Cover Note Number

Driver

 Name of Driver
 CHIN CAI YANG

 NRIC No
 \$8703244B

 Date Of Birth
 14/02/1987

 Occupation
 OUTDOOR

 Date Of Driving Pass
 19/12/2007

Driving Experience 10 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-92326104

Fax Number

Contact Number

EMail Address NOEMAIL

Address

143 LOR AH SOO

OTHER - HIRER

Postcode

530143

Was driver an employee of the Insured's Company NO If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

NO 3

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

YES

ambulance? Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: JULIUS TAN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes.Please state which Police Station

Police Station Name

TRAFFIC POLICE DIVISION HQ

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact Was notice of intended Prosecution given?

TEL NO: 65470000 - FAX NO:

If Yes, against whom?

NO

Circumstances of Accident

SEE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC7375L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJS6199C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 213/7/18 @ 0950hs

Reporting Centre Personnel's Signature Name:

NRIC/FIN No .:





1 of 4

Report No. T/20180729/7000

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

	ne Report N 018 01:05	Made:	Vide Report No.: G/20180727/0157	Station Diary No.:
Informa	nt's Partic	ulars		
CHIN CA			Address: APT BLK 143 LORONG AH S 530143	SOO #06-227 SINGAPORE
ID Type NRIC NO	/ ID No.: D / S87032	44B	Contact No.: Home/Office:	Mobile: 92326104
Nationali SINGAP	ity: ORE CITIZ	ΈN	Email: chincaiyang@yahoo.co.uk	
Sex: Male	Age: 31	Date of Birth: 14/02/1987	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupati Centre M			Driving Licence Information: Class:	Date of Evoing

General Infor	mation of the Accident			
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 27/07/2018 17:15	Type of Location: Straight Road
EAST COAS	T PARKWAY			
Weather: Clear		Road Surface: Dry		Road Speed Limit: 90 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collis Between Mov	ion: ing Vehicles - Head To Re	ear		Anyone conveyed by ambulance:

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenc
SHC7375L	Car	HYUNDAI	Sonata	Yellow	Concinon	3
SJS6199C	Car	TOYOTA	Altis	Blue	Seriously	2
SLR4003D	Car				Damaged	





3 of 4

Report No. T/20180729/7000

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

I found out that the vehicle that collided into me was a yellow taxi (SHC7375L). I checked with the driver and he said he was alright. However, his 3 passenger needs to be conveyed. The driver of SJS6199C also informed that one of his two passengers needed to be conveyed as well. Ambulances were activated and traffic police arrived at scene.

I wish to state that I am not injured during incident time. My vehicle has a front and rear camera. The SD card can be obtained from my rental company 'Alpine Rental'.







Certificate of Insurance

Cover : drivo PREMIUM

: ALPINE CAR RENTAL PTE LTD

: W0LID7EC2HB180519

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5093613878

1. Index mark and Registration Number of Vehicle

Chassis Number

2. Name of Policyholder

3. Effective Date of Insurance

4. Expiry Date of Insurance

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

: SLR4003D

: 01 Sep 2017

: 31 Aug 2018

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

EXCESS (SECTION 1)

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

: \$\$1,400 EXCESS (SECTION 2) : S\$1,400 WINDSCREEN EXCESS : \$\$100 ADDITIONAL EXCESS : N/A UNNAMED DRIVER EXCESS : PLEASE REFER OVERLEAF REPAIR AT OWNER'S PREFERRED WORKSHOP : YES INSURE WITH COE : YES NCD PROTECTION : NO TRANSPORT ALLOWANCE : NO **EXCESS WAIVER** : NO PRIMARY DRIVER : N/A

NAMED DRIVER (1) : N/A NAMED DRIVER (2) : N/A HIRE PURCHASE COMPANY : N/A SUM INSURED

: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

: ALPINE CREDIT PTE LTD (00000615424)

Date of Issue

: 21 Aug 2017 12:23 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

Ace Auto Solution

Registration number : 53228991M 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date: 2/8/2018

TP 15 Cap Studen

Reference:

SLR4003D

Make:

OPEL MOKKA X 1.6 CDTI 6AT

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SLR4003D

CHASSIS NO.:W0LJD7EC2HB180519 ENGINE NO.A1170105GU7X0087

Name of insured .: Alpine Car Rental Pte Ltd

Date of accident.: 27/07/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Bonnet Denfed.	\$ 1,635.00
2	1	LHF Headlamp Crube	\$ 2,872.00
3	1	RHF Headlamp Zweled.	\$ 2,872.00
4	1	Front Radiator Grille Moulding, Base	\$ 206.00 -
<u>5</u>	1	Front Radiator Grille Chrome Moulding	\$ 393.00 -
<u>6</u>	1	Front Opel Emblem	\$ 58.00
7	1	Front Bumper - Upper Delad	\$ 1,170.00 /
8	1	Front Bumper - Lower	\$ 373.00 /
9	1	Front Bumper Lower Grille De Le	\$ 198.00 /
<u>10</u>	1	Front Bumper Lower Sill Plate Pelad.	\$ 156.00
<u>11</u>	1	Front Bumper Towing Cover 1	\$ 56.00 +
<u>12</u>	1	Front License Plate Bracket 2-4	\$ 220.00
<u>13</u>	1	LHF Foglamp Cover Relied	\$ 102.00
<u>14</u>	1	LHF Foglamp CruC	\$ 353.00
<u>15</u>	1	RHF Foglamp Cover	\$ 102.00 }
<u>16</u>	1	RHF Foglamp CmCd	\$ 353.00 2
<u>17</u>	1	Bonnet Latch Page.	\$ 236.00
<u>19</u>	1	Front Bumper Reinforcement Bar Upper Best	\$ 428.00

20 303.00 Front Bumper Reinforcement Bar Lower 21 \$ 120.00 Front Bumper Absorber - Upper 22 \$ 80.00 Front Bumper Absorber - Lower 23 1 Front Support Panel Assy Report 806.00 ト 24 1 45.00 LHF Bumper Bracket - Guide 25 1 \$ 45.00 RHF Bumper Bracket - Guide Bert 26 1 \$ 98.00 Top Centre Bumper Bracket and c 1 27 1,035.00 Radiator Devted 28 1 \$ 510.00 Condensor 29 1 Dented \$ 998.00 Turbo Intercooler 31 LHF Fender Protector AH w \$ 104.00 1 32 He m \$ 236.00 LHF Fender Liner 34 RHF Fender Protector NH ~ \$ 104.00 we m 35 1 \$ 236.00 RHF Fender Liner Derted. 1 36 \$ 1,914.00 Rear Tailgate 37 1 2,408.00 Rear Tailgate Top Moulding (incl rr view camera) ** ** 38 1 Dand \$ 179.00 Rear Tailgate Outer Handle w lock 39 1 135.00 Rear Tailgate Opel Logo 40 1 New Lettering Mokka X 91.00 41 1 Lettering CDTI 69.00 42 1 Not n \$ 1,048.00 Rear Windscreen With Moulding Hen could 43 1 \$ 361.00 Tailgate Inner Trim Board 44 1 Tailgate LH Inner Trim Board upper 2, 14 93.00 + 45 \$ Tailgate RH Inner Trim Board upper 93.00 46 \$ LHR Tailgate Hinge 65.00 47 1 NH \$ RHR Tailgate Hinge 65.00 M 48 1 \$ 111.00 LHR Tailgate Damper 49 1 \$ 111.00 RHR Tailgate Damper 50 Rear Tailgate Latch Pour d. \$ 231.00 51 \$ 40.00 Rear Tailgate Striker 52 1 \$ LHR Taillamp 452.00 53 \$ RHR Taillamp 452.00 Rear Bumper Upper 900 54 \$ 1,158.00 <u>55</u> \$ 883.00 Rear Bumper Lower <u>56</u> \$ 286.00 Rear Bumper Sill Plate 57 \$ 25.00 Rear Bumper Towing Cover (mild 58 \$ 102.00 LHR Bumper Reflector - LH Rear

59	1	RHR Bumper Reflector - RH Rear Could	\$ 102.0	0
<u>60</u>	1	RHR Bumper Reflector - RH Rear Could Rear Bumper Absorber - RH 2 Could	\$ 45.0	0
<u>61</u>	1	Rear Bumper Absorber - LH	\$ 45.0	0
<u>62</u>	1	Rear Bumper Reinforment Bar	\$ 951.0	0
<u>63</u>	1	Rear Bumper Air Ventilator	\$ 85.0	0
<u>64</u>	1	LHR Bumper Bracket, Guide	\$ 58.0	0
<u>65</u>	1	RHR Bumper Bracket, Guide	\$ 58.0	0
<u>67</u>	1	LHR Bumper Lower Bracket 2000	\$ 35.0	0
<u>68</u>	1	RHR Bumper Lower Bracket	\$ 35.0	0
<u>70</u>	1	Spare Tyre Panel Coult Penis	\$ 1,188.0	0
<u>71</u>	1	Rear End Panel Deated	\$ 1,217.00	0
<u>72</u>	1	Rear End Panel Trim Del-d	\$ 136.00	0
<u>75</u>	1	Spare tyre panel mat	\$ 510.00	0
<u>77</u>	1	RHR Fender Protector 7	\$ 138.00	0
<u>78</u>	1	RHR Fender Liner	\$ 228.00	0
<u>80</u>	1	LHR Fender Protector	\$ 138.00	0
<u>81</u>	1	LHR Fender Liner	\$ 228.00	0

23077

Parts Total: \$ 32,072.00

\$

Less10%: \$ 3,207.20

Total: \$ 28,864.80

Labour

2

	Labour Description			
No.		Pr	rice (SGD)	
	Front portion			
1	To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts. (\$200 PER DAY)	\$	1,200.00	600
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$	1,000.00	800
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$	30.00	_
4	To remove and refit aircon condensor,vacuum,refill and check air con gas system	\$	600.00	60
<u>5</u>	To remove and refix radiator and conduct pressure test	\$	100.00	60
<u>6</u>	S.R.S. Reset of system	\$	300.00	+ 14
7	To refocus headlamp	\$	80.00	x ' '
8	To remove and refit front sensor	\$	80,00	60.
	Rear portion			1 -
1	To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts. (\$200 PER DAY)	\$	1,800.00	1800
				1

Carry out spray painting on accident affected area (\$200 PER PANEL)

3	To conduct anti rust of under carriage tuff coat	\$ 120,00
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>5</u>	To remove and refix reverse sensor and conduct test	\$ 80,00
<u>6</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00
7	To conduct water leakage test after repairs of vehicle	\$ 50.00
<u>8</u>	To apply sealant to rear tailgate	\$ 80.00
9	To remove and replace rear tail gate windscreen	\$ 120.00
10	To remove and refit rear spoiler	\$ 80.00

2130

Labour Total: \$ 7,030.00

Others

Other Description

No.	Qty		Price (SGD)		
		Front portion			
1	1	Number plate with casement But	\$ 45.00	~	
2	10	Front bumper clip Bonnet insulator clip **Market Properties** **Properties** **Properties*	\$ 65.00	ت 3 -	
3	10	Bonnet insulator clip	\$ 65.00	×	
4	1	Coolant	\$ 80.00	50	
5	5	Front support panel top garnish clip	\$ 32.50	15	
6	6	Front fender liner clip XLP MA	\$ 39.00	×	
7	1	Front sensor(1 set)	\$ 720.00	+	
		Rear portion			
1	1	Rear number plate ************************************	\$ 45.00	+	
2	10	Rear bumper clip	\$ 65.00	30	
3	6	Rear fender liner clips	\$ 39.00	+	
4	8	Rear end panel trim clip 🎎	\$ 52.00	-20	
5	1	Reverse sensor (1 set) Pod	\$ 720.00	350	
6	1	Rear end panel insulation seal	\$ 80.00	60	
7	1	Rear floor panel insulation seal ** ~	\$ 120.00	+	
8	20	Rear fender inner trim clip ************************************	\$ 130.00	×	
9	10	Tail gate inner trim board clip	\$ 65.00	30	
10	1	Tailgate windscreen sealant	\$ 120.00	-60	
11	1	Tailgate windscreen solar film Mer	\$ 220.00	4	
12	1	Rear Spoiler Sealant Not Ne	\$ 80.00	2	

Other Total: \$ 2,782.50

GRAND TOTAL: \$ 38,677.30

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

Suhaimi

HP: 9189 2617 Email - aceautosolution@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lig total: 2459930 P/P 1/08/18.

Finalisation

Ace Auto Solution

Registration number: 53228991M

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

INVOICE

To: MS FIRST CAPITAL INSURANCE LIMITED

Rear Tailgate Opel Logo

Lettering Mokka X

30

36 ROBINSON ROAD, #16 - 01

CITY HOUSE

SINGAPORE 068877

Invoice No: ACC-2015001

\$

135.00

91.00

AMOUNT

SGD

Invoice Date:

Vehicle No: SLR4003D

DESCRIPTION

Chasis No: W0LJD7EC2HB180519 Engine No: A1170105GU7X0087

Parts			
No.	Qty.		Price (SGD)
1	1	Bonnet	\$ 1,635.00
2	1	LHF Headlamp	\$ 2,872.00
3	1	RHF Headlamp	\$ 2,872.00
4	1	Front Radiator Grille Moulding, Base	\$ 206.00
5	1	Front Radiator Grille Chrome Moulding	\$ 393.00
6	1	Front Opel Emblem	\$ 58.00
7	1	Front Bumper - Upper	\$ 1,170.00
8	1	Front Bumper - Lower	\$ 373.00
9	1	Front Bumper Lower Grille	\$ 198.00
<u>10</u>	1	Front Bumper Lower Sill Plate	\$ 156.00
11	1	Front License Plate Bracket	\$ 220.00
<u>12</u>	1	LHF Foglamp Cover	\$ 102.00
13	1	LHF Foglamp	\$ 353.00
14	1	RHF Foglamp Cover	\$ 102.00
<u>15</u>	1	RHF Foglamp	\$ 353.00
<u>16</u>	1	Bonnet Latch	\$ 236.00
<u>17</u>	1	Front Bumper Reinforcement Bar Upper	\$ 428.00
<u>18</u>	1	Front Bumper Reinforcement Bar Lower	\$ 303.00
<u>19</u>	1	Front Bumper Absorber - Upper	\$ 120.00
<u>20</u>	1	Front Bumper Absorber - Lower	\$ 80.00
<u>21</u>	1	LHF Bumper Bracket - Guide	\$ 45.00
22	1	RHF Bumper Bracket - Guide	\$ 45.00
23	1	Top Centre Bumper Bracket	\$ 98.00
24	1	Radiator	\$ 1,035.00
<u>25</u>	1	Condensor	\$ 510.00
<u>26</u>	1	Turbo Intercooler	\$ 998.00
<u>27</u>	1	Rear Tailgate	\$ 1,914.00
28	1	Rear Tailgate Outer Handle w lock	\$ 179.00

<u>31</u>	1	Lettering CDTI	\$ 69.00
<u>32</u>	1	Tailgate Inner Trim Board	\$ 361.00
<u>33</u>	1	Rear Tailgate Latch	\$ 231.00
<u>34</u>	1	Rear Bumper Upper	\$ 1,158.00
<u>35</u>	1	Rear Bumper Lower	\$ 883.00
<u>36</u>	1	Rear Bumper Sill Plate	\$ 286.00
37	1	Rear Bumper Towing Cover	\$ 25.00
<u>38</u>	1	LHR Bumper Reflector - LH Rear	\$ 102.00
<u>39</u>	1	RHR Bumper Reflector - RH Rear	\$ 102.00
<u>40</u>	1	Rear Bumper Absorber - RH	\$ 45.00
<u>41</u>	1	Rear Bumper Absorber - LH	\$ 45.00
<u>42</u>	1	Rear Bumper Reinforment Bar	\$ 951.00
<u>43</u>	1	LHR Bumper Bracket, Guide	\$ 58.00
44	1	RHR Bumper Bracket, Guide	\$ 58.00
<u>45</u>	1	LHR Bumper Lower Bracket	\$ 35.00
<u>46</u>	1	RHR Bumper Lower Bracket	\$ 35.00
<u>47</u>	1	Rear End Panel	\$ 1,217.00
<u>48</u>	1	Rear End Panel Trim	\$ 136.00

Total: \$ 23,077.00 Less 10%: \$ 2,307.70 Parts Total: \$ 20,769.30

Labour

No.		Price (SGD)
	Front portion	
	To dismantle / renew the accident damaged portion to panel	

1	beating,reshape,straighten,orientate and align repair /replacement parts. (\$200 PER DAY)	\$ 600.00
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 600.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 60.00
<u>5</u>	To remove and refix radiator and conduct pressure test	\$ 60.00
<u>6</u>	To remove and refit front sensor	\$ 60.00
	Rear portion	

	<u>Real portion</u>	
1	To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts. (\$200 PER DAY)	\$ 1,000.00
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 800.00
3	To conduct anti rust of under carriage tuff coat	\$ 50.00
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>5</u>	To remove and refix reverse sensor and conduct test	\$ 50.00
<u>6</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00
7	To remove and replace rear tail gate windscreen	\$ 120.00

Labour Total: \$ 3,540.00

Other

No.			Price (SGD)
		Front portion	
1	1	Number plate with casement	\$ 45.00
2	10	Front bumper clip	\$ 30.00
3	1	Coolant	\$ 50.00
4	5	Front support panel top garnish clip	\$ 15.00
		Rear portion	•
1	10	Rear bumper clip	\$ 30.00
2	8	Rear end panel trim clip	\$ 20.00
3	1	Reverse sensor (1 set)	\$ 350.00
4	1	Rear end panel insulation seal	\$ 60.00
5	10	Tail gate inner trim board clip	\$ 30.00
6	1	Tailgate windscreen sealant	\$ 60.00

Other Total: \$

690.00

Total: \$

24,999.30

Grand Total: \$

24,999.30

Yours Faithfully,

Suhaimi

Service Executive

Tel: 9189 2617 Fax:6844 5185

Email: aceautosolution@gmail.com

E&OE

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "ACE AUTO SOLUTION".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

181		Affiliated to Federation Intern	nationale Des Experts En Auton	nobile
FIRS	T CAPITAL INSU	RANCE LTD	Ref : CS/FCI180140	25/Asbe2
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 15-10-2018 Code: FCI2	
1.		Policy Particula	ars :- THIRD PARTY CLA	M
	Insured Veh.	SHC 7375L	Veh. Inspected	SLR 4003D
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18005794MFSH	Excess (\$)	0.00
	Assign From	LURENE JAW	Assign Date	01/08/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model	OPEL MOKKA	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	W0LJD7EC2HB180519	Colour	RED
	Odometer	65935	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/55 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	215/55 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/55 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/55 R16	BRIDGESTONE	6 mm
١.		Descri	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT AND REAR PORTIO	DN.
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	27/07/2018	Inspection Date	01/08/2018
	Survey held at	ACE AUTO SOLUTION		
		23 KAKI BUKIT AVE 4,#04-0	1 (SOUTH WING) SINGAPO	RE 415933
ia.			Remarks	A THE RESERVE TO A STATE OF THE PARTY OF THE
	B)THE INSPECTION	NSISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	SIS. SED REPAIRS.
5b.		Estim	ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	13 Working Da	ays



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 4003D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	DENTED	1,635.00	1,635.00
1	LHF HEADLAMP	CRACKED	2,872.00	2,872.00
1	RHF HEADLAMP	CRACKED	2,872.00	2,872.00
1	FRONT RADIATOR GRILLE MOULDING BASE	CUT	206.00	206.00
1	FRONT RADIATOR GRILLE CHROME MOULDING	CUT	393.00	393.00
1	FRONT OPEL EMBLEM	NECESSARY	58.00	58.00
1	FRONT BUMPER - UPPER	DEFORMED	1,170.00	1,170.00
1	FRONT BUMPER - LOWER	DEFORMED	373.00	373.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	198.00	198.00
1	FRONT BUMPER LOWER SILL PLATE	DEFORMED	156.00	156.00
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	56.00	-
1	FRONT LICENSE PLATE BRACKET	DEFORMED	220.00	220.00
1	LHF FOGLAMP COVER	DEFORMED	102.00	102.00
1	LHF FOGLAMP	CRACKED	353.00	353.00
1	RHF FOGLAMP COVER	DEFORMED	102.00	102.00
1	RHF FOGLAMP	CRACKED	353.00	353.00
1	BONNET LATCH	DAMAGED	236.00	236.00
1	FRONT BUMPER REINFORCEMENT BAR UPPER	BENT	428.00	428.00
1	FRONT BUMPER REINFORCEMENT BAR LOWER	BENT	303.00	303.00
1	FRONT BUMPER ABSORBER - UPPER	CRACKED	120.00	120.00
1	FRONT BUMPER ABSORBER - LOWER	CRACKED	80.00	80.00
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	806.00	.=
1	LHF BUMPER BRACKET - GUIDE	DAMAGED	45.00	45.00
1	RHF BUMPER BRACKET - GUIDE	DAMAGED	45.00	45.00
1	TOP CENTRE BUMPER BRACKET	BENT	98.00	98.00
1	RADIATOR	CRACKED	1,035.00	1,035.00
1	CONDENSOR	DENTED	510.00	510.00
1	TURBO INTERCOOLER	DENTED	998.00	998.00
1	LHF FENDER PROTECTOR	NOT NECESSARY	104.00	
1	LHF FENDER LINER	NOT NECESSARY	236.00	-



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	RHF FENDER PROTECTOR	NOT NECESSARY	104.00	2
1	RHF FENDER LINER	NOT NECESSARY	236.00	-
1	REAR TAILGATE	DENTED	1,914.00	1,914.00
1	REAR TAILGATE TOP MOULDING (INCL RR VIEW CAMERA)	NOT NECESSARY	2,408.00	-
1	REAR TAILGATE OUTER HANDLE W LOCK	DAMAGED	179.00	179.00
1	REAR TAILGATE OPEL LOGO	NECESSARY	135.00	135.00
1	LETTERING MOKKA X	NECESSARY	91.00	91.00
1	LETTERING CDTI	NECESSARY	69.00	69.00
1	REAR WINDSCREEN WITH MOULDING	NOT NECESSARY	1,048.00	-
1	TAILGATE INNER TRIM BOARD	CRACKED	361.00	361.00
1	TAILGATE LH INNER TRIM BOARD UPPER	NOT NECESSARY	93.00	-
1	TAILGATE RH INNER TRIM BOARD UPPER	NOT NECESSARY	93.00	-
1	LHR TAILGATE HINGE	NOT NECESSARY	65.00	-
1	RHR TAILGATE HINGE	NOT NECESSARY	65.00	-
1	LHR TAILGATE DAMPER	NOT NECESSARY	111.00	-
1	RHR TAILGATE DAMPER	NOT NECESSARY	111.00	-
1	REAR TAILGATE LATCH	DAMAGED	231.00	231.00
1	REAR TAILGATE STRIKER	NOT NECESSARY	40.00	-
1	LHR TAILLAMP	NOT NECESSARY	452.00	-
1	RHR TAILLAMP	NOT NECESSARY	452.00	-
1	REAR BUMPER UPPER	DEFORMED	1,158.00	1,158.00
1	REAR BUMPER LOWER	DEFORMED	883.00	883.00
1	REAR BUMPER SILL PLATE	DEFORMED	286.00	286.00
1	REAR BUMPER TOWING COVER	DEFORMED	25.00	25.00
1	LHR BUMPER REFLECTOR - LH REAR	CRACKED	102.00	102.00
1	RHR BUMPER REFLECTOR - RH REAR	CRACKED	102.00	102.00
1	REAR BUMPER ABSORBER - RH	CRACKED	45.00	45.00
1	REAR BUMPER ABSORBER - LH	CRACKED	45.00	45.00
1	REAR BUMPER REINFORCEMENT BAR	BENT	951.00	951.00
1	REAR BUMPER AIR VENTILATOR	NOT NECESSARY	85.00	-
1	LHR BUMPER BRACKET, GUIDE	NECESSARY	58.00	58.00
1	RHR BUMPER BRACKET, GUIDE	NECESSARY	58.00	58.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	LHR BUMPER LOWER BRACKET	NECESSARY	35.00	35.00
1	RHR BUMPER LOWER BRACKET	NECESSARY	35.00	35.00
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,188.00	-
1	REAR END PANEL	DENTED	1,217.00	1,217.00
1	REAR END PANEL TRIM	DEFORMED	136.00	136.00
1	SPARE TYRE PANEL MAT	NOT NECESSARY	510.00	-
1	RHR FENDER PROTECTOR	NOT NECESSARY	138.00	-
1	RHR FENDER LINER	NOT NECESSARY	228.00	-
1	LHR FENDER PROTECTOR	NOT NECESSARY	138.00	-
1	LHR FENDER LINER	NOT NECESSARY	228.00	-
	LESS 10% DISCOUNT		-3,207.20	-2,307.70
			28,864.80	20,769.30
	SPECIAL NETT ITEMS			
1	NUMBER PLATE WITH CASEMENT (SN)	BENT	45.00	45.00
10	FRONT BUMPER CLIP (SN)	NECESSARY	65.00	30.00
10	BONNET INSULATOR CLIP (SN)	NOT NECESSARY	65.00	-
1	COOLANT (SN)	NECESSARY	80.00	50.00
5	FRONT SUPPORT PANEL TOP GARNISH CLIP (SN)	NECESSARY	32.50	15.00
6	FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	39.00	-
1	SET FRONT SENSOR (SN)	NOT NECESSARY	720.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
10	REAR BUMPER CLIP (SN)	NECESSARY	65.00	30.00
6	REAR FENDER LINER CLIPS (SN)	NOT NECESSARY	39.00	-
8	REAR END PANEL TRIM CLIP (SN)	NECESSARY	52.00	20.00
1	SET REVERSE SENSOR (SN)	DAMAGED	720.00	350.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	80.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
20	REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	130.00	-
10	TAILGATE INNER TRIM BOARD CLIP (SN)	NECESSARY	65.00	30.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
1	TAILGATE WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	220.00	-



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR SPOILER SEALANT (SN)	NOT NECESSARY	80.00	
	No control Medicine to the Control Con		2,782.50	690.00
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. (\$200 PER DAY)		1,200.00	600.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (\$200 PER PANEL)		1,000.00	600.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		30.00	30.00
	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM.		600.00	60.00
	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.		100.00	60.00
	S.R.S. RESET OF SYSTEM.	NOT NECESSARY	300.00	-
	TO REFOCUS HEADLAMP.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT FRONT SENSOR.		80.00	60.00
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. (\$200 PER DAY). INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL ASSY AND SPARE TYRE PANEL.		1,800.00	1,000.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (\$200 PER PANEL)		1,200.00	800.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.		120.00	50.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		30.00	30.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		80.00	50.00
	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE.		80.00	80.00
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	50.00	
	TO APPLY SEALANT TO REAR TAILGATE.	NOT NECESSARY	80.00	-



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REPLACE REAR TAIL GATE WINDSCREEN.		120.00	120.00
	TO REMOVE AND REFIT REAR SPOILER.	NOT NECESSARY	80.00	
			7,030.00	3,540.00
	GRAND TOTAL		38,677.30	24,999.30

RECOMMENDED COST OF REPAIRS	24,999.30
THE COMMENTED COOL OF THE PARTY	

Report Ref No. CS/FCI18014025/Asbe2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.