

22/03/2002

ASS. REC. BY:

REF:

CS/FCL180141B3/Asb02

Special Instruction:

Surveyor

Adnan

ASSIGNMENT (Office)

From (Person):

AWS Sthura

of

FCL

Date/Time:

01082018 355pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 73A

Insured:

SHB 3532G

at Workshop m/s

Tick Hai Motor

Tel:

6342 9089

of

Blk 1 Kaki Bukit Ave 6 #01-54

Policy No:

Claim No:

D18005759 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24072018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

01082018 550pm

Person Contacted:

Connie

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 73A - X

SHB 3532G - C4 / ASM18010716 / K123

DCA 11062018

3/8/18

Email Fcs informed pending est from repairer

REF: FCL

ASSIGNMENT

From: Date: 02082018
 Estimated Cost
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKP 73A
 at Workshop n/s Tick Hai
 of Blk 1 Kaki Bukit Ave 6 #01-54
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKP 73A. Yr Regn: 2012 Sept
 Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or
 Make: Porsche Panamera. CC: 3605
 Colour: Black. A/C: Insured / Std / NI / NA
 Sp. Reading: 179264. T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: WP022297ZDL000069.
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Modi: Nil ☒ S/Rim / ☐ STD A/Rim or
 Tyre Size: F: 285/40R19.
 R: 285/40R19.
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /
 TOYO / YOKO or
 Front: Rear:
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A. D.O.I. 02/08/18
 Survey held at: Tick Hai.
 Des. of Damages: Frt / Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.
 19/11/18 Confirmed L/S \$2,100/- @ 5 days with Adrian.
 (\$15,500/- Red - 88%)

RECEIVED 19 NOV 2018

Date/Time, File Pass to:

19/11/18

1)

Typist

Date/Time, File Return to:

2)

Report Format:

Lump Sum / I.B. / L/S 2,100/- L/S

☐ : Prelim. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee

Transportation

) S + RE \$

) Photos

) Other

TOTAL

TX15: 105

170+105

50

50

19

394



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS3/FCI18014032/Az4b	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-08-2018	
			Code : FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHB 2008K	Veh. Inspected	XD 4673B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005666MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	01/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/07/2018	Inspection Date		
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

MOTOR SURVEY ASSIGNMENT

Date	30-07-2018	Our Ref No. D18005759MFSH
Accident Date	24-07-2018	Claim Type. Third Party
Insured Vehicle	SHB3532G	Third Party Vehicle. SKP73A
Survey Location	1 Kaki Bukit Avenue 6 #01-54Autobay @ Kaki Bukit	
Contact Person.	MS CONNIE SEE	
Contact No.	68429089/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TICK HAI MOTOR & WELDING SERVICES	Attention. NIL
Cc : TP Solicitor	ARIDAS & ASSOCIATES	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 3 August 2018 11:02 AM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005759MFSH/1, SKP 73A

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKP 73A on 2/8/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler on behalf of Shirley

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 1 August 2018 5:52 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005759MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 1 August, 2018 3:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005759MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

Vehicle Number : SKP73A
 Vehicle Model : Porsche Panamera
 Chassis Number : WP0ZZZ97ZDL000069
 Year of Manufacture : 2012

TP 12" Cap
Chirley

S/N.	Item Description	Amount (\$)
1	Rear Door (RH) <i>Repair</i>	\$ 6,400.00
	Total :	\$ 6,400.00
	Less 10% :	\$ 640.00
	Amount :	\$ 5,760.00

+

S/N	Special Nett Item	Amount (\$)
1	Rear Tyre Rim (RH) <i>ht</i>	\$ 6,800.00
2	Car Sticker x 3 pcs (door, bumper, fender) <i>100</i>	\$ 1,800.00
	Amount :	\$ 8,600.00

1300
800
2100

Labour	Amount (\$)
4 - wheel alignment	\$ 160.00
To check door electrical wiring system	\$ 180.00
To transfer component from old door to new door	\$ 300.00
To straighten, repair, realign on front affected area and replace damaged parts	\$ 1,800.00
To spray paint on affected areas	\$ 800.00
Labour Total :	\$ 3,240.00
Total (Parts & Labour)	\$ 17,600.00

80
+
+
200
250
530

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 2630
4/5/2012
05 Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014033/Asbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3532G	Veh. Inspected	SKP 73A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005759MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	01/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE PANAMERA	c.c	3605	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WP0ZZZ97ZDL000069	Colour	BLACK	
Odometer	179264	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	285/40 R19	PIRELLI	6 mm	
L/H Front Tyre	285/40 R19	PIRELLI	6 mm	
R/H Rear Tyre	285/40 R19	PIRELLI	6 mm	
L/H Rear Tyre	285/40 R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2018	Inspection Date	02/08/2018	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 73A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR (RH)	TO REPAIR SEE LABOUR	6,400.00	-
	LESS 10% DISCOUNT		-640.00	-
			5,760.00	-
	SPECIAL NETT ITEMS			
1	REAR TYRE RIM (RH)(SN)	CUT	6,800.00	1,300.00
1	CAR STICKER X 3PCS (DOOR,BUMPER,FENDER)(SN)	NECESSARY	1,800.00	800.00
			8,600.00	2,100.00
	LABOUR			
	4 WHEEL ALIGNMENT.		160.00	80.00
	TO CHECK DOOR ELECTRICAL WIRING SYSTEM.	NOT NECESSARY	180.00	-
	TO TRANSFER COMPONENT FROM OLD DOOR TO NEW DOOR.	NOT NECESSARY	300.00	-
	TO STRAIGHTEN,REPAIR,REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR DOOR (RH).		1,800.00	200.00
	TO SPRAY PAINT ON AFFECTED AREAS.		800.00	250.00
			3,240.00	530.00
	GRAND TOTAL		17,600.00	2,630.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CS/FCI18014033/Asbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.