

75/113

Surveyor: Tam/Ph

REF:

ms161

C13/msh18014056/T1b9

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SHV 7676E

Policy No. A80453787Amy

Claims No. 56626Y


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh.No: SHC4084X Yr Regn: 2013 Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Moroon A/C: Insured / Std / NI / NA

Sp. Reading: 5/6/05 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: STDKN364805700633

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 215

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 20/7/18 @ 1645

Survey held at Sumit WL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 4084X - COLL / EQ114015275 / Kiny340
	SHV 7676E - NA / DALL 8017515 / HU
6/8/18	Sent GIA to MSH
	Confirm LIS \$1500 @ 3 days (Red: \$4535.68, 751.)

Date/Time, File Pass to?

☐ : Preli. Report

1) typid

☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / L.B. (\$) 1500

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GtA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/07/2018 12:49
Date Of Accident	27/07/2018 17:30
Exact Location Of Accident	PIE TOWARDS WOODLANDS (AFTER STEVEN RD EXIT)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4084X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	TEO GUAN CHIN
NRIC No	S1196573C
Date Of Birth	03/12/1956
Occupation	OUTDOOR
Date Of Driving Pass	14/12/1974
Driving Experience	43 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG PIE TOWARDS WOODLANDS (AFTER STEVEN RD EXIT) WITH TWO PASSENGERS (MALAY COUPLE) ON BOARD. FRONT VEHICLE STOPPED AND I FOLLOWED SUIT. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SGV7676E HAD COLLIDED ONTO THE REAR OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV7676E
Vehicle Make/Model/Colour	
Details Of Properties	NISSAN NOTE
Vehicle Category	PRIVATE CAR
Name of Driver	LIM ENG SZE JONATHAN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

27-7-18 Fri  
5.30pm

To-Ward Woodland

A-54c494x  
B-55v767AE

Stellen Po

247-18

□ □

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature *[Signature]*  
(If driver is not the policyholder)  
Date & Time: 27-7-18

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4084X  
 Ref. No : TAX/07/18/2137  
 Reg. Date : 30/10/2013  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : TEO GUAN CHIN  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 27/07/2018 05:30:00 PM  
 Accident Reported Date / Time : 28/07/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024097271  
 Special Instruction to ARC, if any :  
 DROVE IN/ SGV7676E  
 Prepared Date : 28/07/2018 12:29:13 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjiah 97445749  
 WP  
 03 days  
 sue/whant.com  
 30/7/18E 1645  
 Resurvey after repair.

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U80-5700633


Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	400.00
Total Spray Painting Charges	: 918.00	300.00
Total Material Charges	: 480.87	480.87
Other Charges	: 656.88	316.88
<b>TOTAL</b>	<b>: 2,900.75 6035.68</b>	<b>1,497.75</b>
<b>Lum Sum Total</b>	<b>: 2,900.00</b>	<b>1,500.00</b>
No. of Repair Days	: 5.00	3.00
Prepared / Adjusted By	:	TAUFIKH (LKK)
Arc / Surveyor Sign Off Date	: 30/07/2018 01:54:48 PM	30/07/2018 04:47:36 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 30/07/2018 01:51:33 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : GN-008-0071  
Quotation Date : 4/8  
Invoice Amount :

Invoice No :  
Invoice Date :  
Prepared Date :

$$\begin{array}{r} 601.09 \\ - 20\% \\ \hline 480.87 \\ 400 \\ + 616.88 \\ \hline 1497.75 \end{array}$$

45-1500



**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	400.00
<b>Total Labour</b>	<b>845.00</b>	<b>400.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY REAR SPOILER	180.00	0.00
TO RESPRAY REAR PANEL	180.00	100.00 8
<b>Total Spray Painting &amp; Panel Beating</b>	<b>918.00</b>	<b>300.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET) <i>Alvin</i>	296.88	296.88
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>656.88</b>	<b>316.88</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No <i>R</i>
52161-16010			BUMPER CLIPS	0	1.61	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
76088-47020		6505617	BUMPER LIP COVER RR/LH	0	72.20	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
76087-47020		6505618	BUMPER LIP COVER RR/RH	0	118.10	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
76891-47020		6505619	BUMPER LIP REAR	0	228.90	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	30.00	143.99	Replace	Replace <i>bt S</i>	No <i>✓</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	30.00	97.72	Replace	Replace <i>bt S</i>	No <i>✓</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	30.00	97.72	Replace	Replace <i>bt S</i>	No <i>✓</i>
			SENSOR REVERSE	0	180.00	0.00	0.00	Replace	Not given	No <i>X nn</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>nn</i>	No <i>✓</i>
52592-47021			BUMPER SEAL, RR LH	0	88.90	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
52591-47021			BUMPER SEAL, RR RH	0	65.70	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	0	94.80	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	0	94.80	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
76085-47910		6505620	SPOILER REAR	0	953.70	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
58307-47060		6505522	END PANEL	0	602.10	30.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
	COMMON	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace <i>nn S</i>	No <i>✓</i>
<b>TOTAL MATERIALS</b>								<b>601.09</b>	<b>601.09</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>480.87</b>	<b>480.87</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
89997-30070		ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace	No
<b>TOTAL SUPPLEMENTARY MATERIALS</b>						<b>141.66</b>			

**Janice Lee (LKKAUTO)**

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>  
**Sent:** Sunday, August 05, 2018 8:50 AM  
**To:** Taufikh (LKKAUTO)  
**Cc:** SUR; CS A Team; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); 'Leong Chee kwong'  
**Subject:** SHC4084X  
**Attachments:** img-804113944-0001.pdf

Hi Taufikh,

Attached herewith the repair estimate of SHC 4084X having Case No: TAX/07/18/2137.

There is no change to the approved amount of \$1,500 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
Sent: Saturday, 4 August 2018 11:40 AM  
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
Subject: Scan Data from FX-D421D6


1.8.18 / 09:00  
 1.8.18 / 13:50  
 ADV  
 2.8.18 / 8:00

# SMRT Accident Vehicle Repair Estimates

31.7.18 / 8:00

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4084X  
 Ref. No : TAX/07/18/2137  
 Reg. Date : 30/10/2013  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : TEO GUAN CHIN  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 27/07/2018 05:30:00 PM  
 Accident Reported Date / Time : 28/07/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : Taufik  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024097271  
 Special Instruction to ARC, if any :




DROVE IN/ SGV7676E - MSIG - LKK  
 Before paint photo and after paint photo, FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR  
 TAUFIKH, HP 9749 5749/ EMAIL: sur@lkkauto.com  
 lumpsum repair  
 Prepared Date : 28/07/2018 12:29:13 PM

1/8/18 18:30 Reject RR & RR R Bumper Lip Adjust  
 2.8.18 8:40 pass

Recording Camera ☐ ☒  
 Radio Antenna ☐ ☒  
 1<sup>st</sup> witness 12 Date 31-7-18  
 2<sup>nd</sup> witness \_\_\_\_\_ Date \_\_\_\_\_

Vehicle to Wage Date to:	31/7	Towing:	Ref
Time to:	12:00	Driver:	
Wage Job No:	07/04486		
Vehicle sent to:	SMRT Auto Inc.	Towing:	
Time to:		Driver:	

E  F  
 KM 1/6105

Attached  
 Supplementary

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U80-5700633

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	918.00	0.00
Total Material Charges :	2,236.85	2,236.85
Other Charges :	656.88	0.00
<b>TOTAL :</b>	<b>4,656.73</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>4,650.00</b>	<b>0.00</b>
No. of Repair Days :	5.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	30/07/2018 01:54:48 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 30/07/2018 01:51:33 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	0.00
<b>Total Labour</b>	<b>845.00</b>	<b>0.00</b> <i>200</i>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 <i>200</i>
TO RESPRAY BUMPER BEAM	180.00	0.00 <i>x</i>
TO RESPRAY REAR SPOILER	180.00	0.00 <i>x</i>
TO RESPRAY REAR PANEL	180.00	0.00 <i>x 100</i>
<b>Total Spray Painting &amp; Panel Beating</b>	<b>918.00</b>	<b>0.00</b> <i>300</i>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 <i>20</i>
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 <i>✓</i>
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 <i>x</i>
TO REPLACE SUNDRY PARTS	100.00	0.00 <i>x</i>
TO WASH AND VACUUM	60.00	0.00 <i>x</i>
<b>Total Other Costs</b>	<b>656.88</b>	<b>0.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>Ry</i>
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No <i>X</i>
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No <i>X</i>
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No <i>X</i>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No <i>X</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No <i>X</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No <i>X</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No <i>X</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>X</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>mu</i>
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace	No <i>X</i>
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace	No <i>X</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No <i>X</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No <i>X</i>
76085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace	No <i>X</i>
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No <i>X</i>
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No <i>X</i>
TOTAL MATERIALS								2,796.10	2,796.06	
TOTAL MATERIALS(Discounted)								2,236.85	2,236.85	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jul 2018		21 Aug 2018 08:54 <a href="#">Edit Adj Rpt</a>	<b>S\$1,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by Insurer]</a></span>									
Insured: <b>LIM JIN WAN</b> , ID: S1518364									
Main Claimant: <b>SMRT TAXIS PTE LTD</b> , Co. Reg. No.: 198905369X									
Vehicle Reg. No.: <b>SHC4084X</b>		Date of Loss: 27/07/2018 17:00 - :59 [56 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 566264</b>		Policy/Cover Note No.: A80453787QMY (Comprehensive) Coverage: 22/02/2018 - 21/02/2019							
Vehicle Reg. No. (Insured): <b>SGV7676E</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>SMRT Automotive Services Pte Ltd (Woodlands)</b> 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Lionel Tan Tian Pei</b> - 6643 1307]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Imm.Advice due 22/08/2018]									
Driver/Custodian (Insured): LIM ENG SZE, JONATHAN (LIN YINGSHI) (), NRIC: 59101334G, Tel: +6590997020									
Adj Asg. Remarks: Direct Survey done									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SHC4084X (566264)  
[SGV7676E]  
TP  
SMRT TAXIS PTE LTD  
Jul 27 2018 5:00PM  
[LIM JIN WAN]  
SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	14/08/18 16:39	<b>Accident Statement</b> From: SC - Reg. No: SGV7676E, Claimant: LIM JIN WAN		Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
2	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
3	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
4	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
5	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
6	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
7	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
8	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
9	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
10	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
11	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
12	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
13	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
14	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
15	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
16	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
17	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
18	07/09/18 12:56	General View		Load JPG	<input checked="" type="checkbox"/>
19	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	07/09/18 12:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	07/09/18 12:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	07/09/18 12:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	07/09/18 12:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	07/09/18 12:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	07/09/18 12:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	07/09/18 12:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	07/09/18 12:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/08/18 16:39	<b>SHC4084X E-FILE REPORT</b> <small>From: SC - Reg. No: SGV7676E, Claimant: LIM JIN WAN</small>	 Load PDF	
2	14/08/18 16:41	<b>SHC 4084X ESTIMATE</b>	 Load PDF	
3	14/08/18 16:42	<b>tp direct survey</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18014056/T1RBQ2

Date: 10/09/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80453787QMY

Claimant Vehicle No: SHC4084X

Insured Vehicle No: SGV7676E

Date of Loss: 27/07/2018

Nature of Claim: TP

Claim No: 566264

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4084X

Make & Model: TOYOTA PRIUS, 1.8 (A)

Engine No: 2ZR6089104

Reg. Date: 30/10/2013 (Man. Year: 2013)

Chassis No: JTDKN36U805700633

Colour: Maroon

Odometer: 516105 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,055.59	897.97	3,157.62	77.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,103.00	720.00	1,383.00	65.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,158.59</b>	<b>1,617.97</b>	<b>4,540.62</b>	<b>73.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,158.59</b>	<b>1,500.00</b>	<b>4,658.59</b>	<b>75.64</b>

### INSPECTION

Date of Assignment: 21/08/2018

Date Inspected: 30/07/2018 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4084X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REINFORCEMENT REAR (DISC 30%)	Bent	205.70 F	*143.99 F
2	1		*ARM SUB-ASSY ,RR BUMPER LH (DISC 30%)	Bent	139.60 F	*97.72 F
3	1		*ARM SUB-ASSY ,RR BUMPER RH (DISC 30%)	Bent	139.60 F	*97.72 F
4	1		*ANTENNA ELECTRICAL LOWER REAR (DISC 10%)	Cracked	157.40 F	*141.66 F
5	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F
6	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
7	1		*BUMPER REAR	Repair	458.60 F	*- F
8	1		*BUMPER CLIPS	Not Necessary	1.61 F	*- F
9	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
10	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
11	1		*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
12	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
13	1		*BUMPER SEAL ,RR LH	Not Necessary	88.90 F	*- F
14	1		*BUMPER SEAL ,RR RH	Not Necessary	65.70 F	*- F
15	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F
16	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
17	1		*SPOILER REAR	Not Necessary	953.70 F	*- F
18	1		*END PANEL	Not Necessary	602.10 F	*- F
19	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>4,055.59</b>	<b>897.97</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	845.00	400.00
2	SPRAY PAINT	New	918.00	300.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	100.00	0.00
5	TO WASH AND VACUUM	New	60.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (S\$)			2,103.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >