

15/9/2018

INS. CASE OWNER:

L7i

CC4 / EQ11801

4088

U 463

LKK:
IDAC:

Surveyor:

Marcus

DOI:

ASSIGNMENT

6/8/18

Date / Time:

18/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

EX 9613L

Name of Insured:

LEE GIR TANN

Insured Tel No.:

HP: 96376271

Excess Sec II :SS

D.O.A: 11/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

18/18/18/VP15/020798

Policy No.:

717VPO 5713424

Make / Model:

ALFA Romeo

Place of Accident:

NEWLOOLW ST

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKM 3823Z

INSRS:
WSP:
Tel:
Liability:
RMKS:

progressive

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

6/8/18

TH

31/1/19

8/1/19

SKM 3823Z - 4

EX 9613L - 7

TP converted to OD
pls close file

File pos to show for future up.

STAGE

DATE/ PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(S

x

days)

Loss of Income (LOI):

S\$

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
8/1/19

(M)

350-W

(08/11/13) wef

ASS. REC. BY:

REF: LPC

14088/14083

ASSIGNMENT

From:

Date:

6/8/18

Estimated Cost:

OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

SKM 38232

at Workshop m/s

Progressive Automotive

of 31K3022A Ubi Rd 1 #01-45/46

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

11 am @ owner waiting

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value:

1486.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Cup

L7A103720

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKM 38232

Vr Regn:

S 13

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

CA /

Make:

BMW

X6

c.c.

2979

Colour:

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

042809

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAFG22090L597322

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

275/40R20

R:

315/35R20

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

3/7/18

D.O.I.

6/8/18

Survey held at

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

N/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4 yrs 9 mths Dep 2016 \$44 net

Submit

PIP \$ 529.78 (Red \$ 11558.12/69%) - accident check
Rems \$ 5434.71.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18014088/ub3

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 02-08-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EX 9613L	Veh. Inspected	SKM 3823Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/07/2018	Inspection Date	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18014088/Uub3

Date: 13.08.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKM3823Z


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.08.2018 at the premises of M/s Progressive Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	16,787.95
Revised Estimate Amount	: S\$	3,677.24
"Check" Items Amount	: S\$	10,460.29
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

Not Authorised
Wale
6/8/18
Take photo before
20.77.
4 day.

M/S : SIM KWANG OO
BLK 114 KITCHENER LINK #08-31
SINGAPORE 207223

Estimate No: **EST1503918**
Date: 31 Jul 2018
Policy No: GA148950
Veh Reg No: **SKM3823Z**
Make/Model: B.M.W. X6 XDRIVE35i
AWD SR DSC NAV HUD
LED

ATTN: LONPAC

Your Ref No: TP 0718-5171
Claim Type: Third Party
Accident Date: 31/07/2018
TP Veh Reg No: EX 9613 L

Chassis No: WBAFG22090L597322
Engine No: 03228414N55B30A
Reg. Date: 09/05/2013

Estimate Repair Cost to Vehicle No :SKM3823Z

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 FRONT BUMPER <i>Dis</i>	1,218.600	1 PC	1,218.60	<i>✓</i>
2 FRONT BUMPER LOWER <i>Dis</i>	234.6000	1 PC	234.60	<i>✓</i>
3 FRONT BUMPER CENTRE LOWER LIP, NO 3 <i>17X</i>	176.7500	1 PCS	176.75	<i>X</i>
4 FRONT BUMPER RIVET CLIPS <i>rec</i>	5.0000	10 PCS	50.00	<i>✓</i>
5 FRONT BUMPER SIDE HOLDER - LH <i>sal</i>	301.1000	1 PC	301.10	<i>✓</i>
6 FRONT BUMPER SIDE HOLDER - RH <i>17</i>	301.1000	1 PC	301.10	<i>X</i>
7 FRONT BUMPER SENSOR <i>shut off</i>	236.8500	6 PC	1,421.10	<i>30C</i>
8 FRONT BUMPER SENSOR WIRE <i>17</i>	162.0500	1 PCS	162.05	<i>X</i>
9 FRONT BUMPER FOG LAMP - LH <i>17</i>	258.1500	1 PC	258.15	<i>X</i>
10 FRONT BUMPER FOG LAMP COVER, SILVER - LH <i>17</i>	50.3000	1 PCS	50.30	<i>X</i>
11 FRONT BUMPER FOG LAMP COVER, BLACK - LH <i>17</i>	84.2800	1 PCS	84.28	<i>X</i>
12 FRONT BUMPER FOG LAMP - RH <i>17</i>	258.1500	1 PC	258.15	<i>X</i>
13 FRONT BUMPER FOG LAMP COVER, SILVER - RH <i>17</i>	50.3000	1 PCS	50.30	<i>X</i>
14 FRONT BUMPER FOG LAMP COVER, BLACK - RH <i>17</i>	84.2500	1 PCS	84.25	<i>X</i>
15 FRONT BUMPER REINFORCEMENT <i>17</i>	708.1500	1 PC	708.15	<i>X</i>
16 LHF FENDER <i>no/cm</i>	1,397.400	1 PCS	1,397.40	<i>✓</i>
17 LHF FENDER COWLING, FRONT <i>to 17</i>	179.2500	1 PCS	179.25	<i>✓</i>
18 LH FENDEWR COWLING, REAR <i>to 17</i>	179.2500	1 PCS	179.25	<i>✓</i>
19 LHF FENDER COWLING CLIPS <i>rec</i>	5.0000	10 PCS	50.00	<i>✓</i>
20 LHF FENDER OUTER WHEEL ARCH GARNISH <i>bow/ny</i>	202.4500	1 PCS	202.45	<i>✓</i>
21 LHF FENDER SIGNAL LAMP <i>320</i>	45.0000	1 PCS	45.00	<i>✓</i>
22 LHF FENDER LAMP <i>17</i>	37.9500	1 PCS	37.95	<i>X</i>
23 LHF FENDER TOP RUBBER <i>17</i>	65.6500	1 PCS	65.65	<i>X</i>
24 AIRCON FAN COWLING <i>17</i>	300.5000	1 PCS	300.50	<i>X</i>
25 LH HEADLAMP	5,433.550	1 PCS	5,433.55	<i>?</i>
26 LH HEADLAMP LOWER RETAINER	254.0500	1 PCS	254.05	<i>?</i>
27 LH HEADLAMP SIDE RETAINER	33.1500	1 PCS	33.15	<i>?</i>
28 LHF TYRE RIM <i>n</i>	1,654.200	1 PCS	1,654.20	<i>X</i>
29 LHF TYRE RIM BMW STICKER, SMALL <i>17</i>	24.3000	1 PCS	24.30	<i>X</i>
30 BONNET BMW LOGO <i>17</i>	69.5000	1 PCS	69.50	<i>X</i>
31 LHF DOOR XDRIVE 321 WORDING <i>17</i>	93.8500	1 PCS	93.85	<i>X</i>
32 FOG LAMP COVER LH <i>17</i>	67.3500	1 PCS	67.35	<i>X</i>
33 FOG LAMP COVER RH <i>17</i>	67.3500	1 PCS	67.35	<i>X</i>
			15,513.63	
Less 5%			775.68	14,737.95

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : SIM KWANG OO
BLK 114 KITCHENER LINK #08-31
SINGAPORE 207223

ATTN: LONPAC

Your Ref No: TP 0718-5171
Claim Type: Third Party
Accident Date: 31/07/2018
TP Veh Reg No: EX 9613 L

Estimate No: EST1503918
Date: 31 Jul 2018
Policy No: GA148950
Veh Reg No: SKM3823Z
Make/Model: B.M.W. X6 XDRIVE35I
AWD SR DSC NAV HUD
LED
Chassis No: WBAFG22090L597322
Engine No: 03228414N55B30A
Reg. Date: 09/05/2013

Estimate Repair Cost to Vehicle No :SKM3823Z

Description	U/Price	Quantity	Price SS	Amount SS
Labour				
34 TO KNOCK OUT DENTS, REMOVE, REPLACE LHF FRONT FENDER & REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	600
35 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,000.000	1 JOB	1,000.00	600
36 TO CHECK WIRING	20.0000	1 JOB	20.00	✓
37 TO 4 WHEEL ALIGNMENT	60.0000	1 JOB	60.00	✓
38 TO RESET CHECK LIGHT	60.0000	1 JOB	60.00	✓
39 TO REMOVE, REPLACE LHF TYRE RIM & BALANCING	50.0000	1 JOB	50.00	✓
40 TO TUFF-KOTE	60.0000	1 JOB	60.00	✓
			2,050.00	2,050.00
Total				SS 16,787.95
Add GST @ 7%				1,175.16
Total Amount Payable				SS 17,963.11

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND NINE HUNDRED SIXTY THREE AND CENTS ELEVEN ONLY

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 2 August 2018 9:07 AM
To: assignments@lkkauto.com; 'Nivitha (LKK Auto)'
Cc: MT_Claim_SG
Subject: Our Ref: 18/18/18/VP05/020798
Attachments: 02082018082711.pdf

10:06am @ 2/8/18
person @ 500
vehicle not in

Hi Nivitha

Please refer to the attached and arrange survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

18/18/18/VP05/0 20798

By fax.

62962706.
62507388


THE MOTOR CLAIM DEPARTMENT

Lompac Insurance BHD.

300 Beach Rd.

#17-04/07: The Lincourse. (199.555.)

Date : 11/8/18.

Progressive Automotive Pte Ltd
Blk 3022A Ubi Road 1
#01-45/46
Singapore 408716

Dear Sir / Madam

Accident involving : SKM 38232 / EX 9613L

On : 31/7/18.

Along / At : Bencoolen Street.

I am the registered owner of motor vehicle no. SKM38232 which was involved in the above accident.As a result of your insured vehicle no. EX9613L negligence thereby causing the above-said accident.Please appoint your assessor to inspect my vehicle at the above-mentioned workshop as currently vehicle is IN NOT IN

Please find enclosed herewith the repairer's estimate for your reference.

Thank you

Signature of Owner

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST 201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
S068811

ATTN: Motor Claim Department

Your Ref No: OD 0818-6621
Claim Type: Own Damage
Accident Date: 31/07/2018

Claim No: EST1503918
Final No: PA1507409
Date: 20 Sep 2018
Policy No: GA148950
Veh Reg No: SKM3823Z
Make/Model: B.M.W. X6 XDRIIVE35I
AWD SR DSC NAV HUD
LED
Chassis No: WBAFG22090L597322
Engine No: 03228414N55B30A
Reg. Date: 09/05/2013

TAX INVOICE SKM3823Z

Description	U/Price	Quantity	Cost <u>SS</u>	Amount <u>SS</u>
Spare Parts				
1 EXPANSION TANK	185.00	1	185.00	
2 FRONT BUMPER COVER	780.00	1	780.00	
3 FRT BUMPER MNTG KIT	20.00	1	20.00	
4 L/F BUMPER INSERT	55.00	1	55.00	
5 L/F OUT U-SONIC SENS	165.00	1	165.00	
6 L/F SIDE REFLECTOR	30.00	1	30.00	
7 L/F WHEELARCH TRIM	150.00	1	150.00	
8 L/F W-HOUSE CVR FRT	130.00	1	130.00	
9 L/F WING	800.00	1	800.00	
10 L/F WING MNTG KIT	15.00	1	15.00	
11 L/LED HEADLAMP	4,200.00	1	4,200.00	
12 L/LOWER SUPPORT	275.00	1	275.00	
13 LOWER FRONT BUMPER	175.00	1	175.00	
			6,980.00	
	Add 10%		698.00	7,678.00
Labour				
14 Total Paint Labour	162.00	1	162.00	
15 Total Paint Materials	104.86	1	104.86	
16 Total Panel/Mechanical Labour	240.00	1	240.00	
				506.86

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
S068811

ATTN: Motor Claim Department

Your Ref No: OD 0818-6621
Claim Type: Own Damage
Accident Date: 31/07/2018

Claim No: EST1503918
Final No: PA1507409
Date: 20 Sep 2018
Policy No: GA148950
Veh Reg No: SKM3823Z
Make/Model: B.M.W. X6 XDRIVE35I
AWD SR DSC NAV HUD
LED
Chassis No: WBAFG22090L597322
Engine No: 03228414N55B30A
Reg. Date: 09/05/2013

TAX INVOICE SKM3823Z

Amount Before Excess	S\$ 8,184.86
Less Excess	S\$ 500.00
Amount Before GST	S\$ 7,684.86
Add GST @ 7%	537.94
Total Amount payable	S\$ 8,222.80

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND TWO HUNDRED TWENTY TWO AND CENTS EIGHTY ONLY

For Progressive Car Care Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE


Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-45/46
Singapore 408716
Tel: 6741 5336 Fax: 6741 7208
Email: claims@procarcare.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18014088/Upb3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 11-01-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	EX 9613L	Veh. Inspected	SKM 3823Z	
Policy No.	Z17VP05013424	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020798	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X6 (A)	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBAFG22090L597322	Colour	BROWN	
Odometer	042809	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/40R20	BRIDGESTONE	6 mm	
L/H Front Tyre	275/40R20	BRIDGESTONE	6 mm	
R/H Rear Tyre	315/35R20	BRIDGESTONE	6 mm	
L/H Rear Tyre	315/35R20	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/07/2018	Inspection Date	06/08/2018	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 3823Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DISTORTED	1,218.60	1,218.60
1	FRONT BUMPER LOWER	DISTORTED	234.60	234.60
1	FRONT BUMPER CENTRE LOWER LIP, NO 3	NOT NECESSARY	176.75	-
10	FRONT BUMPER RIVET CLIPS @ \$5.00	NECESSARY	50.00	50.00
1	FRONT BUMPER SIDE HOLDER - LH	BENT	301.10	301.10
1	FRONT BUMPER SIDE HOLDER - RH	NOT NECESSARY	301.10	-
6	FRONT BUMPER SENSOR @ \$236.85	N/S SHORTED 1PC ONLY	1,421.10	236.85
1	FRONT BUMPER SENSOR WIRE	NOT NECESSARY	162.05	-
1	FRONT BUMPER FOG LAMP - LH	NOT NECESSARY	258.15	-
1	FRONT BUMPER FOG LAMP COVER, SILVER - LH	NOT NECESSARY	50.30	-
1	FRONT BUMPER FOG LAMP COVER BLACK - LH	NOT NECESSARY	84.28	-
1	FRONT BUMPER FOG LAMP - RH	NOT NECESSARY	258.15	-
1	FRONT BUMPER FOG LAMP COVER, SILVER - RH	NOT NECESSARY	50.30	-
1	FRONT BUMPER FOG LAMP COVER, BLACK - RH	NOT NECESSARY	84.25	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	708.15	-
1	LHF FENDER	DENTED / CRACKED	1,397.40	1,397.40
1	LHF FENDER COWLING, FRONT	TORN	179.25	179.25
1	LH FENDER COWLING, REAR	TORN	179.25	179.25
10	LHF FENDER COLWLING CLIPS @ \$5.00	NECESSARY	50.00	50.00
1	LHF FENDER OUTER WHEEL ARCH GARNISH	BROKEN / MISSING	202.45	202.45
1	LHF FENDER SIGNAL LAMP	BROKEN	45.00	45.00
1	LHF FENDER LAMP	NOT NECESSARY	37.95	-
1	LHF FENDER TOP RUBBER	NOT NECESSARY	65.65	-
1	AIRCON FAN COWLING	NOT NECESSARY	300.50	-
1	LH HEADLAMP	* CHECK	5,433.55	-
1	LH HEADLAMP LOWER RETAINER	* CHECK	254.05	-
1	LH HEADLAMP SIDE RETAINER	* CHECK	33.15	-
1	LHF TYRE RIM	TO REPAIR SEE LABOUR	1,654.20	-
1	LHF TYRE RIM BMW STICKER, SMALL	NOT NECESSARY	24.30	-

Report Ref No. CC4/LPC18014088/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET BMW LOGO	NOT NECESSARY	69.50	-
1	LHF DOOR XDRIVE 321 WORDING	NOT NECESSARY	93.85	-
1	FOGLAMP COVER LH	NOT NECESSARY	67.35	-
1	FOGLAMP COVER RH	NOT NECESSARY	67.35	-
	LESS 5% DISCOUNT		-775.68	-204.72
			14,737.95	3,889.78
	LABOUR			
	TO KNOCK OUT DENTS, REMOVE, REPLACE LHF FRONT FENDER & REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF LHF TYRE RIM.		800.00	600.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		1,000.00	600.00
	TO CHECK WIRING.		20.00	20.00
	TO 4 WHEEL ALIGNMENT.		60.00	60.00
	TO RESET CHECK LIGHT.		60.00	60.00
	TO REMOVE, REPLACE LHF TYRE RIM & BALANCING.	NOT NECESSARY	50.00	-
	TO TUFF-KOTE.	NOT NECESSARY	60.00	-
			2,050.00	1,340.00
GRAND TOTAL			16,787.95	5,229.78
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$5,434.71 NETT)				5,229.78

Report Ref No. CC4/LPC18014088/Upb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.