

22/03/2003

ASS. REC. BY:

REF:

CS/CT18014096/Krdsⁿ²

Special Instruction:

Surveyor:

Munir

Kenneth

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 02/08/18 @ 2:29pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 6068 X

Insured:

YN1776T

at Workshop m/s

Ching Motor Repair

Tel:

64534085 / 9100 4390

of

31k 176, 8m Ming Drive #02-08

Policy No:

DMCVSN 3022/51800

Claim No:

SNM18803775C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/07/2018

03/08/2018 @ Morning

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

1up

Date/Time:

3:20pm 2/8/18

Person Contacted:

Sandy

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

GBD 6068 X-X

YN1776T-X

28/11/18 @ 11:09am / 1 Lp @ 3900 enat confirmed by email (Red 8258.60, 6775)

(08/11/13) wef

REF: CFI

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 03/08/2018

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No: GBD 6068X

at Workshop m/s Ching Motor Repair

of BIK 176, Sir Ming Drive #02-08

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Susan

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBD 6068X Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS NV200 c.c. 1461

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 63267 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSK 48AM 20 Z 00 91181

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14

R: _____

BS ☒ BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm

L/Bal. 2 mm


D.O.A. 30/7/18

Survey held at ☒

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

6/8 PM 1455 to 1719

RECEIVED 29 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 7

1)

☐

Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 24/11 - typist

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format:

merimen

Lump Sum / I.B.I. (\$

3900/2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18014096/Kvd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 02-08-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 1776T	Veh. Inspected	GBD 6068X	
Policy No.	DMCVSN3022151800	Coverage (\$)	0.00	
Claim No.	SNM18D03775C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/07/2018	Inspection Date	03/08/2018	
Survey held at	CHING MOTOR REPAIR SHOP BLK 176 SIN MING DRIVE #02-08 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2018		02 Aug 2018 14:29 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	HE ZHOU FENG ENGINEERING		
Vehicle Reg. No.:	GBD6068X	Date of Loss:	30/07/2018 00:00 - :59
Claim Type:	TP / SNM18D03775C02	Policy/Cover Note No.:	DMCVSN3022151800
Vehicle Reg. No. (Insured):	YN1776T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ching Motor Repair Shop (HQ) BLK 176 SIN MING DRIVE, #02-08 SIN MING AUTOCARE, 575721 Sin Ming - Tel: 64534085		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/08/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Shawn Chua <shawnychua@tanchong.com>
Sent: Thursday, 11 October 2018 2:54 PM
To: Veron Chen (LKKAUTO)
Subject: RE: CHECK PARTS PRICES

Good afternoon & apologies for my late reply.

Rear left fender, 78101-JX00C, \$1709.70

Regards,

Shawn Chua
Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515
HP: +65 96450023
Fax: +65 64795019



From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 11 October, 2018 2:17 PM
To: Shawn Chua <shawnychua@tanchong.com>
Subject: CHECK PARTS PRICES

Dear Shawn,

Kindly assist to check parts prices

MODEL-NISSAN NV 200
YEAR -2014, 1461 cc
CHASSIS : VSKYBAM20Z0091161

- 1) Left side rear mudguard panel (Parts no : 781016500A)

Many thanks.

Best Regards,

Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2018 13:56
Date Of Accident	30/07/2018 09:50
Exact Location Of Accident	32 SUNGEI KADUT WAY COMPOUND
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD6068X
Insured/Policyholder	
Name Of Registered Owner	HE ZHOU FENG ENGINEERING
Co Reg No	53211756E
Email Address	YEOHC42@YAHOO.COM
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV200-1.5 D L ABS AIRBAG 2WD 6DR (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1445281703
Cover Note Number	

Driver

Name of Driver	GUO YUANZHUO
NRIC No	S8264534I
Date Of Birth	21/11/1982
Occupation	OUTDOOR
Date Of Driving Pass	18/02/2010
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83999991
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	734 JURONG WEST ST73 #08-12
Postcode	640734
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 30/07/2018 AT AROUND 0950HRS, I DRIVE MY VEHICLE TO 32 SUNGEI KADUT WAY AND PARKED MY VEHICLE IN THE COMPOUND AND WENT FOR MEETING. I RECEIVED A CALL FROM VEHICLE B DRIVER BUT I DID NOT PICK UP AS WHILE I STILL IN THE MEETING. THEN I RECEIVED A MESSAGE FROM VEHICLE B DRIVER AND SAY HIS VEHICLE HAD COLLIDED ONTO MY VEHICLE WHICH PARKED ON THAT TIME. BEFORE I WENT DOWN TO SEE MY VEHICLE, I ALSO RECEIVED A CALL FROM THE SECURITY GUARD THAT MY VEHICLE WAS BEING COLLIDED BY VEHICLE B. I REACHED MY VEHICLE & NOTICED THAT MY VEHICLE HAD COLLIDED ON MY REAR LEFT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM1776T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ALEX LEE
NRIC/Passport Number	
Contact Number	90669150
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Ching Motor Repair Shop.

Blk 176 #02-08 Sin Ming Drive Sin Ming AutoCare

Singapore 575721 HP 91004390/91254449 Fax 6484 1482

Email : chingmotorrepair@gmail.com

*Not Withheld
1/2m @ 3900/
Resurvey After Paint*

M/s China Taiping Insurance (S) Pte Ltd DATE 02.08.2018
3 Anson Road #16-00 Spring leaf Tower CAR NO GBD 6068 X
Singapore 079909 MAKE Nissan NV200 Van

7 days

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.

YOUR INSURED : YN 1776 T

Pc	Pcs	Chassis No : VSKYBAM20Z0091161	UNIT PRICE	AMOUNT
		<i>781016500A 1791.60 1709.70</i>		
1pc	Left side rear mudguard panel	Nett	<i>R</i>	\$2,997.20 ✓
1pc	Left side rear mudguard panel railing	Nett	<i>Sm</i>	\$264.00 X
1pc	Left side rear mudguard panel railing bracket	Nett	<i>R</i>	\$181.20 X
1pc	Left side rear mudguard panel inner cowling	Nett	<i>Sm</i>	\$99.10 X
8pcs	Left side rear mudguard panel cowling clips	Nett	\$2.60 <i>un</i>	\$20.80 X
1pc	Left side rear mudguard panel inner board	Nett	<i>Sm</i>	\$202.50 X
1pc	Left side tail gate	Nett	<i>R R</i>	\$1,470.40 X
2pcs	Left side tail gate top & bottom hinge	Nett	\$125.50 <i>R</i>	\$151.00 X
1pc	Left side tail gate "70" sticker	Nett	<i>un</i>	\$5.00 ✓
1pc	Left side tail gate "NV200" emblem	Nett	<i>un</i>	\$135.80 ✓
1pc	Left side tail gate "Nissan" logo	Nett	<i>un</i>	\$66.40 ✓
1pc	Left side tail lamp	Nett	<i>R</i>	\$258.70 ✓
1pc	Left side sliding door	Nett	<i>R</i>	\$1,281.70 ✓
2pc	Left side sliding door top & bottom roller	Nett	\$127.10 <i>R</i>	\$254.20 X
1pc	Left side sliding door outer handle	Nett	<i>Sm</i>	\$135.80 X
1pc	Left side sliding door inner board	Nett	<i>Sm</i>	\$860.00 X
1pc	Rear bumper	Nett	<i>Sm</i>	\$624.80 X

108

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total

Page 1 of 2

Ching Motor Repair Shop.

Acknowledged by Repairer
Signature:
Date:

Ching Motor Repair Shop

Blk 176 #02-08 Sin Ming Drive Sin Ming AutoCare
Singapore 575721 HP 91004390/91254449 Fax 6484 1482
Email : chingmotorrepair@gmail.com

M/s China Taiping Insurance (S) Pte Ltd DATE 02.08.2018
3 Anson Road #16-00 Spring leaf Tower CAR NO GBD 6068 X
Singapore 079909 MAKE Nissan NV200 Van

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : YN 1776 T

Pc	Pcs	Chassis No. : VSKYBAM20Z0091161	UNIT PRICE	AMOUNT
		Continue from page one.		\$9,008.60
		Checking front head lamp wiring system including checking for water leakage.		\$80.00 201
		Spraying anti-rust coating onto the new and affected panels.		\$150.00 601
		Straightening, repairing, realigning onto the affected portion, cutting left side rear mudguard renew left side center sliding door, dismantle and replace all the damage parts.		9001 \$1,500.00 601
		Spraying painting onto left side rear mudguard, left side center sliding door, left side front door and left side tial gate.		601 \$1,200.00
		To apply silicon onto left side center sliding door top window.		4001 \$80.00
		Dismantle & refix left side center sliding door glass.		601 \$140.00
			Total	\$12,158.60

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118014096/KVD3N2

Date: 05/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3022151800
Claimant Vehicle No :	GBD6068X	Insured Vehicle No :	YN1776T
Date of Loss:	30/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03775C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD6068X		
Make & Model:	NISSAN NV200, 1.5 D L ABS AIRBAG 2WD 6DR (M)	Engine No:	K9KC400D054070
Reg. Date:	29/12/2014 (Man. Year: 2014)	Chassis No:	VSKYBAM20Z0091161
Colour:	Metallic Grey	Odometer:	63267 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Dunlop 2 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Dunlop 2 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,008.60	3,111.57	5,897.03	65.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	1,740.00	1,410.00	44.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,158.60	4,851.57	7,307.03	60.10
Approved Total (Overridden) (S\$)		3,900.00		
Nett Amount (S\$)	12,158.60	3,900.00	8,258.60	67.92

INSPECTION

Date of Assignment:	02/08/2018	
Date Inspected:	03/08/2018 Inspected At:	Ching Motor Repair Shop (HQ) BLK 176 SIN MING DRIVE, #02-08 SIN MING AUTOCARE Singapore 575721

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Dec 2018)	
Parts:	N/A	NISSAN NV200 1.5 D L ABS AIRBAG 2WD 6DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD6068X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT SIDE REAR MUDGUARD PANEL	Bent	2,997.20 F	*1,709.70 FN
2	1		*LEFT SIDE REAR MUDGUARD PANEL RAILING	Serviceable	264.00 F	*- FN
3	1		*LEFT SIDE REAR MUDGUARD PANEL RAILING BRACKET	Repair	181.20 F	*- FN
4	1		*LEFT SIDE REAR MUDGUARD PANEL INNER COWLING	Serviceable	99.10 F	*- FN
5	8		*LEFT SIDE REAR MUDGUARD PANEL COWLING CLIPS	Not Necessary	20.80 F	*- FN
6	1		*LEFT SIDE REAR MUDGUARD PANEL INNER BOARD	Serviceable	202.50 F	*- FN
7	1		*LEFT SIDE TAIL GATE	Repair	1,470.40 F	*- FN
8	2		*LEFT SIDE TAIL GATE TOP & BOTTOM HINGE	Repair	151.00 F	*- FN
9	1		*LEFT SIDE TAIL GATE 70 STICKER	Necessary	5.00 F	*5.00 FN
10	1		*LEFT SIDE TAIL GATE NV200 EMBLEM	Necessary	135.80 F	*135.80 FN
11	1		*LEFT SIDE TAIL GATE NISSAN LOGO	Necessary	66.40 F	*66.40 FN
12	1		*LEFT SIDE TAIL LAMP	Broken	258.70 F	*258.70 FN
13	1		*LEFT SIDE SLIDING DOOR	Bent	1,281.70 F	*1,281.70 FN
14	2		*LEFT SIDE SLIDING DOOR TOP & BOTTOM ROLLER	Repair	254.20 F	*- FN
15	1		*LEFT SIDE SLIDING DOOR OUTER HANDLE	Serviceable	135.80 F	*- FN
16	1		*LEFT SIDE SLIDING DOOR INNER BOARD	Serviceable	860.00 F	*- FN
17	1		*REAR BUMPER	Serviceable	624.80 F	*- FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	9,008.60	3,457.30
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	345.73
Total Parts (\$\$)	9,008.60	3,111.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECKING LAMP WIRING SYSTEM INCLUDING CHECKING FOR WATER LEAKAGE	New	80.00	20.00
2	SPRAYING ANTI-RUST COATING ONTO THE NEW AND AFFECTED PANELS	New	150.00	60.00
3	STRAIGHTENING,REPAIRING,REALIGNING ONTO THE AFFECTED PORTION,CUTTING LEFT SIDE REAR MUDGUARD RENEW LEFT SIDE CENTER SLIDING DOOR,DISMANTLE AND REPLACE ALL THE DAMAGE PARTS	New	1,500.00	900.00
4	SPRAYING PAINTING ONTO LEFT SIDE REAR MUDGUARD,LEFT SIDE CENTER SLIDING DOOR,LEFT SIDE FRONT DOOR AND LEFT SIDE TAIL GATE	New	1,200.00	660.00
5	TO APPLY SILICON ONTO LEFT SIDE CENTER SLIDING DOOR TOP WINDOW	New	80.00	40.00
6	DISMANTLE & REFIX LEFT SIDE CENTER SLIDING DOOR GLASS	New	140.00	60.00
Gross Labour Cost (\$\$)			3,150.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >