

22/03/2002

ASS. REC. BY:

REF:

CSB/MSG15014047/B-903¹²⁻¹ Special Instructions:

SURVIVOR:

ASSIGNMENT (Office)

From (Person):

Ng Chen Haw

of

MSIG

Date/Time:

01/08/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JGS 4712

Insured:

FBD 9838X

at Workshop m/s

Sg Motor Enterprise

Tel:

6452 4898

of

Bk 4001 Amy Ind Park 1 #01-21

Policy No:

MSD / VMT / 15-319462

Claim No:

MSC/V/15-001167

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16082015

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

19082015 1:14 PM

Person Contacted:

Rose

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	JGS 4712 - X
	FBD 9838X - NA / 2NC15013831 / 43
	The estimated repair cost of the damaged vehicle is
	in the region of \$5k - \$6k.
11/01/16	Submit PR.

US \$4350, 5 days (Red \$6650, 60%)

Repair days 5.


 6/8/2018



Advanced Automotive Consultancy Pte Ltd

Business Regn No: 201416413W

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

1 REFERENCE			
Our reference no	:	TP/JQS4712/SG98/1215/02	
Date of request	:	7-Dec-2015	
Date of survey	:	7-Dec-2015	
Date of accident	:	16-Aug-2015	
Requested by	:	DANIEL KAU WING KIT	
	:	C/o , Blk 4001 Ang Mo Kio Ind Park 1 #01-21, Singapore 569622	
Type of claim	:	Third party	
Workshop	:	M/S SG MOTOR ENTERPRISE	
	:	Blk 4001 Ang Mo Kio Ind Park 1 #01-21	
	:	Singapore 569622	
2 DETAILS OF VEHICLE			
Registration No.	:	JQS4712	
Make & Model	:	ZR1000-F	
Date of registration	:	8-Mar-2015	
Engine No.	:	ZRT00DE062519	
Engine Capacity	:	1043 cc	
Chassis No.	:	JKAZRT00FFA002507	
Speedometer reading	:	No current supply	
Transmission	:	-	
Colour	:	Black	
3 STATIC CHECK			
Steering	:	In order	Paintwork : Good
Footbrake	:	In order	Modification : Nil
Handbrake	:	In order	General condition : Good
4 TYRE CONDITION			
		<u>Nearside/Make</u>	<u>Size</u>
Front tyre	:	2mm/Dunlop	180/70ZR17
Rear tyre	:	3mm/Dunlop	190/50ZR17
5 POINT OF IMPACT			
The said vehicle has sustained an impact damages on the LH and RH portion. Kindly refer to the attached photographs for more detail of the damages.			
6 REMARK			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Business Regn No: 201416413W Blk 432, Ang Mo Kio Ave 10 #04-1447, S(560432)

Tel no / Fax no : 67566321 Email : advapp@outlook.com

Advanced Automotive Consultancy Pte Ltd

Annex A : Assesment / Adjustment on Spare Parts

TPI/QS4712/SG98/1215/02

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)	
List Items							
1	Handle guard -LH/RH	grazed	1/2	\$145.00	10%	\$130.50	SCR ✓
2	Handle bar	bent	115.00 ✓ 1	\$345.00	10%	\$310.50	BT ✓
3	Handle bar balancer LH (1 set)	grazed	✓ 1	\$120.00	10%	\$108.00	SCR ✓
4	Handle bar grip (1 set)	necessary	✓ 1	\$86.50	10%	\$77.85	NNX
5	Horn-LH	cracked	✓ 1	\$102.60	10%	\$92.34	CRAV ✓
6	Front slider- LH/RH	grazed	55.00 ✓ 1/2	\$290.00	10%	\$261.00	SCR ✓
7	Magneto cover-LH	grazed	✓ 1	\$242.30	10%	\$218.07	SCR ✓
8	Magneto cover gasket-LH	necessary	✓ 1	\$46.50	10%	\$46.50	NECV ✓
9	Front footrest bracket-LH	broken	✓ 1	\$165.00	10%	\$148.50	BR ✓
10	Front footrest -LH	grazed	45.50 ✓ 1	\$88.50	10%	\$79.65	SCR ✓
11	Gear shift pedal	bent	✓ 1	\$86.00	10%	\$77.40	BT ✓
12	Gear shift pedal linkage	distorted	✓ 1	\$75.60	10%	\$68.04	BT ✓
13	Exhaust muffler-LH/RH	grazed	995.00 ✓ 2	\$4,428.20	10%	\$3,985.38	CUT ✓
14	Exhaust muffler protector -LH/RH	grazed/scratched	1/2	\$290.00	10%	\$261.00	SCR ✓
15	Rear side covers -LH/RH	grazed	1/2	\$482.60	10%	\$434.34	SCR ✓
16	Seat assy (came with set)	torn/cracked/grazed	375.00 ✓ 1	\$646.20	10%	\$580.68	CUT ✓
17	Seat lower cover (garnish)	cracked	✓ 1	\$186.30	10%	\$167.67	CRAV ✓
18	Side mirror- LH/RH	grazed	55.00 ✓ 1/2	\$330.00	10%	\$297.00	SCR ✓
19	Wind shield	broken	✓ 1	\$209.00	10%	\$188.10	BR ✓
20	Fuel tank assy	dented	local repair 200.00 ✓ 1	\$1,250.00	10%	\$1,125.00	
21	Rear footrest- LH/RH	grazed	45.00 ✓ 1/2	\$177.00	10%	\$159.30	CUT ✓
22	Engine guard (Z1000)-RH	grazed	✓ 1	\$98.20	10%	\$88.38	NNX
23	Tail lamp assy	cracked/grazed	✓ 1	\$125.00	10%	\$112.50	SVEX
24	Seat under RH side frame	distorted	✓ 1	\$642.60	10%	\$578.34	NNX
25	Seat under LH side frame	distorted	✓ 1	\$642.60	10%	\$578.34	CUT
26	Seat under frame-Front (aluminium)	distorted	✓ 1	\$523.50	10%	\$471.15	BT ✓
				\$11,823.20		\$10,645.53	
						4917.35	
						491.74	
						4426.62	
S/Nett Items							
1	Rear number plate	bent	✓ 1	\$20.00		\$15.00	SVEX
				\$20.00		\$15.00	
Total for Spare Parts :				\$11,843.20		\$10,660.53	4425.62

Advanced Automotive Consultancy Pte Ltd

Annex B : Adjustment on Labour and Spray Painting

TP/JQS4712/SG98/1215/02

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	To provide towing charge.	\$60.00	\$50.00 NNX
2	To check wiring and lighting system.	\$100.00	\$50.00
3	To respray motorcycle on the repair and replace parts	\$800.00	\$650.00 500.00
4	To remove, replace, repair and realign above body damaged parts.	\$750.00	\$520.00 400.00
5	To remove, replace and align rear body frame	\$350.00	\$220.00 150.00
6	To remove and replace magneto cover & gasket	\$120.00	\$60.00
		\$2,180.00	\$1,550.00
TOTAL FOR LABOUR & SPRAY PAINTING :		\$2,180.00	\$1,550.00

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$11,843.20	\$10,660.53
TOTAL FOR LABOUR & SPRAY PAINTING :	\$2,180.00	\$1,550.00
TOTAL REPAIR COSTS :	\$14,023.20	\$12,210.53

Advanced Automotive Consultancy Pte Ltd

TP/JQS4712/SG98/1215/02

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S SG Motor Enterprise estimated repair cost is **S\$14,023.20** and we have adjusted it to **S\$12,210.53** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.


The repairer have agreed to undertake the repairs on a contract lump sum of **S\$11,000.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of 7 working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,



Hendry Low
Automotive License Appraiser
CMTM, DMTM, IPTM (UNF)



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Aug 2015		19 Aug 2015 11:47 Edit Adj Rpt	S\$4,350.00 Edit Estimates	S\$4,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHONG SENG THONG, ID: S1363197B		
Main Claimant:	DANIEL KAU MING KIAT, ID: G7549489R		
Vehicle Reg. No.:	JQS4712	Date of Loss:	16/08/2015 14:00 - :59 [5 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/15-001167	Policy/Cover Note No.:	MSD/VMT/15-319462 (Third Party Only) Coverage: 27/03/2015 - 26/03/2016
Vehicle Reg. No. (Insured):	FBD9838X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Sg Motor Enterprise (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 6452 4898 / 6451 3923		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 03/08/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- MSIG_SG (01/08/2018): Report Send Back Alerts - JQS4712 (TP)

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***JQS4712 (MSC/V/15-001167)**
[FBD9838X]

TP

DANIEL KAU MING KIAT

Aug 16 2015 2:00PM

[CHONG SENG THONG]

Sg Motor Enterprise

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

1 per page
 ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/09/15 16:07	Accident Statement From: SC - Reg. No: FBD9838X, Claimant: CHONG SENG THONG	Load HTM	☒

Photos/Images

3 per page
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/01/16 17:51	General View	Load JPG	☒
2	11/01/16 17:51	General View	Load JPG	☒
3	11/01/16 17:51	General View	Load JPG	☒
4	11/01/16 17:51	General View	Load JPG	☒
5	11/01/16 17:51	General View	Load JPG	☒
6	11/01/16 17:51	General View	Load JPG	☒
7	11/01/16 17:51	General View	Load JPG	☒
8	11/01/16 17:51	General View	Load JPG	☒
9	11/01/16 17:51	General View	Load JPG	☒
10	11/01/16 17:51	General View	Load JPG	☒
11	11/01/16 17:51	General View	Load JPG	☒
12	11/01/16 17:51	General View	Load JPG	☒
13	11/01/16 17:51	General View	Load JPG	☒
14	11/01/16 17:51	General View	Load JPG	☒
15	11/01/16 17:51	General View	Load JPG	☒
16	11/01/16 17:51	General View	Load JPG	☒
17	11/01/16 17:51	General View	Load JPG	☒
18	11/01/16 17:51	General View	Load JPG	☒
19	11/01/16 17:51	General View	Load JPG	☒
20	11/01/16 17:51	General View	Load JPG	☒
21	11/01/16 17:52	General View	Load JPG	☒
22	11/01/16 17:52	General View	Load JPG	☒
23	11/01/16 17:52	General View	Load JPG	☒
24	11/01/16 17:52	General View	Load JPG	☒
25	11/01/16 17:52	General View	Load JPG	☒
26	11/01/16 17:52	General View	Load JPG	☒
27	11/01/16 17:52	General View	Load JPG	☒
28	11/01/16 17:52	General View	Load JPG	☒
29	11/01/16 17:52	General View	Load JPG	☒
30	11/01/16 17:52	General View	Load JPG	☒
31	11/01/16 17:52	General View	Load JPG	☒

Assessment Reports				☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	11/01/16 17:52	General View	 Load JPG	☒
33	11/01/16 17:52	General View	 Load JPG	☒
34	11/01/16 17:52	General View	 Load JPG	☒
35	11/01/16 17:52	General View	 Load JPG	☒
36	11/01/16 17:52	General View	 Load JPG	☒
37	11/01/16 17:52	General View	 Load JPG	☒
38	11/01/16 17:52	General View	 Load JPG	☒
39	11/01/16 17:52	General View	 Load JPG	☒
40	11/01/16 17:52	General View	 Load JPG	☒
41	11/01/16 17:54	General View	 Load JPG	☒
42	11/01/16 17:54	General View	 Load JPG	☒
43	11/01/16 17:54	General View	 Load JPG	☒
44	11/01/16 17:54	General View	 Load JPG	☒
45	11/01/16 17:54	General View	 Load JPG	☒
46	11/01/16 17:54	General View	 Load JPG	☒
47	11/01/16 17:54	General View	 Load JPG	☒
48	11/01/16 17:54	General View	 Load JPG	☒
49	11/01/16 17:54	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/08/15 11:48	PRE-REPAIR INSPECTION	 Load PDF	
2	24/08/15 10:46	EMAIL TO TP REQUESTED A COPY OF POLICE REPORT DD 24.08.15	 Load PDF	
3	31/08/15 14:58	EMAIL FROM OI DAUGHTER WITH POLICE REPORTS DD 29.08.15	 Load PDF	
4	31/08/15 14:58	EMAIL ENCLOSED POLICE REPORT DD 31.08.15	 Load PDF	
5	31/08/15 14:58	POLICE REPORT PG 1	 Load JPG	☒
6	31/08/15 14:58	POLICE REPORT PG 2	 Load JPG	☒
7	31/08/15 14:58	POLICE REPORT PG 3	 Load JPG	☒
8	15/10/15 10:02	EMAIL FROM TP ENCLOSED POLICE REPORT DD 15.10.15	 Load HTM	
9	16/10/15 13:48	POLICE REPORT OF JQS4712	 Load PDF	
10	07/01/16 16:36	EMAIL TP OI POLICE REPORT DD 07.01.16	 Load PDF	
11	01/08/18 17:12	Survey Report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/18 10:09	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG15014047/BQD3S2-1
Date: 13/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMT/15-319462
 Claimant Vehicle No: JQS4712 Insured Vehicle No: FBD9838X
 Date of Loss: 16/08/2015 Nature of Claim: TP Claim No: MSCV/15-001167

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JQS4712
 Make & Model: KAWASAKI ZR1000, 1.0 (M) Engine No: ZRT00DE062519
 Reg. Date: 08/03/2015 (Man. Year: 2013) Chassis No: JKAZRT00FFA002507
 Colour: Black Odometer: 6470 km
 Engine Capacity: 1043 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70R17 Rear Tyre Size: 190/50R17
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,843.20	4,289.33	7,553.87	63.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,160.00	1,020.00	46.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,023.20	5,449.33	8,573.87	61.14
Approved Total (Overridden) (S\$)		4,350.00		
Nett Amount (S\$)	14,023.20	4,350.00	9,673.20	68.98

INSPECTION

Date of Assignment: 19/08/2015
 Date Inspected: 19/08/2015 Inspected At: Sg Motor Enterprise (HQ)
 BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21
 Singapore 569622
 Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Aug 2018)	
Parts:	N/A	KAWASAKI ZR1000 1.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JQS4712)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE GUARD LH / RH	N/s Scratched	145.00 F	*72.50 FL
2	1		*HANDLE BAR	Bent	345.00 F	*115.00 FL
3	1		*SET HANDLE BAR BALANCER LH	Scratched	120.00 F	*120.00 FL
4	1		*SET HANDLE BAR GRIP	Not Necessary	86.50 F	*- FL
5	1		*HORN - LH	Cracked	102.60 F	*102.60 FL
6	1		*FRONT SLIDER - LH/RH	N/s Scratched	290.00 F	*55.00 FL
7	1		*MAGNETO COVER - LH	Scratched	242.30 F	*242.30 FL
8	1		*MAGNETO COVER GASKET - LH	Necessary	46.50 F	*46.50 FL
9	1		*FRONT FOOTREST BRACKET - LH	Broken	165.00 F	*165.00 FL
10	1		*FRONT FOOTREST - LH	Scratched	88.50 F	*45.50 FL
11	1		*GEAR SHIFT PEDAL	Bent	86.00 F	*86.00 FL
12	1		*GEAR SHIFT PEDAL LINKAGE	Bent	75.60 F	*75.60 FL
13	1		*EXHAUST MUFFLER - LH/RH	N/s Cut	4,428.20 F	*995.00 FL
14	1		*EXHAUST MUFFLER PROTECTOR - LH/RH	N/s Scratched	290.00 F	*145.00 FL
15	1		*REAR SIDE COVERS - LH/RH	N/s Scratched	482.60 F	*241.30 FL
16	1		*SEAT ASSY (CAME WITH SET)	Cut	645.20 F	*375.00 FL
17	1		*SEAT LOWER COVER (GARNISH)	Cracked	186.30 F	*186.30 FL
18	1		*SIDE MIRROR - LH/RH	N/s Scratched	330.00 F	*55.00 FL
19	1		*WIND SHIELD	Broken	209.00 F	*209.00 FL
20	1		*REAR FOOTREST - LH/RH	N/s Cut	177.00 F	*45.00 FL
21	1		*ENGINE GUARD (Z1000) (GRAZED)	Not Consistent With The Impact	98.20 F	*- FL
22	1		*TAIL LAMP ASSY	Serviceable	125.00 F	*- FL
23	1		*SEAT UNDER RH SIDE FRAME (DISTORTED)	Not Consistent With The Impact	642.60 F	*- FL
24	1		*SEAT UNDER LH SIDE FRAME	Cut	642.60 F	*642.60 FL
25	1		*SEAT UNDER FRAME - FRONT (ALUMINIUM)	Bent	523.50 F	*523.50 FL
26	1		*FUEL TANK ASSY (LOCAL REPAIR)	Dented	1,250.00 FS	*200.00 FS
27	1		*REAR NUMBER PLATE	Serviceable	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,843.20	4,743.70
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	454.37
Total Parts (S\$)	11,843.20	4,289.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING CHARGE.	New	60.00	0.00
2	TO CHECK WIRING AND LIGHTING SYSTEM.	New	100.00	50.00
3	TO RESPRAY MOTORCYCLE ON THE REPAIR AND REPLACE PARTS.	New	800.00	500.00
4	TO REMOVE, REPLACE, REPAIR AND REALIGN ABOVE BODY DAMAGED PARTS.	New	750.00	400.00
5	TO REMOVE, REPLACE AND ALIGN REAR BODY FRAME.	New	350.00	150.00
6	TO REMOVE AND REPLACE MAGNETO COVER & GASKET.	New	120.00	60.00
Gross Labour Cost (S\$)			2,180.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >