

15/5/2010

INS. CASE OWNER:

June

CC 7/EQ1801

4117

Kphb sz

LKK:

IDAC:

Surveyor:

Kinneth

DOI:

ASSIGNMENT

7/8/18

Date / Time:

7/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUM 8730M

Name of Insured:

WEE CHING SENG

Insured Tel No.:

HP: 96718976

Excess Sec II :SS

D.O.A: 30/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

0M18H001964 (ST

Policy No.:

0MPPH018-00245

Make / Model:

TAYOTIN

Place of Accident:

LTE SUP RD TRANS BMT KPEI

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHD 9830M



INSRS:

WSP:

Tel:

Liability:

RMKS:

TRANS
CAB

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

6/8/18

MIT

8/8/18

24/9/18

SHD 9830M - 4

SUM 8730M - 8

OI rear ended TP.

RMK ⊕

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

7/8/18

Sent By:

DOL

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

20/6/19

Confirm with JASMIN

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

2A

If NO or B 28, Ass. Lia:

Repair Cost:

SS 1979.50

Loss of Rental (LOR):

SS 198.60

(S 50 x 2 days) K99.32

Loss of Use (LOU):

SS 100

(S 50 x 2 days)

Loss of Income (LOI):

SS

(S x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

Total:

SS 2285.59

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 2285.59

Name 1:

Trans cab Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

01C
26/6/17
01C

ASS. REC. BY:

REF:

EQ1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / PWS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Trans Ccb

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02

days

Res.: _____

Yes or No

Lum Sum: _____

20

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

S110 9833M

Yr Regn: _____

04, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Renault Latitude

c.c

1995

Colour: _____

M. White / Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

253.882

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

VF1 ABL 15AUC

277414

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Giti

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

9

mm

L/Bal. _____

9

mm

L/Bal. _____

9

mm

D.O.A. _____

30/7/18

D.O.I. _____

2/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/8

File pass to Catherine

27/9

21 Lp @ 1850t confirmed Jasmin (2 x 9932 + 100)

(Red # 6449753/977.)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

S - RS. SI

Fictos

Others

Report Format :

Lum Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC3/EQ18014117/Kpb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 03-08-2018	
Code : EQI				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLM 8730M	Veh. Inspected	SHD 9833M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/07/2018	Inspection Date	02/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI18014117/Kpb3

Date: 03.08.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD9833M


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.08.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	66,347.53
Revised Estimate Amount	: S\$	1,850.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9833M**AAD1807-295***Not Authored
1/1 Sep @ 1850h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9833M

VF1ABL15AUC277414

RENAULT

LATITUDE

30.7.2018

EQ**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	<i>✓</i>
2	1 BUMPER LOWER REAR	\$	<i>Ref 1011</i> 768.84	<i>✓</i>
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	<i>X</i>
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
5	1 BUMPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
8	1 BUMPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	<i>X</i>
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	
18	1 BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36	
19	1 BOOT BADGE	\$	<i>nn</i> 225.36	
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	

11364.36

Trans-cab Auto Services Pte Ltd

AAD1807-295

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9833M

30	1 FENDER PANEL REAR LH	\$	3,299.13	}	X
31	1 WHEELARCH REAR LH	\$	543.47		
32	1 FENDER PANEL INNER TRIM REAR RH	\$	671.45		
33	1 FENDER PANEL REAR RH	\$	3,299.13		
34	1 WHEELARCH REAR RH	\$	543.47		
35	1 TAILLAMP RH	\$	552.55		
36	1 TAILLAMP PANEL RH	\$	986.70		
37	1 TAILLAMP LH	\$	552.55		
38	1 TAILLAMP PANEL LH	\$	986.70		
39	1 OUTER PANEL REAR (End Panel)	\$	1,471.77		
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	404.56		
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	2,189.88		
42	1 SPARE WHEEL PANEL TRIM	\$	612.21		
43	1 EXHAUST REAR	\$	7,489.05		
44	1 EXHAUST CAP REAR	\$	230.49		
45	1 CHASSIS PANEL REAR RH	\$	3,766.43		
46	1 KUCKLE ARM REAR RH L70Y	\$	736.67		
47	1 BRAKE DISC REAR L70Y	\$	525.91		
48	1 WHEEL HUB NUT L70Y	\$	51.11		
49	1 WHEEL HUB CAP L70Y	\$	57.82		
50	1 ABS SENSOR REAR RH L70Y	\$	255.75		
51	1 REAR AXLE L70Y	\$	4,167.03		
52	1 AXLE ARM RH L70Y	\$	117.22		
53	1 LOWER ARM REAR RH L70Y	\$	905.99		
54	1 ABSORBER REAR	\$	389.75		
55	1 STABILIZER BAR REAR RH	\$	604.65		
56	1 BRAKE CALIPER REAR RH	\$	1,300.67		
57	1 WHEEL HOUSING PANEL REAR RH	\$	4,682.09		
58	1 CHASSIS PANEL REAR RH	\$	3,766.43		
TOTAL		\$	56,525.01	99	
10%		\$	5,652.50		
		\$	50,872.51	49	45160.63

Specical Nett

1 1SET PARKING AID	\$	700.00	X
2 1SET REAR BUMPER CLIP	\$	66.00	✓
3 1SET BUMPER BRACKET CTR CLIP	\$	33.00	✓
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X

Trans-cab Auto Services Pte Ltd

AAD1807-295

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9833M

5 1SET BUMPR RETAINER RH CLIP RR	\$	nn	20.00	X
6 1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7 1SET BUMPR RETAINER CLIP LH RR	\$	nn	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	sn	17.82	} X
11 1SET BOOT FINISHER CLIP	\$	nn	24.20	
12 1 BOOT STICKER "Trans-cab"	\$	nn	30.00	
13 1 BOOT STICKER "6555-3333"	\$	nn	30.00	
14 1 BOOT INNER TRIM CLIP	\$	nn	45.00	
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	
17 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	
18 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	
19 1 TAILLAMP CLIP RH	\$	nn	5.00	
20 1 TAILLAMP CLIP LH	\$	nn	5.00	
21 2 REAR WINDSCREEN SELANT	\$	nn	80.00	}
22 1 WINDSCREEN MOULDING	\$	nn	100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	
25 1 SPARE TYRE	\$	sn	330.00	
26 1 RIGHT REAR TYRE	\$	sn	330.00	
27 1 RIGHT REAR TYRE RIM	\$	sn	380.00	

TOTAL \$ 2,935.02

TOTAL PARTS \$ 53,807.53**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	2001
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1807-295**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9833M

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	X

TOTAL \$ 12,540.00**Over All Total \$ 66,347.53****(LUMP SUM)****Repair Days****20 DAYS****2 days****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shu Pei (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 3 August 2018 3:45 PM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Hsiao Tong (LKKAUTO)
Subject: FW: Direct Settlement - Accident Involving SLM8730M (OI : EQI - DM18HO01964/JT) and SHD9833M (TP : LKK REF - CC3/EQI18014117/Kpb3) on 30.07.2018
Attachments: Preliminary_Advice.pdf; TP ESTIMATE- MARKED.PDF; TP GIA REPORT.PDF; SAS2448425.pdf

Dear Shu Pei

As attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Friday, August 3, 2018 3:35 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Direct Settlement - Accident Involving SLM8730M (OI : EQI - TBA) and SHD9833M (TP : LKK REF - CC3/EQI18014117/Kpb3) on 30.07.2018

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 9833M at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC3/EQI18014117/Kwb3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 03-07-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 8730M	Veh. Inspected	SHD 9833M
Policy No.	DMPPHQ18-002375	Coverage (\$)	0.00
Claim No.	DM18HO01964/JT	Excess (\$)	0.00
Assign From		Assign Date	02/08/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC277414	Colour	METALLIC WHITE / RED
Odometer	253882	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	9 mm
L/H Front Tyre	215/60R16	GITI	9 mm
R/H Rear Tyre	215/60R16	GITI	9 mm
L/H Rear Tyre	215/60R16	GITI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/07/2018	Inspection Date	02/08/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9833M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / DISTORTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CC3/EQI18014117/Kwb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	CHASSIS PANEL REAR RH	TO REPAIR SEE LABOUR	3,766.43	-
1	KNUCKLE ARM REAR RH L70Y	SERVICEABLE	736.67	-
1	BRAKE DISC REAR L70Y	SERVICEABLE	525.91	-
1	WHEEL HUB NUT L70Y	SERVICEABLE	51.11	-
1	WHEEL HUB CAP L70Y	SERVICEABLE	57.82	-
1	ABS SENSOR REAR RH L70Y	SERVICEABLE	255.75	-
1	REAR AXLE L70Y	SERVICEABLE	4,167.03	-
1	AXLE ARM RH L70Y	SERVICEABLE	117.22	-
1	LOWER ARM REAR RH L70Y	SERVICEABLE	905.99	-

Report Ref No. CC3/EQI18014117/Kwb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ABSORBER REAR	SERVICEABLE	389.75	-
1	STABILIZER BAR REAR RH	SERVICEABLE	604.65	-
1	BRAKE CALIPER REAR RH	SERVICEABLE	1,300.67	-
1	WHEEL HOUSING PANEL REAR RH	TO REPAIR SEE LABOUR	4,682.09	-
1	CHASSIS PANEL REAR RH	TO REPAIR SEE LABOUR	3,766.43	-
	LESS 10% DISCOUNT		-5,652.50	-187.73
			50,872.49	1,689.57
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-

Report Ref No. CC3/EQ18014117/Kwb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	RIGHT REAR TYRE (SN)	SERVICEABLE	330.00	-
1	RIGHT REAR TYRE RIM (SN)	SERVICEABLE	380.00	-
			2,935.02	165.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	220.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR, EXHAUST CAP REAR, }		4,200.00	200.00
	CHASSIS PANEL REAR RH, WHEEL HOUSING PANEL REAR RH AND CHASSIS PANEL REAR RH. }		-	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TYO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CC3/EQ118014117/Kwb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			12,920.00	480.00
GRAND TOTAL			66,727.51	2,334.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,850.00

Report Ref No. CC3/EQ18014117/Kwb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.