

ASS. REC. BY:

REF: CS/FCI18014154/Ked3 n2
Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

Form (Person):

Lurene juw

of

FCI

Date/Time 02/08/2018 07:05pm

Estimated Cost:

Bill to:

OD ☒ IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5155T

Insured:

SHB 2026H

at Workshop m/s:

Trans-Cub

Tel:

6287 6666

of

No-2 AMK St. 63

Policy No:

Claim No:

D18005850MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/08/2018

CA / REV / REP. / REV 24 HRS ^{cup}

H.O.D. Endorsement:

Date/Time:

8:45am 3/8/18

Person Contacted:

kek zhwei

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 5155T-X
	SHB 2026H - CC3/AIG/2001346/Hbr 1q.2 DOA: 16/01/12
6/8/18	Email preli revised to FCI

(08/11/13) wef

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From: Date: 3/8/18

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 5155T

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Cup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 5155T

Yr Regn:

01, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Meravit Latitude c.c.

1995

Colour

M. white / Red

A/C: Insured / Std / NI / NA

Sp. Reading

440096

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VIF/ABL 15AUC 276538

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

Prime well 215/60R16

Ling. Long

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

11/8/18

D.O.I.

3/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/8

File pass to Ninito

61 Lg. @ 6450L.

(\$28,891.77 Red - 81%)

RECEIVED 15 AUG 2018

Date/Time, File Pass to?

15/08/18

1)

Typist

Date/Time, File Return to?

2)

☐

Preli. Report

☒

Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

25X15: 375

170+375

50

15

610

Report Format :

Lump Sum / I.B.I: (\$ 6,450.00 4/5)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014154/Ksd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2026H	Veh. Inspected	SHC 5155T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005850MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	03/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/08/2018	Inspection Date	03/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005850MFSH

Our ref: CS/FCI18014154/Ksd3

Date : 6/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO.SHC 5155T


We thank for your instruction on 2/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/8/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$35,341.77
Revised Estimate Amount	: S\$6,450.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	02-08-2018	Our Ref No. D18005850MFSH
Accident Date	01-08-2018	Claim Type. Third Party
Insured Vehicle	SHB2026H	Third Party Vehicle. SHC5155T
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242966)



PRI Documents



Close



PRI Header Details

Claim No	D18005850MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : KEK ZHEWEI)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: ZHEWEI.KEK@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2026H	TP Vehicle No	SHC5155T
PRI Recieved Date	02-08-2018 03:32:57 PM	Surveyor Appointed Date	02-08-2018 07:04:47 PM	Surveyor Accept Date	03-08-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	03-08-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 6 August 2018 4:23 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005850MFSH/1, SHC 5155T
Attachments: SHC 5155T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 5155T
Date of survey: 3/8/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 3 August 2018 8:17 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005850MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 2 August 2018 7:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005850MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details	
Vehicle No.:	SHC5155T
Vehicle to be Exported:	Yes
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000817
Chassis No.:	VF1ABL15AUC276538
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Jan 2014
First Registration Date:	14 Jan 2014
Transfer Count:	0
Actual ARE Paid:	\$12,498.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2022
PARF Rebate Amount:	\$9,373.00

COE Expiry Date:	13 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,888.00
COE Rebate Amount:	\$26,249.00
Total Rebate Amount:	\$35,622.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5155T**AAD1808-001***Not Authorized
C1 Reg # 64506*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5155T

VF1ABL15AUC276538

RENAULT

LATITUDE

1.8.2018

FCIL

PART		LIST	
1	FENDER PANEL FRT RH	\$	B ₁ 783.83 ✓
1	WHEELARCH FRT RH	\$	D ₁ 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	S ₂ 15.79 X
1	FENDER INSULATOR RH	\$	S ₂ 130.84 X
1	WHEEL HOUSING COMPLETE SET FRT RH	\$	R 5,978.22 X
1	DOOR PANEL FRT RH	\$	B ₁ 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	Oil R ₂ 261.28 X
1	DOOR HINGE LOWER RH	\$	B ₁ 300.55 ✓
1	DOOR CHECK FRT RH	\$	S ₂ 194.77
1	DOOR LOCK FRT RH	\$	R 908.75
1	DOOR CATCH FRT RH	\$	S ₂ 131.23
1	DOOR HANDLE OUTER FRT RH	\$	S ₂ 477.76
1	DOOR HANDLE COVER FRT RH	\$	S ₂ 13.22
1	DOOR HANDLE MODULE FRT RH	\$	S ₂ 133.60
1	DOOR REGULATOR FRT RH	\$	S ₂ 505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	S ₂ 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	S ₂ 120.97
1	LOWER ARM RH	\$	S ₂ 685.76
1	KUNCKLE ARM RH	\$	S ₂ 846.98
1	ABSORBER FRT RH	\$	S ₂ 360.54
1	STABILIZER BAR FRT	\$	S ₂ 604.65
1	DRIVESHAFT RH	\$	R 1,747.45
1	WIPER RESERVOIR	\$	S ₂ 348.25
1	WIPER RESERVOIR NECK	\$	S ₂ 136.11
1	WIPER RESERVOIR MOTOR	\$	B ₁ 270.06
1	DOOR MIRROR ASSY RH	\$	CR ₂ 1,483.40 ✓
1	ROCKER PANEL INNER GARNISH RH	\$	S ₂ 466.51 X
1	ROCKER PANEL INNER RH	\$	R 1,024.79 X
1	ROCKER PANEL CENTER RH	\$	B ₁ 990.25 ✓
1	DOOR HARNESS WIRE	\$	S ₂ 2,670.00 X

Trans-cab Auto Services Pte Ltd

AAD1808-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5155T

	\$	25,510.71
10%	\$	2,551.07
	\$	22,959.64

Specical Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	30.50	✓
1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00	60.00
1	FRONT FENDER ADVERTISEMENT STICKER	\$	300.00	X
1	FRONT DOOR ADVERTISEMENT STICKER	\$	300.00	X
1	DOOR CHECK BOLT	\$	22.69	} X
1	DOOR GUIDE SCREW	\$	10.85	
1	DOOR HINGE BOLT	\$	10.85	
1	DOOR HINGE NUT RH	\$	14.60	
1	DOOR CHECK BOLT	\$	22.69	
1	DOOR CHECK NUT	\$	3.75	
1	DOOR LOCK SCREW L70Y	\$	6.12	
1	DOOR CATCH SCREW L70Y	\$	10.06	

TOTAL	\$	932.13
--------------	-----------	---------------

TOTAL PARTS	\$	23,891.77
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00	700
----	----------	-----

Putty and spray painting of the affected portion.

\$	4,200.00	720
----	----------	-----

To rust-proofing of the affected areas.

\$	170.00	90
----	--------	----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	100
----	--------	-----

Trans-cab Auto Services Pte Ltd

AAD1808-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5155T

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 <i>601</i>
Towing Fees.	\$	120.00 <i>501</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>

TOTAL \$ 11,450.00**Over All Total \$ 35,341.77****LUMP SUM (REPAIR DAY)**~~15 DAYS~~*5 days*

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3661 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 5155T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3661 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18014154/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2026H	Veh. Inspected	SHC 5155T	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005850MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC276538	Colour	METALLIC WHITE / RED	
Odometer	440096	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	PRIMEWELL	9 mm	
L/H Front Tyre	215/60 R16	PRIMEWELL	9 mm	
R/H Rear Tyre	215/60 R16	LING LONG	8 mm	
L/H Rear Tyre	215/60 R16	LING LONG	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/08/2018	Inspection Date	03/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5155T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	DISTORTED	278.84	278.84
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	WHEEL HOUSING COMPLETE SET FRT RH	TO REPAIR SEE LABOUR	5,978.22	-
1	DOOR PANEL FRT RH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER RH	DISTORTED	261.28	261.28
1	DOOR HINGE LOWER RH	BENT	300.55	300.55
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	SERVICEABLE	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	LOWER ARM RH	SERVICEABLE	685.76	-
1	KNUCKLE ARM RH	SERVICEABLE	846.98	-
1	ABSORBER FRT RH	SERVICEABLE	360.54	-
1	STABILIZER BAR FRT	SERVICEABLE	604.65	-
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	1,747.45	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	DOOR MIRROR ASSY RH	CRACKED	1,483.40	1,483.40
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-

Report Ref No. CS/FCI18014154/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL CENTER RH	BENT	990.25	990.25
1	DOOR HARNESS WIRE	SERVICEABLE	2,670.00	-
	LESS 10% DISCOUNT		-2,551.07	-694.28
			22,959.64	6,248.53
	SPECIAL NETT ITEMS			
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NECESSARY	30.50	30.50
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT FENDER ADVERTISEMENT STICKER (SN)	NOT NECESSARY	300.00	-
1	FRONT DOOR ADVERTISEMENT STICKER (SN)	NOT NECESSARY	300.00	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
			932.11	90.50
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF WHEEL HOUSING COMPLETE SET FRT RH,DOOR LOCK FRT RH,DRIVESHAFT RH AND ROCKER PANEL INNER RH.		4,500.00	700.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	720.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.		380.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TOWING FEES.		120.00	50.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			11,450.00	1,740.00
	GRAND TOTAL		35,341.75	8,079.03
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,450.00

Report Ref No. CS/FC118014154/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.