

*Not with in
 1/1pm @?
 Presurvey After Paint
 4-5days*

C. S. ONG AUTO PTE. LTD.

Business.Reg.No.: 201408916W
 GST Reg.No.: 201408916W
 10, Ang Mo Kio Ind. Park 2A, #02-16 AMK Autopoint, Singapore (568047).
 Tel: 6484 1933 Fax: 6484 1922
 E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,
 AIG Asia Pacific Insurance Pte Ltd

Date: 31-07-2018

Accident Involving Vehicles SKZ8988E & SGQ8286S [Your Insured] on 31/07/2018 @
 0715hrs along KPE TOWARDS ECP

Estimate For SKZ8988E [BMW740] WBAYE42010DD87319

1Pc	Rear Bumper		\$	1,896.35	✓
2Pcs	Rear Bumper Side Guide LH/RH @ \$198.15 Each	<i>ALJ D1</i>	\$	396.30	✓
2Pcs	Rear Bumper Reflector RH & LH @ \$55.20	<i>ALJ RH/LH</i>	\$	110.40	✓
1Pc	Rear Bumper Lower Exhaust Diffuser	<i>CM/100</i>	\$	254.45	✓
1Pc	Rear Bumper Centre Guide		\$	65.50	?
1Pc	Rear Bootlid		\$	2,107.90	?
1Pc	Rear Bootlid "740 LI" Emblem	<i>me</i>	\$	72.55	✓
1Pc	Rear "BMW" Logo	<i>me</i>	\$	79.50	✓
1Pc	Rear Tailgate Inner Weatherstrip Rubber	<i>me</i>	\$	208.65	X
2Pcs	Rear Tailgate Inner Lamp RH & LH @ \$526.15 Each	<i>me</i>	\$	1,052.30	X
2Pcs	Rear Tailgate Outer Lamp RH & LH @ \$810.50 Each	<i>ALJ ?</i>	\$	1,621.00	X
2Pcs	Rear Tailgate Inner Lamp Chrome RH & LH @ \$87.10 Each	<i>me</i>	\$	174.20	X
1Pc	Rear Tailgate Centre Chrome	<i>me</i>	\$	93.65	X
1Pc	Rear Bumper Tow Hook Cover	<i>me</i>	\$	60.65	X
2 Pcs	Rear Bumper Reverse Sensor @ \$256.85 Each	<i>short</i>	\$	1,027.40	✓
1Pc	Rear Bumper Reinforcement with Holder		\$	910.80	?
4pcs	Rear Bumper Reverse Sensor 'O' Ring @ \$10.00 Each	<i>me</i>	\$	40.00	✓
1Set	Rear Bumper Clips	<i>me</i>	\$	150.00	✓
1Pc	Rear Exhaust Pipe Chrome Tip	<i>me</i>	\$	208.65	✓
	Parts Sum:		\$	10,530.25	
	Parts Less 5%:		\$	526.51	
	Parts Total:		\$	10,003.74	

Labour & MISC Charges

1	To remove all rear interior upholstery items on all rear affected areas & to replace it back once repair is done.	\$	500.00	?
2	To cut and remove all damaged panels,replace new parts, refit & realign all of the above.	\$	1,500.00	600
3	To putty & respray new paintwork on all affected areas.	\$	1,500.00	800
4	To refit & retest new rear sensors on new bumper.	\$	150.00	60
5	To conduct a check on all wiring systems.	\$	150.00	20
6	To apply anti-rust on all affected areas.	\$	200.00	?

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Labour & MISC Charges Total:	\$	3,650.00
Parts Total:	\$	10,003.74
Labour & MISC Charges Total:	\$	3,650.00
Grand Total:	\$	13,653.74